

TI81xx-HDVPSS-01.00.01.25 ReleaseNotes

HDVPSS Version 01.00.01.25

Release Notes

December 17th, 2010

Document License

This work is licensed under the Creative Commons Attribution-Share Alike 3.0 United States License. To view a copy of this license, visit <http://creativecommons.org/licenses/by-sa/3.0/us/> or send a letter to Creative Commons, 171 Second Street, Suite 300, San Francisco, California, 94105, USA.

Introduction

This release notes provides important information that will assist you in using the HDVPSS software package. This document provides the product information and know issues that are specific to the HDVPSS software package.

What is Supported

Common

- Supports HDVPSS drivers for TI814x/TI816x EVMs
- Supports FVID2 interfaces for all the supported drivers
- Package includes HDVPSS DSP/BIOS driver sources, sample applications sources on HDVPSS DSP/BIOS drivers, sample applications executable

Display Drivers

- Supports Display Controller driver
- Supports Bypass Path Display driver
- Supports Secondary Path Display driver
- Supports Graphics Display driver

Capture Drivers

- Supports VIP capture driver (For TI814x only VIP 0 port A and port B are supported)

Memory to Memory Drivers

- Supports Scalar driver through Secondary Path 0-SC5
 - Supports Scalar driver through Bypass Path 0/1-SC5
 - Supports SC3/4 Scalar driver through Secondary Path 0/1-SC3/4- VIP0/1
 - Supports Noise filter driver
 - Supports DEI driver
-

Driver Maturity

Driver Maturity

Driver	TI816x	TI814x
VIP 0/1 Capture	EA	EA
Display Controller	Beta	EA
Bypass Path 0/1 Display	Beta	EA
Secondary Path 1 SD Display	EA	Not supported
GRPX Path 0/1/2 Display	Beta	EA
NSF M2M	Beta	EA
DEIH-WB0 M2M	Beta	NA
DEIH-VIP0 SC3 M2M	Beta	NA
DEIH-WB0-VIP0 SC3 M2M	Beta	NA
DEI-WB1 M2M	Beta	NA
DEI-VIP1 SC4 M2M	Beta	NA
DEI-WB1-VIP1 SC4 M2M	Beta	NA
DEI-WB0 M2M	NA	EA
DEI-VIP0 SC3 M2M	NA	Not supported
DEI-WB0-VIP0 SC3 M2M	NA	EA
Secondary Path 0 - SC5 M2M	Beta	EA
Bypass Path 0/1 - SC5 M2M	EA	Not supported
Secondary Path 0/1 - VIP SC3/4 M2M	EA	Not supported
Proxy Server	Beta	Not supported

Supported/Validated Examples

Supported/Validated Examples

Examples	TI816x	TI814x
VIP Capture	YES	YES
Chains	YES	YES (All the options of chains are not supported)
Mosaic Display	YES	YES (On-Chip HDMI not validated)
SD Display	YES	NO
Tri Display	YES	NO
GRPX Display	YES	YES
Multi-Region GRPX Display	YES	YES
M2M NSF	YES	YES
M2M DEI	YES	YES

M2M DEI Mode 1	YES	NA
M2M SC Down Scale	YES	NO
M2M SC Up Scale	YES	NO
M2M SC Multi Channel	YES	YES

What is Not Supported

TI816x

- None

TI814x

- SD Display is not supported
- Secondary Path 0/1 - VIP SC3/4 M2M
- SubFrame based processing in m2m drivers is not supported
- Stenciling feature of GRPX Display Driver is not supported
- Tri-Display sample application is not supported
- Option 5, 6, and 7 of chains sample application is not supported
- CCS based HDMI.out is not supported

Fixed in this Release

Common

- SDOCM00076819: HDVPSS 1.0.1.24 does not build on linux
- SDOCM00073152: [DC]: Re-Run of display is not working if display path is connected to VENC through HDCOMP Mux
- SDOCM00075582: [Display] Driver doesn't update the runtime parameter present in the first frame submitted to driver
- SDOCM00076324: [GRPX]Driver fails to handle the region scaling case where the input region size is bigger than the venc output size
- SDOCM00072826: [SCWRBK]Scalar Writeback giving warning when multiple frame submitted with same channel number
- SDOCM00075693: SCWRBK M2M: Driver open count is incremented even in failure case
- SDOCM00076828: [UserGuide] VIP Capture sample application section mentions many .xem3 application which is not present in the package

TI816x

- SDOCM00076145: [DCTRL]: VENC overflow is not cleared at the startup
- SDOCM00075902: [SD Display]: Display does not start when Secondary path is connected to SD Venc with the small input video size
- SDOCM00075186: [TrippleDisplay]: Flickering on DVO2 output for option 1 in tridisplay application
- SDOCM00077000: [M2M SC] SEC0/1-SC3/SC4 scalar driver uses wrong SOCH number instead of using SOCH on secondary chroma client
- SDOCM00072187: [M2M DEI] Trailing effect seen on DEI HQ output in 5 field, advanced deinterlacing mode

TI814x

- SDOCM00075801: FVID2_DeInt is not working
- SDOCM00076999: Vps_platformGetBoardId was returning incorrect boardId
- SDOCM00074780: [VIP Capture] Assert is generated when the chains is ran second time
- SDOCM00076739: [DEI M2M] Line average mode is used for deinterlacing even though 3 field mode is selected
- SDOCM00075907: [DEI] Centaurus DEI chains seems to drop frames after 50 mins or so...

New in this Release

Common

- Addition of VIP reset IOCTL IOCTL_VPS_CAPT_RESET_VIP0 and IOCTL_VPS_CAPT_RESET_VIP1. Refer API guide for details
- Addition of NSF read advance config IOCTL_IOCTL_VPS_READ_ADV_NSF_CFG

TI816x

- M2M DEI - Supports runtime change of input resolution (only in DEI bypass mode)
- M2M SC3/SC4 - Supports YUV422SP input format
- M2M SC3/SC4 - Supports runtime change of input resolution, output resolution and scalar parameters
- A8 CCS executable to configure on-Chip HDMI encoder
- Bug fixes

TI814x

- On-chip HDMI is supported on A8 side character driver
- VC chain option is verified with SIL9135 HDMI receiver
- GRPX driver is validated
- Bug Fixes

Known Issues / Limitations

Common

- Few seconds delay is needed between board power cycle. When power cycle is done very fast, board doesn't get reset properly and hence I2C devices don't respond
 - Cropping feature in all driver is done using scalar rather than VPDMA. Hence the entire frame bandwidth will be consumed
 - NTSC capture through VIP will result in 243 lines per field instead of 240 lines. There is no mechanism to crop this in the VIP. Hence application has to allocate a bigger buffer and ignore the extra lines
-

- SDOCM00075785: [M2M NSF] Driver not working in TNF bypass only mode
- SDOCM00076965: [SII9022] A small green bar is seen on the left corner from sii9022 output
- SDOCM00074833: [User Guide] Table of contents missing in HDVPSS user guide

TI816x

- SDOCM00076436: Creation of SC4 Fails when VIP2 is active and already created
- SDOCM00074824: Randomly display getting blank with mosaic layout change
- SDOCM00075203: [DEI M2M] Compressor enable is not supported in progressive TNR mode

TI814x

- SDVENC is not validated
- On-chip HDMI does not work with 1080P60 mode
- Stenciling feature is not supported in GRPX display driver
- SDOCM00077435: TVP 7002 won't work on VC card
- SDOCM00077437: Capture Lot of descriptors errors seen. No impact on the frames captured.

Installation and Usage

Installation and Usage of the HDVPSS package could be found at HDVPSS User Guide

Upgrade and Compatibility Information

Following are the interfaces changes in the HDVPSS drivers compared to the previous release.

- File "\$HDVPSS_Install_Dir\packages\ti\psp\vps\vps_capture.h" structure `Vps_CaptCreateParams` variable added `inScanFormat`. User need to set this variable depending upon the input scan format. More details could be found in the header file and userGuide.
- File "\$HDVPSS_Install_Dir\packages\ti\psp\vps\vps_displayCtrl.h" structure `Vps_DcOutputInfo` variables added `dvoFidPolarity`, `dvoVsPolarity`, `dvoHsPolarity` and `dvoActVidPolarity`. These variables need to be set according to the polarity of the control signals required out of the Venc. More details could be found in the userGuide and header file.
- File "\$HDVPSS_Install_Dir\packages\ti\psp\vps\vps_displayCtrl.h" member `tInfo` of structure `Vps_DcModeInfo` has been changed from a pointer to an instance.
- Occurrence of `DEIMQ/DeiMq` for DEI enums, file name, structures and structure members are replaced with `DEI/Dei`. Like `Vps_DeiMqEdiMode` is renamed to `Vps_DeiEdiMode`
- XDC build support is removed
- Functions are added in platform folder to get the CPU, base board and daughter card revisions.
- `clkEdge` field added to `Vps_VideoEncoderCreateParams` structure to enable the application to specify whether the clock should be enabled in rising or falling clock edge.

Dependencies

This release requires following tools/packages to be installed.

- Code Composer Studio Version : 4.2.0.09000 or 5.0.0.000xx
- XDC Tools Version : 3.20.05.76
- BIOS Version : 6.31.00.18
- CG Tool (TMS470) Version : 4.6.3
- IPC : 1.22.00.19
- Syslink : 02.00.00.66_alpha2

Devices Supported

- TI816x EVM
- TI814x EVM

Validation Information

- This release is validated on TI814x/TI816x EVMs for the above mentioned components.

Technical Support and Product Updates

For further information or to report any problems, contact <http://e2e.ti.com> or <http://community.ti.com> or <http://support.ti.com>.

Article Sources and Contributors

TI81xx-HDVPSS-01.00.01.25 ReleaseNotes *Source:* <http://ap-fpdsp-swapps.dal.design.ti.com/index.php?oldid=80773> *Contributors:* A0131716, A0868651, HardikShah, SivarajR, SujithShivalingappa