

775 Spindle Adapter for MonkeyLaser - Assembly Guide (WIP)

Introduction

The **775 Spindle Adapter for MonkeyLaser** is a custom 3D-printed mount designed to attach a **775 spindle motor** to a **MonkeyLaser** CNC or laser engraver. This adapter includes a motorized **Z-axis**, allowing fine control over spindle height for improved machining precision.

Bill of Materials (BoM)

3D-Printed Parts

- **Spindle Grip** (PLA+CF recommended)
- **Z-Axis Support**
- **Spindle Cover**
- **Rod Covers (8mm guides)**
- **Adjustment Knob**
- **Z-Axis Adapter Bracket**

Hardware

- **M4 Heat Inserts** (for spindle grip adjustment screw)
- **8mm Rods** (Z-axis guide)
- **Brass Lead Screw Nut** (M8)
- **Stepper Motor** (NEMA 17)
- **M4 Screws & Nuts** (for securing components)
- **M3 Screws** (for attaching covers and fine adjustments)
- **Threaded Rod Coupler (8mm to Stepper Shaft)**
- **Rubber Gasket (2mm thick, 154mm x 15mm)** (for spindle grip padding)

Assembly Instructions

Step 1: Preparing the Z-Axis

1. Insert the **8mm rods** into the **Z-axis support**, using the 8mm bushings, ensuring they slide smoothly.
2. Secure the **brass lead screw nut** using M3 screws.
3. Attach the **stepper motor** to the top of the Z-axis bracket with the spacers.
4. Connect the **threaded rod coupler** between the motor and lead screw.

Step 2: Assembling the Spindle Grip

1. Insert **heat inserts** into the grip's tightening section.

2. Fit the **rubber gasket** inside the spindle grip groove to improve friction.
3. Attach the **adjustment knob** with an M4 screw, threading into the heat insert.
4. Insert the **spindle motor** and adjust the grip using the knob.

Step 3: Mounting the Adapter

1. Align the **Z-axis support** onto the CNC's existing frame.
2. Secure the **adapter bracket** to the Z-axis using M4 screws.
3. Attach the **spindle grip assembly** onto the bracket.
4. Ensure the spindle moves freely and tighten all fasteners.

Configuration & Calibration

1. **Check spindle alignment** by running the Z-axis up and down.
2. **Adjust grip tension** to hold the spindle firmly without excessive force.
3. **Wire the stepper motor** to the **DLC32 controller** (or other CNC driver).
4. **Test movement** using a simple G-code command to verify smooth operation.

Wiring & Electronics (DLC32)

- Connect **Stepper Motor** to Z-Axis driver.
- Ensure correct stepper voltage settings.
- Adjust GRBL configuration (steps per mm) in the CNC controller firmware.

Troubleshooting & Adjustments

Common Issues & Solutions

- **Spindle slipping:** Tighten grip screw or check rubber gasket.
- **Z-axis misalignment:** Loosen screws, align, and retighten.
- **Stepper motor skipping:** Verify motor current settings and check lead screw tightness.

Conclusion

This **775 Spindle Adapter for MonkeyLaser** provides a reliable way to add spindle height control to your CNC. If you encounter issues, refer to the troubleshooting section or adjust settings in your controller software. Happy machining!

This guide is maintained at: [GitHub Repository](#)