

# TAP-042

## Clear LIF Unit Alarm

### PURPOSE

Provides procedures for clearing an LIF alarm.

### GENERAL

This procedure assumes that you have logged on to the alarmed Network Element (NE) and have opened the 1603 SM Application browser ([DLP-117](#)). Unless stated otherwise, all menu items referenced in this procedure are selected from the browser context menu.

Refer to [TAP-001](#) for assistance in analyzing alarms and isolating alarms to specific NEs.

---

## Procedure

1. Have alarms and conditions been retrieved?

If yes, go to step [3](#).

If no, go to step [2](#).

2. Retrieve LIF alarms:

**Alarm Surveillance> Current Conditions>Filter>LIF>OK>Retrieve**

3. From the Active Alarms screen, identify the Condition, then go to the step indicated in Table [A](#) to clear alarm.

**Table A. Alarms/Conditions/Events**

ALARM/CONDITION	DESCRIPTION	STEP
BOOT	Unit processor is running bootcode	<a href="#">4</a>
BUERR	B2 parity errors on internal STS1 bus between interconnecting equipment	<a href="#">13</a>
CNTBUS	Standby SBI reflection loop test	<a href="#">133</a>

	failure	
CONTBUS	Control bus error	<a href="#">62</a>
CONTCOM	Control equipment communication failure. An active NEP-LIF link communication link failure has occurred.	<a href="#">73</a>
CONTEQPT	Control equipment failure. An A/B selection failure has occurred.	<a href="#">100</a>
CONTRDUP	Active LIF to standby LIF link failure	<a href="#">118</a>
CTNEQPT	Failure on internal STS1 bus between interconnecting equipment	<a href="#">13</a>
FAILTOSW	Failed to switch	<a href="#">153</a>
FWCONTCOM	STAR to Ethernet board communication failure	<a href="#">164</a>
FWPROGFLT	Firmware program storage failure	<a href="#">172</a>
FWMJVER	Firmware major version error	<a href="#">180</a>
FWMNVER	Firmware minor version error	<a href="#">192</a>
HITEMP	Laser high temperature	<a href="#">206</a>
IMPROPRMVL	Improper removal	<a href="#">215</a>
INHDBGN	Inhibit diagnostics	<a href="#">218</a>
INHMPREPT	Inhibit PM reporting	<a href="#">221</a>
INHSWDX	Inhibit switch to duplex	<a href="#">224</a>
INT	LIF internal failure (SFMT, R/W, error count)	<a href="#">228</a>
INVERR	Inventory error	<a href="#">235</a>
LBCL	High TX laser bias	<a href="#">249</a>
LOTEMP	Laser low temperature	<a href="#">206</a>
LPT	Low laser power (transmitter)	<a href="#">206</a>
MEA	Mismatch of unit and provisioning data	<a href="#">256</a>
MTCE	Removed from service for maintenance	<a href="#">269</a>
PROGFLT	Program storage failure	<a href="#">273</a>
PROGVER	Program version error	<a href="#">279</a>
SYNC	Distributed clock failure	<a href="#">289</a>
SYNCCLK	Sync clock fail or SFMT	<a href="#">301</a>
SYNCSEL	Sync reference in use	<a href="#">315</a>
<b>CONDITION</b>	<b>DESCRIPTION</b>	<b>ACTION</b>
ACT	Unit is active	No action
AINS	Unit is in Automatic-In-Service state	No action

CLKSELA	CLK A is active clock reference	No action
CLKSELB	CLK B is active clock reference	No action
FWDL	Firmware download in progress (manual or auto)	No action
STBY	Unit is standby	No action
SWDL	Automatic or manual download in progress	No action
<b>EVENT</b>	<b>DESCRIPTION</b>	<b>ACTION</b>
AINS	Unit is in Automatic-In-Service state	No action
AUTODL	Automatic download in progress	No action
AUTODLFAIL	Automatic download failed	No action
AUTORESET-0	Automatic reset level 0 (warm restart)	No action
AUTORESET-1	Automatic reset level 1 (cold restart)	No action
EQUIP	Unit is equipped	No action
FRCD SW	Forced switch	No action
FWAUTODL	Automatic download to FW processor is in progress	No action
FWAUTODLFAIL	Automatic download to FW processor failed	No action
FWAUTORESET	Ethernet board processor reset	No action
MANRESET-0	Manual reset level 0 (warm restart)	No action
MANRESET-1	Manual reset level 1 (cold restart)	No action
MANRESET-2	Manual reset level 2 (download)	No action
MANSW	Manual equipment switch	No action
UNASSIGN	Unit is unassigned	No action
UNEQUIP	Unit is unequipped	No action
WTRREVERT	Wait to restore/ revertive time-out	No action

#### Alarm/Condition - BOOT

1. The processor-based unit does not have working software installed and is running bootcode only.

If unit was just installed, an automatic download may be in progress. The ACT (green) LED on the alarmed unit flashes during download process. If download is in progress, wait until it is completed.

2. Retrieve download status of NE:

a. Select the following menu item:  
**Download...**

b. Select Status tab.

c. Select Retrieve.

3. From response, is Automatic S/W Download Inhibited?

If yes, go to step [7](#).

If no, go to step [8](#).

4. Enable the automatic download feature:

a. Select the following menu items:  
**Provision>Network Element>Settings**

b. Select Allow/Inhibit tab.

c. Select NE Global.

d. Select Retrieve.

e. Select Modify.

f. From Auto Download Feature drop-down list, select Allow.

g. Click on OK.

h. Click on Send, then Close.

5. **NOTE:** If COA with expanded memory (COAxx5/xx6 or COA603 - 610) is equipped, it must have current version of software that NEP is running. For software compatibility of

units, refer to [DLP-101](#).

Is the NE equipped with COA with expanded memory or a compatible unit from which software can be auto-downloaded.

If yes, go to step [9](#).

If no, go to step [11](#).

6. Wait for auto-download to complete.
  7. STOP. This procedure is complete.
- Unit must be manually downloaded ([DLP-116](#)).
  - STOP. This procedure is complete.

#### Alarm/Condition - BUERR and CTNEQPT

1. A B2 parity error (BUERR) or failure (CTNEQPT) has been detected on internal STS1 bus between DMI and interconnecting equipment.
2. An attempt is made to record the autonomous message associated with the alarm condition. The message most likely states which side (A or B) of the internal STS1 path the error was detected on, which helps in isolating the faulty unit if it is not the LIF unit.
3. **NOTE:** The type of autonomous message is REPT-ALM-EQPT with the aid format of DGx-LIFy (where x = 1, 2, or 3, and y = A or B). If BUERR alarm, the conddescr parameter contains B2ERRORA or B2ERRORB. If CTNEQPT alarm, the conddescr parameter contains STS1AFAIL, STS1BFAIL, STSAINTERX or STSBINTERX. The highlighted A or B in the conddescr indicates which STS bus (Side A or Side B) the error was detected on.

Do you have a record of the autonomous message associated with the BUERR or CTNEQPT alarm?

If yes, go to step [18](#).

If no, go to step [16](#).

4. Retrieve and review the message log:

**Alarm Surveillance> History Log**  
**Filter>Message Type=Alarms**  
**Retrieve>Details**

From the Details screen, record the description associated with the alarm condition.

5. Record the autonomous message associated with the alarm condition.
6. Perform diagnostics on LIF:
  - a. Select the following menu items:  
**Manual Controls>Diagnostics> Equipment**
  - b. Select LIF tab.
  - c. Modify the Group, Termination Method, Iterations and Phase, where:
    - Group = Drop Group 1A - 3B
    - Termination Method = Immediate
    - Iteration = 5
    - Phase 4 = NSA, STS1 Interconnect
  - d. Click on Send and wait for diagnostics to complete.
7. Did diagnostics pass?

If yes, go to step [20](#).  
If no, go to step [22](#).
8. An intermittent error has occurred. Monitor for further alarms. If alarms continue, go to step [22](#).
9. STOP. This procedure is complete.
10. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF to avoid interrupting service.

11. Replace alarmed LIF per [DLP-101](#).

12. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

13. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [26](#).

14. What type of VSCC is in NE?

If VSCC101, VSCC30x, or VSCC501, go to step [45](#).

If VSCC20x, go to step [27](#).

15. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing plug-in units to avoid interrupting service.

16. Per the VSCC20x configuration (see Figure [1](#)) determine which line group or drop group the LIF is connected to.

17. Was an autonomous message recorded with the conddescr parameter (see step [16](#))?

If yes, go to step [30](#).

If no, go to step [37](#).

**[Figure 1. VSCC20x Traffic Routing Diagrams](#)**

1. **NOTE:** If BUERR alarm, the conddescr parameter contains B2ERRORA or B2ERRORB. If CTNEQPT alarm, the conddescr parameter contains STS1AFAIL, STS1BFail, STSAINTERX or STSBINTERX. The highlighted A or B in the conddescr indicates which internal STS1 bus (Side A or Side B) the error was detected on.

From the conddescr parameter, determine which STS1 bus was alarmed: Side A or Side B.

2. Which STS1 bus was alarm reported on?

If Side A, go to step [32](#).

If Side B, go to step [33](#).

3. In the line group or drop group connected to the alarmed LIF, replace the Side A unit per [DLP-101](#). Go to step [34](#).

4. In the line group or drop group connected to the alarmed LIF, replace the Side B unit per [DLP-101](#).

5. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [35](#).

6. Contact Customer Service ([TNG-505](#)).

7. STOP. This procedure is complete.

8. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing plug-in units to avoid interrupting service.

9. In the line group or drop group connected to the alarmed LIF, replace the unit the LIF is cross-connected to (replace the standby unit, if duplex) per [DLP-101](#).

10. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [40](#).

11. Are units duplex (two units)?

If yes, go to step [41](#).

If no, go to step [43](#).

12. Replace active unit the LIF is cross-connected to per [DLP-101](#).

13. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [43](#).

14. Contact Customer Service ([TNG-505](#)).

15. STOP. This procedure is complete.

16. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when



replacing the VSCC to avoid affecting service.

17. Was an autonomous message recorded with the conddescr parameter (see step [16](#))?

If yes, go to step [47](#).

If no, go to step [54](#).

18. If BUERR alarm, the conddescr parameter contains B2ERRORA or B2ERRORB. If CTNEQPT alarm, the conddescr parameter contains STS1AFAIL, STS1BFAIL, STSAINTERX or STSBINTERX. The highlighted A or B in the conddescr indicates which internal STS1 bus (Side A or Side B) the error was detected on.

From the conddescr parameter, determine which STS1 bus was alarmed: Side A or Side B.

19. Which STS1 bus was alarm reported on?

If Side A, go to step [49](#).

If Side B, go to step [50](#).

20. Replace VSCC-A unit (Side A) per [DLP-101](#); then go to step [51](#).

21. Replace VSCC-B unit (Side B) per [DLP-101](#).

22. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [52](#).

23. Contact Customer Service ([TNG-505](#)).

24. STOP. This procedure is complete.

25. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the VSCC to avoid affecting service.

26. Replace the VSCC unit (replace the standby unit, if duplex) per [DLP-101](#).

27. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [57](#).

28. Are there two VSCC units?

If yes, go to step [58](#).

If no, go to step [60](#).

29. Replace the other VSCC unit per [DLP-101](#).

30. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [60](#).

31. Contact Customer Service ([TNG-505](#)).

32. STOP. This procedure is complete.

#### Alarm/Condition - CONTBUS

1. CONTBUS indicates that an LIF has detected a loss of frame, reflected parity error, or received parity error on the communication bus (SBI) to the active NEP.

2. Perform diagnostics on LIF:

a. Select the following menu items:

**Manual Controls>Diagnostics> Equipment**

b. Select LIF tab.

c. Modify the Group, Termination Method, Iterations and Phase, where:

■ Group = Drop Group 1A - 3B

■ Termination Method = Immediate

■ Iteration = 5

■ Phase 1 = NSA, Active NEP-LIF Comm

d. Click on Send and wait for diagnostics to complete.

3. Did diagnostics pass?

If yes, go to step [65](#).

If no, go to step [67](#).

4. Problem is intermittent; monitor. If problem continues, go to step [67](#).

5. STOP. This procedure is complete.

6. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF to avoid interrupting service.

7. Replace alarmed LIF per [DLP-101](#).

8. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

9. Did the alarm(s) clear?

If yes, STOP. This procedure is complete.

If no, go to step [71](#).

10. Suspect a bad active NEP; go to [TAP-028](#).

11. STOP. This procedure is complete.

**Alarm/Condition - CONTCOM**

1. A CONTCOM alarm indicates that the LIF to NEP link has failed.

2. Perform diagnostics on LIF:

a. Select the following menu items:  
**Manual Controls>Diagnostics> Equipment**

b. Select LIF tab.

c. Modify the Group, Termination Method, Iterations and Phase, where:

- Group = Drop Group 1A - 3B
- Termination Method = Immediate
- Iteration = 5
- Phase 1 = NSA, Active NEP-LIF Comm

d. Click on Send and wait for diagnostics to complete.

3. Did diagnostics pass?

If yes, go to step [76](#).

If no, go to step [78](#).

4. Problem is intermittent; monitor. If problem continues, go to step [78](#).

5. STOP. This procedure is complete.

6. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing plug-in units to avoid interrupting service.

7. Replace alarmed LIF per [DLP-101](#).

8. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

9. Did the alarm(s) clear?

If yes, STOP. This procedure is complete.

If no, go to step [82](#).

10. Replace NEP per [DLP-101](#).

11. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

12. Did the alarm(s) clear?

If yes, STOP. This procedure is complete.

If no, go to step [85](#).

13. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the CLK to avoid interrupting service.

14. Replace same side CLK unit (i.e., if alarmed LIF is on side A , replace CLK-A and if alarmed LIF is on side B, replace CLK-B). Refer to [DLP-101](#) when replacing the clock.

15. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

16. Did the alarm(s) clear?

If yes, STOP. This procedure is complete.

If no, go to step [89](#).

17. If LIF version is:

LIF20x, LIF30x, or LIF901 and VSCC is 10x/20x/301 or 501, go to step [90](#).

LIF40x/50x, LIF601/701, or LIFB01 and VSCC is 10x or 20x, go to step [90](#).

LIF40x/50x, LIF601/701, or LIFB01 and VSCC is 301 or 501, go to step [93](#).

18. Replace opposite side CLK unit per [DLP-101](#).

19. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

20. Did the alarm(s) clear?

If yes, STOP. This procedure is complete.

If no, go to step [97](#).

21. 93 Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the VSCC to avoid interrupting service.

22. Replace opposite side VSCC unit per [DLP-101](#).

23. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

24. Did the alarm(s) clear?

If yes, STOP. This procedure is complete.

If no, go to step [97](#).

25. Suspect backplane bus problem.

26. Contact Customer Support ([TNG-505](#)).

27. STOP. This procedure is complete.

#### Alarm/Condition - CONTEQPT

1. When testing an LIF switch (A/B), the NEP did not get a response from the LIF.

2. Perform diagnostics on LIF:

a. Select the following menu items:

**Manual Controls>Diagnostics> Equipment**

b. Select LIF tab.

c. Modify the Group, Termination Method, Iterations and Phase, where:

- Group = Drop Group 1A - 3B
- Termination Method = Immediate
- Iteration = 5
- Phase 3 = NSA, Switch Code

d. Click on Send.

3. Did diagnostics pass?

If yes, go to step [103](#).

If no, go to step [105](#).

4. Alarm may be intermittent; monitor. If condition continues, go to step [105](#).

5. STOP. This procedure is complete.

6. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF to avoid interrupting service.

7. Replace the alarmed LIF per [DLP-101](#).

8. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

9. Did alarms clear?

If yes, STOP. This procedure is complete.

If no, go to step [109](#).

10. Replace the COA per [DLP-101](#).

11. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

12. Did alarms clear?

If yes, STOP. This procedure is complete.

If no, go to step [112](#).

13. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the NEP to avoid interrupting service.

14. Replace the NEP per [DLP-101](#).

15. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

16. Did alarms clear?

If yes, STOP. This procedure is complete.

If no, go to step [116](#).

17. Suspect backplane bus problem. Contact Customer Service ([TNG-505](#)).

18. STOP. This procedure is complete.

**Alarm/Condition - CONTRDUP**

1. The communications link between the active and standby LIFs has failed.

2. Perform diagnostics on LIF:

a. Select the following menu items:

**Manual Controls>Diagnostics> Equipment**

b. Select LIF tab.

c. Modify the Group, Termination Method, Iterations and Phase, where:



- Group = Drop Group 1A - 3B
- Termination Method = Immediate
- Iteration = 5
- Phase 5 = NSA, Inter LIF Comm

d. Click on Send.

3. Did diagnostics pass?

If yes, go to step [121](#).

If no, go to step [123](#).

4. The alarm may be intermittent; monitor it. If it continues, go to step [123](#).

5. STOP. This procedure is complete.

6. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF to avoid interrupting service.

7. Replace alarmed LIF per [DLP-101](#).

8. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

9. Did the alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [127](#).

10. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF to avoid interrupting service.

11. Replace opposite LIF per [DLP-101](#).

12. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

13. Did the alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [131](#).

14. Suspect backplane bus problem. Contact Customer Service ([TNG-505](#)).

15. STOP. This procedure is complete.

#### Alarm/Condition - CNTBUS

1. An error has been detected on the MSI bus between LIF and LDR units in the drop group. Alarm could be caused by any one of the LIF and LDR units on the bus.
2. **CAUTION: Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF and LDR units to avoid interrupting service.**
3. Replace standby LIF unit per [DLP-101](#).
4. Perform diagnostics on the alarmed LIF:
  - a. Select the following menu items:  
**Manual Controls>Diagnostics> Equipment**
  - b. Select LIF tab.
  - c. Modify the Group, Termination Method, Iterations and Phase, where:
    - Group = Drop Group and side (A or B) of unit being diagnosed
    - Termination Method = Immediate

- Iteration = 5

- Phase 8 = NSA, Inter LIF-LIF communications test via MSI bus.

d. Click on Send.

5. Did diagnostics pass?

If yes, go to step [138](#).

If no, go to step [139](#).

6. STOP. This procedure is complete.

7. Replace the active LIF unit per [DLP-101](#).

8. Repeat diagnostics on the alarmed LIF per step [136](#).

9. Did diagnostics pass?

If yes, go to step [142](#).

If no, go to step [143](#).

10. STOP. This procedure is complete.

11. Replace the standby LDR unit per [DLP-101](#).

12. Repeat diagnostics on the alarmed LIF per step [136](#).

13. Did diagnostics pass?

If yes, go to step [146](#).

If no, go to step [147](#).

14. STOP. This procedure is complete.

15. Replace the active LDR unit per [DLP-101](#).

16. Repeat diagnostics on the alarmed LIF per step [136](#).

17. Did diagnostics pass?

If yes, go to step [150](#).

If no, go to step [151](#).

18. STOP. This procedure is complete.

19. Suspect backplane bus problem. Contact Customer Service ([TNG-505](#)).

20. STOP. This procedure is complete.

#### Alarm/Condition - FAILTOSW

1. The LIF unit failed to switch to standby side.

2. Perform diagnostics on alarmed LIF:

a. Select the following menu items:

**Manual Controls>Diagnostics> Equipment**

b. Select LIF tab.

c. Modify the Group, Termination Method, Iterations and Phase, where:

- Group = Drop Group 1A - 3B

- Termination Method = Immediate

- Iteration = 5

- Phase 5 = NSA, Inter LIF Comm

d. Click on Send.

3. Did diagnostics pass?

If yes, go to step [158](#).

If no, go to step [156](#).

4. Problem is intermittent; monitor it. If it continues, go to step [158](#).

5. STOP. This procedure is complete.

6. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF to avoid interrupting service.

7. Replace the alarmed LIF per [DLP-101](#).

8. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

9. Did the alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [162](#).

10. Suspect opposite LIF, COA, or NEP.

If LIF, go to step [154](#).

If COA, go to [TAP-015](#).

If NEP, go to [TAP-028](#).

11. STOP. This procedure is complete.

#### Alarm/Condition - FWCONTCOM

1. **NOTE:** An FWCONTCOM alarm indicates a communication failure has occurred to the Ethernet portion of the LIF901 unit. The most likely cause is an internal board failure.

2. **CAUTION:** Possibility of service interruption. Reseating LIF901 unit interrupts

**service.**

3. Reseat alarmed LIF901 unit.

4. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

5. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [169](#).

6. **CAUTION: Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF901.**

7. Replace alarmed LIF901 per [DLP-101](#).

8. STOP. This procedure is complete.

#### Alarm/Condition - FWPROGFLT

1. **NOTE:** *An FWPROGFLT alarm indicates a firmware program storage failure has occurred on LIF901 unit. The most likely cause is an internal board failure.*

2. **CAUTION: Possibility of service interruption. Reseating LIF901 unit interrupts service.**

3. Reseat alarmed LIF901 unit.

4. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

5. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [177](#).

6. **CAUTION: Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing LIF901 unit.**
7. Replace alarmed LIF901 per [DLP-101](#).
8. STOP. This procedure is complete.

#### Alarm/Condition - FWMJVER

1. **NOTE:** *The FWMJVER alarm indicates that the major version number of the firmware image embedded in the system software is different than the major version number of the firmware version currently executing (i.e., the in use firmware) on the LAN portion of the LIF901 unit. To clear the alarm, the in use firmware must be overwritten.*
2. Retrieve software inventory:  
  
**Administration> Inventory>Software**
3. On Inventory dialog, verify that Embedded Firmware Version and Inuse Firmware Version are different.
4. **CAUTION: Possibility of service interruption. Overwriting the in use firmware on the Ethernet portion of the LIF901 interrupts service. Loss of service continues until the download is completed.**
5. **NOTE:** *There are two ways to overwrite the in use firmware: enable (allow) automatic download of firmware or manually download firmware.*

Do you want to allow automatic download or manually download LAN firmware?

If you want to allow automatic download, go to step [185](#).

If you want to do a manual download, go to step [187](#).

6. Allow automatic download of firmware:
  - a. Select the following menu items:  
**Provision>Network Element>Settings**
  - b. On NE Settings screen, select Allow/Inhibit tab.

- c. Select Retrieve.
- d. Click on NE Global row to activate Modify.
- e. Select Modify.
- f. From Auto Download ATM LAN drop-down list, select Allow.
- g. Click on OK.
- h. Click on Send, then Close.

7. Go to step [188](#).

8. Manually download firmware:

- a. Select the following menu item:  
**Download**
- b. Select Copy Program - Local tab.
- c. Select Retrieve.
- d. In To region, select DGx-LIFA-FW.
- e. In From region, select Auto Select.
- f. Click on Send.

***NOTE:*** During the download process, LEDs on the front panel of the LIF901 light in a scrolling pattern.

- g. After firmware download completes, click on Close.



9. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

10. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [190](#).

11. Contact Alcatel Customer Support ([TNG-505](#)).

12. STOP. This procedure is complete.

Alarm/Condition - FWMNVER

1. **NOTE:** *The minor version number of the firmware image embedded in the system software is different than the minor version number of the in use firmware on the Ethernet portion of the LIF901 unit. The system software is compatible with the embedded firmware, but they are at different revision levels.*

2. Retrieve software inventory:

**Administration> Inventory>Software**

3. On Inventory dialog, note the minor version number of the Embedded Firmware and the Inuse Firmware.

4. Which version number is greater?

If Embedded Firmware, go to step [200](#) and overwrite in use firmware.

If Inuse Firmware, go to step [196](#).

5. **NOTE:** *The firmware loaded on the LIF901 is the most current version available, which is okay. If you want to silence the alarm, there are two ways to do it: 1) perform a manual download to overwrite the in use firmware so the embedded firmware and in use firmware versions are the same or 2) change the FWMNVER notification code to Not Reported.*

Do you want to silence the alarm?

If yes, go to step [197](#).

If no, STOP. This procedure is complete.

6. Do you want to silence alarm by changing notification code or by overwriting in use

firmware?

If notification code change, go to step [198](#).

If firmware overwrite, go to step [200](#).

7. Change FWMNVER notification code to Not Reported:
  - a. Select the following menu items:  
**Provision>Equipment>LIF**
  - b. On Provision LIF dialog, select Alarm Conditions tab.
  - c. On Alarm Condition dialog, select FWMNVER from list of Alarm Conditions.
  - d. Select Retrieve.
  - e. In LIF column, select alarmed LIF.
  - f. Select Modify.
  - g. From Active Notification Code drop-down list, select Not Reported.
  - h. Click on OK.
  - i. Click on Send, then Close.
8. STOP. This procedure is complete.
9. Possibility of service interruption. Overwriting the in use firmware on the Ethernet portion of the LIF901 interrupts service.
10. There are two ways to overwrite the in use firmware: enable (allow) automatic download of firmware or manually download firmware.

Do you want to allow automatic download or manually download firmware?

If you want to allow automatic download, go to step [202](#).

If you want to do a manual download, go to step [204](#).

11. Enable automatic download of firmware:

- a. Select the following menu items:  
**Provision>Network Element>Settings**
- b. On NE Settings screen, select Allow/Inhibit tab.
- c. Select Retrieve.
- d. Click on NE Global row to activate Modify.
- e. Select Modify.
- f. From Auto Download ATM LAN drop-down list, select Allow.
- g. Click on OK.
- h. Click on Send, then Close.

12. STOP. This procedure is complete.

13. Manually download firmware:

- a. Select the following menu item:  
**Download**
- b. On Download dialog, select Copy Program - Local tab.
- c. Select Retrieve.
- d. In To region, select DGx-LIFA-FW.

e. In From region, select Auto Select.

f. Click on Send.

**NOTE:** During the download process, LEDs on the front panel of the LIF901 light in a scrolling pattern.

g. Click on Close.

14. STOP. This procedure is complete.

#### Alarm/Condition - HITEMP, LOTEMP and LPT

1. A unit has detected a HITEMP, LOTEMP, or LPT alarm condition. HITEMP indicates laser high temperature, LOTEMP indicates laser low temperature, an LPT indicates low laser transmit power.

2. **CAUTION: Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF to avoid interrupting service.**

3. Replace alarmed LIF per [DLP-101](#).

4. Retrieve alarms:

#### **Alarm Surveillance> Current Alarms>Retrieve**

5. Did the alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [211](#).

6. Perform step [207](#) through step [209](#) at far end.

7. Did the alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [213](#).

8. Perform transmission test on the fiber per local procedure.

9. STOP. This procedure is complete.

#### Alarm/Condition - IMPROPRMVL

1. An LIF was physically removed.
  - The peer LIF should be active.
  - The removed LIF should be replaced.
- Reinstall or replace LIF unit per [DLP-101](#).
- STOP. This procedure is complete.

#### Alarm/Condition - INHDGN

1. Diagnostic tests are inhibited. Do you want to allow diagnostics?

If yes, go to step [219](#).

If no, STOP. This procedure is complete.

2. Allow diagnostics:
  - a. Select the following menu items:  
**Provision>Equipment>LIF**
  - b. Select Allow/Inhibit tab.
  - c. Select alarmed LIF.
  - d. Select Retrieve.
  - e. Select Modify.

- f. From Diagnostic Tests drop-down list, select Allow.
  - g. Click on OK.
  - h. Click on Send, then Close.
3. STOP. This procedure is complete.

#### Alarm/Condition - INHPMREPT

1. Scheduled reporting of performance monitoring is inhibited. Do you want to allow PM reporting?  
  
If yes, go to step [222](#).  
If no, STOP. This procedure is complete.
2. Allow PM reporting:
  - a. Select the following menu items:  
**Provision>Equipment>LIF**
  - b. Select Allow/Inhibit tab.
  - c. Select alarmed LIF.
  - d. Select Retrieve.
  - e. Select Modify.
  - f. From PM Reports drop-down list, select Allow.
  - g. Click on OK.
  - h. Click on Send, then Close.

3. STOP. This procedure is complete.

#### Alarm/Condition - INHSWDX

1. Duplex switching of LIF unit is inhibited. Do you want to allow duplex switching?

If yes, go to step [226](#).

If no, STOP. This procedure is complete.

2. **CAUTION: Possibility of service interruption. Under normal conditions, do not leave duplex switching inhibited.**

3. Allow duplex switching of LIF unit:

- a. Select the following menu items:

**Provision>Equipment>LIF**

- b. Select Allow/Inhibit tab.

- c. Select alarmed LIF.

- d. Select Retrieve.

- e. Select Modify.

- f. From Switch to Duplex drop-down list, select Allow.

- g. Click on OK.

- h. Click on Send, then Close.

4. STOP. This procedure is complete.

#### Alarm/Condition - INT

1. An LIF INT alarm condition is caused by an ASIC failure, a read/write check fail, ASIC identification error, a device error count fail, or other internal failure.
2. **CAUTION: Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF to avoid interrupting service.**

3. Replace alarmed LIF per [DLP-101](#).

4. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

5. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [233](#).

6. Are there any PWR unit alarms?

If yes, go to [TAP-030](#).

If no, contact Customer Service ([TNG-505](#)).

7. STOP. This procedure is complete.

#### Alarm/Condition - INVERR

1. Contents of inventory data are inconsistent or absent due to EEPROM communication problem.

2. Retrieve hardware inventory:

**Administration> Inventory>Hardware**

3. Was a response obtained?

If yes, go to step [241](#).

If no, go to step [238](#).

4. **CAUTION: Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF to avoid interrupting service.**



5. Replace unit per [DLP-101](#); EEPROM is bad.
6. STOP. This procedure is complete.
7. Is data consistent with unit description?  
  
If yes, go to step [242](#).  
If no, unit EEPROM is bad. Go to step [244](#).
8. Error is intermittent; check for other alarms.
9. STOP. This procedure is complete.
10. Are there any other LIF alarms?  
  
If yes, go to step [245](#).  
If no, go to step [246](#).
11. Resolve LIF alarms first. Refer to Table [A](#).
12. Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF to avoid interrupting service.
13. Replace unit per [DLP-101](#); EEPROM is bad.
14. STOP. This procedure is complete.

#### Alarm/Condition - LBCL

1. There is a high transmission laser bias alarm indicating that the bias current has exceeded 1.5 times its initial value.
2. **CAUTION: Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF to avoid interrupting service.**

3. Replace alarmed LIF per [DLP-101](#).

4. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

5. Did the alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [254](#).

6. Check for PWR unit alarms. Go to [TAP-030](#).

7. STOP. This procedure is complete.

**Alarm/Condition - MEA**

1. The database entry for the alarmed unit does not match equipment type parameter on unit EEPROM.

2. Retrieve hardware inventory, and note the Unit Name of the alarmed unit:

**Administration> Inventory>Hardware**

3. Was data retrieved successfully?

If yes, go to step [259](#).

If no, go to step [266](#).

4. Retrieve provisioned data for alarmed unit, and note the Equipment Type of the alarmed unit:

**Provision>Equipment >LIF>Parameters>Retrieve**

5. From response, compare Equipment Type parameter to Unit Name.

6. Is database entry incorrect or is wrong unit installed?

If incorrect entry, go to step [262](#).

If wrong unit, go to step [266](#).

7. Change the database entry for the alarmed unit:

- a. From the Parameters screen opened in step [259](#), select alarmed LIF unit.
- b. Click on Modify.
- c. From Equipment Type drop-down list, select unit name that matches name found on faceplate.
- d. Click on OK.
- e. Click on Send.

8. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

9. Did alarm clear?

If yes, STOP. This procedure is complete.

If no (command was denied), go to step [265](#).

10. **NOTE:** *Command was denied because installed unit is not compatible with database entry. Installing an incompatible unit may be considered an upgrade.*

Refer to A Guide to Upgrading manual for more information.

11. **CAUTION: Possibility of service interruption. Adhere to the procedure in [DLP-101](#) when replacing the LIF unit to avoid interrupting service.**

12. Replace the LIF unit per [DLP-101](#).

13. STOP. This procedure is complete.

**Alarm/Condition - MTCE**

1. Unit has been removed from service for maintenance.

2. Is this a desired result?

If yes, STOP. This procedure is complete.

If no, go to step [271](#).

3. Restore LIF to service:

a. Select the following menu items:

**Provision>Equipment>LIF**

b. Select Parameters tab.

c. Select the alarmed LIF.

d. Select Retrieve.

e. Select Modify.

f. From Service State drop-down list, select In Service.

g. Click on OK.

h. Click on Send, then Close.

4. STOP. This procedure is complete.

Alarm/Condition - PROGFLT

1. Either automatic or manual download failed because of a program memory failure. The fault is raised against the target of the download, not the source.
2. **CAUTION: Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF to avoid interrupting service.**
3. Replace LIF per [DLP-101](#); EEPROM is bad.

4. Did the alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [277](#).

5. Contact Customer Service ([TNG-505](#)).

6. STOP. This procedure is complete.

#### Alarm/Condition - PROGVER

1. The program version downloaded to the LIF is not the same as the program version in the NEP (which is assumed to be the correct version).

2. Retrieve and note the NEP and LIF software version numbers:

**Administration> Inventory>Software**

3. Are NEP and LIF program versions the same?

If yes, go to step [282](#).

If no, go to step [284](#).

4. **CAUTION: Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing the LIF to avoid interrupting service.**

5. Replace the alarmed LIF ([DLP-101](#)); then go to step [285](#).

6. Download the inconsistent LIF per [DLP-116](#).

7. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [286](#).

8. Was LIF replaced?

If yes, go to step [287](#).

If no, go to step [282](#).

9. Contact Customer Service ([TNG-505](#)).

10. STOP. This procedure is complete.

#### Alarm/Condition - SYNC

1. A SYNC alarm condition signifies that the LIF has lost internal shelf clock input.

2. Retrieve alarms:

##### **Alarm Surveillance> Current Alarms>Retrieve**

3. Is there a SYNCCLK alarm?

If yes, go to step [301](#).

If no, go to step [292](#).

4. **CAUTION: Possibility of service interruption. Adhere to the procedure in [DLP-101](#) when replacing the LIF to avoid interrupting service.**

5. Replace the LIF per [DLP-101](#).

6. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [295](#).

7. Replace the VSCC on the opposite side per [DLP-101](#).

8. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [297](#).

9. Replace the same side CLK unit per [DLP-101](#).

10. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [299](#).

11. Contact Customer Service ([TNG-505](#)).

12. STOP. This procedure is complete.

#### Alarm/Condition - SYNCCLK

1. An LIF has either lost the clock from the clock PBA, frame sync, STS sync, or VT sync.

2. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

3. **NOTE:** CLK alarms and equipment alarms reported as ISLTD (isolated) should be cleared first.

Are there any other EQPT alarms?

If yes, go to [TAP-021](#).

If no, go to step [304](#).

4. **CAUTION: Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing plug-in units to avoid interrupting service.**

5. Replace alarmed LIF per DPL-101.

6. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

7. Did alarm clear?

If yes, STOP. This procedure is complete..

If no, go to step [308](#).

8. Replace the CLK unit on the same side as the alarmed LIF per [DLP-101](#).

9. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

10. Did alarms clear?

If yes, STOP. This procedure is complete.

If no, go to step [311](#).

11. Replace other CLK unit per [DLP-101](#).

12. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [313](#).

13. Suspect backplane problem; contact Customer Service ([TNG-505](#)).

14. STOP. This procedure is complete.

#### Alarm/Condition - SYNCSEL

1. **NOTE:** *This condition could be due to failure of LIFs in other drop groups. Replace units in other drop groups sequentially. Contact Customer Service ([TNG-505](#)) after replacing all LIFs if alarms are still active.*

A SYNCSEL indicates synchronization signal failure for NE timing from the LIF.

2. **CAUTION: Possibility of service interruption. Adhere to [DLP-101](#) in the following steps when replacing plug-in units to avoid interrupting service.**

3. Replace the standby (STBY) LIF per [DLP-101](#).

4. Retrieve alarms:

**Alarm Surveillance> Current Alarms>Retrieve**

5. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [320](#).

6. Replace active (ACT) LIF per [DLP-101](#).

7. Retrieve alarms:



**Alarm Surveillance> Current Alarms>Retrieve**

8. Did alarm clear?

If yes, STOP. This procedure is complete.

If no, go to step [323](#).

9. Contact Customer Service ([TNG-505](#)).

10. STOP. This procedure is complete.