

Tags	ID	Name	Desc	Notes	Status	Owner	Due
Osprey R4	US67691	OAC setup for Osprey R4	OAC setup for Osprey R4	[FW47]verification is done in staging server [FW46]T2 option setting on stage in OAC has been completed.It has been confirmed that the requested settings and OAC settings match.MFG is checking whether the option key created in OAC is working properly.	Completed	HanIl.Lee	
Osprey R4	DE15056	Koios On-Scanner demo design change	Design change to add T2 osprey in Koios On-Scanner demo. Things to be expected to be done.Confirm Osprey images are compatible with Koios modeling. (DICOM conformance)Light SUT testing to ensure Osprey with Koios installed remains a functional medical ultrasound device within a customer demo implementation Address delivery methodGE engineering change for the existing partDistribution of updated payload (the actual launch and release to user community.)	[FW49] Meeting/Nils wil be held FW49.3.	In-Progress	Taeyang	
Osprey R4	US69031	P&S deliverables for Osprey R4 M3	Completion of P&S deliverables for Osprey R4 M3. SAS revise.	[FW01]Security Assessment Summary (SAS) : Done (Revision 4)	Completed	KyuDong	
Osprey R4	US69032	RsVP(service platform) promotion to production server	RsVP promotion to production server	[FW01]Share screen shot for server list : SharedRSvP MI test : In routing in MWS (Multy device and eDelivery)Promotion template : Shared	In-Progress	KyuDong	FW01.2
Osprey R4	US69612	Make closure plan for the open SPRs left over from R4.5.7	This data should be updated in ""Status update"" column in ALM, this action should be completed by FW03 2024.	[FW01]-Review the SPRS : In Prog-Update completed by FW03 2024.	In-Progress	DJ.Sung	FW01.5

Osprey R5;Osprey2mainline	US67688	T2 Baselmage integration with mainline	Creating Automation scripts of T2 specific configuration such as audio and PDF printer for R5 mainline.	[FW01] Asking code review to S.Mike[FW50] Code review in Swarm Review 4354445.	In-Progress	Donald K	FW50.5
Osprey2 mainline	US68622	Realtek's Audio Configuration Automation for Osprey	Realtek's Audio Configuration Automation for Osprey	[FW01]- Done	Completed	Suncheol Heo	FW01.2
Gemini R5	US69207	Implement and submit Prototype 3rd step	This step is to implement prototypes of Step 1 and 2 properly.Prototype codes need to be cleaned and structured according to codes of Auto Preset version 1.0	[FW01]Implementing ROI changing from Convex to Linear for CFM only, using information of convex.	In-Progress	Ho	FW01.5
Gemini R5	US69730	VITA 2.0 backlog	Gemini R5를 위한 VITA 2.0 backlog 작성	[FW50]Write VITA 2.0 backlog list - done	Completed	DJ.Sung	
Maru R4.5	DE15258	SPR 93997 Thyroid Productivity Package for DICOM SR – H42792LP is required for DICOM Thyroid measurements to successfully transfer Thyroid SR measurements to DICOM destination	Thyroid Productivity Package for DICOM SR – H42792LP is required for DICOM Thyroid measurements to successfully transfer Thyroid SR measurements to DICOM destination	[FW01] We will continue to discuss it on FW02 as Mayumi is on vacation until 9 Jan.	In-Progress	Dongyou ng Choi	FW50.5
Maru R4.5;Maru R4	DE15292	MDC issue	MDC issue Acquisition DCDC sync 분석 요청	[FW01] No update	In-Progress	DJ.Sung	FW49.5
Maru R4.5	US70253	EEPROM reading error in AdvTECH COMExp-A4	Failed EEPROM reading error in AdvTECH COMExp-A4	[FW01]susi4 api full installed Read successfully.	In-Progress	DJ.Sung	FW01.5

Others	US70270	Cyber Security Inquiry Process #00105782	SPC340 - Réseau de l'Arc	[FW01]Questionnaires review : In progress	In- Progres s	KyuDong FW01.1
Advante ch	US67689	[Adv. SOM] Power Recycling & Random Test	Adv. SOM ver A4 shall be working OK and has no problem.	[FW01] >Resolved ""Bluescreen"" (BSOD) problem.It seems that Adv. SOM has a problem of detecting NVME device when boot media is changed (USB=>NVME).Forced to use Microsoft general NVME controller driver only to avoid BSOD. >Power recycling : SOM#1: 775(Stopped) / SOM#2: 1765(Running)RandEx: SOM#3 776(Running) >Need to test & verify boot up time is less than 90 seconds.	In- Progres s	Donald K FW01.5