

TMS320F2837xD Dual-Core Delfino™ MCUs Silicon Revisions C, B, A, 0

1 Introduction

This document describes the silicon updates to the functional specifications for the TMS320F2837xD microcontrollers (MCUs).

The updates are applicable to the following:

- 337-ball New Fine Pitch Ball Grid Array, ZWT Suffix
- 176-pin PowerPAD™ Thermally Enhanced Low-Profile Quad Flatpack, PTP Suffix

2 Device and Development Support Tool Nomenclature

To designate the stages in the product development cycle, TI assigns prefixes to the part numbers of all [TMS320] DSP devices and support tools. Each TMS320™ DSP commercial family member has one of three prefixes: TMX, TMP, or TMS (for example, **TMS320F28379D**). Texas Instruments recommends two of three possible prefix designators for its support tools: TMDX and TMDS. These prefixes represent evolutionary stages of product development from engineering prototypes (with TMX for devices and TMDX for tools) through fully qualified production devices and tools (with TMS for devices and TMDS for tools).

TMX	Experimental device that is not necessarily representative of the final device's electrical specifications
TMP	Final silicon die that conforms to the device's electrical specifications but has not completed quality and reliability verification
TMS	Fully qualified production device

Support tool development evolutionary flow:

TMDX	Development-support product that has not yet completed Texas Instruments internal qualification testing
TMDS	Fully qualified development-support product

TMX and TMP devices and TMDX development-support tools are shipped against the following disclaimer:

"Developmental product is intended for internal evaluation purposes."

TMS devices and TMDS development-support tools have been characterized fully, and the quality and reliability of the device have been demonstrated fully. TI's standard warranty applies.

Predictions show that prototype devices (TMX or TMP) have a greater failure rate than the standard production devices. Texas Instruments recommends that these devices not be used in any production system because their expected end-use failure rate still is undefined. Only qualified production devices are to be used.

TI device nomenclature also includes a suffix with the device family name. This suffix indicates the package type (for example, PTP) and temperature range (for example, T).

3 Device Markings

Figure 1 provides an example of the 2837xD device markings and defines each of the markings. The device revision can be determined by the symbols marked on the top of the package as shown in Figure 1. Some prototype devices may have markings different from those illustrated. Figure 2 shows an example of the device nomenclature.




Figure 1. Example of Device Markings

Table 1. Determining Silicon Revision From Lot Trace Code

SILICON REVISION CODE	SILICON REVISION	REVID ⁽¹⁾ Address: 0x5D00C	COMMENTS
Blank	0	0x0000	This silicon revision is available as TMX.
A	A	0x0000	This silicon revision is available as TMX.
B	B	0x0002	This silicon revision is available as TMX.
C	C	0x0003	This silicon revision is available as TMS.

⁽¹⁾ Silicon Revision ID




Figure 2. Example of Device Nomenclature

4 Usage Notes and Known Design Exceptions to Functional Specifications

4.1 Usage Notes

Usage notes highlight and describe particular situations where the device's behavior may not match presumed or documented behavior. This may include behaviors that affect device performance or functional correctness. These usage notes will be incorporated into future documentation updates for the device (such as the device-specific data sheet), and the behaviors they describe will not be altered in future silicon revisions.

Table 2 shows which silicon revision(s) are affected by each usage note.

Table 2. List of Usage Notes

TITLE	SILICON REVISION(S) AFFECTED			
	0	A	B	C
PIE: Spurious Nested Interrupt After Back-to-Back PIEACK Write and Manual CPU Interrupt Mask Clear	Yes	Yes	Yes	Yes
Caution While Using Nested Interrupts	Yes	Yes	Yes	Yes

4.1.1 PIE: Spurious Nested Interrupt After Back-to-Back PIEACK Write and Manual CPU Interrupt Mask Clear

Revision(s) Affected: 0, A, B, C

Certain code sequences used for nested interrupts allow the CPU and PIE to enter an inconsistent state that can trigger an unwanted interrupt. The conditions required to enter this state are:

1. A PIEACK clear is followed immediately by a global interrupt enable (EINT or asm(" CLRC INTM")).
2. A nested interrupt clears one or more PIEIER bits for its group.

Whether the unwanted interrupt is triggered depends on the configuration and timing of the other interrupts in the system. This is expected to be a rare or nonexistent event in most applications. If it happens, the unwanted interrupt will be the first one in the nested interrupt's PIE group, and will be triggered after the nested interrupt reenables CPU interrupts (EINT or asm(" CLRC INTM")).

Workaround: Add a NOP between the PIEACK write and the CPU interrupt enable. Example code is shown below.

```
//Bad interrupt nesting code
PieCtrlRegs.PIEACK.all = 0xFFFF;    //Enable nesting in the PIE
EINT;                                //Enable nesting in the CPU

//Good interrupt nesting code
PieCtrlRegs.PIEACK.all = 0xFFFF;    //Enable nesting in the PIE
asm(" NOP");                          //Wait for PIEACK to exit the pipeline
EINT;                                //Enable nesting in the CPU
```

4.1.2 Caution While Using Nested Interrupts

Revision(s) Affected: 0, A, B, C

If the user is enabling interrupts using the EINT instruction inside an interrupt service routine (ISR) in order to use the nesting feature, then the user must disable the interrupts before exiting the ISR. Failing to do so may cause undefined behavior of CPU execution.

4.2 Known Design Exceptions to Functional Specifications

Table 3 shows which silicon revision(s) are affected by each advisory.

Table 3. List of Advisories

TITLE	SILICON REVISION(S) AFFECTED			
	0	A	B	C
Analog Trim of Some TMX Devices	Yes	Yes	Yes	
ADC: ADC Post-Processing Block Limit Compare	Yes	Yes	Yes	Yes
ADC: ADC Offset Trim in Different Modes	Yes	Yes	Yes	Yes
ADC: Random Conversion Errors	Yes	Yes	Yes	
ADC: ADC PPB Event Trigger (ADCxEVT) to ePWM Digital Compare Submodule	Yes	Yes	Yes	
ADC: 12-Bit Switch Resistance	Yes	Yes	Yes	
ADC: 12-Bit Input Capacitance When Switching Channel Groups	Yes	Yes	Yes	
ADC: Functionality of V_{REFLO} Pins	Yes	Yes		
ADC: Sensitivity to ESD Events	Yes	Yes		
ADC: ADC Input Multiplexer Connection at Beginning of Acquisition Window	Yes	Yes		
ADC: ADC Sparkle Codes	Yes	Yes		
ADC: ADC Linearity Performance	Yes			
XRS may Toggle During Power Up	Yes	Yes	Yes	
USB: USB DMA Event Triggers are not Supported	Yes	Yes	Yes	Yes
VREG: VREG Will be Enabled During Power Up Irrespective of VREGENZ	Yes	Yes	Yes	
Flash: A Single-Bit ECC Error May Cause Endless Calls to Single-Bit-Error ISR	Yes	Yes	Yes	Yes
Flash: Minimum Programming Word Size	Yes	Yes	Yes	Yes
Flash: Reset of CPU2 While it has Pump Ownership Can Cause Erroneous Flash Reads From CPU1	Yes	Yes		
ePIE: Spurious VCU Interrupt (ePIE 12.6) Can Occur When First Enabled	Yes	Yes	Yes	
eQEP: Position Counter Incorrectly Reset on Direction Change During Index	Yes	Yes	Yes	Yes
eQEP: eQEP Inputs in GPIO Asynchronous Mode	Yes	Yes	Yes	Yes
PLL: May Not Lock On the First Lock Attempt	Yes	Yes	Yes	Yes
SDFM: Data Filter Output Does Not Saturate at Maximum Value With Sinc3 and OSR = 256	Yes	Yes	Yes	Yes
SDFM: Spurious Data Acknowledge Event When Data Filter is Configured and Enabled for the First Time	Yes	Yes	Yes	Yes
SDFM: Spurious Data Acknowledge Event When Data Filter is Synchronized Using PWM FILRES Signal	Yes	Yes	Yes	Yes
SDFM: Comparator Filter Module may Generate Spurious Over-Value and Under-Value Conditions	Yes	Yes	Yes	Yes
SDFM: Dynamically Changing Threshold Settings (LLT, HLT), Filter Type, or COSR Settings Will Trigger Spurious Comparator Events	Yes	Yes	Yes	Yes
SDFM: Dynamically Changing Data Filter Settings (Such as Filter Type or DOSR) Will Trigger Spurious Data Acknowledge Events	Yes	Yes	Yes	Yes
FPU: FPU-to-CPU Register Move Operation Preceded by Any FPU 2p Operation	Yes	Yes	Yes	Yes
FPU: LUF, LVF Flags are Invalid for the EINVF32 and EISQRTF32 Instructions	Yes	Yes	Yes	Yes
Memory: Prefetching Beyond Valid Memory	Yes	Yes	Yes	Yes
Low-Power Modes: Power Down Flash or Maintain Minimum Device Activity	Yes	Yes	Yes	Yes
CMPSS: COMPxLATCH May Not Clear Properly Under Certain Conditions	Yes	Yes	Yes	Yes
CMPSS: Ramp Generator May Not Start Under Certain Conditions	Yes	Yes	Yes	Yes
CMPSS: CMPIN4N, CMPIN4P, CMPIN5N, and CMPIN5P Not Available	Yes	Yes		
Boot ROM: Device Will Hang During Boot if X1 Clock Source is not Present			Yes	
HRPWM: HRCNFG Register Reads and Bit-Wise Writes	Yes	Yes		
SYSBIOS in ROM References Different Flash Sector (Changed From Sector A to Sector B)	Yes	Yes		

Table 3. List of Advisories (continued)

TITLE	SILICON REVISION(S) AFFECTED			
	0	A	B	C
McBSP: McBSP Transmit in SPI Slave Mode	Yes	Yes		
Crystal: Maximum Equivalent Series Resistance (ESR) Values are Reduced	Yes	Yes		
GPIO: GPIO0–GPIO7, GPIO46, GPIO47 Shunt to V_{SS} Due to Fast Transients at High Temperature	Yes	Yes		

Table 4. Table of Contents for Advisories

Title	Page
Advisory — Analog Trim of Some TMX Devices	7
Advisory — ADC: ADC Post-Processing Block Limit Compare	8
Advisory — ADC: ADC Offset Trim in Different Modes.....	8
Advisory — ADC: Random Conversion Errors	8
Advisory — ADC: ADC PPB Event Trigger (ADCxEVT) to ePWM Digital Compare Submodule.....	9
Advisory — ADC: 12-Bit Switch Resistance	9
Advisory — ADC: 12-Bit Input Capacitance When Switching Channel Groups	9
Advisory — ADC: Functionality of V_{REFLO} Pins	10
Advisory — ADC: Sensitivity to ESD Events	10
Advisory — ADC: ADC Input Multiplexer Connection at Beginning of Acquisition Window	10
Advisory — ADC: ADC Sparkle Codes.....	11
Advisory — ADC: ADC Linearity Performance	11
Advisory — \overline{XRS} may Toggle During Power Up	12
Advisory — USB: USB DMA Event Triggers are not Supported.....	12
Advisory — VREG: VREG Will be Enabled During Power Up Irrespective of VREGENZ	12
Advisory — Flash: A Single-Bit ECC Error May Cause Endless Calls to Single-Bit-Error ISR	13
Advisory — Flash: Minimum Programming Word Size.....	13
Advisory — Flash: Reset of CPU2 While it has Pump Ownership Can Cause Erroneous Flash Reads From CPU1.....	14
Advisory — ePIE: Spurious VCU Interrupt (ePIE 12.6) Can Occur When First Enabled.....	15
Advisory — eQEP: Position Counter Incorrectly Reset on Direction Change During Index	16
Advisory — eQEP: eQEP Inputs in GPIO Asynchronous Mode	16
Advisory — PLL: May Not Lock on the First Lock Attempt	17
Advisory — SDFM: Data Filter Output Does Not Saturate at Maximum Value With Sinc3 and OSR = 256.....	19
Advisory — SDFM: Spurious Data Acknowledge Event When Data Filter is Configured and Enabled for the First Time	19
Advisory — SDFM: Spurious Data Acknowledge Event When Data Filter is Synchronized Using PWM FILRES Signal	19
Advisory — SDFM: Comparator Filter Module may Generate Spurious Over-Value and Under-Value Conditions	20
Advisory — SDFM: Dynamically Changing Threshold Settings (LLT, HLT), Filter Type, or COSR Settings Will Trigger Spurious Comparator Events.....	20
Advisory — SDFM: Dynamically Changing Data Filter Settings (Such as Filter Type or DOSR) Will Trigger Spurious Data Acknowledge Events.....	20
Advisory — FPU: FPU-to-CPU Register Move Operation Preceded by Any FPU 2p Operation	21
Advisory — FPU: LUF, LVF Flags are Invalid for the EINVF32 and EISQRTF32 Instructions	24
Advisory — Memory: Prefetching Beyond Valid Memory	27
Advisory — Low-Power Modes: Power Down Flash or Maintain Minimum Device Activity	28
Advisory — CMPSS: COMPxLATCH May Not Clear Properly Under Certain Conditions	29
Advisory — CMPSS: Ramp Generator May Not Start Under Certain Conditions	29
Advisory — CMPSS: CMPIN4N, CMPIN4P, CMPIN5N, and CMPIN5P Not Available	29
Advisory — Boot ROM: Device Will Hang During Boot if X1 Clock Source is not Present	30
Advisory — HRPWM: HRCNFG Register Reads and Bit-Wise Writes	30

Table 4. Table of Contents for Advisories (continued)

Advisory —SYSBIOS in ROM References Different Flash Sector (Changed From Sector A to Sector B)	30
Advisory —McBSP: McBSP Transmit in SPI Slave Mode	31
Advisory —Crystal: Maximum Equivalent Series Resistance (ESR) Values are Reduced	31
Advisory —GPIO: GPIO0–GPIO7, GPIO46, GPIO47 Shunt to V_{ss} Due to Fast Transients at High Temperature.....	32

Advisory *Analog Trim of Some TMX Devices*

Revision(s) Affected 0, A, B

Details Some TMX samples may not have analog trims programmed. This could degrade the performance of the ADC, buffered DAC, and internal oscillators. A value of all zeros in these trim registers due to lack of trim will have the following impact.

TRIM	REGISTER	IMPACT OF UNTRIMMED REGISTER
ADC reference	AnalogSubsysRegs.ANAREFTRIMA AnalogSubsysRegs.ANAREFTRIMB AnalogSubsysRegs.ANAREFTRIMC AnalogSubsysRegs.ANAREFTRIMD	Degraded performance of the ADC for all specifications.
ADC linearity	AdcaRegs.ADCINLTRIM1-6 AdcbRegs.ADCINLTRIM1-6 AdccRegs.ADCINLTRIM1-6 AdcdRegs.ADCINLTRIM1-6	Degraded INL and DNL specifications of the ADC in 16-bit mode. No workaround available.
ADC offset	AdcaRegs.ADCOFFTRIM AdcbRegs.ADCOFFTRIM AdccRegs.ADCOFFTRIM AdcdRegs.ADCOFFTRIM	Degraded performance of the ADC offset error specification.
Internal oscillator	AnalogSubsysRegs.INTOSC1TRIM AnalogSubsysRegs.INTOSC2TRIM	Degraded frequency accuracy and temperature drift of the internal oscillators.
Buffered DAC offset	DacaRegs.DACTRIM DacbRegs.DACTRIM DaccRegs.DACTRIM	Degraded offset error specification of the buffered DAC. No workaround available.

Workaround(s) The following workarounds can be used for improved performance, though it still may not meet data sheet specifications.

To determine if a device is TMX in software, check the status of the PARTIDL[QUAL]. If this field is 0, the device is TMX. PARTIDL[QUAL] can be read via the function call SysCtl_getDeviceParametric(SYSCTL_DEVICE_QUAL).

If the **ADC reference trim** registers contain all zeros, write the static reference trim value of 0x7BDD to the reference trim register for all ADCs.

Missing **ADC offset trim** can be generated by following the instructions in the “ADC Zero Offset Calibration” section of the [TMS320F2837xD Dual-Core Delfino Microcontrollers Technical Reference Manual](#).

If the **internal oscillator trim** contains all zeros, the user can adjust the lowest 10 bits of the oscillator trim register between 1 (minimum) and 1023 (maximum) while observing the system clock on the XCLOCKOUT pin.

Advisory	<i>ADC: ADC Post-Processing Block Limit Compare</i>
Revision(s) Affected	0, A, B, C
Details	When using a non-zero offset reference in the ADC post-processing block (PPB), the resultant ADCPPBxRESULT can be signed. TRIPHI or TRIPLO limit compares do not function correctly with this result if it is signed.
Workaround(s)	<p>When using the TRIPHI or TRIPLO limit compares, leave the offset reference as zero. The offset reference (and zero compare) can be used as long as the limit compares are disabled.</p> <p>If the limit compares, the offset reference, and the zero-crossing compare are to be used at the same time, then two PPBs can be used. Both PPBs should be configured to use the same SOC. One PPB can implement the TRIPHI and/or TRIPLO limit compares while the other can implement offset reference subtraction and zero-crossing detection.</p>
Advisory	<i>ADC: ADC Offset Trim in Different Modes</i>
Revision(s) Affected	0, A, B, C
Details	A different offset trim is required when switching between 12-bit and 16-bit resolution and when switching between single-ended and differential signaling mode.
Workaround(s)	Whenever setting the resolution or signal mode of the ADC, use the "AdcSetMode" function in controlSUITE™. This will ensure the correct trims are loaded into the offset trim register. Note that on start-up, trims will be loaded for 12-bit, single-ended operation.
Advisory	<i>ADC: Random Conversion Errors</i>
Revision(s) Affected	0, A, B
Details	The ADC may have errors at a rate as high as 1 in $10^{6.5}$ ADC conversions in 12-bit mode and as high as 1 in $10^{8.75}$ conversions in 16-bit mode. When a conversion error occurs, it will be a significant random jump in the digital output of the ADC without a corresponding change in the ADC input voltage, otherwise known as a "sparkle code". The magnitude of this jump will typically be in the range of 20 LSBs to 200 LSBs; however, larger or smaller jumps may occur.
Workaround(s)	<p>For the revisions affected, the error rate will be lower than 1 error in $10^{14.5}$ ADC conversions for both 12-bit mode and 16-bit mode when all of the following configurations are used:</p> <ul style="list-style-type: none"> • The S+H duration is at least 320 ns • ADCCLK is 40 MHz or less • ADCCLK prescale is a whole number: /1.0, /2.0, /3.0, /4.0, /5.0, /6.0, /7.0, or /8.0 • The value of 0x7000 is written to memory locations 0x0000 743F, 0x0000 74BF, 0x0000 753F, and 0x0000 75BF (writing this value is only valid when the ADCCLK prescale is a whole number).

Advisory	ADC: ADC PPB Event Trigger (ADCxEVT) to ePWM Digital Compare Submodule
Revision(s) Affected	0, A, B
Details	The ADCxEVT trigger to the ePWM digital compare submodule may not be detected by the ePWM.
Workaround(s)	The ADCxEVT can generate an ADCx_EVT interrupt to the PIE. The ISR can be used to perform the desired task in software.

Advisory	ADC: 12-Bit Switch Resistance
Revision(s) Affected	0, A, B
Details	The ADC input model should be used to select the sample-and-hold (S+H) duration for each ADC input. For the revisions affected, the 12-bit input model under-estimates the value of the sampling switch resistance (R_{on}). A R_{on} value of 2 k Ω should be used to select the S+H duration for these revisions.
Workaround(s)	For the revisions affected, the S+H duration should be chosen to account for the additional switch resistance.

Advisory	ADC: 12-Bit Input Capacitance When Switching Channel Groups
Revision(s) Affected	0, A, B
Details	The ADC input model should be used to select the sample-and-hold (S+H) duration for each ADC input. For the revisions affected, if the currently converting channel is an even-numbered channel and the previously converted channel was an odd-numbered channel (or vice versa), then the 12-bit input model will not accurately predict ADC input performance. Under these conditions, an additional capacitance should be added to the model. This capacitance has a value of 11.5 pF and should be placed between the S+H switch and R_{on} as shown in Figure 3 .




Figure 3. Single-Ended Input Model

Workaround(s)	For the revisions affected, when subsequent conversions switch between channel groups, the S+H duration should be chosen to account for the additional capacitance.
----------------------	---

Advisory	ADC: Functionality of V_{REFLO} Pins
Revision(s) Affected	0, A
Details	<p>The V_{REFLO} pins on Revision 0 and Revision A silicon are not connected. V_{REFLO} functionality for all ADCs is provided by an internal connection to V_{SSA} on these revisions. This may result in increased ADC noise and increased ADC-to-ADC crosstalk.</p> <p>It is recommended that all V_{REFLO} pins be connected to either V_{SSA} or to 0-V low reference voltage for these device revisions. This will allow printed circuit boards to be compatible with future devices.</p>
Workaround(s)	None
Advisory	ADC: Sensitivity to ESD Events
Revision(s) Affected	0, A
Details	<p>These TMX revisions have shown sensitivity to ESD damage when safe handling procedures are not strictly followed. Specifically, the ADC performance can be degraded after an ESD event.</p>
Workaround(s)	<p>TI always recommends best practice ESD safe device handling. For these TMX revisions, extra care should be taken to ensure proper ESD handling procedures are followed (that is, use ESD mats, wrist-straps, ionizers, and so forth). If ADC performance becomes degraded, replace the device.</p>
Advisory	ADC: ADC Input Multiplexer Connection at Beginning of Acquisition Window
Revision(s) Affected	0, A
Details	<p>The input of the ADC may experience a brief connection to either V_{SSA} or another input channel at the beginning of the sample-and-hold phase of the conversion. The conditions where this occurs are summarized below:</p> <ul style="list-style-type: none"> • If the previously converted channel is the same as the currently converting channel, then no additional connection occurs. • If the previously converted channel and the currently converting channel are both odd-numbered channels or both even-numbered channels (for example, A6 and A14), then the two channels will be briefly connected. • If the previously converted channel and the currently converting channel are not both odd-numbered channels or not both even-numbered channels (for example, A6 and A15), then the currently converting channel will be briefly connected to V_{SSA}. <p>In the worst case, the connection resistance could be as low as 30 Ω and the duration of the connection could be as long as 5 ns.</p>
Workaround(s)	<p>This typically will not present a significant issue for low-impedance signal sources (for example, an op-amp). For high-impedance sources, it may be necessary to increase the duration of the acquisition window beyond what would be suggested by the characteristics of the ADC input model.</p>

Advisory **ADC: ADC Sparkle Codes**

Revision(s) Affected 0, A

Details The ADC may give conversion results with large random errors (sparkle codes). When present, this is typically observed as a large jump in the conversion result for a single code while sampling a continuously varying waveform.

Workaround(s) Bad codes can be reduced by writing the value 0x7000 to memory locations 0x0000 743F, 0x0000 74BF, 0x0000 753F, and 0x0000 75BF.

This workaround is valid only on the revisions affected.

Advisory **ADC: ADC Linearity Performance**

Revision(s) Affected 0

Details INL/DNL performance does not meet data sheet specifications. For 16-bit mode, typical performance is: INL = ± 12 LSBs, DNL = [+1.5, -1] LSBs. Missing codes are present every 512 codes, in sets of up to 16 missing codes in a row. For 12-bit mode, typical performance is: INL = ± 4 LSB, DNL = [+1, -1] LSBs. Missing codes are present every 128 codes, in sets of up to 4 missing codes in a row.

Workaround(s) None

Advisory	<i>\overline{XRS} may Toggle During Power Up</i>
Revision(s) Affected	0, A, B
Details	During device power up, the \overline{XRS} pin may toggle high prematurely. After the V_{DDIO} and V_{DD} supplies reach the recommended operation conditions, the \overline{XRS} pin behavior will be per the pin description. This is only an issue with the external state of the \overline{XRS} pin. Internally, the device will be held in reset by the POR logic until the supplies are within an acceptable range and \overline{XRS} is high.
Workaround(s)	Disregard \overline{XRS} activity on the board prior to supplies reaching recommended operating conditions.
Advisory	<i>USB: USB DMA Event Triggers are not Supported</i>
Revision(s) Affected	0, A, B, C
Details	The USB module generates inadvertent extra DMA requests, causing the FIFO to overflow (on IN endpoints) or underflow (on OUT endpoints). This causes invalid IN DATA packets (larger than the maximum packet size) and duplicate receive data.
Workaround(s)	None
Advisory	<i>VREG: VREG Will be Enabled During Power Up Irrespective of VREGENZ</i>
Revision(s) Affected	0, A, B
Details	During power up of the 3.3-V V_{DDIO} , the internal Voltage Regulator (VREG) will be active until the 1.2-V V_{DD} supply reaches approximately 0.7 V. After this time, the VREGENZ pin tied to V_{DDIO} will disable the internal VREG. This will not impact device operation.
Workaround(s)	None

Advisory	<i>Flash: A Single-Bit ECC Error May Cause Endless Calls to Single-Bit-Error ISR</i>
Revision(s) Affected	0, A, B, C
Details	<p>When a single-bit ECC error is detected, the CPU executes the single-bit-error interrupt service routine (ISR). When the ISR returns, the same instruction that caused the first error is fetched again. If the ECC error threshold (ERR_THRESHOLD.THRESHOLD) is 0, then the same error is detected and another ISR is executed. This continues in an endless loop. This sequence of events only occurs if the error is caused by a program fetch operation, not a data read.</p>
Workaround(s)	Set the error threshold bit-field (ERR_THRESHOLD.THRESHOLD) to a value greater than or equal to 1. Note that the default value of the threshold bit-field is 0.
Advisory	<i>Flash: Minimum Programming Word Size</i>
Revision(s) Affected	0, A, B, C
Details	<p>The Main Array flash programming must be aligned to 64-bit address boundaries and each 64-bit word may only be programmed once per write/erase cycle.</p> <p>Applications using Fapi_issueProgrammingCommand() in Fapi_AutoEccGeneration or Fapi_DataAndEcc modes are implicitly performing 64-bit programming since ECC is programmed for each 64 bits. Applications using Fapi_DataOnly mode with fewer than 64 bits may be impacted by this advisory.</p> <p>The DCSM OTP programming must be aligned to 128-bit address boundaries and each 128-bit word may only be programmed once. The exceptions are:</p> <ol style="list-style-type: none"> 1. The DCSM Zx-LINKPOINTER1 and Zx-LINKPOINTER2 values in the DCSM OTP should be programmed together, and may be programmed 1 bit at a time as required by the DCSM operation. 2. The DCSM Zx-LINKPOINTER3 values in the DCSM OTP may be programmed 1 bit at a time on a 64-bit boundary to separate it from Zx-PSWDLOCK, which must only be programmed once.
Workaround(s)	All applications should follow the restrictions outlined in this advisory. Contact TI for devices already in production which violate this advisory.

Advisory	<i>Flash: Reset of CPU2 While it has Pump Ownership Can Cause Erroneous Flash Reads From CPU1</i>
Revision(s) Affected	0, A
Details	<p>If the CPU2 Subsystem is reset while it owns the flash pump semaphore, then the flash pump itself will also reset. Since the flash pump is also used by the CPU1 Subsystem, any instruction fetch or data read from flash by CPU1 will return invalid data. This will result in a hard fault, incorrect program execution, or an unspecified error in the application.</p> <p>This erratum does not apply if the CPU2 Subsystem never writes to the PUMPREQUEST register to take ownership of the flash pump semaphore.</p>
Workaround(s)	<p>CPU1 must not access flash while CPU2 holds the flash pump semaphore ownership. The following steps describe how this can be achieved:</p> <ol style="list-style-type: none"> 1. At application start-up, CPU2 reads the PUMPREQUEST semaphore register. If it is the owner, CPU2 relinquishes the flash pump semaphore. 2. When CPU2 wants to own the flash pump semaphore, it must notify CPU1 and wait for an acknowledgement. 3. The CPU1 application branches to RAM and notifies CPU2 that it has done so. Any data being accessed by CPU1 must also reside in RAM at this time. 4. CPU2 takes ownership of the semaphore. 5. CPU1 will refrain from accessing the flash until CPU2 releases ownership of the flash pump semaphore.

Advisory	<i>ePIE: Spurious VCU Interrupt (ePIE 12.6) Can Occur When First Enabled</i>
Revision(s) Affected	0, A, B
Details	<p>The VCU-II can power up in a state which incorrectly sets the VCU VSTATUS[DIVE] error bit and, subsequently PIEIFR12[INTx6], when the CPU is released from reset. When the VCU interrupt enable PIEIER12[INTx6] is enabled for the first time by the application, a spurious interrupt can occur due to the erroneous pending interrupt.</p>
Workaround(s)	<p>Before enabling VCU interrupt 12.6, execute the following instructions to avoid the spurious interrupt.</p> <pre>// Clear VCU divide by zero status asm(" VCLR DIVE"); // Clear PIE interrupt for VCU PieCtrlRegs.PIEIFR12.bit.INTx6 = 0;</pre> <p>Beginning with revision C silicon, the Boot ROM will perform the above workaround before branching to the application.</p>

Advisory	<i>eQEP: Position Counter Incorrectly Reset on Direction Change During Index</i>
Revision(s) Affected	0, A, B, C
Details	<p>While using the PCRM = 0 configuration, if the direction change occurs when the index input is active, the position counter (QPOSCNT) could be reset erroneously, resulting in an unexpected change in the counter value. This could result in a change of up to ± 4 counts from the expected value of the position counter and lead to unexpected subsequent setting of the error flags.</p> <p>While using the PCRM = 0 configuration [that is, Position Counter Reset on Index Event (QEPCNTL[PCRM] = 00)], if the index event occurs during the forward movement, then the position counter is reset to 0 on the next eQEP clock. If the index event occurs during the reverse movement, then the position counter is reset to the value in the QPOS MAX register on the next eQEP clock. The eQEP peripheral records the occurrence of the first index marker (QEPSTS[FIMF]) and direction on the first index event marker (QEPSTS[FIDF]) in QEPSTS registers. It also remembers the quadrature edge on the first index marker so that same relative quadrature transition is used for index event reset operation.</p> <p>If the direction change occurs while the index pulse is active, the module would still continue to look for the relative quadrature transition for performing the position counter reset. This results in an unexpected change in the position counter value.</p> <p>The next index event without a simultaneous direction change will reset the counter properly and work as expected.</p>
Workaround(s)	<p>Do not use the PCRM = 0 configuration if the direction change could occur while the index is active and the resultant change of the position counter value could affect the application.</p> <p>Other options for performing position counter reset, if appropriate for the application [such as Index Event Initialization (IEI)], do not have this issue.</p>
Advisory	<i>eQEP: eQEP Inputs in GPIO Asynchronous Mode</i>
Revision(s) Affected	0, A, B, C
Details	<p>If any of the eQEP input pins are configured for GPIO asynchronous input mode via the GPxQSELn registers, the eQEP module may not operate properly because the eQEP peripheral assumes the presence of external synchronization to SYSCLKOUT on inputs to the module. For example, QPOSCNT may not reset or latch properly, and pulses on the input pins may be missed.</p> <p>For proper operation of the eQEP module, input GPIO pins should be configured via the GPxQSELn registers for synchronous input mode (with or without qualification), which is the default state of the GPxQSEL registers at reset. All existing eQEP peripheral examples supplied by TI also configure the GPIO inputs for synchronous input mode.</p> <p>The asynchronous mode should not be used for eQEP module input pins.</p>
Workaround(s)	Configure GPIO inputs configured as eQEP pins for non-asynchronous mode (any GPxQSELn register option except "11b = Asynchronous").

Advisory	<i>PLL: May Not Lock on the First Lock Attempt</i>
Revision(s) Affected	0, A, B, C
Details	<p>The PLL may not start properly at device power up or wake up from Hibernate. The PLLSTS[LOCKS] bit is set, but the PLL does not produce a clock.</p> <p>Once the PLL has properly started, the PLL can be disabled and reenabled with no issues and will stay locked. However, the PLL lock problem could reoccur on a subsequent power-up or Hibernate cycle.</p> <p>If the SYSPLL has not properly started and is selected as the CPU clock source, the CPU will stop executing instructions. The occurrence rate of this transient issue is low and after an initial occurrence, this issue may not be subsequently observed in the system again. Implementation of the workaround reduces the rate of occurrence.</p> <p>This advisory applies to both PLLs, with a different workaround for each.</p>
Workaround(s)	<p><i>SYSPLL Workaround:</i></p> <p>Repeated lock attempts will reduce the likelihood of seeing the condition on the final attempt. TI recommends a minimum of five lock sequences in succession when the PLL is configured the first time after a power up. A lock sequence means disabling the PLL, starting the PLL locking, and waiting for the LOCKS bit to set. After the final sequence, the clock source is switched to use the PLL output as normal.</p> <p>The Watchdog timer can be used to detect that the condition has occurred because it is not clocked by the PLL output. The Watchdog should be enabled before selecting the PLL as the clock source and configured to reset the device. If the PLL is not producing a clock, the Watchdog will reset the device and the user initialization software will therefore repeat the PLL initialization.</p> <p>Many applications do not have a different initialization sequence for a Watchdog-initiated reset; for these applications, no further action is required. For applications that do use a different device initialization sequence when a Watchdog reset is detected, a flag can be used to identify the Watchdog reset as a PLL cause. The SYSDBGCTL[BIT_0] bit (which is bit 0 at 0x0005D12C) can be set active during the PLL lock sequence and used to distinguish a Watchdog PLL retry attempt versus a different Watchdog reset source.</p> <p>The SYSPLLSTS[SLIPS] should also be checked immediately after setting the PLL as the SYSCLK source with SYSPLLCTL1[PLLCLKEN]. If SLIPS indicates a PLL slip, then the PLL should be disabled and locked again until there are no slips detected.</p> <p>See the C2000Ware InitSysPll() function for an example implementation of this workaround, as well as the DriverLib function SysCtl_setClock().</p> <p>The workaround can also be applied at the System level by a supervisor resetting the device if it is not responding.</p>

AUXPLL Workaround:

CPU Timer 2 can be used to detect that the AUXPLL is active before it is used as a clock source for USB. If the AUXPLL is not active, repeat the lock attempt until successful.

The AUXPLLSTS[SLIPS] should also be checked immediately after setting the PLL as the AUXPLLCLK source with AUXPLLCTL1[PLLCLKEN]. If SLIPS indicates a PLL slip, then the PLL should be disabled and locked again until there are no slips detected.

See the C2000Ware InitAuxPll() function for an example implementation of this workaround, as well as the DriverLib function SysCtl_setAuxClock().

NOTE: The USB Boot Mode does not implement the previous workarounds. Applications using USB Boot will need to implement any retry attempts at the system level.

Advisory	<i>SDFM: Data Filter Output Does Not Saturate at Maximum Value With Sinc3 and OSR = 256</i>
Revision(s) Affected	0, A, B, C
Details	If the differential input of the Sigma-Delta Filter Module (SDFM) is greater than or equal to +FSR (full-scale differential voltage input range), then the output of the SDFM clips with a stream of ones. When this stream of ones is fed to a data filter that is configured as a sinc3 filter with an OSR = 256, the output of the filter does not saturate at the maximum value (16777215 in 32-bit mode or 32767 in 16-bit mode); but, instead roll over to the minimum value (–16777216 in 32-bit mode or –32768 in 16-bit mode).
Workaround(s)	Maintain the differential input of the SDFM in the specified linear input range as specified in the modulator data sheet.
Advisory	<i>SDFM: Spurious Data Acknowledge Event When Data Filter is Configured and Enabled for the First Time</i>
Revision(s) Affected	0, A, B, C
Details	When the SDFM data filter is configured and enabled for the first time, it is possible to get one spurious data acknowledge event (AFx) before the data filter settles to give correct digital data. Subsequent data acknowledge events (AFx)/DMA events occur correctly as per data filter configuration.
Workaround(s)	Do the following: <ol style="list-style-type: none"> 1. Configure and enable the SDFM data filter. 2. Delay for at least latency of data filter + 5 SD-Cx clock cycles. 3. Enable SDFM data acknowledge interrupts/DMA events.
Advisory	<i>SDFM: Spurious Data Acknowledge Event When Data Filter is Synchronized Using PWM FILRES Signal</i>
Revision(s) Affected	0, A, B, C
Details	When the SDFM data filters are synchronized using the PWM FILRES signal, it is possible to get a spurious data acknowledge event (AFx) before the data filter settles to give correct digital data. Subsequent data acknowledge events (AFx) occur correctly as per data filter configuration before the next PWM FILRES signal.
Workaround(s)	Do the following: <ol style="list-style-type: none"> 1. Choose any PWMx to work in the same time base as the PWM that generates the FILRES pulse. 2. PWMx should also interrupt the CPU/CLA at least 1.2 µs after the PWM FILRES pulse gets applied in order to clear the SDIFLG register that may be set because of the spurious data acknowledge event. 3. SDFM_CPUISR or SDFM_CLATask: <ol style="list-style-type: none"> i. Collect the required number of samples, N, after the FILRES pulse. ii. If the number of samples is less than or equal to N, clear the SDIFLG register; otherwise, do not clear the SDIFLG register to prevent further SDFM interrupts.

Advisory	<i>SDFM: Comparator Filter Module may Generate Spurious Over-Value and Under-Value Conditions</i>
Revision(s) Affected	0, A, B, C
Details	When interrupts are enabled in the SDFM comparator module, it may trigger spurious over-value (SDIFLG.IEHx, x = 1 to 4) or under-value (SDIFLG.IELx, x = 1 to 4) conditions. These are depicted as IELx and IEHx interrupt outputs in the “Block Diagram of One Filter Module” figure in the TMS320F2837xD Dual-Core Delfino Microcontrollers Technical Reference Manual .
Workaround(s)	<p>For silicon revisions 0 and A – Disable SDFM comparator interrupt sources to avoid spurious events.</p> <p>For future silicon revisions – These erroneous interrupts can be eliminated by implementing the following workaround:</p> <ul style="list-style-type: none"> • Comparator OSR (COSR) value should be greater than or equal to 5. • After changing COSR, wait for at least latency of comparator filter and 5 SD-Cx cycles before enabling comparator interrupts SDCPARMx.IEH and SDCPARMx.IEL.
Advisory	<i>SDFM: Dynamically Changing Threshold Settings (LLT, HLT), Filter Type, or COSR Settings Will Trigger Spurious Comparator Events</i>
Revision(s) Affected	0, A, B, C
Details	When SDFM comparator settings—such as filter type, lower/upper threshold, or COSR settings—are changed while low-level/high-level events are enabled, a spurious comparator lower threshold (or) higher threshold event will be triggered.
Workaround(s)	<p>When comparator settings need to be changed dynamically, follow the procedure below:</p> <ol style="list-style-type: none"> 1. Disable the SDFM comparator interrupts. 2. Change comparator settings such as lower/upper threshold, filter type, or COSR. 3. Comparator OSR (COSR) value should be greater than or equal to 5. 4. Delay for at least a latency of comparator filter + 5 SD-Cx clock cycles. 5. Enable the SDFM comparator interrupts.
Advisory	<i>SDFM: Dynamically Changing Data Filter Settings (Such as Filter Type or DOSR) Will Trigger Spurious Data Acknowledge Events</i>
Revision(s) Affected	0, A, B, C
Details	When SDFM data filter settings—such as filter type or DOSR settings—are changed while the data filter and its data acknowledge events are enabled, spurious data acknowledge events will be triggered.
Workaround(s)	<p>When data filter settings need to be changed dynamically, follow the procedure below:</p> <ol style="list-style-type: none"> 1. Disable the SDFM data filter. 2. Change data filter settings such as filter type or DOSR. 3. Delay for at least a latency of data filter + 5 SD-Cx clock cycles. 4. Enable the SDFM data filter.

Advisory

FPU: FPU-to-CPU Register Move Operation Preceded by Any FPU 2p Operation

Revision(s) Affected

0, A, B, C

Details

This advisory applies when a multi-cycle (2p) FPU instruction is followed by a FPU-to-CPU register transfer. If the FPU-to-CPU read instruction source register is the same as the 2p instruction destination, then the read may be of the value of the FPU register before the 2p instruction completes. This occurs because the 2p instructions rely on data-forwarding of the result during the E3 phase of the pipeline. If a pipeline stall happens to occur in the E3 phase, the result does not get forwarded in time for the read instruction.

The 2p instructions impacted by this advisory are MPYF32, ADDF32, SUBF32, and MACF32. The destination of the FPU register read must be a CPU register (ACC, P, T, XAR0...XAR7). This advisory does not apply if the register read is a FPU-to-FPU register transfer.

In the example below, the 2p instruction, MPYF32, uses R6H as its destination. The FPU register read, MOV32, uses the same register, R6H, as its source, and a CPU register as the destination. If a stall occurs in the E3 pipeline phase, then MOV32 will read the value of R6H before the MPYF32 instruction completes.

Example of Problem:

```
MPYF32 R6H, R5H, R0H ; 2p FPU instruction that writes to R6H
|| MOV32 *XAR7++, R4H
F32TOUI16R R3H, R4H ; delay slot
ADDF32 R2H, R2H, R0H
|| MOV32 *--SP, R2H ; alignment cycle
MOV32 @XAR3, R6H ; FPU register read of R6H
```

Figure 4 shows the pipeline diagram of the issue when there are no stalls in the pipeline.

	Instruction	F1	F2	D1	D2	R1	R2	E	W		Comments
		FPU pipeline-->				R1	R2	E1	E2	E3	
I1	MPYF32 R6H, R5H, R0H MOV32 *XAR7++, R4H	I1									
I2	F32TOUI16R R3H, R4H	I2	I1								
I3	ADDF32 R3H, R2H, R0H MOV32 *--SP, R2H	I3	I2	I1							
I4	MOV32 @XAR3, R6H	I4	I3	I2	I1						
			I4	I3	I2	I1					
				I4	I3	I2	I1				
					I4	I3	I2	I1			
						I4	I3	I2	I1		
							I4	I3	I2	I1	I4 samples the result as it enters the R2 phase. The product R6H=R5H*R0H (I1) finishes computing in the E3 phase, but is forwarded as an operand to I4. This makes I4 appear to be a 2p instruction, but I4 actually takes 3p cycles to compute.
								I4	I3	I2	
									I4	I3	

Figure 4. Pipeline Diagram of the Issue When There are no Stalls in the Pipeline

Figure 5 shows the pipeline diagram of the issue if there is a stall in the E3 slot of the instruction I1.

	Instruction	F1	F2	D1	D2	R1	R2	E	W		Comments
		FPU pipeline-->				R1	R2	E1	E2	E3	
I1	MPYF32 R6H, R5H, R0H MOV32 *XAR7++, R4H	I1									
I2	F32TOUI16R R3H, R4H	I2	I1								
I3	ADDF32 R3H, R2H, R0H MOV32 *--SP, R2H	I3	I2	I1							
I4	MOV32 @XAR3, R6H	I4	I3	I2	I1						
			I4	I3	I2	I1					
				I4	I3	I2	I1				
					I4	I3	I2	I1			
						I4	I3	I2	I1		
							I4	I3	I2	I1 (STALL)	I4 samples the result as it enters the R2 phase, but I1 is stalled in E3 and is unable to forward the product of R5H*R0H to I4 (R6H does not have the product yet due to a design bug). So, I4 reads the old value of R6H.
							I4	I3	I2	I1	There is no change in the pipeline as it was stalled in the previous cycle. I4 had already sampled the old value of R6H in the previous cycle.
								I4	I3	I2	Stall over

Figure 5. Pipeline Diagram of the Issue if There is a Stall in the E3 Slot of the Instruction I1

Workaround(s)

Treat MPYF32, ADDF32, SUBF32, and MACF32 in this scenario as 3p-cycle instructions. Three NOPs or non-conflicting instructions must be placed in the delay slot of the instruction.

The C28x Code Generation Tools v.6.2.0 and later will both generate the correct instruction sequence and detect the error in assembly code. In previous versions, v6.0.5 (for the 6.0.x branch) and v.6.1.2 (for the 6.1.x branch), the compiler will generate the correct instruction sequence but the assembler will not detect the error in assembly code.

Example of Workaround:

```

MPYF32 R6H, R5H, R0H
| | MOV32 *XAR7++, R4H      ; 3p FPU instruction that writes to R6H
  F32TOUI16R R3H, R4H      ; delay slot
  ADDF32 R2H, R2H, R0H
| | MOV32 *--SP, R2H        ; delay slot
  NOP                      ; alignment cycle
  MOV32 @XAR3, R6H         ; FPU register read of R6H

```

Figure 6 shows the pipeline diagram with the workaround in place.

	Instruction	F1	F2	D1	D2	R1	R2	E	W		Comments
		FPU pipeline-->				R1	R2	E1	E2	E3	
I1	MPYF32 R6H, R5H, R0H MOV32 *XAR7++, R4H	I1									
I2	F32TOUI16R R3H, R4H	I2	I1								
I3	ADDF32 R3H, R2H, R0H MOV32 *--SP, R2H	I3	I2	I1							
I4	NOP	I4	I3	I2	I1						
I5	MOV32 @XAR3, R6H	I5	I4	I3	I2	I1					
			I5	I4	I3	I2	I1				
				I5	I4	I3	I2	I1			
					I5	I4	I3	I2	I1		
						I5	I4	I3	I2	I1 (STALL)	Due to one extra NOP, I5 does not reach R2 when I1 enters E3; thus, forwarding is not needed.
						I5	I4	I3	I2	I1	There is no change due to the stall in the previous cycle.
							I5	I4	I3	I2	I1 moves out of E3 and I5 moves to R2. R6H has the result of R5H*R0H and is read by I5. There is no need to forward the result in this case.
								I5	I4	I3	

Figure 6. Pipeline Diagram With Workaround in Place

Advisory	<i>FPU: LUF, LVF Flags are Invalid for the EINVF32 and EISQRTF32 Instructions</i>				
Revision(s) Affected	0, A, B, C				
Details	<p>This advisory applies to the EINVF32 and EISQRTF32 instructions. The expected results for these instructions are correct; however, the underflow (LUF) and overflow (LVF) flags are not. These flags are invalid and should not be used.</p> <p>The LUF and LVF flags are not accessible using C code, so the overall impact of this advisory is expected to be small. If the user chooses to use these flags (for example, when coding a time-critical algorithm) in assembly as part of a mixed C/ASM project, the user will need to disable interrupts around the assembly code using the flags, and also preserve the flags through any use of EINVF32 or EISQRTF32 instructions.</p>				
Workaround(s)	<p>There is no workaround for using these flags in C code, and they should be considered invalid for the reasons presented under NOTES ON COMPILER AND TOOLS USAGE.</p> <p>The workaround shown here provides a way to preserve the LVF, LUF flags across the use of EISQRTF32 and EINVF32 in assembly-only code.</p> <p>Do not rely on the LUF and LVF flags to catch underflow/overflow conditions resulting from the EINVF32 and EISQRTF32 instructions. Instead, check the operands for the following conditions (in code) before using each instruction:</p> <table> <tr> <td>EINVF32</td><td>Divide by 0</td></tr> <tr> <td>EISQRTF32</td><td>Divide by 0, Divide by a negative input</td></tr> </table> <p>Disregard the contents of the LUF and LVF flags by saving the flags to the stack before calling the instruction, and subsequently restoring the values of the flags once the instruction completes.</p> <pre> MOV32 *SP++,STF ; Save off current status flags EISQRTF32/EINVF32 ; Execute operation NOP ; Wait for operations to complete MOV32 STF, *--SP ; Restore previous status flags </pre> <p>If the PIE interrupts are tied to the LUF and LVF flags, disable the interrupts (at the PIE) before using either the EINVF32 or EISQRTF32 instruction. Check to see if the LUF and LVF flags are set; if they are, a variable can be set to indicate that a false LUF/LVF condition is detected. Clear the flags in the STF (FPU status flag) before re-enabling the interrupts.</p> <p>Once the interrupts are reenabled at the PIE, the interrupt may occur (if the LUF/LVF interrupt lines were asserted by either of the two instructions) and execution branches to the Interrupt Service Routine (ISR). Check the flag to determine if a false condition has occurred; if it has, disregard the interrupt.</p> <p>Do not clear the PIE IFR bits (that latch the LUF and LVF flags) directly because an interrupt event on the same PIE group (PIE group 12) may inadvertently be missed.</p>	EINVF32	Divide by 0	EISQRTF32	Divide by 0, Divide by a negative input
EINVF32	Divide by 0				
EISQRTF32	Divide by 0, Divide by a negative input				

Here is an example:

```
__flag_LVFLUF_set    .usect ".ebss",2,1,1
...
MOV32    *SP++,STF                ; Save off current status flags
; Load the PieCtrlRegs page to the DP
MOVW     DP, #_PieCtrlRegs.PIEIER12.all
; Zero out PIEIER12.7/8, i.e. disable LUF/LVF interrupts
AND      @_PieCtrlRegs.PIEIER12.all, #0xFF3F
EISQRTF32/EINVF32                ; Execute operation
MOVL     XAR3, #__flag_LVFLUF_set ; Wait for operation to complete
MOV32    *+XAR3[0], STF            ; save STF to __flag_LVFLUF_set
AND      *+XAR3[0], #0x3          ; mask everything but LUF/LVF
; Clear Latched overflow, underflow flag
SETFLG   LUF=0, LVF=0
; Re-enable PIEIER12.7/8, i.e. re-enable the LUF/LVF interrupts
OR        @_PieCtrlRegs.PIEIER12.all, #0x00C0
MOV32    STF,*--SP                ; Restore previous status flags
```

In the ISR,

```
__interrupt void fpu32_luf_lvf_isr (void)
{
    // Check the flag for whether the LUF, LVF flags set by
    // either EISQRTF32 or EINVF32
    if((__flag_LVFLUF_set & 0x3U) != 0U)
    {
        //Reset flag
        __flag_LVFLUF_set = 0U;
        // Do Nothing
    }
    else
    {
        //If __flag_LVFLUF_set was not set then this interrupt
        // is the legitimate result of an overflow/underflow
        // from an FPU operation (not EISQRTF32/EINVF32)
        ...
        // Handle Overflow/Underflow condition
        ...
        ...
        ...
    }
    // Ack the interrupt and exit
}
```

NOTES: NOTES ON COMPILER AND TOOLS USAGE

The compiler does not use LVF/LUF as condition codes for conditional instructions and neither does the Run Time Support (RTS) Library test LVF/LUF in any way.

The compiler may generate code that modifies LVF/LUF, meaning the value of the STF register (that contain these flags) is undefined at function boundaries. Thus, although the sqrt routine in the library may cause LVF/LUF to be set, there is no assurance in the CGT that the user can read these bits after sqrt returns.

Although the compiler does provide the `__eisqrtf` and `__einvf32` intrinsics, it does not provide an intrinsic to read the LVF/LUF bits or the STF register. Thus, the user has no way to access these bits from C code.

The use of inline assembly code to read the STF register is unreliable and is discouraged. The workaround presented in the Workaround(s) section is applicable to assembly code that uses the EISQRTF32 and EINVF32 instructions and does not call any compiler-generated code. For C code, the user must consider these flags to be unreliable, and therefore, neither poll these flags in code nor trigger interrupts off of them.

Advisory
Memory: Prefetching Beyond Valid Memory
Revision(s) Affected

0, A, B, C

Details

The C28x CPU prefetches instructions beyond those currently active in its pipeline. If the prefetch occurs past the end of valid memory, then the CPU may receive an invalid opcode.

Workaround

The prefetch queue is 8 x16 words in depth. Therefore, code should not come within 8 words of the end of valid memory. Prefetching across the boundary between two valid memory blocks is all right.

Example 1: M1 ends at address 0x7FF and is not followed by another memory block. Code in M1 should be stored no farther than address 0x7F7. Addresses 0x7F8-0x7FF should not be used for code.

Example 2: M0 ends at address 0x3FF and valid memory (M1) follows it. Code in M0 can be stored up to and including address 0x3FF. Code can also cross into M1 up to and including address 0x7F7.

Table 5. Memories Impacted by Advisory

MEMORY TYPE	ADDRESSES IMPACTED	F28378D F28377D F28375D	F28376D F28374D
M1	0x0000 07F8–0x0000 07FF	Yes	Yes
GS11	0x0001 7FF8–0x0001 7FFF	No	Yes
GS15	0x0001 BFF8–0x0001 BFFF	Yes	N/A
Flash	0x000B FFF8–0x000B FFFF	Yes	N/A

Advisory	Low-Power Modes: Power Down Flash or Maintain Minimum Device Activity
Revision(s) Affected	0, A, B, C
Details	The device has an intentional current path from V_{DD3VFL} (flash supply) to V_{DD} . Since the HALT, STANDBY, or IDLE modes can have low current demand on V_{DD} , this V_{DD3VFL} current can cause V_{DD} to rise above the recommended operating voltage.
Workaround(s)	Workaround 1: Power down the flash before entering HALT, STANDBY, or IDLE. This will disable the internal current path. This workaround must be executed from RAM.

```
// CPU-1
EALLOW;
// seize the pump semaphore
while (IpcRegs.PUMPREQUEST.bit.SEM != 0x2)
{
    IpcRegs.PUMPREQUEST.all = IPC_PUMP_KEY | 0x2;
}
Flash0CtrlRegs.FBFALLBACK.bit.BNKPWR0 = 0;
asm(" RPT #8 || NOP");
// power down pump
Flash0CtrlRegs.FPAC1.bit.PMPPWR = 0;
asm(" RPT #8 || NOP");
// release pump semaphore
IpcRegs.PUMPREQUEST.all = IPC_PUMP_KEY | 0x0;
EDIS;
// enter low power mode
asm(" IDLE");

// CPU-2
EALLOW;
// seize the pump semaphore
while (IpcRegs.PUMPREQUEST.bit.SEM != 0x1)
{
    IpcRegs.PUMPREQUEST.all = IPC_PUMP_KEY | 0x1;
}

Flash0CtrlRegs.FBFALLBACK.bit.BNKPWR0 = 0;
asm(" RPT #8 || NOP");
// power down pump
Flash0CtrlRegs.FPAC1.bit.PMPPWR = 0;
asm(" RPT #8 || NOP");
// release pump semaphore
IpcRegs.PUMPREQUEST.all = IPC_PUMP_KEY | 0x0;
EDIS;
// enter low power mode
asm(" IDLE");
```

Workaround 2: Keep SYSCLK at a minimum of 100 MHz during STANDBY or IDLE. This activity will be sufficient to consume the internal current.

Advisory	<i>CMPSS: COMPxLATCH May Not Clear Properly Under Certain Conditions</i>
Revision(s) Affected	0, A, B, C
Details	<p>The CMPSS latched path is designed to retain a tripped state within a local latch (COMPxLATCH) until it is cleared by software (via COMPSTSCLR) or by PWMSYNC.</p> <p>COMPxLATCH is set indirectly by the comparator output after the signal has been digitized and qualified by the Digital Filter. The maximum latency expected for the comparator output to reach COMPxLATCH may be expressed in CMPSS module clock cycles as:</p> $\text{LATENCY} = 1 + (1 \times \text{FILTER_PRESCALE}) + (\text{FILTER_THRESH} \times \text{FILTER_PRESCALE})$ <p>When COMPxLATCH is cleared by software or by PWMSYNC, the latch itself is cleared as desired, but the data path prior to COMPxLATCH may not reflect the comparator output value for an additional LATENCY number of module clock cycles. If the Digital Filter output resolves to a logical 1 when COMPxLATCH is cleared, the latch will be set again on the following clock cycle.</p>
Workaround(s)	<p>Allow the Digital Filter output to resolve to logical 0 before clearing COMPxLATCH.</p> <p>If COMPxLATCH is cleared by software, the output state of the Digital Filter can be confirmed through the COMPSTS register prior to clearing the latch. For instances where a large LATENCY value produces intolerable delays, the filter FIFO may be flushed by reinitializing the Digital Filter (via CTRIPxFILCTL).</p> <p>If COMPxLATCH is cleared by PWMSYNC, the user application should be designed such that the comparator trip condition is cleared at least LATENCY cycles before PWMSYNC is generated.</p>
Advisory	<i>CMPSS: Ramp Generator May Not Start Under Certain Conditions</i>
Revision(s) Affected	0, A, B, C
Details	<p>The Ramp Generator is designed to produce a falling-ramp DAC reference that is synchronized with a PWMSYNC signal. Upon receiving a PWMSYNC signal, the Ramp Generator will start to decrement its DAC value. When COMPSTS[COMPSTS] is asserted by a trip event, the Ramp Generator will stop decrementing its DAC value.</p> <p>If COMPSTS[COMPSTS] is asserted simultaneously with a PWMSYNC signal, the desired behavior is for the PWMSYNC signal to take priority such that the Ramp Generator starts to decrement in the new EPWM cycle. Instead of the desired behavior, the COMPSTS[COMPSTS] trip condition will take priority over PWMSYNC such that the Ramp Generator stops decrementing for a full EPWM cycle until the next PWMSYNC signal is detected.</p>
Workaround(s)	Avoid COMPSTS[COMPSTS] trip conditions when PWMSYNC is generated. For example, peak current mode control applications can limit the PWM duty cycle to a maximum value that will avoid simultaneous COMPSTS[COMPSTS] and PWMSYNC assertions.
Advisory	<i>CMPSS: CMPIN4N, CMPIN4P, CMPIN5N, and CMPIN5P Not Available</i>
Revision(s) Affected	0, A
Details	The CMPIN4N, CMPIN4P, CMPIN5N, and CMPIN5P functions are not available on the silicon revisions affected.
Workaround(s)	None

Advisory	<i>Boot ROM: Device Will Hang During Boot if X1 Clock Source is not Present</i>
Revision(s) Affected	B
Details	The device boot code will attempt to configure the device using X1 as the clock source. When X1 is not present, the device boot will hang. This advisory applies to any system which is designed to use the INTOSC as the primary clock source with no clock on X1 during boot. This issue only affects some silicon revision B devices and it will be fixed in all future silicon revisions.
Workaround(s)	Apply external clock source to X1 on silicon revision B devices, even if using INTOSC as the application clock source.
Advisory	<i>HRPWM: HRCNFG Register Reads and Bit-Wise Writes</i>
Revision(s) Affected	0, A
Details	For even-numbered HRPWM modules (2, 4, 6, and 8), HRCNFG register reads return all 0s instead of the actual register contents. Full register writes to HRCNFG do work. For odd-numbered HRPWM modules (1, 3, 5, and 7), HRCNFG register reads work properly.
Workaround(s)	Do not perform bit-wise (read-modify-write) writes using the 'HRCNFG.bit' register structures on even-numbered HRPWM modules. This would result in the clearing of other bits in the HRCNFG register. Do not perform bit-wise writes to HRCNFG using the debugger window on even-numbered HRPWM modules. This would result in the clearing of other bits in the HRCNFG register. Do not read the even-numbered HRPWM module registers or use the contents in any software. Only modify the entire register with 'HRCNFG.all' when writing to the even-numbered HRPWM module registers.
Advisory	<i>SYSBIOS in ROM References Different Flash Sector (Changed From Sector A to Sector B)</i>
Revision(s) Affected	0, A
Details	This advisory applies only to applications using SYSBIOS components available in ROM. The Flash memory region referenced by the SYSBIOS in ROM has changed from Sector A to Sector B.
Workaround(s)	The linker command file should be changed as follows: <ul style="list-style-type: none"> On silicon revisions 0 and A, use Sector A: <ul style="list-style-type: none"> SYSBIOS_FLASH: origin = 0x080010, length = 0x0007BE On future silicon revisions, use Sector B: <ul style="list-style-type: none"> SYSBIOS_FLASH: origin = 0x082000, length = 0x000824

Advisory
McBSP: McBSP Transmit in SPI Slave Mode
Revision(s) Affected

0, A

Details

When using the McBSP peripheral in SPI Slave mode, the data transmitted to the Master (SOMI) is incorrect.

McBSP in SPI Slave mode receives data properly from the master.

Workaround(s)

Do not transmit data using SPI Slave mode of the McBSP.

Advisory
Crystal: Maximum Equivalent Series Resistance (ESR) Values are Reduced
Revision(s) Affected

0, A

Details

The maximum ESR values are reduced. For the revisions affected, the data in [Table 6](#) supersedes the data given in the "Crystal Equivalent Series Resistance (ESR) Requirements" table in the [TMS320F2837xD Dual-Core Delfino™ Microcontrollers Data Manual](#). The differences between the two tables are highlighted in [Table 6](#).

Table 6. Crystal Equivalent Series Resistance (ESR) Requirements⁽¹⁾

CRYSTAL FREQUENCY (MHz)	MAXIMUM ESR (Ω) (CL1/2 = 12 pF)	MAXIMUM ESR (Ω) (CL1/2 = 24 pF)
2	175	375
4	100	195
6	75	145
8	65	105
10	55	70
12	50	45
14	50	35
16	45	25
18	40	20
20	30	15

⁽¹⁾ Crystal shunt capacitance (C0) should be less than or equal to 7 pF.

Workaround(s)

None

Advisory	<i>GPIO: GPIO0–GPIO7, GPIO46, GPIO47 Shunt to V_{SS} Due to Fast Transients at High Temperature</i>
Revision(s) Affected	0, A
Details	<p>There is a potential temporary internal shunt to V_{SS} condition identified on pins GPIO0, GPIO1, GPIO2, GPIO3, GPIO4, GPIO5, GPIO6, GPIO7, GPIO46, and GPIO47. In this condition, an on-chip path to V_{SS} is turned on, which can bring down the logic level of these pins below V_{IL} and V_{OL}. The condition can occur when the pin is in input or output mode and with any of the alternate functions muxed on to this pin.</p> <p>The condition is more likely to occur at high temperatures and has not been observed below 85°C under normal operating use cases. The triggering event is dependent on board design and the speed of signals switching on these pins, with fast-switching transients more likely to induce the condition. The condition has only been observed when the signal at the device pin has a rise time or fall time faster than 2 ns (measured 10% to 90% of V_{DDIO}).</p> <p>The condition will resolve upon toggle of the IO at a lower temperature.</p>
Workaround(s)	<p>Try one of these two options:</p> <ul style="list-style-type: none"> • Option 1: Avoid the use of these pins in the revisions affected. • Option 2: This condition is not seen on all products. Many PCB designs have enough capacitance and slow enough edge rates that the condition does not occur. If the application can be tested and functions correctly with the temperature margin above the end-use temperature, then no action may be required. If the issue is seen or additional margin is desired, then the following can be applied. Place a capacitor of 56 pF or greater between each of these pins and ground, placed as closely as possible to the device. This will slow down the fast transient seen by the device and avoid triggering the condition. Larger capacitors will be more effective at filtering the transient but must be balanced against the PCB level timing requirements of these pins.

5 Documentation Support

For device-specific data sheets and related documentation, visit the TI web site at: <http://www.ti.com>.

For more information regarding the TMS320F2837xD Delfino devices, see the following documents:

- [TMS320F2837xD Dual-Core Delfino™ Microcontrollers Data Manual](#)
- [TMS320F2837xD Dual-Core Delfino Microcontrollers Technical Reference Manual](#)

Trademarks

Delfino, PowerPAD, TMS320, controlSUITE are trademarks of Texas Instruments.
All other trademarks are the property of their respective owners.

Revision History

Changes from July 25, 2017 to January 4, 2018 (from H Revision (July 2017) to I Revision)		Page
• Section 4.1 (Usage Notes): Added Caution While Using Nested Interrupts usage note.....	3	
• Section 4.2 (Known Design Exceptions to Functional Specifications): Updated Workaround(s) of Analog Trim of Some TMX Devices advisory.	7	
• Section 4.2 : Updated PLL: May Not Lock on the First Lock Attempt advisory.....	17	
• Section 4.2 : Added Low-Power Modes: Power Down Flash or Maintain Minimum Device Activity advisory.....	28	

IMPORTANT NOTICE FOR TI DESIGN INFORMATION AND RESOURCES

Texas Instruments Incorporated ("TI") technical, application or other design advice, services or information, including, but not limited to, reference designs and materials relating to evaluation modules, (collectively, "TI Resources") are intended to assist designers who are developing applications that incorporate TI products; by downloading, accessing or using any particular TI Resource in any way, you (individually or, if you are acting on behalf of a company, your company) agree to use it solely for this purpose and subject to the terms of this Notice.

TI's provision of TI Resources does not expand or otherwise alter TI's applicable published warranties or warranty disclaimers for TI products, and no additional obligations or liabilities arise from TI providing such TI Resources. TI reserves the right to make corrections, enhancements, improvements and other changes to its TI Resources.

You understand and agree that you remain responsible for using your independent analysis, evaluation and judgment in designing your applications and that you have full and exclusive responsibility to assure the safety of your applications and compliance of your applications (and of all TI products used in or for your applications) with all applicable regulations, laws and other applicable requirements. You represent that, with respect to your applications, you have all the necessary expertise to create and implement safeguards that (1) anticipate dangerous consequences of failures, (2) monitor failures and their consequences, and (3) lessen the likelihood of failures that might cause harm and take appropriate actions. You agree that prior to using or distributing any applications that include TI products, you will thoroughly test such applications and the functionality of such TI products as used in such applications. TI has not conducted any testing other than that specifically described in the published documentation for a particular TI Resource.

You are authorized to use, copy and modify any individual TI Resource only in connection with the development of applications that include the TI product(s) identified in such TI Resource. NO OTHER LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE TO ANY OTHER TI INTELLECTUAL PROPERTY RIGHT, AND NO LICENSE TO ANY TECHNOLOGY OR INTELLECTUAL PROPERTY RIGHT OF TI OR ANY THIRD PARTY IS GRANTED HEREIN, including but not limited to any patent right, copyright, mask work right, or other intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information regarding or referencing third-party products or services does not constitute a license to use such products or services, or a warranty or endorsement thereof. Use of TI Resources may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

TI RESOURCES ARE PROVIDED "AS IS" AND WITH ALL FAULTS. TI DISCLAIMS ALL OTHER WARRANTIES OR REPRESENTATIONS, EXPRESS OR IMPLIED, REGARDING TI RESOURCES OR USE THEREOF, INCLUDING BUT NOT LIMITED TO ACCURACY OR COMPLETENESS, TITLE, ANY EPIDEMIC FAILURE WARRANTY AND ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, AND NON-INFRINGEMENT OF ANY THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

TI SHALL NOT BE LIABLE FOR AND SHALL NOT DEFEND OR INDEMNIFY YOU AGAINST ANY CLAIM, INCLUDING BUT NOT LIMITED TO ANY INFRINGEMENT CLAIM THAT RELATES TO OR IS BASED ON ANY COMBINATION OF PRODUCTS EVEN IF DESCRIBED IN TI RESOURCES OR OTHERWISE. IN NO EVENT SHALL TI BE LIABLE FOR ANY ACTUAL, DIRECT, SPECIAL, COLLATERAL, INDIRECT, PUNITIVE, INCIDENTAL, CONSEQUENTIAL OR EXEMPLARY DAMAGES IN CONNECTION WITH OR ARISING OUT OF TI RESOURCES OR USE THEREOF, AND REGARDLESS OF WHETHER TI HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

You agree to fully indemnify TI and its representatives against any damages, costs, losses, and/or liabilities arising out of your non-compliance with the terms and provisions of this Notice.

This Notice applies to TI Resources. Additional terms apply to the use and purchase of certain types of materials, TI products and services. These include; without limitation, TI's standard terms for semiconductor products (<http://www.ti.com/sc/docs/stdterms.htm>), [evaluation modules](#), and [samples](http://www.ti.com/sc/docs/sampterm.htm) (<http://www.ti.com/sc/docs/sampterm.htm>).

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265
Copyright © 2018, Texas Instruments Incorporated