



MECHANICAL

Issue No. 02	Rev. No: 00	Effective Date: 01.11.2019	SOP/MEC/188
Issued By: M.R		Approved By: HOD-Mechanical	
SOP-JSA for TORQUE SUPPORT LINER REPLACEMENT			

SOP FOR VRM TORQUE SUPPORT LINER REPLACEMENT

Scope : This SOP is applicable to Safe working of Torque support Liner replacement..

Responsibility : **Section Engineer mech**

Accountability : **Section Incharge mech**

PPE:

1. Safety helmet,
2. Safety shoe
3. Safety Belt
4. Mask.
5. Asbestos Gloves.

Tools:

1. Chain block (5 Ton)-2 Nos
2. Belt Sling
3. Hammer
4. Box Spanner set
5. Ring Spanner set
6. Cutting set
7. Welding m/c with cable
8. Hydraulic jack 100 ton

Hazards:

Risks associated

Mitigating Measures

Falling of Men

Wear Safety belt

Training needs:

1. Emergency preparedness
2. Fire Fighting
3. Hydraulic jack operation

Procedure:

1. Take the line clearance for the following.

- a) Mill feed RAL
- b) Mill main drive
- c) Classifier drive
- d) Mill booster fan
- e) Mill fan



MECHANICAL

Issue No. 02	Rev. No: 00	Effective Date: 01.11.2019	SOP/MEC/188
Issued By: M.R		Approved By: HOD-Mechanical	
SOP-JSA for TORQUE SUPPORT LINER REPLACEMENT			

- f) Hydraulic tension unit
- g) Inlet damper for hot gas entry
2. Before unscrewing the mill manual inspection door the following parameters to be checked.
 - a) The temperature inside the mill to be maintained less than 45°.
 - b) The roller position should be ZERO. Ensure from CCR.
3. Open the mill manual inspection door, scrapper chamber manual door, classifier manual inspection door and torque support buffer cap inspection door.
4. Lock the pressure Frame by angle to maintain the gap between the pressure frame and mill torque support side housing to make the people to work safely by using hydraulic jack
5. Keep the chain block above the torque support to remove the liner plate of torque support by loosening the locking bolt
6. Place one more chain block opposite side to remove the torque support pin with cap by placing the two eye bolts on liner plate of torque support
7. Remove the locking bolt of torque support liner plate
8. Remove the support rib of Torque support liner plate
9. Remove the Torque support liner plate by using the chain block
10. Check the condition of liner plate seating area
11. Fixing the new liner plate by using chain block
12. Put the liner plate locking bolt and to be tightened
13. Remove the Locking angle by using hydraulic jack arrangement.
14. Close all the doors of the mill
15. Clear LC for start the Mill.

Emergency / Emergency Shut OFF:

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222.



DALMIA CEMENT (B) LIMITED – ARIYALUR



MECHANICAL

Issue No. 02	Rev. No: 00	Effective Date: 01.11.2019	SOP/MEC/188
--------------	-------------	----------------------------	-------------

Issued By: M.R	Approved By: HOD-Mechanical
----------------	-----------------------------

SOP-JSA for TORQUE SUPPORT LINER REPLACEMENT

Records/Annexure:

1. Refer Line clearance certificates.
2. JSA as enclosed below.

Job Safety Analysis	Job: Torque support liner replacement	Date: 20.04.2020	Analysis by: Section Engineer	Reviewed by: Section Head
Title of employee doing job: Section in charge	Supervisor: Section Engineer	Department: Mechanical	Section: Cement Mill	Approved by: HOD
Req'd/recommended PPE: Safety helmet, Safety shoe, Safety goggles, Safety Belt & Asbestos Gloves.				
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action



DALMIA CEMENT (B) LIMITED – ARIYALUR



MECHANICAL

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/188

Issued By: M.R Approved By: HOD-Mechanical

SOP-JSA for TORQUE SUPPORT LINER REPLACEMENT

Position of the chain blocks for removing the Torque support nitrogen cylinder housing and putting the same	Leg and hand injury	Use correct lifting Tackles Teflon/wire rope slings	Chain block may slip and fall while removing and inserting the belt	1. Check the condition of the ropes and slings
Lock the pressure frame by welding the angle by using hydraulic jack	Leg injury	Use proper lifting tools to lift the material	Material may slip during tag welding	2. Check the correct size of slings to operate/actual capacity and ensure certificate of clearance.
Removing the flange bolt of nitrogen cylinder housing and flange bolt and flange of torque support pin and cap.	Leg and hand injury.	Use proper standard tool for removing the bolt.	Material may slip	Ensure the person Lifting the material as per lifting procedure
				Ensure the person using proper PPE

S L N o	Tag / Name of the Equipment			
	Activity			
	Isolation Type			
			Electrical Energy	Other Energy



DALMIA CEMENT (B) LIMITED – ARIYALUR



MECHANICAL

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/188

Issued By: M.R Approved By: HOD-Mechanical

SOP-JSA for TORQUE SUPPORT LINER REPLACEMENT

1	Cement Mill Inspection	Name and Tag for the Equipment	561MD 2 / Mill Main Motor	561SR1 / Classifier	561FN1 / Mill Fan	561AD2/ Auxiliary drive Chain not to be connected	Rollers Position Landed & Pressure Zero at Panel				
		Name and Tag for the Equipment	561RA 1 / Mill feed RAL	561FN4 / Booster fan	561SD2 / Hot Air Shut-off Damper(In closed condition only)						
		Name and Tag for the Equipment	K21 RA4								