


<< Search more Solutions!

Found Errors in Solution? >> [Report here!](#)

To do: If you are getting wrong answer or irrelevant answer.

Fix #1 >> We suggest you to follow the directions shown in the below image to get right question link.



Answer


Please give me an upvote for my efforts . It'll help to answer more questions. If you are having any doubt s please comment me before giving down the vote.thank you

$$R_a = 0.05 \Omega$$

$$I = 100 \text{ A}; R_s = 0.025 \Omega$$

$$I_{sh} = \frac{220}{50} \\ = 4.4 \text{ A}$$

$$I_a = 104.4 \text{ A}$$



$$E_g = V_t + I_a (R_a + R_{sh}) + \text{brush drop}$$

$$= 220 + (104.4)(0.075) + 2$$

$$E_g = 229.834$$

$$\text{stray losses} = 1 \text{ kW (Iron \& friction losses)}$$

$$E_g = 229.834$$

$$\text{Copper losses} = I_a^2 (R_a + R_{se}) + V I_{sh} \\ = 1.785 \text{ kW}$$

$$\text{output of prime mover} = V_t I_a + \text{Cu losses} \\ = 220 \times 100 + 1.785 \text{ kW} \\ = 23.785 \text{ kW}$$

$$\text{Generator input} = 23.785 \text{ kW}$$

$$P = 22.785 \text{ W}$$

$$\begin{aligned} \text{Generator Efficiency} &= \frac{22 \text{ kW}}{22 \text{ kW} + 2.785} \\ &= 88.763\% \end{aligned}$$

Likes: 1**Dislikes: 0**