


# Thapar Institute of Engineering & Technology, Patiala

## Manufacturing Processes UTA026



Thapar Institute of Engineering & Technology  
(Deemed to be University)  
Bhadson Road, Patiala, Punjab, Pin-147004.  
Contact No. : +91-175-2393201  
Email : [info@thapar.edu](mailto:info@thapar.edu)

**ti**  
**THAPAR INSTITUTE**  
OF ENGINEERING & TECHNOLOGY  
(Deemed to be University)

# THEORY OF CHIP FORMATION


- The cutting tool removes the metal from the workpiece in the form of *“chips”*.
- As the tool advances into the workpiece, the metal in front of the tool is *compressed* and when the *compression limit* of the metal has been *exceeded*, it is separated from the workpiece and *flows plastically* in the form of chip.

# THEORY OF CHIP FORMATION

- The plastic flow of the metal takes place in a localised region called *shear plane*, which extends from the cutting edge obliquely upto the uncut surface in front of the tool.

*Or in other words*

- The chip is formed by shear deformation (*primary shear*) along a plane called the *shear plane*, which is oriented at an *angle  $\phi$*  with the surface of the work.



# THEORY OF CHIP FORMATION


- *Another shearing* action occurs in the chip after it has been formed.
- This additional shear is referred to as *secondary shear* to distinguish it from primary shear.
- *Secondary shear results* from *friction* between the chip and the tool as the chip slides along the *rake face* of the tool.

# THEORY OF CHIP FORMATION

- During cutting, the cutting edge of the tool is positioned a certain distance below the original work surface.
- This corresponds to the *thickness* of the chip *before* the *chip formation* =  $t_o$ .
- *As the chip is formed* along the shear plane, its *thickness increases* to =  $t_c$ .

# THEORY OF CHIP FORMATION

$$t_o < t_c$$



# THEORY OF CHIP FORMATION

- The ratio of  $t_o$  to  $t_c$  is called the *chip thickness ratio* (or simply the chip ratio)  $r$ .

$$r = \frac{t_o}{t_c}$$

- Since the chip thickness after cutting is always greater than the corresponding thickness before cutting, the chip ratio will *always be less than 1*.



# TYPES OF CHIPS

- Chip is a small piece of material removed in the course of chopping, cutting, or breaking something, esp. a hard material such as wood , stone or metal.
- In a metal cutting operation chips are separated from the workpiece to impart the required size and shape to the workpiece.

# TYPES OF CHIPS

- The chips that are formed during metal cutting operations can be classified into three types:


***1. Discontinuous or segmental chips***

***2. Continuous chips***

***3. Continuous chips with built-up edge.***

# 1. DISCONTINUOUS CHIP

- ***Brittle work materials***
- ***Low cutting speeds***
- ***Large feed and depth of cut***
- ***High tool-chip friction***
- ***Low or Negative rake angle***



# 1. DISCONTINUOUS CHIP

- When brittle materials like cast iron are cut, the deformed material gets fractured very easily and thus the chip produced is in the form of *discontinuous segments*.
- In this type the deformed material instead of flowing continuously gets *ruptured periodically*.

# 1. DISCONTINUOUS CHIP


- Also they generally *provide better surface finish* (for *brittle material only*).
- Discontinuous chips are *easier from the chip disposal view point*.
- However, in case of *ductile materials* they cause *poor surface finish* and low tool life.

# 1. DISCONTINUOUS CHIP

- A discontinuous chip comes off as small chunks or particles. When we get this chip it may indicate:
  - *brittle work material*
  - *small or negative rake angles*
  - *large feed, depth of cut and low cutting speed*

## 2. CONTINUOUS CHIP

- *Ductile work materials*
- *High cutting speeds*
- *Small feeds and depths*
- *Sharp cutting edge*
- *Low tool-chip friction*
- *High or Positive rake angle*




## 2. CONTINUOUS CHIP

- Continuous chips are normally produced when machining steel or *ductile metals* at *high cutting speeds*.
- The continuous chip which is like a ribbon flows along the rake face.
- Continuous chip is possible because of the ductility of metal.



## 2. CONTINUOUS CHIP



## 2. CONTINUOUS CHIP

- It can be assumed that each layer of metal flows along the slip plane till it is stopped by work hardening.
- Each of these layers get welded to the previous ones because of the high temperature, thus forming a continuous chip.

## 2. CONTINUOUS CHIP

- Some ideal conditions that promote continuous chips in metal cutting are:
  - *sharp cutting edge,*
  - *small chip thickness (fine feed),*
  - *large rake angle,*
  - *high cutting speed,*
  - *ductile work materials and*
  - *less friction between chip tool interface through efficient lubrication.*

## 2. CONTINUOUS CHIP

- This is the most desirable form of chip since the surface finish obtained is good and cutting is smooth.
- It also helps in having higher tool life and lower power consumption.
- *However, long continuous chips (as in turning) can cause problems with regard to chip disposal.*

## 2. CONTINUOUS CHIP

- These chips also *cause a hazard* to
  - *the machine operator and*
  - *the workpart finish,*
  - *and they interfere with automatic operation of the turning process.*


## 2. CONTINUOUS CHIP

- Therefore it is *essentially needed to break such continuous chips* into small regular pieces for
  - *safety of the working people*
  - *prevention of damage of the product*
  - *easy collection and disposal of chips.*

## 2. CONTINUOUS CHIP ( Chip Breakers)

- To help in this direction various forms of *chip breakers* are frequently used with single-point tools
  - *to force the chips to curl more tightly* than they would naturally do, *thus* causing them to be *broken* into small pieces so that they can be *easily disposed off.*
- They work on the principle that *“If you decrease the radius of chip enough you can break the chip.”*


# Chip Curl



- A single point cutting tool (without a chip breaker) showing a long chip curl




# Groove-type : CHIP BREAKER




- Groove-type chip breaker designed into the cutting tool itself.

# Integrated Obstruction Type : CHIP BREAKER



- Integrated Obstruction-type chip breakers are in the form of step made as an integral part on the rake face of the tool.


# Clamped On Obstruction Type : CHIP BREAKER



- Clamped on obstruction-type chip breaker designed as an additional device on the rake face of the tool.

### 3. CONTINUOUS CHIP WITH BUILT-UP EDGE

- ***Ductile materials***
- ***Low-to-medium cutting speeds***
- ***Tool-chip friction causes portions of chip to adhere to rake face***
- ***BUE forms, then breaks off, cyclically***



### 3. CONTINUOUS CHIP WITH BUILT-UP EDGE

- When machining ductile materials at low-to-medium cutting speeds, friction between tool and chip tends to cause portions of the work material to adhere to the rake face of the tool near the cutting edge.
- This formation is called a built-up edge (BUE).
- The formation of a BUE is cyclical; it forms and grows, then becomes unstable and breaks off.

### 3. CONTINUOUS CHIP WITH BUILT-UP EDGE

- Much of the detached BUE is carried away with the chip, sometimes taking portions of the tool rake face with it, which reduces the life of the cutting tool.
- Portions of the detached BUE that are not carried off with the chip become imbedded in the newly created work surface, causing the surface to become rough.

### 3. PREVENTION OF BUILT-UP EDGE CHIP FORMATION

- The formation of a built-up edge is also referred to as chip welding.
- Since chip welding has a considerable adverse effect on tool life, power consumption, and surface finish, every attempt must be made to prevent it occurring.

### 3. PREVENTION OF BUILT-UP EDGE CHIP FORMATION

- This is largely achieved by reversing the conditions that cause chip welding in the first place.
- Prevention is mainly done by
  - *Reduction of friction*
  - *Reducing the pressure*
  - *Preventing metal to metal contact*
  - *Reducing the temperature*



### 3. PREVENTION OF BUILT-UP EDGE CHIP FORMATION

- **Reduction of friction**

- This can be achieved by increasing the rake angle, using a cutting fluid that is an extreme pressure lubricant as well as a coolant, and polishing the rake face.

- **Reducing the pressure**

- This can be achieved by increasing the rake angle. Remember this also weakens the tool and there is a limit to how far the rake angle can be increased for any given workpiece material.
- Reducing the rate of feed will also help.

### 3. PREVENTION OF BUILT-UP EDGE CHIP FORMATION

- **Preventing metal to metal contact**

- This can be achieved by the use of a lubricant containing an extreme pressure additive. Such additives are usually sulphur or chlorine compounds. These additives tend to build up a non-metallic film on the surfaces of the tool and the chip. Since metal is not then in contact with metal chip welding cannot take place.

### 3. PREVENTION OF BUILT-UP EDGE CHIP FORMATION

- **Reducing the temperature**

- This can also be achieved by any of the above solutions. The temperature can also be achieved by reducing the spindle speed but this reduces the rate of metal removal.

# References:

- M. P. Groover, Fundamentals Of Modern Manufacturing: Materials, Processes, and Systems, Wiley (2010), 4<sup>th</sup> edition.
- Degarmo, E. P., Kohser, Ronald A. and Black, J. T., Materials and Processes in Manufacturing, Prentice Hall of India (2008) 8<sup>th</sup> ed.
- Kalpakjian, S. and Schmid, S. R., Manufacturing Processes for Engineering Materials, Dorling Kingsley (2006) 4<sup>th</sup> ed.