


3 Triax to 4 wire sensor measurement



Parts list:

1. Pomona 5219, Triax bulkhead socket, 3 off
2. Pomona 5251, SOIC 14 test clip – 1 off
3. Multicomp 0.5mm² flexible cable, 100mm – 4 off
4. Diecast box 115x90x55 – 1 off
5. Header 2.54 single row, 1x2 – 2 off
6. Heat shrink sleeve 1.5mm inner dia recovered, 2cm, Red – 1 off
7. Heat shrink sleeve 1.5mm inner dia recovered, 2cm, Blue – 1 off
8. Heat shrink sleeve 1.5mm inner dia recovered, 2cm, Black – 1 off
9. Heat shrink sleeve 1.5mm inner dia recovered, 2cm, Yellow – 1 off
10. M4 Earthing stud
11. Earthing lead, Yellow/Green, 1m – 1 off

Assembly Instructions:

1. Equally space the triax connectors centered on the longest side of the box
2. Add Earthing stud to centered short side of the box.
3. Triax chassis connection is shown as GND
4. All connections should be heat shrunk
5. Apply labels for sockets to exterior of box
6. Item 2, supplied inside box
7. Assembly should be labelled with drawing number

Silveray Ltd

Sheet: /

File: td2210_reva.kicad_sch

Title: TD 22010 –3 Triax to 2 wire sensor measurement

Size: A4 Date: 2022-12-01

KiCad E.D.A. kicad (6.0.7)

Rev: b

Id: 1/1