



Arm Cortex-R82 Processor MP130

Software Developer Errata Notice

Date of issue: 04-Apr-2023

Non-Confidential

Document version: 11.0

Copyright © 2023 Arm® Limited (or its affiliates). All rights reserved.

Document ID: SDEN-1956900

This document contains all known errata since the r0p0 release of the product.



Non-confidential proprietary notice

This document is protected by copyright and other related rights and the practice or implementation of the information contained in this document may be protected by one or more patents or pending patent applications. No part of this document may be reproduced in any form by any means without the express prior written permission of Arm. No license, express or implied, by estoppel or otherwise to any intellectual property rights is granted by this document unless specifically stated.

Your access to the information in this document is conditional upon your acceptance that you will not use or permit others to use the information for the purposes of determining whether implementations infringe any third party patents.

THIS DOCUMENT IS PROVIDED "AS IS". ARM PROVIDES NO REPRESENTATIONS AND NO WARRANTIES, EXPRESS, IMPLIED OR STATUTORY, INCLUDING, WITHOUT LIMITATION, THE IMPLIED WARRANTIES OF MERCHANTABILITY, SATISFACTORY QUALITY, NON-INFRINGEMENT OR FITNESS FOR A PARTICULAR PURPOSE WITH RESPECT TO THE DOCUMENT. For the avoidance of doubt, Arm makes no representation with respect to, and has undertaken no analysis to identify or understand the scope and content of, third party patents, copyrights, trade secrets, or other rights.

This document may include technical inaccuracies or typographical errors.

TO THE EXTENT NOT PROHIBITED BY LAW, IN NO EVENT WILL ARM BE LIABLE FOR ANY DAMAGES, INCLUDING WITHOUT LIMITATION ANY DIRECT, INDIRECT, SPECIAL, INCIDENTAL, PUNITIVE, OR CONSEQUENTIAL DAMAGES, HOWEVER CAUSED AND REGARDLESS OF THE THEORY OF LIABILITY, ARISING OUT OF ANY USE OF THIS DOCUMENT, EVEN IF ARM HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

This document consists solely of commercial items. You shall be responsible for ensuring that any use, duplication or disclosure of this document complies fully with any relevant export laws and regulations to assure that this document or any portion thereof is not exported, directly or indirectly, in violation of such export laws. Use of the word "partner" in reference to Arm's customers is not intended to create or refer to any partnership relationship with any other company. Arm may make changes to this document at any time and without notice.

If any of the provisions contained in these terms conflict with any of the provisions of any click through or signed written agreement covering this document with Arm, then the click through or signed written agreement prevails over and supersedes the conflicting provisions of these terms. This document may be translated into other languages for convenience, and you agree that if there is any conflict between the English version of this document and any translation, the terms of the English version of the Agreement shall prevail.

The Arm corporate logo and words marked with ® or ™ are registered trademarks or trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere. All rights reserved. Other brands and names mentioned in this document may be the trademarks of their respective owners. Please follow Arm's trademark usage guidelines at <https://www.arm.com/company/policies/trademarks>.

Copyright © 2023 Arm® Limited (or its affiliates). All rights reserved.

Arm Limited. Company 02557590 registered in England.

110 Fulbourn Road, Cambridge, England CB1 9NJ.

(LES-PRE-20349)

Confidentiality status

This document is Non-Confidential. The right to use, copy and disclose this document may be subject to license restrictions in accordance with the terms of the agreement entered into by Arm and the party that Arm delivered this document to.

Unrestricted Access is an Arm internal classification.

Feedback

Arm welcomes feedback on this product and its documentation. To provide feedback on Arm Cortex-R82 Processor MP130 , create a ticket on <https://support.developer.arm.com>.

To provide feedback on the document, fill the following survey: <https://developer.arm.com/documentation-feedback-survey>.

Inclusive language commitment

Arm values inclusive communities. Arm recognizes that we and our industry have used language that can be offensive. Arm strives to lead the industry and create change.

If you find offensive language in this document, please email terms@arm.com.

Contents

Introduction	8
Scope	8
Categorization of errata	8
Change Control	9
Errata summary table	14
Errata descriptions	19
Category A	19
2215640 A cacheable write to LLRAM could cause data corruption of a Main Master cacheline	19
Category A (rare)	20
Category B	21
2113395 Incorrect value could be reported in AFSR0_ELx for external errors on store-exclusive and load atomic instructions	21
2114617 Cortex-R82 could deadlock in the presence of an L2 cache data RAM ECC error	23
2130548 An ECC error could cause a deadlock under certain conditions	24
2177521 Physical interrupts might not be taken	26
2188383 ECC error might cause wrong execution of certain System register access instructions	27
2272083 Utility bus accesses to RAS registers target wrong registers	28
2275980 Cluster transitions to a lower power mode might cause deadlocks in the presence of Core transitions to higher power modes	29
2284596 Interrupt can be routed to a Core in FULL_RET although SCLK Q-channel is not in QRUN	31
2290922 Link register might be incorrect after taking an SError interrupt exception or entering Debug state	32
2295080 Shared register writes do not respect context synchronization barriers	34
2309270 Transition to FULL_RET is denied if IMP_CPUPWRCTLR_EL1.FPURET > 0	35
2324971 Critical error interrupt will not be indicated for UC error on Error Records 1, 2 and 3	36
2329077 Cluster PMU register interface has limited functionality	37
2330574 Transition from L2 cache FULL RAM ON to DL1ONLY operating mode might cause a deadlock	39
2342667 An ECC error during a power-down sequence might affect execution of FP/AdvSIMD instructions	40
2344782 DSB might not ensure completion of previous stores when multiple contexts are using the same port	42

2413308	Read of CNTKCTL_EL1, CNTHCTL_EL2 or CNTVOFF_EL2 might return the value from last interrupted write	44
2416441	Clock is not gated correctly when the core is in the Full retention power mode	46
2455174	Cluster MEM_RET is not sustained	48
2487068	Cluster IRQs may be lost in the presence of cluster MEM_RET and OFF power transitions	50
2639772	Turning a core ON while the cluster is being powered OFF may deadlock	52
2666600	CLUSTERPWRDN.PWRDWN is not functional	54
2684598	Software step might go to wrong state	56
2691481	Memory accesses can use old values of some of the Generic System control registers	58
2725097	Interrupting a DSB might cause the DSB for earlier TLBI/IC maintenance operations to fail	60
2772412	DFB does not wait for completion of IC/TLBI from other contexts	62
2776909	A write to LLRAM following a hardware access flag update could result in incorrect translation	64
2795835	A translation table walk may raise an unexpected abort	66
Category B (rare)		67
Category C		68
2110865	RAM ECC errors or poison during core power off transitions may lead to deadlock	68
2131519	RAS Fault Injection to shared memory may cause deadlock or data corruption	70
2131811	DSB does not guarantee the observability of the effects of the GIC CPU interface register accesses	71
2140942	Incorrect value reported in RAS registers on L2 cache ECC errors	73
2151159	Multi-core Cortex-R82 may deadlock when executing L2DBG operations and WFx events	74
2169550	ETM trace might not report certain direct branch instructions	76
2170009	Error injection via ERR0PFGCTL might occur at the wrong time	78
2173953	PMU event counts might be inaccurate	79
2215960	An atomic with Acquire semantics may be observed before an earlier Store-Release to TCM or LLPP	81
2218751	Data cache maintenance operations by Set/Way targeting a 4MB L2 cache might affect incorrect cache index	83
2224832	Debug APB accesses to reserved core address is accessible when core powered off	85
2226045	ATB flush is unreliable	86
2246499	Some RAS and Debug identification registers have wrong values	87
2248150	Accesses to Non-secure EL2 physical timer registers and Secure EL2 virtual timer registers are not UNDEFINED	88

2254257	Read of ERRGSR might return incorrect value	89
2261658	A single bit hard error on poisoned TCM data could cause a deadlock	90
2284986	PMU event counts might be inaccurate	92
2286314	Access to TRCSEQEVR3 is not UNDEFINED	94
2313135	Cacheable accesses to LLRAM might deadlock in the presence of an ECC error	95
2317561	Halting step syndrome might be wrong on stepping a Load-Exclusive instruction	97
2330237	Multi-issuing control with IMP_CPUACTLR_EL1.MI = 0b010 is wrong	98
2338818	IFU Cache errors might report incorrect BANK to the RAS node	99
2339884	Cluster CTI trigger outputs are not reaching cluster ELA CTITRIGINs	100
2358852	Pointer authentication key registers are not initialized	101
2359684	Some unallocated debug and trace System registers might be trapped by HCR_EL2.TIDCP	102
2370219	Use of debug related power states can result in deadlock	103
2375011	PSTATE.SS not restored correctly if OSLK is set to 1 just before debug exit	105
2384696	DPU returns wrong value on MRS to DLR_EL0	106
2386524	Defective RAS registers	107
2416442	Multiple double bit ECC errors on core powerdown might deadlock	109
2440118	Some PMU events count incorrectly	110
2445341	Cache initialization and reset of register fields with UNKNOWN values do not work as expected after Debug recovery	111
2604629	ETM data trace values for ST atomics are incorrect	113
2617173	An external atomic receiving a SLVERR or DECERR might not raise an asynchronous abort	115
2618272	When toggling SPIDEN or DBGEN pins close to a core reset, the system might deadlock	116
2652888	Receiving poison on invalid data lanes might result in a data abort when poison is not supported	117
2656238	New interrupts might not be taken after an atomic instruction is interrupted	119
2659537	Spurious ECC error might be reported when changing operating mode from DL1ONLY to FULL RAM	120
2661859	Incorrect value reported in RAS registers on LLRAM receiving poison when ECC is not supported	122
2693781	Quality of Service is applied to Main Manager accesses when disabled	123
2694966	Fault handling interrupt can cause power transition to deadlock	124
2719885	Software step exception might set the ESR_ELx.ISV to a wrong value	126
2729228	Debug accesses via APB are not supported in EMU power states	127
2729398	L2RDLAT and L2WRLAT fields in IMP_CLUSTERACTLR_EL1 are hardcoded	128

2747728	Some cluster PMU events are incorrect	130
2753234	An external atomic receiving poison might not raise an asynchronous abort	132
2763783	Speculative accesses might still be made when LLRAM is disabled	133
2773193	32-bit accesses to ERR<n>MISC0 (n= 1-6) will not work as expected	134
2780544	Reset of register fields with UNKNOWN values does not work as expected in the presence of debug recovery	136
2788717	An interrupted atomic operation with bus error to LLRAM may raise unexpected asynchronous abort	138
2798198	Incorrect system reset behavior under MEM_RET and MEM_RET_EMU modes for IMP_CLUSTERACTLR_EL1.UBACCLVL	139
2842855	AFSR0_ELx might have stale value after taking an SError interrupt	140
2847045	External read of TCM while CPUHALT<m> is HIGH might see unexpected ECC errors	141

Introduction

Scope

This document describes errata categorized by level of severity. Each description includes:

- The current status of the erratum.
- Where the implementation deviates from the specification and the conditions required for erroneous behavior to occur.
- The implications of the erratum with respect to typical applications.
- The application and limitations of a workaround where possible.

Categorization of errata

Errata are split into three levels of severity and further qualified as common or rare:

Category A	A critical error. No workaround is available or workarounds are impactful. The error is likely to be common for many systems and applications.
Category A (Rare)	A critical error. No workaround is available or workarounds are impactful. The error is likely to be rare for most systems and applications. Rare is determined by analysis, verification and usage.
Category B	A significant error or a critical error with an acceptable workaround. The error is likely to be common for many systems and applications.
Category B (Rare)	A significant error or a critical error with an acceptable workaround. The error is likely to be rare for most systems and applications. Rare is determined by analysis, verification and usage.
Category C	A minor error.

Change Control

Errata are listed in this section if they are new to the document, or marked as "updated" if there has been any change to the erratum text. Fixed errata are not shown as updated unless the erratum text has changed. The [errata summary table](#) identifies errata that have been fixed in each product revision.

04-Apr-2023: Changes in document version v11.0

ID	Status	Area	Category	Summary
2275980	Updated	Programmer	Category B	Cluster transitions to a lower power mode might cause deadlocks in the presence of Core transitions to higher power modes
2780544	New	Programmer	Category C	Reset of register fields with UNKNOWN values does not work as expected in the presence of Debug recovery mode
2798198	New	Programmer	Category C	Incorrect system reset behavior under MEM_RET and MEM_RET_EMU modes for IMP_CLUSTERACTLR_EL1.UBACCLVL
2842855	New	Programmer	Category C	AFSR0_ELx might have stale value after taking an SError interrupt
2847045	New	Programmer	Category C	External read of TCM while CPUHALT<m> is HIGH might see unexpected ECC errors

18-Nov-2022: Changes in document version v10.0

ID	Status	Area	Category	Summary
2725097	New	Programmer	Category B	Interrupting a DSB might cause the DSB for earlier TLBI/IC maintenance operations to fail
2772412	New	Programmer	Category B	DFB does not wait for completion of IC/TLBI from other contexts
2776909	New	Programmer	Category B	A write to LLRAM following a hardware access flag update could result in incorrect translation
2795835	New	Programmer	Category B	A translation table walk may raise an unexpected abort
2652888	Updated	Programmer	Category C	Receiving poison on invalid data lanes might result in a data abort when poison is not supported
2719885	New	Programmer	Category C	Software step exception might set the ESR_ELx.ISV to a wrong value
2729228	New	Programmer	Category C	Debug accesses via APB are not supported in EMU power states
2729398	New	Programmer	Category C	L2RDLAT and L2WRLAT fields in IMP_CLUSTERACTLR_EL1 are hardcoded
2747728	New	Programmer	Category C	Some cluster PMU events are incorrect
2753234	New	Programmer	Category C	An external atomic receiving poison might not raise an asynchronous abort
2763783	New	Programmer	Category C	Speculative accesses might still be made when LLRAM is disabled
2773193	New	Programmer	Category C	32-bit accesses to ERR<n>MISCO (n= 1-6) will not work as expected
2788717	New	Programmer	Category C	An interrupted atomic operation with bus error to LLRAM raised an unexpected asynchronous abort

19-Jul-2022: Changes in document version v9.0

ID	Status	Area	Category	Summary
2639772	New	Programmer	Category B	Turning a core ON while the cluster is being powered OFF may deadlock
2666600	New	Programmer	Category B	CLUSTERPWRDN.PWRDWN is not functional
2684598	New	Programmer	Category B	Software step might go to wrong state
2691481	New	Programmer	Category B	Memory accesses can use old values of some of the Generic System control registers
2604629	New	Programmer	Category C	ETM data trace values for ST atomics are incorrect
2617173	New	Programmer	Category C	An external atomic receiving a SLVERR or DECERR might not raise an asynchronous abort
2652888	New	Programmer	Category C	Receiving poison on invalid data lanes might result in a data abort when poison is not supported
2656238	New	Programmer	Category C	New interrupts might not be taken after an atomic instruction is interrupted
2659537	New	Programmer	Category C	Spurious ECC error might be reported when changing operating mode from DL1ONLY to FULL RAM
2661859	New	Programmer	Category C	Incorrect value reported in RAS registers on LLRAM receiving poison when ECC is not supported
2693781	New	Programmer	Category C	Quality of Service is applied to Main Manager accesses when disabled
2694966	New	Programmer	Category C	Fault handling interrupt can cause power transition to deadlock

22-Apr-2022: Changes in document version v8.0

ID	Status	Area	Category	Summary
2455174	New	Programmer	Category B	Cluster MEM_RET is not sustained
2487068	New	Programmer	Category B	Cluster IRQs may be lost in the presence of cluster MEM_RET and OFF power transitions
2440118	New	Programmer	Category C	Some PMU events count incorrectly
2445341	New	Programmer	Category C	Cache initialization and reset of register fields with UNKNOWN values do not work as expected after Debug recovery
2618272	New	Programmer	Category C	When toggling SPIDEN or DBGEN pins close to a core reset, the system might deadlock

21-Feb-2022: Changes in document version v7.0

ID	Status	Area	Category	Summary
2413308	New	Programmer	Category B	Read of CNTKCTL_EL1, CNTHCTL_EL2 or CNTVOFF_EL2 might return the value from last interrupted write
2416441	New	Programmer	Category B	Clock is not gated correctly when the core is in the Full retention power mode
2416442	New	Programmer	Category C	Multiple double bit ECC errors on core powerdown might deadlock

13-Dec-2021: Changes in document version v6.0

ID	Status	Area	Category	Summary
2275980	New	Programmer	Category B	Cluster transitions to a lower power mode might cause deadlocks in the presence of Core transitions to higher power modes
2284596	New	Programmer	Category B	Interrupt can be routed to a Core in FULL_RET although SCLK Q-channel is not in QRUN
2295080	New	Programmer	Category B	Shared register writes do not respect context synchronization barriers
2313135	New	Programmer	Category C	Cacheable accesses to LLRAM might deadlock in the presence of an ECC error
2358852	New	Programmer	Category C	Pointer authentication key registers are not initialized
2359684	New	Programmer	Category C	Some unallocated debug and trace System registers might be trapped by HCR_EL2.TIDCP
2370219	New	Programmer	Category C	Use of debug related power states can result in deadlock
2375011	New	Programmer	Category C	PSTATE.SS not restored correctly if OSLK is set to 1 just before debug exit
2384696	New	Programmer	Category C	DPU returns wrong value on MRS to DLR_ELO
2386524	New	Programmer	Category C	Defective RAS registers

12-Nov-2021: Changes in document version v5.0

ID	Status	Area	Category	Summary
2309270	New	Programmer	Category B	Transition to FULL_RET is denied if IMP_CPUPWRCTLR_EL1.FPURET > 0
2324971	New	Programmer	Category B	Critical error interrupt will not be indicated for UC error on Error Records 1, 2 and 3
2329077	New	Programmer	Category B	Cluster PMU register interface has limited functionality
2330574	New	Programmer	Category B	Transition from L2 cache FULL RAM ON to DL1ONLY operating mode might cause a deadlock
2342667	New	Programmer	Category B	An ECC error during a power-down sequence might affect execution of FP/AdvSIMD instructions
2344782	New	Programmer	Category B	DSB might not ensure completion of previous stores when multiple contexts are using the same port
2284986	Updated	Programmer	Category C	PMU event counts might be inaccurate
2317561	New	Programmer	Category C	Halting step syndrome might be wrong on stepping a Load-Exclusive instruction
2330237	New	Programmer	Category C	Multi-issuing control with IMP_CPUACTLR_EL1.MI = 0b010 is wrong
2338818	New	Programmer	Category C	IFU Cache errors might report incorrect BANK to the RAS node
2339884	New	Programmer	Category C	Cluster CTI trigger outputs are not reaching cluster ELA CTITRIGINS

23-Sep-2021: Changes in document version v4.0

ID	Status	Area	Category	Summary
2290922	New	Programmer	Category B	Link register might be incorrect after taking an SError interrupt exception or entering Debug state
2284986	New	Programmer	Category C	PMU event counts might be inaccurate
2286314	New	Programmer	Category C	Access to TRCSEQEVR3 is not UNDEFINED

19-Aug-2021: Changes in document version v3.0

ID	Status	Area	Category	Summary
2272083	New	Programmer	Category B	Utility bus accesses to RAS registers target wrong registers
2151159	New	Programmer	Category C	Multi-Core Cortex-R82 may deadlock when executing L2DBG operations and WFX events
2173953	Updated	Programmer	Category C	PMU event counts might be inaccurate
2224832	New	Programmer	Category C	Debug APB accesses to reserved core address is accessible when core powered off
2246499	New	Programmer	Category C	Some RAS and Debug identification registers have wrong values
2248150	New	Programmer	Category C	Accesses to non-secure EL2 physical timer registers and secure EL2 virtual timer registers are not UNDEFINED
2254257	New	Programmer	Category C	Read of ERRGSR might return incorrect value
2261658	New	Programmer	Category C	A single bit hard error on poisoned TCM data could cause a deadlock

27-Jul-2021: Changes in document version v2.0

ID	Status	Area	Category	Summary
2215640	New	Programmer	Category A	A cacheable write to LLRAM could cause data corruption of a Main Master cacheline
2113395	New	Programmer	Category B	Incorrect value could be reported in AFSR0_ELx for external errors on store-exclusive and load atomic instructions
2114617	New	Programmer	Category B	Cortex-R82 could deadlock in the presence of an L2 Cache Data RAM ECC Error
2130548	New	Programmer	Category B	An ECC error could cause a deadlock under certain conditions
2177521	New	Programmer	Category B	Physical interrupts might not be taken
2188383	New	Programmer	Category B	ECC error might cause wrong execution of certain system register access instructions
2110865	New	Programmer	Category C	RAM ECC errors or poison during core power off transitions may lead to deadlock
2131519	New	Programmer	Category C	RAS Fault Injection to shared memory may cause deadlock or data corruption
2131811	New	Programmer	Category C	DSB does not guarantee the observability of the effects of the GIC CPU interface register accesses
2140942	New	Programmer	Category C	Incorrect value reported in RAS registers on L2 cache ECC errors
2169550	New	Programmer	Category C	ETM trace might not report certain direct branch instructions
2170009	New	Programmer	Category C	Error injection via ERROPFGCTL might occur at the wrong time
2173953	New	Programmer	Category C	PMU event counts might be inaccurate
2215960	New	Programmer	Category C	An atomic with acquire semantics may be observed before an earlier store-release to TCM or LLPP
2218751	New	Programmer	Category C	Data cache maintenance operations by set/way targeting a 4MB L2 cache might affect incorrect cache index
2226045	New	Programmer	Category C	ATB flush is unreliable

26-Mar-2021: Changes in document version v1.0

No errata in this document version.

Errata summary table

The errata associated with this product affect the product versions described in the following table.

ID	Area	Category	Summary	Found in versions	Fixed in version
2215640	Programmer	Category A	A cacheable write to LLRAM could cause data corruption of a Main Master cacheline	r0p0	r0p1
2113395	Programmer	Category B	Incorrect value could be reported in AFSR0_ELx for external errors on store-exclusive and load atomic instructions	r0p0	r0p1
2114617	Programmer	Category B	Cortex-R82 could deadlock in the presence of an L2 Cache Data RAM ECC Error	r0p0	r0p1
2130548	Programmer	Category B	An ECC error could cause a deadlock under certain conditions	r0p0	r0p1
2177521	Programmer	Category B	Physical interrupts might not be taken	r0p0	r0p1
2188383	Programmer	Category B	ECC error might cause wrong execution of certain system register access instructions	r0p0	r0p1
2272083	Programmer	Category B	Utility bus accesses to RAS registers target wrong registers	r0p0	r0p1
2275980	Programmer	Category B	Cluster transitions to a lower power mode might cause deadlocks in the presence of Core transitions to higher power modes	r0p0, r0p1, r0p2, r1p0, r1p1	Open
2284596	Programmer	Category B	Interrupt can be routed to a Core in FULL_RET although SCLK Q-channel is not in QRUN	r0p0, r0p1	r0p2
2290922	Programmer	Category B	Link register might be incorrect after taking an SError interrupt exception or entering Debug state	r0p0, r0p1	r0p2
2295080	Programmer	Category B	Shared register writes do not respect context synchronization barriers	r0p0, r0p1	r0p2
2309270	Programmer	Category B	Transition to FULL_RET is denied if IMP_CPUPWRCTLR_EL1.FPURET > 0	r0p0, r0p1	r0p2
2324971	Programmer	Category B	Critical error interrupt will not be indicated for UC error on Error Records 1, 2 and 3	r0p0, r0p1	r0p2
2329077	Programmer	Category B	Cluster PMU register interface has limited functionality	r0p0, r0p1	r0p2

ID	Area	Category	Summary	Found in versions	Fixed in version
2330574	Programmer	Category B	Transition from L2 cache FULL RAM ON to DL1ONLY operating mode might cause a deadlock	r0p0, r0p1	r0p2
2342667	Programmer	Category B	An ECC error during a power-down sequence might affect execution of FP/AdvSIMD instructions	r0p0, r0p1	r0p2
2344782	Programmer	Category B	DSB might not ensure completion of previous stores when multiple contexts are using the same port	r0p0, r0p1	r0p2
2413308	Programmer	Category B	Read of CNTKCTL_EL1, CNTHCTL_EL2 or CNTVOFF_EL2 might return the value from last interrupted write	r0p0, r0p1, r0p2	r1p0
2416441	Programmer	Category B	Clock is not gated correctly when the core is in the Full retention power mode	r0p2	r1p0
2455174	Programmer	Category B	Cluster MEM_RET is not sustained	r0p0, r0p1, r0p2	r1p0
2487068	Programmer	Category B	Cluster IRQs may be lost in the presence of cluster MEM_RET and OFF power transitions	r0p0, r0p1, r0p2	r1p0
2639772	Programmer	Category B	Turning a core ON while the cluster is being powered OFF may deadlock	r0p0, r0p1, r0p2	r1p0
2666600	Programmer	Category B	CLUSTERPWRDN.PWRDWN is not functional	r0p0, r0p1, r0p2	r1p0
2684598	Programmer	Category B	Software step might go to wrong state	r0p0, r0p1, r0p2	r1p0
2691481	Programmer	Category B	Memory accesses can use old values of some of the Generic System control registers	r0p0, r0p1, r0p2	r1p0
2725097	Programmer	Category B	Interrupting a DSB might cause the DSB for earlier TLBI/IC maintenance operations to fail	r1p0	r1p1
2772412	Programmer	Category B	DFB does not wait for completion of IC/TLBI from other contexts	r1p0	r1p1
2776909	Programmer	Category B	A write to LLRAM following a hardware access flag update could result in incorrect translation	r1p0	r1p1
2795835	Programmer	Category B	A translation table walk may raise an unexpected abort	r1p0	r1p1
2110865	Programmer	Category C	RAM ECC errors or poison during core power off transitions may lead to deadlock	r0p0	r0p1
2131519	Programmer	Category C	RAS Fault Injection to shared memory may cause deadlock or data corruption	r0p0	r0p1

ID	Area	Category	Summary	Found in versions	Fixed in version
2131811	Programmer	Category C	DSB does not guarantee the observability of the effects of the GIC CPU interface register accesses	r0p0	r0p1
2140942	Programmer	Category C	Incorrect value reported in RAS registers on L2 cache ECC errors	r0p0	r0p1
2151159	Programmer	Category C	Multi-Core Cortex-R82 may deadlock when executing L2DBG operations and WFX events	r0p0	r0p1
2169550	Programmer	Category C	ETM trace might not report certain direct branch instructions	r0p0	r0p1
2170009	Programmer	Category C	Error injection via ERROPFGCTL might occur at the wrong time	r0p0	r0p1
2173953	Programmer	Category C	PMU event counts might be inaccurate	r0p0	r0p1
2215960	Programmer	Category C	An atomic with acquire semantics may be observed before an earlier store-release to TCM or LLPP	r0p0	r0p1
2218751	Programmer	Category C	Data cache maintenance operations by set/way targeting a 4MB L2 cache might affect incorrect cache index	r0p0	r0p1
2224832	Programmer	Category C	Debug APB accesses to reserved core address is accessible when core powered off	r0p0	r0p1
2226045	Programmer	Category C	ATB flush is unreliable	r0p0	r0p1
2246499	Programmer	Category C	Some RAS and Debug identification registers have wrong values	r0p0	r0p1
2248150	Programmer	Category C	Accesses to non-secure EL2 physical timer registers and secure EL2 virtual timer registers are not UNDEFINED	r0p0	r0p1
2254257	Programmer	Category C	Read of ERRGSR might return incorrect value	r0p0	r0p1
2261658	Programmer	Category C	A single bit hard error on poisoned TCM data could cause a deadlock	r0p0	r0p1
2284986	Programmer	Category C	PMU event counts might be inaccurate	r0p0, r0p1	r0p2
2286314	Programmer	Category C	Access to TRCSEQEVR3 is not UNDEFINED	r0p0, r0p1	r0p2
2313135	Programmer	Category C	Cacheable accesses to LLRAM might deadlock in the presence of an ECC error	r0p0, r0p1	r0p2

ID	Area	Category	Summary	Found in versions	Fixed in version
2317561	Programmer	Category C	Halting step syndrome might be wrong on stepping a Load-Exclusive instruction	r0p0, r0p1	r0p2
2330237	Programmer	Category C	Multi-issuing control with IMP_CPUACTLR_EL1.MI = 0b010 is wrong	r0p0, r0p1	r0p2
2338818	Programmer	Category C	IFU Cache errors might report incorrect BANK to the RAS node	r0p0, r0p1	r0p2
2339884	Programmer	Category C	Cluster CTI trigger outputs are not reaching cluster ELA CTITRIGINs	r0p0, r0p1	r0p2
2358852	Programmer	Category C	Pointer authentication key registers are not initialized	r0p0, r0p1	r0p2
2359684	Programmer	Category C	Some unallocated debug and trace System registers might be trapped by HCR_EL2.TIDCP	r0p0, r0p1	r0p2
2370219	Programmer	Category C	Use of debug related power states can result in deadlock	r0p0, r0p1	r0p2
2375011	Programmer	Category C	PSTATE.SS not restored correctly if OSLK is set to 1 just before debug exit	r0p0, r0p1	r0p2
2384696	Programmer	Category C	DPU returns wrong value on MRS to DLR_ELO	r0p0, r0p1	r0p2
2386524	Programmer	Category C	Defective RAS registers	r0p0, r0p1	r0p2
2416442	Programmer	Category C	Multiple double bit ECC errors on core powerdown might deadlock	r0p2	r1p0
2440118	Programmer	Category C	Some PMU events count incorrectly	r0p2	r1p0
2445341	Programmer	Category C	Cache initialization and reset of register fields with UNKNOWN values do not work as expected after Debug recovery	r0p0, r0p1, r0p2	r1p0
2604629	Programmer	Category C	ETM data trace values for ST atomics are incorrect	r0p0, r0p1, r0p2	r1p0
2617173	Programmer	Category C	An external atomic receiving a SLVERR or DECERR might not raise an asynchronous abort	r0p0, r0p1, r0p2	r1p0
2618272	Programmer	Category C	When toggling SPIDEN or DBGEN pins close to a core reset, the system might deadlock	r0p0, r0p1, r0p2	r1p0
2652888	Programmer	Category C	Receiving poison on invalid data lanes might result in a data abort when poison is not supported	r0p0, r0p1, r0p2, r1p0	r1p1
2656238	Programmer	Category C	New interrupts might not be taken after an atomic instruction is interrupted	r0p2	r1p0

ID	Area	Category	Summary	Found in versions	Fixed in version
2659537	Programmer	Category C	Spurious ECC error might be reported when changing operating mode from DL1ONLY to FULL RAM	r0p0, r0p1, r0p2	r1p0
2661859	Programmer	Category C	Incorrect value reported in RAS registers on LLRAM receiving poison when ECC is not supported	r0p0, r0p1, r0p2	r1p0
2693781	Programmer	Category C	Quality of Service is applied to Main Manager accesses when disabled	r0p1, r0p2	r1p0
2694966	Programmer	Category C	Fault handling interrupt can cause power transition to deadlock	r0p0, r0p1, r0p2	r1p0
2719885	Programmer	Category C	Software step exception might set the ESR_ELx.ISV to a wrong value	r0p0, r0p1, r0p2, r1p0	r1p1
2729228	Programmer	Category C	Debug accesses via APB are not supported in EMU power states	r0p0, r0p1, r0p2, r1p0	r1p1
2729398	Programmer	Category C	L2RDLAT and L2WRLAT fields in IMP_CLUSTERACTLR_EL1 are hardcoded	r0p0, r0p1, r0p2, r1p1	r1p1
2747728	Programmer	Category C	Some cluster PMU events are incorrect	r0p0, r0p1, r0p2, r1p0	r1p1
2753234	Programmer	Category C	An external atomic receiving poison might not raise an asynchronous abort	r0p0, r0p1, r0p2, r1p0	r1p1
2763783	Programmer	Category C	Speculative accesses might still be made when LLRAM is disabled	r0p0, r0p1, r0p2, r1p0	r1p1
2773193	Programmer	Category C	32-bit accesses to ERR<n>MISCO (n= 1-6) will not work as expected	r0p0, r0p1, r0p2, r1p0	r1p1
2780544	Programmer	Category C	Reset of register fields with UNKNOWN values does not work as expected in the presence of Debug recovery mode	r0p0, r0p1, r0p2, r1p0, r1p1	Open
2788717	Programmer	Category C	An interrupted atomic operation with bus error to LLRAM raised an unexpected asynchronous abort	r1p0	r1p1
2798198	Programmer	Category C	Incorrect system reset behavior under MEM_RET and MEM_RET_EMU modes for IMP_CLUSTERACTLR_EL1.UBACCLVL	r1p1	Open
2842855	Programmer	Category C	AFSR0_ELx might have stale value after taking an SError interrupt	r0p0, r0p1, r0p2, r1p0, r1p1	Open
2847045	Programmer	Category C	External read of TCM while CPUHALT<m> is HIGH might see unexpected ECC errors	r1p0, r1p1	Open

Errata descriptions

Category A

2215640

A cacheable write to LLRAM could cause data corruption of a Main Master cacheline

Status

Affects: Cortex-R82

Fault Type: Programmer Category A

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor has a *Main Master* (MM) port and a *Low-latency RAM* (LLRAM) port that can both be cached in the L1 data cache. When both ports are used by software without intervening barriers, this erratum could cause corruption of data held in the L1 data cache for the MM port.

Configurations Affected

This erratum affects all configurations of the Cortex-R82 processor with **NUM_CORES** ≥ 2 and the LLRAM port configured (**CFGLLRAMIMP**=1) and in use.

Conditions

This erratum occurs when the following sequence of conditions is met:

1. A store to the LLRAM port is executed and the cacheline for this data is stored in the L1 data cache
2. Another core in the cluster performs a read of the cacheline for the LLRAM store, setting the cacheline to a shared state
3. A linefill to the MM port occurs to the same set and way as the LLRAM cacheline
4. When in a shared state, the LLRAM cacheline is invalidated from the L1 data cache. This could occur due to:
 - An *Error Correcting Code* (ECC) error in the *LLRAM Coherency Unit* (LCU) duplicate L1 tag RAMs
 - The linefill to the MM port to the same set and way above
5. Another store is executed to the same LLRAM cacheline at the same time as the cacheline is invalidated, but to a different 128-bit aligned region from the original store
6. The above conditions occur along with specific micro-architectural conditions with precise timing

Implications

When this erratum occurs, the contents of a cacheline in the L1 data cache holding data for the MM port could be overwritten with incorrect data.

Workaround

There is no workaround for this erratum.

Category A (rare)

There are no errata in this category.

Category B

2113395

Incorrect value could be reported in AFSRO_ELx for external errors on store-exclusive and load atomic instructions

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor reports additional information on faults in the AFSRO_EL1 and AFSRO_EL2 registers. This includes information about the memory port that the fault is associated with and if the fault is associated with data or not.

If an external uncorrectable *Error Correcting Code* (ECC) error occurs on the *Main Master* (MM) port, an atomic instruction to Normal cacheable memory targeting the MM port should report the fault type as Data (AFSRO_ELx.TYPE = 0b0000). However when this erratum occurs, the fault type is always reported as other (AFSRO_ELx.TYPE = 0b0011).

If an external error occurs on the MM port, an exclusive instruction to Normal cacheable memory targeting the MM port should report the port as MM (AFSRO_ELx.PORT = 0b0000). However when this erratum occurs, the port is always reported as **UNKNOWN** (AFSRO_ELx.PORT = 0b0111).

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when all of the following conditions are met:

- A core executes a store-exclusive instruction or a load atomic instruction (for example where the destination register is not the zero register)
- The store-exclusive instruction or the load atomic instruction is to the MM port with Normal Inner Write-Back, Outer Write-Back Cacheable attributes
- The data is not contained in the L1 data cache
- If the instruction is a load atomic instruction and all of the following are true:
 - The data is contained in the L2 cache
 - The data has an uncorrectable ECC error
- If the instruction is a store-exclusive instruction and one of the following conditions is true:

- The data is contained in the L2 cache and has an uncorrectable ECC error
- The data is not in the L2 cache and receives an external error in response to the bus request on the MM port

Implications

If this erratum occurs, then the value reported in the AFSRO_ELx register could be incorrect and be more general than intended.

Workaround

To avoid this erratum, software can confirm:

- If the port is affected by this erratum by using the information in the FAR_ELx register. The information in the FAR_ELx register can be used to show the address the error occurred on and compare it against the system memory map.
- If a data error has occurred by reading the RAS record error registers 3-5

2114617

Cortex-R82 could deadlock in the presence of an L2 cache data RAM ECC error

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor supports RAM protection for single bit and double bit *Error Correcting Code* (ECC) errors on the L2 cache data RAMs. In some cases, an ECC error in the L2 cache data RAMs causes the processor to deadlock.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor configured to include RAM protection (**RAM_PROTECTION** configuration parameter is set to 1).

Conditions

This erratum occurs when all the following conditions are met:

- RAM protection is enabled (IMP_CLUSTERMEMPROTCTLR_EL1.MEMPROTEN=1)
- The L2 cache data RAM internal data buffering is full
- Both read and write accesses to the L2 cache data RAM are ongoing
- A single bit or double bit ECC error occurs on a L2 cache data RAM read request

Implications

If this erratum occurs, the processor deadlocks.

Workaround

To avoid this erratum, disable the RAM protection for shared memories by setting the IMP_CLUSTERMEMPROTCTLR_EL1.MEMPROTEN to 0.

Because this erratum occurs when there is an ECC error and because the ECC errors are not expected in sample silicon, it is still practical to evaluate the performance on sample silicon.

2130548

An ECC error could cause a deadlock under certain conditions

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor has dedicated hardware to forward data from a load instruction to a subsequent load or store address to decrease load-to-use latency. The processor also supports a load and store instruction to be issued together.

Under certain conditions, the combination of these features and an *Error Correcting Code (ECC)* error being detected in the L1 data cache, *Instruction Tightly Coupled Memory (ITCM)*, or *Data Tightly Coupled Memory (DTCM)* can cause the processor to deadlock.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor configured to include RAM protection (**RAM_PROTECTION** configuration parameter is set to 1).

Conditions

This erratum occurs when all the following conditions are met:

- RAM protection is enabled (IMP_MEMPROTCTLR_EL1.MEMPROTEN=1)
- The following instructions exist in a program:
 - A load instruction A
 - A load instruction B
 - A store instruction C
- The destination register of the load instruction A is the same as the address register for the store instruction C. Intermediate instructions between A and C do not modify this register.
- Instructions A and B are consecutive in program order, or only have instructions that are not load/store instructions between them. If the instructions A and B are not consecutive, there must be less than eight instructions between them.
- Instructions B and C are consecutive in program order, or have a single instruction between them which can be triple-issued with instructions B and C.
- There is an ECC error in the 128-bit aligned region of memory targeted by the load instruction A, and one of the following applies:
 - The ECC error is suppressed by data forwarded by a store instruction preceding write to the same address
 - The ECC error occurs in a word that is not accessed by the load instruction

- The load instruction B does not take a synchronous abort

Implications

If this erratum occurs, the processor deadlocks.

Workaround

To avoid this erratum, set the IMP_CPUACTLR_EL1.FPC to 0. This has a slight performance impact for some workloads.

Because this erratum occurs when there is an ECC error and because the ECC errors are not expected in sample silicon, it is still practical to evaluate the performance with IMP_CPUACTLR_EL1.FPC=1 for sample silicon.

2177521

Physical interrupts might not be taken

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor implements the *Generic Interrupt Controller* (GIC) CPU interface.

Because of this erratum, under certain conditions which involve heavy interrupt load, a processor core may stop taking new physical interrupts.

Configurations affected

The erratum affects all configurations of the Cortex-R82 processor when used with the GIC-625 interrupt controller.

Conditions

This erratum occurs when all the following conditions are met:

- The GIC CPU interface is enabled (**GICCDISABLE** signal LOW at reset)
- Group 1 physical interrupts are enabled
- The core has taken no less than four Group 1 physical interrupts, and before each of these there was a close-by physical interrupt acknowledged by the core

Implications

If this erratum occurs, the core might stop taking new physical interrupts.

Workaround

To avoid the erratum, set GICR0_FCTLR.ECP to 0 to disable combined packets in the Redistributor before waking-up the cores. This might increase the interrupt latency in certain cases.

2188383

ECC error might cause wrong execution of certain System register access instructions

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor implements the *Reliability, Availability, and Serviceability* (RAS) Extension as defined in the Arm architecture.

Because of this erratum, the read of certain System registers might return the wrong value or the write might be ignored after a change to the error status registers for the error records 0 to 2.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor configured to include RAM protection (**RAM_PROTECTION** configuration parameter is set to 1).

Conditions

This erratum occurs when all the following conditions are met:

- Core RAM protection is enabled with IMP_MEMPROTCTLR_EL1.MEMPROTEN = 1
- RAS error reporting is enabled with ERROCTLR.ED = 1
- One of the ERR<n>STATUS.V, where n is 0 to 2, is changed due to either a new *Error Correcting Code* (ECC) error or a software write
- At the same time, the core also executes a read/write to a System register belonging to one of the trace registers, the generic timer registers, the IMP_CLUSTER* registers, or the RAS Error Record registers 3 to 5

Implications

If this erratum occurs, the core might read **UNKNOWN** value from the System register or the write might be ignored.

Workaround

To avoid this erratum for the test silicon, set the ERROCTLR.ED to 0 to disable RAS error reporting.

2272083

Utility bus accesses to RAS registers target wrong registers

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor implements the *Reliability, Availability, and Serviceability* (RAS) Extension as defined in the Arm architecture. The Cortex-R82 processor implements 6 error records.

Because of this erratum, the accesses to the RAS registers in error records 0 to 2 over the Utility bus will target wrong registers.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when software accesses to the RAS registers in error records 0 to 2 over the Utility bus.

Implications

If this erratum occurs, software might read incorrect values or will write to wrong RAS registers in error records 0 to 2.

Workaround

To avoid this erratum, software can shift the address offset right by 2 when accessing RAS registers in error records 0 to 2.

2275980

Cluster transitions to a lower power mode might cause deadlocks in the presence of Core transitions to higher power modes

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r0p1, r0p2, r1p0, and r1p1. Open

Description

The Cortex-R82 processor implements individual power domains at the cluster and core levels. Because of this erratum, cluster transitions to a lower power mode might deadlock in the presence of simultaneous Core transitions to a higher power mode.

Configurations affected

This erratum affects all configurations.

Conditions

This erratum occurs when all the following conditions are met:

- The Cluster is transitioning to a lower power mode, particularly, ON->OFF, ON->OFF_EMU or ON->MEM_RET
- A Core in the system is requested to transition to a higher power mode, particularly, OFF->ON or OFF_EMU->ON
- The requests overlap, and additional complex microarchitectural timing conditions occur

Implications

When this erratum occurs, the system deadlocks.

Workaround

For systems without a System Control Processor (or an equivalent agent capable of programming the PPU):

- Set IMP_CPUPWRCTLR_EL1.PWRDN == 0 for at least 1 core in the system

For systems with a System Control Processor (or an equivalent agent capable of programming the PPU):

- For static power transitions:
 - Ensure a previous transition has completed by polling the associated PPU_PWSR.PWR_STATUS (or CLUSTERPPU_PWSR.PWR_STATUS) and ensuring the previously requested power transition completed before issuing a power mode transition to another device
- For dynamic power transitions, it is impossible to use both Core and Cluster simultaneously, but they can be used individually:
 - To use dynamic power modes in a core, disable cluster dynamic power transitions
CLUSTERPPU_PWPR.PWR_DYN_EN == 0
 - To use dynamic power modes in the cluster when the cores are OFF:
 - Disable core dynamic power transitions by setting PPU_PWPR.PWR_DYN_EN == 0 for all cores, enable cluster dynamic power transitions CLUSTERPPU_PWPR.PWR_DYN_EN == 1
 - To restore a core to ON (for example, to answer interrupts), the cluster dynamic power transitions must first be disabled (CLUSTERPPU_PWPR.PWR_DYN_EN == 0)

2284596

Interrupt can be routed to a Core in FULL_RET although SCLK Q-channel is not in QRUN

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r0p1. Fixed in r0p2.

Description

The Cortex-R82 processor implements an SCLK Q-channel that allows SCLK to be gated when all cores are in either OFF or FULL_RET power modes. The processor can also receive external interrupts while in this power mode.

Because of this erratum, in the presence of an interrupt to a core in FULL_RET, the system may deadlock.

Configurations affected

This erratum affects configurations with Full Retention (auxiliary configuration parameter FULL_RET set to 1).

Conditions

This erratum occurs when all the following conditions are met:

- All cores are in FULL_RET.
- SCLK Q-channel is in QSTOPPED mode - but SCLK is still present.
 - If the SCLK Q channel controller used in the design is one that does not provide SCLK at any time during QSTOPPED, this erratum does not apply.
- An interrupt arrives in the system.

Implications

When this erratum occurs, the system deadlocks.

Workaround

To avoid this erratum, disable the SCLK Q channel by setting IMP_CLUSTERACTLR_EL1.SCLKQ to 0.

2290922

Link register might be incorrect after taking an SError interrupt exception or entering Debug state

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r0p1. Fixed in r0p2.

Description

According to the Arm architecture, the link register (ELR_ELx or DLR_ELO) value should reflect the address to return to after taking an SError interrupt exception or restart address after entering the Debug state. The link register value should also account for any already executed instructions.

Because of this erratum, the link register value might not be set to the preferred return address after taking an SError interrupt exception or the preferred restart address after entering the Debug state.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when all the following conditions are met:

- A load instruction and a store instruction are dual-issued
- The older access is a store or a load that has completed
- One of the following occurs before the younger access has completed:
 - Debug state is entered
 - An SError interrupt exception is taken

Implications

If this erratum occurs, the value of the link register will indicate the older instruction that has already been executed. If returning from the SError interrupt exception or exiting the Debug state using the same value of the link register, the instruction pointed to by the link register will be executed including repeating any memory accesses by the instruction.

- If the memory access is to Device memory this could lead to a repeated access.
- If the memory access is a write to Normal memory this could violate single-copy atomicity.

Workaround

No workaround is expected to be required for the implications from taking an SError interrupt exception. This is because the Cortex-R82 processor will enter the Uncontainable error state after taking an SError interrupt exception so no recovery will be possible. If more information is required, then contact Arm support for more details.

To avoid the implications from entering Debug state, software can set `IMP_CPUACTLR_EL1.LSDI` to 1 to disable dual-issuing a load with a store instruction. This will have a small performance impact so should be used only when doing external debug.

2295080

Shared register writes do not respect context synchronization barriers

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in rOp0, rOp1. Fixed in rOp2.

Description

The Cortex-R82 processor implements a set of system registers outside of the core power domain that software can access. A context synchronization event should create a barrier that ensures all system register writes are observable after the barrier.

Because of this erratum, for a set of system registers outside the core, this barrier is not be respected.

Configurations affected

This erratum affects all configurations.

Conditions

This erratum occurs when the following conditions are met:

- A core sends a write to one of the following system registers:
 - Any register whose name starts with IMP_CLUSTER*
 - Any RAS register relevant to the Shared Nodes 0, and 4-6
- A context synchronization event happens
- An instruction is executed that would observe the system configuration changes
- Additional complex microarchitectural conditions occur

Implications

When this erratum occurs, the effects of the system register write are not guaranteed to be observed after the context synchronization event.

Workaround

To work around this erratum, when there are changes to any IMP_CLUSTER* register or RAS register relevant to the Shared Nodes 0, and 4-6 and before executing instructions that are expected to observe the changes to the system registers software should read IMP_CLUSTERCFR_EL1.

2309270

Transition to FULL_RET is denied if IMP_CPUPWRCTLR_EL1.FPURET > 0

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0, 0p1. Fixed in r0p2..

Description

In cases where both Full Retention (FULL_RET) and Functional Retention (FUNC_RET) are enabled in IMP_CPUPWRCTLR_EL1, it is not possible to transition to Full Retention (FULL_RET).

Configurations affected

This erratum affects configurations of the Cortex-R82 processor that have the Advanced SIMD and floating-point support enabled (NEON_FpM == 1) and support both Functional Retention and Full Retention (auxiliary configuration parameters FUNC_RET and FULL_RET both set to 1).

Conditions

This erratum occurs when the following conditions are met:

- IMP_CPUPWRCTLR_EL1.FPURET > 0
- IMP_CPUPWRCTLR_EL1.WFIRET > 0 or IMP_CPUPWRCTLR_EL1.WFERET > 0
- The core enters WFE or WFI
- The timer ticks configured in IMP_CPUPWRCTLR_EL1 are such where both FUNC_RET and FULL_RET are possible

Implications

If this erratum occurs, the core would be incapable of moving into FULL_RET.

Workaround

Whenever entering Full Retention (FULL_RET) is desirable, IMP_CPUPWRCTLR_EL1.FPURET must be set to 0 either permanently (disabling functional retention altogether) or temporarily right before executing WFI/WFE.

2324971

Critical error interrupt will not be indicated for UC error on Error Records 1, 2 and 3

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0 and r0p1. Fixed in r0p2.

Description

The Cortex-R82 processor supports the Critical error interrupt from the *Reliability, Availability, and Serviceability* (RAS) Extension. Due to this erratum a critical error interrupt will not be generated if an *Uncontainable Error* (UC) occurs in one of the components associated with Error Record 1, 2 and 3.

Configurations Affected

This erratum affects all configurations of the Cortex-R82 processor configured to include RAM protection (**RAM_PROTECTION** configuration parameter is set to 1).

Conditions

This erratum occurs when all the following conditions are met:

- Critical error interrupts are enabled for error records 1, 2 and 3 (**ERR1CTLR.CI** is set to 1).
- A double bit error occurs on the L1 data cache dirty RAM.

Implications

When this erratum occurs, no critical error interrupt will be generated.

Workaround

In order to work around this erratum, the critical error interrupt should not be enabled and set **ERR1CTLR.UI** to 1 to enable the error recovery interrupt. On handling an error recovery interrupt the error record register will indicate if a critical error has occurred in **ERR<n>STATUS.CI**.

2329077

Cluster PMU register interface has limited functionality

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r0p1. Fixed in r0p2.

Description

Cortex-R82 includes an **IMPLEMENTATION DEFINED** Cluster *Performance Monitoring Unit* (Cluster PMU) that monitors events in the processor cluster. The Cluster PMU can be accessed either by software running on any of the processor cores using System registers, or by an external agent through the Debug port.

Because of this erratum, the Cluster PMU functionality is limited.

Configurations affected

This erratum affects all configurations.

Conditions

In the case of Cluster PMU accesses through the Debug port, this erratum occurs when one of the following conditions is met:

- Reads of any register with a name starting with CLUSTERPMU_
- Writes to CLUSTERPMU_PMEVCNTR<n>_EL1, CLUSTERPMU_PMOVSSET_EL1, CLUSTERPMU_PMOVSCLR_EL1, CLUSTERPMU_PMINTENSET_EL1, or CLUSTERPMU_PMINTENCLR_EL1
- Resetting the counters by writing 1 to CLUSTERPMU_PMCR_EL1.P

In the case of Cluster PMU accesses through the **IMPLEMENTATION DEFINED** System registers, this erratum occurs when one of the following conditions is met:

- Reads of any register with a name starting with IMP_CLUSTERPM
- Resetting the counters by writing 1 to IMP_CLUSTERPMCR_EL1.P

Implications

When this erratum occurs:

- Reads of the registers that are in the Conditions of this erratum will be incorrect

- Writes to the registers that are in the Conditions of this erratum will have no effect

Workaround

For accesses through the Debug port:

- Reading any of the following six registers CLUSTERPMU_PMEVTYPER<n>EL1, CLUSTERPMU_PMOVSET_EL1, CLUSTERPMU_PMOVSLR_EL1, CLUSTERPMU_PMINTENSET_EL1, CLUSTERPMU_PMINTENCLR_EL1, CLUSTERPMU_PMCR_EL1, is not possible. To read any other register with a name that starts with CLUSTERPMU_, first write 0 to CLUSTERPMU_PMEVTYPER<n>EL1 (n= 0-5), and then perform the read.
- Resetting the counters through CLUSTERPMU_PMCR_EL1.P or other direct writes to the counters is not possible. A functionally equivalent behavior can be obtained by, reading the counter (bearing in mind the conditions of workaround 1) before event sampling is started and after it completed, and then performing a difference to obtain the counted value.
- Memory mapped writes to CLUSTERPMU_PMOVSET_EL1, CLUSTERPMU_PMOVSLR_EL1, CLUSTERPMU_PMINTENSET_EL1, CLUSTERPMU_PMINTENCLR_EL1 are not possible.
- The EDITR can be used to execute MSR and MRS instructions while the PE is in debug state which use the workarounds listed below to perform System register accesses to the affected registers.

For accesses through the System registers:

- To read any register with a name that starts with IMP_CLUSTERPM, first write 0 to IMP_CLUSTERPMXEVTYPER_EL1 for the selected IMP_CLUSTERPMSELR_EL1.SEL
- Instead of resetting the counters by writing 1 to IMP_CLUSTERPMCR_EL1.P, write 0 to IMP_CLUSTERPMXVCNTR_EL1 while iterating all 6 counters on IMP_CLUSTERPMSELR_EL1.SEL

2330574

Transition from L2 cache FULL RAM ON to DL1ONLY operating mode might cause a deadlock

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0 and r0p1. Fixed in r0p2.

Description

The Cortex-R82 processor supports operating modes which allow powering down specific components. This includes the DL1ONLY operating mode where the L2 cache is powered down with supporting shared logic still active. If there is a stash request ongoing when the operating mode is requested to transition to DL1ONLY it could cause the processor to deadlock.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor with an L2 cache (**L2_CACHE_SIZE** > 0).

Conditions

This erratum occurs when the following sequence of conditions is met:

1. A stash request occurs from a core targeting an address in the L2 cache.
2. A transition from FULL RAM ON to DL1ONLY is requested while the stash is being handled.

Implications

If this erratum occurs, the Cortex-R82 processor deadlocks.

Workaround

In order to workaround this erratum, the DL1ONLY operating mode should not be used. This will have a small impact on power as the L2 cache will remain powered up, but a transition to the OFF power mode is not affected by this erratum so it is still possible to power down the entire cluster.

2342667

An ECC error during a power-down sequence might affect execution of FP/AdvSIMD instructions

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0 and r0p1. Fixed in r0p2.

Description

The Cortex-R82 processor implements the *Reliability, Availability, and Serviceability* (RAS) Extension as defined in the Arm architecture. The processor has the capability of detecting *Error Correcting Code* (ECC) errors in RAMs and flagging an external RAS IRQ interrupt.

The processor can also power down its cores. If the processor generates an error-triggered RAS interrupt during a core power off sequence, it will abort and revert the power down to preserve the error information.

Because of this erratum, if a power-down transition is aborted due to a RAS interrupt the processor will deadlock when attempting to execute any floating-point or Advanced SIMD instruction at any point after the power transition is aborted.

Configurations affected

This erratum affects configurations with NEON_FP = 1 and RAM_PROTECTION = 1.

Conditions

This erratum occurs when all the following conditions are met:

- ERR<n>CTLR is configured to generate an interrupt.
- Error reporting is enabled (ERR<n>CTLR.ED = 1).
- A request to transition a core to the OFF power mode is underway.
- An ECC error (real or injected) occurs, which causes the power transition to be aborted.
- The processor attempts to execute a floating-point or Advanced SIMD instruction at any point after the power transition aborts.

Implications

If this erratum occurs, the processor deadlocks.

Workaround

To avoid this erratum, set the CI, DUI, CFI, FI, and UI fields in the ERR<n>CTLR to 0 before requesting a transition to the OFF power mode for any core.

2344782

DSB might not ensure completion of previous stores when multiple contexts are using the same port

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r0p1. Fixed in r0p2.

Description

The Cortex-R82 processor provides multiple memory ports for different requirements. These ports have differing real-time characteristics and may be used by a single context or multiple contexts depending on the requirements of a particular system.

Due to this erratum, if the *Main Master* (MM) or *Low-latency RAM* (LLRAM) ports are shared across multiple contexts, then a DSB may complete before all previous stores that were performed to the shared port have completed.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when the following sequence of conditions is met:

1. Store(s) are performed in a context to the MM or LLRAM ports
2. The context is changed, this could be:
 - A change between EL0/EL1 and EL2
 - Changing the value of VSCTLR_EL2.VMID
3. Store(s) to the same port are performed without an intervening barrier
4. A DSB that is affecting stores is executed before the stores from the old context have completed

Implications

When this erratum occurs, the DSB may complete before all previous outstanding stores have completed. It is expected that in the typical use case for Cortex-R82 the hypervisor code at EL2 will be in *Tightly Coupled Memories* (TCMs) to ensure a real-time response and so this erratum would not occur.

For a context switch between multiple guest operating systems, the expected latency of the context switch means that, in most cases, previous outstanding stores will be completed prior to starting execution of a different guest operating system and this erratum will not occur.

Workaround

To avoid this erratum, a DFB can be inserted when a context switch is performed to a guest operating system which uses the MM port or LLRAM port.

Note that a DFB should not be inserted when changing to a real-time context that does not use these ports to ensure that the latency of a context switch to a real-time context is not impacted by the MM or LLRAM accesses.

2413308

Read of CNTKCTL_EL1, CNTHCTL_EL2 or CNTVOFF_EL2 might return the value from last interrupted write

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r0p1, and r0p2. Fixed in r1p0.

Description

Cortex-R82 processor implements the Generic Timer registers as defined by the Arm architecture.

Because of this erratum, read of CNTKCTL_EL1, CNTHCTL_EL2 or CNTVOFF_EL2 might return the value from last interrupted write to it.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor configured to include RAM protection (**RAM_PROTECTION** configuration parameter is set to 1).

Conditions

This erratum occurs when all the following conditions are met:

- Core RAM protection is enabled with IMP_MEMPROTCTLR_EL1.MEMPROTEN = 1
- RAS error reporting is enabled with ERR1CTLR.ED = 1
- One of the ERR<n>STATUS.V, where n is 1 to 3, is changed due to either a new *Error Correcting Code* (ECC) error or a software write
- Software writes to CNTKCTL_EL1, CNTHCTL_EL2 or CNTVOFF_EL2
- An interrupt is taken
- Software reads the last written CNTKCTL_EL1, CNTHCTL_EL2 or CNTVOFF_EL2

Implications

If this erratum occurs, the write might be interrupted so the write is not successful but the read would still return the written value.

If the software exits from the interrupt handler with the preferred return address, the write will be replayed and the read mismatch will disappear.

Workaround

No workaround is expected to be required as the write is expected to be replayed. If the software might switch contexts before returning from the interrupt handler and read one of the CNTKCTL_EL1, CNTHCTL_EL2 or CNTVOFF_EL2, this erratum can be avoided by reading the affected System register and writing the value again.

2416441

Clock is not gated correctly when the core is in the Full retention power mode

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p2. Fixed in r1p0.

Description

The Cortex-R82 processor implements per core power modes, including, optionally, Full retention (FULL_RET) which allows the core to save power while retaining the values of its memory and registers.

Because of this erratum, when a core enters the FULL_RET power mode due to a *Wait for Event* (WFE) or *Wait for Interrupt* (WFI) instruction and at the same time an event arrives targeting that core, this can prevent the clock from being gated correctly while the core is in the FULL_RET power mode.

Furthermore, some types of events could fail to wake up the core for the WFE case.

Configurations affected

This erratum affects configurations of the Cortex-R82 processor that implement Full Retention for logic retention (auxiliary configuration parameter FULL_RET set to 1).

Conditions

This erratum occurs when the following sequence of conditions is met:

1. IMP_CPUPWRCTLR_EL1.WFIRET > 0 or IMP_CPUPWRCTLR_EL1.WFERET > 0
2. A core executes a WFE or WFI instruction
3. The core transitions to the FULL_RET power mode
4. During the transition, or at any time while in the FULL_RET power state, an event arrives from another core or component in the system

Implications

If this erratum occurs, the clock to the core can toggle when the logic is in a retention state. This could cause undesirable physical effects in the power domain, including damaging the device. Additionally, depending on complex microarchitectural timing conditions, data corruption or system deadlock could also occur.

Workaround

To avoid this erratum, do not enable the FULL_RET power mode. This can be achieved by setting IMP_CPUPWRCTLR_EL1.WFIRET and IMP_CPUPWRCTLR_EL1.WFERET to their default value of 0.

2455174

Cluster MEM_RET is not sustained

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r0p1, r0p2. Fixed in r1p0..

Description

Cortex-R82 supports multiple power modes including the cluster Memory retention power mode (MEM_RET). The system can choose to go into MEM_RET power mode with Dynamic power mode transitions or Static power mode transitions. The device power requirements are indicated by internal Pactive signals.

Due to this erratum, once MEM_RET is entered, the cluster will fail to keep requesting MEM_RET.

Configurations affected

This erratum affects all configurations of Cortex-R82 processor with the L2_RET auxiliary configuration parameter set to 1.

Conditions

This erratum occurs in either of the following cases of power mode transition:

- Through a cluster Static power mode transition and when the following sequence of conditions is met:
 - a. CLUSTERPPU_PWPR.PWR_DYN_EN is set to 0
 - b. All the cores are powered down (Power OFF mode)
 - c. CLUSTERPPU_PWPR.PWR_POLICY is set to 0b0010 (MEM_RET).
- Through a cluster Dynamic power mode transition and when the following sequence of conditions is met:
 - a. CLUSTERPPU_PWPR.PWR_DYN_EN is set to 1
 - b. CLUSTERPPU_PWPR.PWR_POLICY is set to either of the following:
 - 0b0010 (MEM_RET)
 - 0b0001 (OFF_EMU) or 0b0000 (OFF).
 - c. One of the system cores sets IMP_CLUSTERPWRDN_EL1.MEMRET to 1
 - d. All the cores are powered down (Power OFF mode)

Implications

When this erratum occurs, the system might indicate an incorrect value in `CLUSTERPPU_DISR.PWR_DEVACTIVE_STATUS[3] == 0`.

In the conditions of Dynamic power mode transitions when the lowest mode is `OFF_EMU` or `OFF` (`CLUSTERPPU_PWPR.PWR_POLICY` is `0b0001` or `0b0000`) the system might unexpectedly further lower its power mode.

Workaround

To avoid this erratum:

If there is a Utility bus connection either via a *System Control Processor* (SCP) or loopback connection:

- For any power mode transition, after entering `MEM_RET` state, `CLUSTERPPU_DISR.PWR_DEVACTIVE_STATUS[3]` must not be relied upon to decide to further lower the system power mode.
- If using dynamic power mode transitions to go into `MEM_RET` state (`IMP_CLUSTERPWRDN_EL1.MEMRET == 1`), `CLUSTERPPU_PWPR.PWR_POLICY` should be set to `0b0010` (`MEM_RET`) prior to setting `IMP_CLUSTERPWRDN_EL1.MEMRET` to 1. This will avoid the system further lowering its power mode, but `CLUSTERPPU_DISR.PWR_DEVACTIVE_STATUS[3]` will still indicate an unreliable value while in `MEM_RET`.

If there is no Utility bus connection:

- `MEM_RET` should not be used (`IMP_CLUSTERPWRDN_EL1.MEMRET` should always be 0, default).

2487068

Cluster IRQs may be lost in the presence of cluster MEM_RET and OFF power transitions

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r0p1, r0p2. Fixed in r1p0.

Description

Cortex-R82 generates *Reliability, Availability, and Serviceability* (RAS) and *Performance Monitoring Unit* (PMU) IRQs at the cluster level. It also supports power modes which put the cluster in OFF or MEM_RET state.

Because of this erratum, IRQs that are generated while handling a power mode transition to OFF or MEM_RET may be lost.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when the following sequence of conditions is met:

1. One or more of the following is enabled:
 - Cluster PMU interrupts.
 - RAS Critical error interrupt, Fault handling interrupt, or Uncorrected error recovery interrupt.
2. A cluster power mode transition to OFF or MEM_RET is initialized with no cluster interrupt active (that is, nCLUSTERPMUIRQ, nCOMPLEXFAULTIRQ, nCOMPLEXERRIRQ, nCOMPLEXCRITIRQ all set to 1).
3. An event generates an enabled interrupt from step 1.

Implications

When a transition to OFF or MEM_RET completes, any pending cluster interrupt will be de-asserted, and the interrupt information lost.

Workaround

To avoid this erratum, the last powered on core in a Cortex-R82 processor should ensure that the L2 cache is cleaned via software before the core is powered off. This does not prevent missing IRQs, but it is not expected that PMU or RAS IRQs will then contain critical information, because all cores will be OFF and no dirty data will be within the L2 cache.

Alternatively prevent the cluster from going into OFF or MEM_RET power mode by keeping CLUSTERPPU_PWPR default, setting IMP_CLUSTERPWRDN_EL1.MEMRET == 0 (default) and IMP_CLUSTERPWRDN_EL1.PWRDWN == 1

2639772

Turning a core ON while the cluster is being powered OFF may deadlock

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r0p1, and r0p2. Fixed in r1p0

Description

The Cortex-R82 processor allows power of the shared cluster logic and the cores to be controlled separately. When the cluster logic is being powered OFF from the ON power state, if there is an attempt to power ON one of the cores then it could cause the processor to deadlock.

Configurations affected

This erratum affects all configurations of the Cortex-R82 process with an L2 cache (**L2_CACHE_SIZE** > 0).

Conditions

This erratum occurs when all the following conditions are met:

- All cores are powered down
- A power transition from Cluster ON to Cluster OFF is started
- One of the following conditions occur:
 - A dynamic power transition occurs to power a core up due to a COREWAKE interrupt
 - Static programming of the *Power Policy Units* (PPUs) requests one of the cores to power up
- The L2 write back overlaps with the core power transition, and additional complex microarchitectural timing conditions occur

Implications

When this erratum occurs, the system deadlocks.

Workaround

- For systems without a System Control Processor (or an equivalent agent capable of programming the PPU):
 - Set `IMP_CPUPWRCTLR_EL1.PWRDN == 0` for at least 1 core in the system.
- For systems with a System Control Processor (or an equivalent agent capable of programming the

PPU);

- For static power transitions:
 - Ensure a previous transition has completed by polling the associated PPU_PWSR.PWR_STATUS (or CLUSTERPPU_PWSR.PWR_STATUS) and ensuring the previously requested power transition completed before issuing a power mode transition to another device.
- For dynamic power transitions, it is impossible to use both Core and Cluster simultaneously, but they can be used individually:
 - To use dynamic power modes in a core, disable cluster dynamic power transitions CLUSTERPPU_PWPR.PWR_DYN_EN == 0.
 - To use dynamic power modes in the cluster, when the cores are OFF:
 - Disable core dynamic power transitions by setting PPU_PWPR.PWR_DYN_EN == 0 for all cores, enable cluster dynamic power transitions CLUSTERPPU_PWPR.PWR_DYN_EN == 1.
 - To restore a core to ON (e.g., to answer interrupts), the cluster dynamic power transitions must first be disabled (CLUSTERPPU_PWPR.PWR_DYN_EN == 0).

2666600

CLUSTERPWRDN.PWRDWN is not functional

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r0p1, and r0p2. Fixed in r1p0

Description

The Cortex-R82 processor controls its power domains through the built-in *Power Policy Unit* (PPU). It also provides software hinting for certain power transitions through CLUSTERPWRDN, for the cases when all cores are in OFF power mode.

Due to this erratum, the PPU is given wrong hints, which can result in an unexpected cluster Power Off when all cores are in an OFF power mode.

Configurations affected

This erratum affects all configurations Cortex-R82.

Conditions

- IMP_CLUSTERPWRDN_EL1.PWRDWN is set to 1 in at least one Cortex-R82 Core, that is, at least one core requests for the cluster to never power itself off.
- All the cores in Cortex-R82 are powered OFF.

Implications

If this erratum occurs, CLUSTERPPU_DISR.PWR_DEVACTIVE_STATUS will display a lower value than expected.

Additionally, if CLUSTERPPU_PWPR.PWR_DYN_EN and CLUSTERPPU_PWPR.PWR_POLICY have default values (i.e., Dynamic Power Mode transitions to OFF are enabled) the cluster will power itself OFF.

Workaround

If the Utility Bus is accessible, CLUSTERPPU_PWPR.PWR_POLICY should be set to 0b1000 (ON power mode) and no hints should be taken from the system through CLUSTERPPU_DISR.PWR_DEVACTIVE_STATUS to decide power mode transitions.

If there is no Utility Bus access, to prevent the cluster from going OFF, there should be at least one core in the system guaranteed to stay ON, i.e., a core should have `IMP_CPUPWRCTLR_EL1.PWRDN == 0` (default).

2684598

Software step might go to wrong state

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r0p1 and r0p2. Fixed in r1p0.

Description

Software step is a debug resource that a debugger can use to make the core single-step instructions.

Because of this erratum, the software step might go to a wrong state after executing an exception return instruction or exiting Debug state.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when either of the two following sequences occur:

- Sequence 1

1. Core is executing at EL2 and might be in Debug state.
2. Software step is disabled at EL2 and at target Exception level.
3. The debugger changes HCR_EL2.TGE to 1 to enable software step at target Exception level, but without Context synchronization events.
4. The debugger sets MDSCR_EL1.SS to 1.
5. The debugger executes an Exception return instruction with SPSR_EL2.SS set to 1 or exits Debug state with DSPSR_ELO.SS set to 1.
6. Software step is now in Active-not-pending state.

- Sequence 2

1. Core is executing at EL2 and might be in Debug state.
2. Software step is disabled at EL2 but enabled at target Exception level.
3. The debugger changes HCR_EL2.TGE to 0 to disable software step at target Exception level, but without Context synchronization events.
4. The debugger sets MDSCR_EL1.SS to 1.
5. The debugger executes an Exception return instruction with SPSR_EL2.SS set to 1 or exits Debug state with DSPSR_ELO.SS set to 1.
6. Software step is now in Inactive state.

7. Software step moves to Active-pending state.

Implications

If the first sequence causes this erratum, the PSTATE.SS will not be set to 1 by copying from SPSR_EL2.SS or DSPSR_ELO.SS, so the software step will enter Active-pending state instead of the expected Active-not-pending state. Software Step exception will be generated without stepping the first instruction after returning to core execution.

If the second sequence causes this erratum, the PSTATE.SS will be wrongly set to 1 by copying from SPSR_EL2.SS or DSPSR_ELO.SS. In the last condition, software step will move to Active-not-pending state rather than the expected Active-pending state.

Workaround

The debugger can execute an ISB after programming HCR_EL2.TGE before the Exception return or exiting Debug state.

2691481

Memory accesses can use old values of some of the Generic System control registers

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r0p1, r0p2. Fixed in r1p0.

Description

Software can set up characteristics of memory accesses through different System control registers. Some of these characteristics are setup using MAIR_EL2, VSTCR_EL2 and VTCR_EL2 registers. When these registers are updated by the software then, after a Context synchronization event, any following memory accesses use the updated values of these registers. This erratum causes the following memory accesses to use the old values of these registers instead of the updated values.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when the following sequence of conditions is met:

1. Memory accesses use a particular set of values from MAIR_EL2, VSTCR_EL2 and VTCR_EL2 registers
2. Software updates fields of only MAIR_EL2, VSTCR_EL2 or VTCR_EL2 registers that these memory accesses are using
3. Software executes a Context synchronization event (which could include an Exception Return (ERET))
4. New memory accesses use the updated fields of MAIR_EL2, VSTCR_EL2 and VTCR_EL2 registers

Implications

When this erratum occurs, memory accesses use old values of MAIR_EL2, VSTCR_EL2 and VTCR_EL2 registers even after updates to these registers and the Context synchronization event.

Workaround

To avoid this erratum, read and then write back the unmodified value of SCTLR_EL2 register after updating any of the MAIR_EL2, VSCTR_EL2 and VTCR_EL2 registers and before the Context synchronization event that is meant to apply the new values.

2725097

Interrupting a DSB might cause the DSB for earlier TLBI/IC maintenance operations to fail

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r1p0. Fixed in r1p1

Description:

A DSB guarantees the completion of older *TLB Invalidate* (TLBI) and/or older *Instruction Cache* (IC) maintenance operation before the DSB completes. This erratum causes the DSB to complete before the older TLBI or older IC maintenance operation completes on the *Main Manager* (MM) port.

Configurations Affected:

All configurations are affected.

Conditions:

This erratum occurs when the following sequence of conditions are met:

1. TLBI or IC maintenance operation is executed to MM port
2. IC maintenance operation is executed to *Low-latency RAM* (LLRAM) port
 - a. Note: (1) and (2) can be in either order for this erratum to occur
3. DSB is executed
4. DSB is interrupted before it completes
5. New TLBI or IC maintenance operation is executed to MM port
6. DSB is executed
7. The above conditions occur along with specific micro-architectural conditions with precise timing

Implications:

Memory access using a TLB entry that has been invalidated by the subsequent TLBI, could not have been completed when the DSB to MM finishes. Instruction cache access that should see the effect of previous IC maintenance operation could not see that affect. Most of the software are not expected to use MM and LLRAM ports in the manner that can cause this issue.

Workaround:

This erratum can be avoided if a DSB is executed after sending the operation (TLBI/IC maintenance to MM or IC maintenance to LLRAM port) to each port, instead of executing the DSB after sending the operation to both ports.

2772412

DFB does not wait for completion of IC/TLBI from other contexts

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r1p0. Fixed in r1p1

Description

The *Data Full Barrier* (DFB) instruction is intended to ensure completion of memory accesses from all contexts. Due to this erratum, DFB may not ensure completion of IC or TLBI operations that were executed in a different context.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs if the following sequence of events occurs:

1. A TLBI or IC operation is executed in an Exception level lower than EL2
2. An exception is taken to EL2
3. A DFB is executed in EL2

Implications

If this erratum occurs, the DFB may complete before the preceding TLBI or IC operation. (On returning to the original context a DSB SY will wait for completion of the TLBI or IC, so the original context will not be able to observe old translation tables or old instructions.)

Workaround

This erratum can be avoided by applying the following patch. DFB is not expected to execute often, so any performance impact should be minimal. The code sequence should be applied early in the boot sequence prior to any IC or TLBI ops being executed.

```
mov x0, 0
msr s3_2_c15_c8_0, x0 // IMP_CPUPSELR_EL1
ldr x0, =0xFFFFFFFF
msr s3_2_c15_c8_3, x0 // IMP_CPUPMR_EL1
ldr x0, =0xD5033C9F
msr s3_2_c15_c8_2, x0 // IMP_CPUPOR_EL1
```

```
ldr x0, =0x20100101
msr s3_2_c15_c8_1, x0 // IMP_CPUPCR_EL1
isb
```

2776909

A write to LLRAM following a hardware access flag update could result in incorrect translation

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r1p0. Fixed in r1p1

Description

When the hardware access flag update is enabled, if there is a context change to a context using *Protected Memory System Architecture* (PMSA) and a write to *Low Latency Random Access Memory* (LLRAM) is executed then it is possible for an incorrect translation result to be cached. Subsequent accesses to the address for which the hardware access flag update was performed could receive an incorrect translation.

Configurations Affected

This erratum affects all configurations of the Cortex-R82 which include *Virtual Memory System Architecture* (VMSA).

Conditions

This erratum occurs if the following sequence of events occurs:

1. An instruction is executed which requires a hardware access flag update
2. An interrupt occurs which is taken to EL2
3. A write to LLRAM is executed in a PMSA context (either EL2 or after context switching to a new ELO/1 PMSA context)
4. Specific micro-architectural conditions occur

Implications

When this erratum occurs, an incorrect translation could be cached in the *Translation Lookaside Buffer* (TLB). This could result in incorrect permissions or attributes used for subsequent accesses to the same address for which the access flag update was performed.

Workaround

To work around this erratum, a DFB instruction should be executed in EL2 after taking an exception from a VMSA context. This DFB instruction should be executed before any writes to LLRAM are performed.

2795835

A translation table walk may raise an unexpected abort

Status

Affects: Cortex-R82

Fault Type: Programmer Category B

Fault Status: Present in r1p0. Fixed in r1p1

Description

Due to this erratum, a translation that is performed for an instruction fetch or data side access might return a translation error that causes an abort to be taken. However, this can only occur when a load exclusive is executed to the same address as the translation table walk.

Configurations Affected

This erratum affects all configurations of the Cortex-R82 which include *Virtual Memory System Architecture* (VMSA).

Conditions

This erratum occurs when the following sequence of conditions are met:

1. A load exclusive is executed to the *Main manager* (MM) port:
 - This load is to memory with Normal Inner Write-Back, Outer Write-Back Cacheable attributes
 - This load misses in the L1 cache but the data is held in the L2 cache
 - This might be speculative
2. A translation table walk occurs which is to the same address as the load exclusive was accessing, this could be for:
 - An instruction fetch
 - A different data side memory access if the load exclusive is interrupted
3. Above conditions occur along with specific micro-architectural conditions with precise timing

Implications

When this erratum occurs and the translation table walk is for an instruction fetch, an Instruction Abort will be raised. When this erratum occurs and the translation table walk is for a data side access, that data side access will raise a Data Abort.

Workaround

This erratum can be avoided using Implicit Error Synchronization, by setting SCTLR_EL1.IESB==1, and applying the following patch. The patch code sequence should be applied early in the boot sequence prior to any exclusive operations being executed.

```
mov x0, 1
msr s3_2_c15_c8_0, x0 // IMP_CPUPSELR_EL1
ldr x0, =0xBFEE0000
msr s3_2_c15_c8_3, x0 // IMP_CPUPMR_EL1
ldr x0, =0x08400000
msr s3_2_c15_c8_2, x0 // IMP_CPUPOR_EL1
ldr x0, =0x806001C1
msr s3_2_c15_c8_1, x0 // IMP_CPUPCR_EL1
mov x0, 2
msr s3_2_c15_c8_0, x0 // IMP_CPUPSELR_EL1
ldr x0, =0xBFCE0000
msr s3_2_c15_c8_3, x0 // IMP_CPUPMR_EL1
ldr x0, =0x88400000
msr s3_2_c15_c8_2, x0 // IMP_CPUPOR_EL1
ldr x0, =0x806001C1
msr s3_2_c15_c8_1, x0 // IMP_CPUPCR_EL1
isb
```

Category B (rare)

There are no errata in this category.

Category C

2110865

RAM ECC errors or poison during core power off transitions may lead to deadlock

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor has the capability of detecting *Error Correcting Code* (ECC) errors in RAMs and flagging an external *Reliability, Availability, and Serviceability* (RAS) IRQ interrupt.

The processor can receive poison from external interfaces towards the *LLRAM Coherency Unit* (LCU) and L2 cache through the *Low-latency RAM* (LLRAM) and *Main Master* (MM) interfaces respectively.

The processor can also power down its cores.

If the processor generates an ECC error or poison triggered RAS interrupt during a core power off sequence, the processor deadlocks.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when all the following conditions are met:

- Based on the error type, a relevant field or fields (CI, DUI, CFI, FI, and UI) of the ERR<n>CTLR is set to 1 to generate an IRQ
- Error reporting is enabled (ERR<n>CTLR.ED = 1)
- A request to transition a core to the off power mode is underway
- Either an ECC error occurs in a RAM or poison is received from the LLRAM or MM interfaces

Implications

If this erratum occurs, the processor deadlocks.

Workaround

To avoid this erratum, set the CI, DUI, CFI, FI, and UI fields in the ERR<n>CTLR to 0 before requesting a transition to the off power mode for any core.

2131519

RAS Fault Injection to shared memory may cause deadlock or data corruption

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor supports fault injection for testing of fault handling software. When a *Corrected Error* (CE) or *Deferred Error* (DE) is injected to Error Record 3 (for the shared memories), it may cause a deadlock or data corruption.

Configurations Affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when all the following conditions are met:

- A CE or DE fault is requested to be injected to the Error Record 3
- The fault is injected on the second beat of a transaction

Implications

When this erratum occurs, the L2 memory system will send a spurious response to the L1 memory system which could cause deadlock or data corruption.

This erratum does not affect injection of an *Uncontainable Error* (UC) to the Error Record 3 or any error injection to other Error Records.

Workaround

There is no workaround. It is expected that on test silicon, software can use other Error Records to test fault injection.

2131811

DSB does not guarantee the observability of the effects of the GIC CPU interface register accesses

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor implements the *Generic Interrupt Controller* (GIC) CPU interface. The GIC architecture requires that the execution of a DSB instruction guarantees the effects of the GIC CPU interface register accesses are observed by the Distributor and Redistributor.

Because of this erratum, execution of a DSB instruction after accessing to the GIC CPU interface registers cannot guarantee the observability of the effects. Under certain conditions, a spurious interrupt might be observed or a new interrupt might be lost.

Configurations affected

The erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when the GIC CPU interface is enabled (**GICCDISABLE** signal LOW at reset) and either of the following set of conditions is met:

1. For the first set of conditions to cause this erratum, the following sequence of conditions must occur:
 - a. Program executes a DSB instruction after a write to either of the following:
 - One of the ICC_EOIR0_EL1, ICC_EOIR1_EL1, ICV_EOIR0_EL1, and ICV_EOIR1_EL1 registers when EOImode is not set
 - One of ICC_DIR_EL1 and ICV_DIR_EL1 registers to deactivate an interrupt
 - b. Program writes 1 to the GICD_ISACTIVER<n> or the GICR_ISACTIVER0 registers to re-activate the interrupt
2. For the second set of conditions to cause this erratum, the following sequence of conditions must occur:
 - a. Program executes a DSB after a read to one of the ICC_IAR0_EL1 and ICC_IAR1_EL1 registers to acknowledge the interrupt
 - b. Program clears the source of the interrupt in the peripheral
 - c. A new interrupt is asserted by the peripheral

Implications

If the first set of conditions causes this erratum, a spurious interrupt might be observed.

If the second set of conditions causes this erratum, the new interrupt might be lost.

Workaround

No workaround is required to avoid the implications of the first set of conditions. This is because program can tolerate the spurious interrupt in this case.

To avoid the implications of the second set of conditions, replace the DSB with two writes to the ICC_DIR_EL1 register with an unused but supported SPI INTID before clearing the source interrupt in the interrupt handling routine.

2140942

Incorrect value reported in RAS registers on L2 cache ECC errors

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor reports and records *Error Correcting Code* (ECC) errors in memories and system ports according to the *Reliability, Availability, and Serviceability* (RAS) Extension. Because of this erratum, fields that indicate the primary error code or the error type might be incorrect in the error record registers 3, 4, and 5 that are associated with the L2 cache RAMs (L2 cache data RAMs, L2 cache tag RAMs, L2 cache data buffer RAMs, L2 duplicate L1 tag RAMs).

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor configured to include RAM protection (**RAM_PROTECTION** configuration parameter is set to 1).

Conditions

This erratum occurs when RAM protection is enabled (IMP_CLUSTERMEMPROTCTLR_EL1.MEMPROTEN=1) and one of the following conditions applies:

- Multiple ECC errors (single bit, double bit, or both) occur in different L2 cache RAMs
- A single bit ECC error occurs in the L2 cache data buffer RAM and is deferred

Implications

If this erratum occurs, the information in the ERR<n>MISCO.TYPE and ERR<n>STATUS.SERR fields could be incorrect for the error record register 3, 4 or 5.

There is still significant benefit gained from the ECC logic because this erratum does not impact the detection or correction of the ECC errors. It only affects the reporting of the L2 cache RAM errors in the error record registers.

Workaround

There is no workaround.

2151159

Multi-core Cortex-R82 may deadlock when executing L2DBG operations and WFx events

Status:

Affects: Cortex-R82

Fault type: Programmer Category C

Fault status: r0p0. Fixed in r0p1.

Description:

In a system with the Cortex-R82 processor that has two or more cores, the system can deadlock if multiple cores are doing L2 cache debug operations while simultaneously trying to do a power transition to either OFF or OFF_EMU power modes in a core or there is a change in the L2 cache operating mode (From FULL RAM to DL1ONLY).

Configurations affected:

This erratum affects all configurations of the Cortex-R82 processor configured with **NUM_CORES** ≥ 2

Conditions:

This erratum occurs when there is a core transitioning to OFF or OFF_EMU power mode or the L2 cache operating mode changes from FULL RAM to DL1ONLY and when all the following conditions are met:

- One of the SYS_IMP_CLUSTERCDBGL2D, SYS_IMP_CLUSTERCDBGL2DT, or SYS_IMP_CLUSTERCDBGL2T is executed in two cores
- At least one of the operations above is followed by a WFI or WFE request without an IMP_CLUSTERCDBGDR0_EL1 read

Implications:

If this erratum occurs, the processor deadlocks.

It is expected that the erratum conditions do not represent plausible software. This is because of the absence of an IMP_CLUSTERCDBGDR0_EL1 read before WFI/WFE, and the implicit requirement to execute in the highest Exception level.

Workaround:

The problematic system instructions can be trapped to EL2. To avoid this erratum, always perform a System register read of IMP_CLUSTERCDBGDRO_EL1 following the execution of SYS IMP_CLUSTERCDBGL2D, SYS IMP_CLUSTERCDBGL2DT, or SYS IMP_CLUSTERCDBGL2T before issuing a WFI or WFE request.

2169550

ETM trace might not report certain direct branch instructions

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor implements the *Embedded Trace Macrocell* (ETM). The ETM generates the trace packets of instructions.

Because of this erratum, the ETM might not generate atom elements for certain direct branch instructions under very specific microarchitectural conditions.

Configurations affected

The erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when all the following conditions are met:

- ETM trace is enabled and not prohibited
- The core executes a direct branch instruction which is triple-issued with a load instruction and a store instruction but the direct branch instruction is not the last of the three instruction
- An interrupt is pending and not masked
- One of the load/store instructions and the direct branch instruction are completed
- The other load/store instruction has been stalling and is subsequently interrupted

Implications

If this erratum occurs, the ETM does not generate:

- An Atom element for the branch instruction even though it was executed
- An Address element indicating the target of the branch instruction

The preferred exception return address provided with the Exception element correctly indicates where the exception is taken from. This might cause the trace analyzer to infer incorrect instruction execution.

Workaround

A workaround is not expected to be required for test silicon. This is because the erratum conditions are rarely met.

A trace analyzer might be able to detect that this erratum has occurred:

- If a branch instruction is encountered when inferring execution due to an Exception element
- When load or store instructions are P0 instructions, a load or store instruction is encountered when inferring execution due to an Exception element
- If the preferred exception return address for an Exception element indicates the exception was taken from an address which is at a lower address than the target of the previous P0 element

If a workaround is required, the erratum can be avoided by setting IMP_CPUACTLR_EL1.LSDI to 0 to disable dual-issuing load/store instructions. This has high performance impact.

2170009

Error injection via ERR0PFGCTL might occur at the wrong time

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor supports fault injection for testing of fault handling software. When a *Corrected Error* (CE), *Deferred Error* (DE), or *Uncontainable Error* (UC) is injected to the Error Record 0 (for the per-core memories), the injection might occur at an unexpected time. If fault injection is configured to restart whenever the counter (ERR0PFGCDN_EL1) reaches zero, fault injection may be at a higher rate than expected.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor configured to include RAM protection (**RAM_PROTECTION** configuration parameter is set to 1).

Conditions

This erratum occurs when all of the following conditions are met:

- Error detection is enabled (IMP_MEMPROTCTLR_EL1.MEMPROTEN = 1)
- Fault injection is requested (ERR0PFGCTL.CDNEN = 1 and one of ERR0PFGCTL.{CE, DE, UC} is set to 1)
- An access that would cause fault injection has previously occurred

Implications

If this erratum occurs, fault injections to the Error Record 0 might take place sooner than expected. Errors might be injected whenever the counter reaches zero, without requiring a triggering access as long as one has previously occurred. As a result, ERR0MISCO might contain invalid information. If fault injection is configured to restart whenever the counter reaches zero, the fault injection rate may be higher than expected.

Workaround

There is no workaround. It is expected that on test silicon, software may be able to cope with the fault being injected sooner and not rely on the information in ERR0MISCO.

2173953

PMU event counts might be inaccurate

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor implements a number of performance monitor events. Because of this erratum, some of the events will not count correctly.

Configurations Affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when one of the *Performance Monitoring Unit* (PMU) event counters is configured to count one of the following events:

- 0x0001 L1I_CACHE_REFILL
- 0x000F UNALIGNED_LDST_RETIRED
- 0x0010 BR_MIS_PRED
- 0x0012 BR_PRED
- 0x0015 L1D_CACHE_WB
- 0x0020 L2D_CACHE_ALLOCATE
- 0x0043 L1D_CACHE_REFILL_WR
- 0x0070 LD_SPEC
- 0x0071 ST_SPEC
- 0x0072 LDST_SPEC
- 0x0076 PC_WRITE_SPEC
- 0x00C1 L2D_CACHE_REFILL_PREFETCH
- 0x0331 TCMS_ACCESS_WR
- 0x0361 LLRAM_L1D_CACHE_REFILL_WR
- 0x0362 LLRAM_L1D_CACHE_REFILL

Implications

If this erratum occurs:

- Any count of UNALIGNED_LDST_RETIRED, BR_MIS_PRED, BR_PRED, L2D_CACHE_ALLOCATE,

L1D_CACHE_REFILL_WR, LD_SPEC, ST_SPEC, LDST_SPEC, PC_WRITE_SPEC, TCMS_ACCESS_WR or L2D_CACHE_REFILL_PREFETCH might be lower than it should be.

- Any count of L1D_CACHE_WB or L1I_CACHE_REFILL might be higher than it should be.
- Any count of LLRAM_L1D_CACHE_REFILL_WR or LLRAM_L1D_CACHE_REFILL would be 0. Software will not be able to use these events for performance analysis.

Workaround

There is no workaround.

2215960

An atomic with Acquire semantics may be observed before an earlier Store-Release to TCM or LLPP

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor contains *Tightly Coupled Memories* (TCMs) and a *Low-latency Peripheral Port* (LLPP) that are private to the core. Due to this erratum, an atomic instruction with Acquire semantics could be observed by a different observer before a store with Release semantics performed to the TCMs or LLPP that was earlier in program order.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when the following sequence of conditions is met:

1. There is a Store-Release instruction to the TCMs or LLPP
2. There is an atomic instruction with Acquire but not Release semantics to a different memory port than the Store-Release

Implications

When this erratum occurs, the memory effects of the atomic with Acquire semantics could be observed by a different agent before the memory effects of the Store-Release. For the effects of this erratum to be observed, the Store-Release must be visible to another core, as in cases where the value is read from the TCMs through the *ACE-Lite Slave* (ACELS) port or where the LLPP is connected to a shared interconnect.

For the memory that is intended to be shared between cores, it is recommended to use the *Main Memory* (MM) port or *Low-latency RAM* (LLRAM) port, or for shared peripherals the *Shared Peripheral Port* (SPP).

Workaround

To avoid this erratum, a DMB ST can be inserted between the Store-Release and the atomic with Acquire semantics.

2218751

Data cache maintenance operations by Set/Way targeting a 4MB L2 cache might affect incorrect cache index

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor supports an L2 cache that can be configured to a maximum size of 4MB. When the cache size is configured as 4MB, the Set/Way cache maintenance operations (DC C1SW, DC C2SW, DC C3SW) could affect the wrong index when targeting the L2 cache and when the targeted index has the most significant bit equal to 1.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor where the L2 cache size is 4MB (**L2_CACHE_SIZE** = 4096).

Conditions

This erratum occurs when the following conditions are met:

- A Set/Way cache maintenance operation is executed targeting the L2 cache
- The most significant bit of the Set is 1. For example, bit [18] of the argument to the DC instruction is 1

Implications

When this erratum occurs, software will be unable to perform Set/Way data cache maintenance operations to the L2 cache indexes with the most significant bit set. No data corruption can occur due to this erratum but data may not be externally visible to other agents after a Set/Way operation.

The use of Set/Way instructions to manage coherency is discouraged because the memory accesses from other cores could cause the line to be migrated to the cache of another core. Because of this, typical software is not expected to use Set/Way cache maintenance and as such the implications of this erratum are not expected to be significant.

The cache invalidation performed as part of the power down sequence or after reset is unaffected by this erratum.

Workaround

There is no workaround.

2224832

Debug APB accesses to reserved core address is accessible when core powered off

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

If a read or write transaction is made on the Debug APB interface to a reserved address within the core address space, then it should be treated as RAZ/WI while the core is powered on. If certain reserved addresses are accessed, then they will be treated as RAZ/WI even when the core is powered off, instead of giving an error response.

Configurations affected

This erratum affects all configurations of the Cortex-R82.

Conditions

The erratum occurs when a read or write access is made on the Debug APB interface that is to an address `0x00nm_OD90` where `n` is from 8 to `(8+NUM_CORES-1)` and `m` is from 0 to 4.

Implications

Software is not expected to access these reserved registers, therefore there are no implications.

Workaround

No workaround is necessary.

2226045

ATB flush is unreliable

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description:

The Cortex-R82 processor provides two ATB buses for trace from the internal *Embedded Trace Macrocells* (ETMs) and *Embedded Logic Analyzers* (ELAs). These buses support an external flush request which should be used to ensure the final packets of trace from a session have been captured. Due to this erratum, there are scenarios where the processor will acknowledge a flush request but will not output all of the trace packets or may output trace packets after the flush is acknowledged.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

The erratum occurs if the following sequence of conditions is met:

1. The ETM or ELA is enabled
2. Trace data is generated on the ATB bus
3. An external flush request is generated

Implications

If this erratum occurs, the final few bytes of a trace stream which are expected may not be captured by the Trace Capture Device, and some of the trace packets from the data trace stream may not be output until another external flush request is received. It is not possible to determine if a flush request has been successful.

Due to this erratum, in a system with additional downstream trace infrastructure, trace will not reliably drain from some components (such as upsizers).

Workaround

There is no workaround to reliably avoid this erratum. Generating several flush requests before using a flush and stop sequence is the most reliable way to drain trace data from the processor.

2246499

Some RAS and Debug identification registers have wrong values

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor implements CoreSight registers to identify the components.

Because of this erratum, read of EDDEVARCH.ARCHPART, ERRDEVARCH.ARCHPART, ERRCIDR1, or ERRDEVAFF returns wrong values.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when software reads EDDEVARCH, ERRDEVARCH, ERRCIDR1, or ERRDEVAFF registers.

Implications

If this erratum occurs:

- Read of EDDEVARCH.ARCHPART returns 0xA15 (A Profile Debug) instead of the correct value 0xA05 (R Profile Debug)
- Read of ERRDEVARCH.ARCHPART returns 0x500 instead of the correct value 0xA00 (RAS)
- Read of ERRCIDR1 returns 0x90 instead of the correct value 0xF0
- Read of ERRDEVAFF returns the value of MPIDR_EL1 instead of the correct value 0x0

Workaround

There is no workaround.

2248150

Accesses to Non-secure EL2 physical timer registers and Secure EL2 virtual timer registers are not UNDEFINED

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor implements Generic Timer registers as defined in the Arm architecture. According to the architecture, Non-secure EL2 physical timer registers and Secure EL2 virtual timer registers are not implemented and therefore, they are **UNDEFINED**.

Because of this erratum, accesses to the Non-secure EL2 physical timer registers and Secure EL2 virtual timer registers are not **UNDEFINED**.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when either of the following conditions is met:

- Software reads or writes CNTHP_CVAL_EL2, CNTHP_TVAL_EL2, or CNTHP_CTL_EL2 in EL2
- Software reads or writes CNTHVS_CVAL_EL2, CNTHVS_TVAL_EL2, or CNTHVS_CTL_EL2 in EL2

Implications

If this erratum occurs:

- The accesses to the Non-secure EL2 physical timer registers and Secure EL2 virtual timer registers are not **UNDEFINED**
- There are no effects of triggering events from using the Non-secure EL2 physical timer registers
- **nCNTHVSIRQ** can still be asserted LOW when the timer condition for the Secure EL2 virtual timer is met

Workaround

There is no workaround.

2254257

Read of ERRGSR might return incorrect value

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 processor implements the *Reliability, Availability, and Serviceability* (RAS) Extension as defined in the Arm architecture. The Cortex-R82 processor implements 6 error records. It also implements the ERRGSR which shows the status for the records in the group.

Because of this erratum, the read of ERRGSR might return incorrect value.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor configured to include RAM protection (**RAM_PROTECTION** configuration parameter is set to 1).

Conditions

This erratum occurs when the following sequence of conditions is met:

1. Core RAM protection is enabled with IMP_MEMPROTCTLR_EL1.MEMPROTEN = 1
2. RAS error reporting is enabled with ERROCTLR.ED = 1
3. One of the ERR<n>STATUS.V, where n is 0 to 2, is changed due to either a new *Error Correcting Code* (ECC) error or a software write
4. Immediately after that, a different ERR<n>STATUS.V, where n is 0 to 2, is set due to a new ECC error
5. Software reads ERRGSR

Implications

If this erratum occurs, the software might read incorrect value from the ERRGSR.

Workaround

To avoid this erratum, software should read ERR<n>STATUS.V directly for error records 0 to 2 rather than using ERRGSR.

2261658

A single bit hard error on poisoned TCM data could cause a deadlock

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r0p1.

Description

The Cortex-R82 has *Error Correcting Code* (ECC) error detection on the *Tightly Coupled Memories* (TCMs). *Single Error Correction, Double Error Detection* (SECCDED) is supported, as well as the use of poison to defer errors. There is also support to make forward progress in the presence of a single hard error. Due to this erratum, when a hard error occurs affecting a single bit within the same 128 bits as data that has been poisoned in the TCMs, it could cause the processor to deadlock.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor configured to include RAM protection (**RAM_PROTECTION** configuration parameter is set to 1) and a core in the cluster configured with a TCM (**ITCM_SIZE**<m> or **DTCM_SIZE**<m> parameter greater than 0).

Conditions

This erratum occurs when all the following conditions are met:

- RAM protection is enabled (**IMP_MEMPROTCTLR_EL1.MEMPROTEN=1**)
- There is data in one of the TCM memories which is poisoned
- A single bit error occurs in a different ECC granule to the poisoned data, but within the same 128 bits
 - This single bit error is a hard error and so persists after the core attempts to correct it
- A load to the TCM accesses the data with the single bit error, but not the poisoned data

Implications

If this erratum occurs, the processor deadlocks.

There is no impact to error detection mechanisms due to this erratum. However due to this erratum, forward progress is not always guaranteed in the presence of a hard error in the TCMs.

Because this erratum occurs only when there is an ECC error and because ECC errors are not expected in sample silicon, it is expected that this erratum will have no implications for sample silicon.

Workaround

There is no workaround for this erratum.

2284986

PMU event counts might be inaccurate

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1. Fixed in r0p2.

Description

The Cortex-R82 processor implements a number of performance monitor events. Because of this erratum, some of the events will not count correctly.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when one of the *Performance Monitoring Unit* (PMU) event counters is configured to count one of the following events:

- Core PMU events:
 - 0x003D STALL_SLOT_BACKEND
 - 0x003E STALL_SLOT_FRONTEND
 - 0x0074 ASE_SPEC
 - 0x0075 VFP_SPEC
 - 0x00E4 STALL_BACKEND_ILOCK
 - 0x00E6 STALL_BACKEND_ILOCK_FPU
 - 0x0327 MM_ACCESS
 - 0x032A LLRAM_ACCESS
 - 0x032D SPP_ACCESS
 - 0x0332 TCMS_ACCESS
 - 0x0378 BARRIER_STB_FULL
 - 0x0379 L1I_WT_HIT
 - 0x0019 BUS_ACCESS
 - 0x0060 BUS_ACCESS_RD
 - 0x0061 BUS_ACCESS_WR
- Cluster PMU events:
 - 0x0160 MACP_ACCESS_RD
 - 0x0161 MACP_ACCESS_WR
 - 0x041A MM_ACTIVE
 - 0x041D MM_CYCLES
 - 0x0461 MM_ACCESS_WR

- 0x0462 MM_ACCESS_SHARED
- 0x0463 MM_ACCESS_NOT_SHARED
- 0x0464 MM_ACCESS_NORMAL
- 0x0465 MM_ACCESS_PERIPH

Implications

If this erratum occurs:

- Any count of STALL_SLOT_BACKEND, VFP_SPEC, STALL_BACKEND_ILOCK, STALL_BACKEND_ILOCK_FPU, MM_ACCESS, LLRAM_ACCESS, SPP_ACCESS, TCMS_ACCESS, MACP_ACCESS_RD, MACP_ACCESS_WR, MM_ACTIVE, MM_CYCLES, MM_ACCESS_WR, MM_ACCESS_SHARED, MM_ACCESS_NOT_SHARED, MM_ACCESS_NORMAL, MM_ACCESS_PERIPH, BUS_ACCESS, BUS_ACCESS_RD or BUS_ACCESS_WR might be lower than it should be
- Any count of STALL_SLOT_FRONTEND, ASE_SPEC or BARRIER_STB_FULL might be higher than it should be
- Any count of L1I_WT_HIT would be 0. Software will not be able to use these events for performance analysis

Workaround

There is no workaround.

2286314

Access to TRCSEQEVR3 is not UNDEFINED

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in rOp0, rOp1. Fixed in rOp2.

Description

The Cortex-R82 processor implements the system instruction interface to the *Embedded Trace Macrocell* (ETM) as defined in the Arm architecture. There are 3 registers defined for the TRCSEQEVR<n> so n is in 0 to 2.

Because of this erratum, the access to the TRCSEQEVR3 is not **UNDEFINED**.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when software accesses to the TRCSEQEVR3 register.

Implications

If this erratum occurs, software access to the TRCSEQEVR3 is not **UNDEFINED** and the access is RAZ/WI.

Workaround

There is no workaround.

2313135

Cacheable accesses to LLRAM might deadlock in the presence of an ECC error

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1. Fixed in r0p2.

Description

The Cortex-R82 processor has a *Low-latency RAM* (LLRAM) port to provide a more deterministic shared memory. The LLRAM port is designed on the assumption that it will be connected directly to a low-latency external memory.

If the LLRAM port is not directly connected to a memory but instead to an interconnect which reorders read responses then because of this erratum, and while in the presence of an ECC error, the processor might deadlock.

Configurations affected

This erratum affects configurations in which all the following are true:

- The processor is configured to include RAM protection (**RAM_PROTECTION** configuration parameter is set to 1)
- 4 or less cores are in the cluster (**NUM_CORES** configuration parameter is 4 or less)
- The LLRAM port is not directly connected to an external memory

Conditions

This erratum occurs when all the following conditions apply:

- The LLRAM AXI port is connected to a subordinate that has a read acceptance capacity of 3 or more
- Cacheable accesses are performed to the LLRAM, either explicit accesses or by the prefetcher
 - Read responses to these accesses are reordered
- One of the following occur:
 - A double bit ECC error occurs in the LCU duplicate L1 tag RAM with `IMP_CLUSTERMEMPROTCTLR_EL1.MEMPROTEN=1`
 - An ECC error in the L1 data cache RAMs occurs with `IMP_MEMPROTCTLR_EL1.MEMPROTEN=1`
- Complex micro-architectural conditions occur

Implications

If this erratum occurs, the processor deadlocks. This erratum is not expected to have significant implications for most systems as it is expected that the LLRAM port is directly connected to a memory and so read responses will not be reordered. If read responses are not reordered, then the conditions for this erratum cannot occur.

Workaround

It is not expected that a workaround is required for this erratum. However, if a system is susceptible to this erratum and a workaround is required, disable the RAM protection by setting `IMP_CLUSTERMEMPROTCTLR_EL1.MEMPROTEN` to 0 and `IMP_MEMPROTCTLR_EL1.MEMPROTEN` to 0.

2317561

Halting step syndrome might be wrong on stepping a Load-Exclusive instruction

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in rOp0 and rOp1. Fixed in rOp2.

Description

Halting Step is a debug resource that a debugger can use to make the core step through code one instruction at a time. The EDSCR.STATUS records different scenarios for entering Debug state on a Halting Step debug event.

Because of this erratum, the EDSCR.STATUS might be wrong after entering Debug state on a Halting Step debug event.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when the following sequence of conditions is met:

1. The debugger activates Halting Step with the core in the Debug state
2. The debugger signals the core to exit Debug state
3. The core steps a Load-Exclusive instruction which generates an exception with the relevant SCTLR_ELx.IESB == 1
4. The core enters Debug state
5. The debugger reads EDSCR.STATUS

Implications

If this erratum occurs, the debugger might read EDSCR.STATUS value as 'Halting Step, normal' instead of the correct value as 'Halting Step, exclusive' or 'Halting Step, no syndrome'.

Workaround

There is no workaround.

2330237

Multi-issuing control with IMP_CPUACTLR_EL1.MI = 0b010 is wrong

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0 and r0p1. Fixed in r0p2.

Description

Cortex-R82 processor implements multi-issuing controls with IMP_CPUACTLR_EL1.MI. When IMP_CPUACTLR_EL1.MI is programmed as 0b010, FP/AdvSIMD instructions can only be issued from slot0 while other instructions can be issued from slot0 or slot1.

Because of this erratum, other instructions can be issued from slot2 not respecting the control of IMP_CPUACTLR_EL1.MI.

Configurations affected

This erratum only affects configurations of the Cortex-R82 processor that have the Advanced SIMD and floating-point support enabled.

Conditions

This erratum occurs when the following condition is met:

- Software programs IMP_CPUACTLR_EL1.MI as 0b010

Implications

If this erratum occurs, FP/AdvSIMD instructions can still only be issued from slot0 but other instructions can be issued from slot0, slot1 or slot2.

Workaround

There is no workaround.

2338818

IFU Cache errors might report incorrect BANK to the RAS node

Status

Fault Type: Programmer Category C

Fault Status: Present in rOp0 and rOp1. Fixed in rOp2.

Description

The Cortex-R82 processor reports and records *Error Correcting Code* (ECC) errors in memories and system ports according to the *Reliability, Availability, and Serviceability* (RAS) Extension. Because of this erratum, fields that indicate the bank of the error may be reported inconsistently for Instruction cache data RAMs compared to other RAMs. This applies to the error record registers 1, 2, and 3 that are associated with each core.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor configured to include RAM protection (**RAM_PROTECTION** configuration parameter is set to 1).

Conditions

This erratum occurs when all the following conditions are met:

- RAM protection is enabled (**IMP_CLUSTERMEMPROTCTLR_EL1.MEMPROTEN=1**)
- An ECC error occurs in one of the Instruction cache data RAMs.

Implications

If this erratum occurs, the bank of the error reported will be indicated by the value **ERR<n>MISC0.BANK** and the subbank in **ERR<n>MISC0.CHUNK** fields, rather than both being reported in the **ERR<n>MISC0.BANK** field as for other RAMs.

Workaround

There is no workaround.

2339884

Cluster CTI trigger outputs are not reaching cluster ELA CTITRIGINs

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0. r0p1. Fixed in r0p2.

Description

The Cortex-R82 processor can optionally implement an *Embedded Logic Analyzer* (ELA) at the cluster level. This ELA has trigger inputs from the cluster *Cross Trigger Interface* CTI.

Because of this erratum, the ELA will never observe triggers generated from the cluster CTI.

Configurations affected

This erratum affects configurations of the Cortex-R82 processor with embedded logic analyzers included.

Conditions

This erratum occurs when a trigger from the cluster CTI intended for the cluster ELA is generated.

Implications

The cluster ELA cannot be triggered from events observed by the cluster CTI. There are no alternative trigger inputs to this ELA.

Workaround

There is no workaround to this erratum.

2358852

Pointer authentication key registers are not initialized

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in rOp0 and rOp1. Fixed in rOp2.

Description

Cortex-R82 is required to initialize all programmer-visible registers to known values. Because of this erratum, the pointer authentication key registers are not initialized.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when the following sequence of conditions is met:

1. Core comes out of warm or cold reset which is not because of debug recovery.
2. Software reads the pointer authentication key registers.

Implications

If this erratum occurs, the read will return uninitialized values which might be from the last written values before the reset.

Workaround

This erratum is not expected to require a workaround.

2359684

Some unallocated debug and trace System registers might be trapped by HCR_EL2.TIDCP

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1. Fixed in r0p2.

Description

In Cortex-R82, HCR_EL2.TIDCP is used to trap access to **IMPLEMENTATION DEFINED** System instructions or System registers from EL0 or EL1.

Because of this erratum, the HCR_EL2.TIDCP might trap some unallocated System registers in the debug and trace group with op0==0b10.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when all the following conditions are met:

- HCR_EL2.TIDCP is set
- Software executes an MRS or MSR (register) with op0==0b10 and CRn=={11, 15} in EL1

Implications

If this erratum occurs, the access will be trapped by the HCR_EL2.TIDCP rather than raising an **UNDEFINED** exception.

Workaround

There is no workaround.

2370219

Use of debug related power states can result in deadlock

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1. Fixed in r0p2.

Description

The Cortex-R82 processor can use certain power states to allow debug of power transition sequences and fault conditions.

Because of this erratum, if an interrupt is received during any core transitioning between specific debug related power states, the processor can deadlock.

Configurations affected

This erratum affects all configurations.

Conditions

This erratum occurs when the following sequence of conditions is met for a single core:

1. A core is required to wake up through either of the following:
 - The core was entering OFF mode from WFI, but encountered an *Error Correcting Code* (ECC) error signaling a *Reliability, Availability, and Serviceability* (RAS) interrupt that aborted the power transition
 - The core is transitioning OFF to ON, because its COREWAKEREQUEST pin was asserted by the *Generic Interrupt Controller* (GIC)
2. A debug-related power transition is requested for the cluster through one of the following:
 - The cluster transitions ON to WARM_RST or DBG_RECOV
 - The cluster transitions OFF_EMU to OFF
 - The cluster transitions MEM_RET_EMU to MEM_RET

Implications

If this erratum occurs, outstanding power transitions could cause the processor to deadlock. These transitions are only expected to occur during debug of a device.

Workaround

To avoid this erratum, ensure that the following debug-related cluster power transitions do not occur:

- Avoid transitions OFF_EMU to OFF and MEM_RET_EMU to MEM_RET
- Avoid using WARM_RST and DBG_RECOV to debug a RAS error

2375011

PSTATE.SS not restored correctly if OSLK is set to 1 just before debug exit

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0 and r0p1. Fixed in r0p2.

Description

The Cortex-R82 processor implements debug features up to v8.4 and the optional debug over powerdown feature from v8.5 (FEAT_DoPD). According to the architecture, the debug exit is a context synchronization event which uses the newly synchronized state to perform the PE state restoration.

Because of this erratum, the restoration of PSTATE.SS will be calculated based on old state. Under certain conditions, the PSTATE.SS will have the wrong value after the debug exit.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when the following sequence of conditions is met:

- The Core is in debug state with DSPSR_EL0.SS=1 and OSLK=0.
- An MSR OSLAR_EL1 is executed, setting OSLK=1.
- A debug exit is performed, triggering the PSTATE.SS to be restored from the DSPSR.SS.

Implications

If this erratum occurs, PSTATE.SS will be set after exiting debug state, instead of being masked to zero.

Workaround

An ISB can be executed after the MSR to synchronize the OSLK value, before performing the debug exit.

2384696

DPU returns wrong value on MRS to DLR_ELO

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1. Fixed in r0p2.

Description

The Cortex-R82 processor implements debug features up to Armv8.4 and the optional debug over powerdown feature from Armv8.3 (FEAT_DoPD). According to the architecture, the DLR_ELO register can be accessed from debug state using an MRS.

Because of this erratum, the read value from the DLR will always be word-aligned and might be different than the actual value.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when the following sequence of conditions is met:

- The core is in debug state
- DLR_ELO contains a PC value that is not word-aligned (bits [1:0] != 00)
- An MRS to the DLR_ELO is executed

Implications

If this erratum occurs, the MRS will return the DLR value word-aligned ([1:0] == 0)

Workaround

There is no workaround.

2386524

Defective RAS registers

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1. Fixed in r0p2.

Description

The Cortex-R82 processor implements the *Reliability, Availability and Serviceability* (RAS) extension, up to and including the ARMv8.4-RAS.

Because of this erratum, accesses to ERR4PFGCDN, ERR1PFGCTL, and ERR4PFGCTL might be impacted.

Configurations affected

This erratum affects any configuration of Cortex-R82 processor that includes RAM protection (RAM_PROTECTION configuration parameter is set to 1).

Conditions

For the erratum part concerning the ERR4PFGCDN to occur, the following condition applies:

- A read or write operation is performed via the Utility Bus

For the erratum part concerning the ERR1PFGCTL and ERR4PFGCTL to occur, the following condition applies:

- A read operation is performed via the Utility Bus or by an MRS ERXPFGCTL

Implications

When this erratum occurs:

Implications for ERR4PFGCDN:

- A write access performed via the Utility Bus will have no effect
- A read access performed via the Utility Bus will always return 0

Implications for ERR1PFGCTL and ERR4PFGCTL:

- Bit 12 of these registers will be read as 0b0, instead of the expected 0b1

Workaround

To avoid this erratum for ERR4PFGCDN:

- Software running on the core can access the ERR4PFGCDN by MRS/MSR ERXPFCND_EL1

To avoid this erratum for ERR1PFGCTL and ERR4PFGCTL:

- Software can ignore the read value for bit 12 and assume it has returned a value of 0b1

2416442

Multiple double bit ECC errors on core powerdown might deadlock

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p2. Fixed in r1p0.

Description

The Cortex-R82 processor contains logic to clean and invalidate caches when a core is powered down. If multiple double bit *Error Correcting Code* (ECC) errors occur when a core is being powered down, then it could cause the core to deadlock.

Configurations affected

This erratum affects all configurations of the Cortex-R82 process with an L2 cache (**L2_CACHE_SIZE** > 0) and configured to include RAM protection (**RAM_PROTECTION** == 1).

Conditions

This erratum occurs when the following sequence of conditions is met:

1. A core is being powered down.
2. A double bit ECC error occurs in a L2DB while it contains data evicted from the L1 data cache as part of the power down sequence.
3. Another double bit ECC error occurs in a different L2DB containing data evicted from the L1 data cache for a different way, but for the same set.
4. Requests from other cores are performed to the same index as the data held in the L2DBs which have double bit ECC errors, during the short time window before the data is written out on the bus.

Implications

If this erratum occurs, the Cortex-R82 processor deadlocks.

Workaround

No workaround is expected to be needed due to the rarity of multiple double-bit errors in close proximity. If a workaround is required, the L1 data cache can be manually invalidated with set/way operations before powering down a core.

2440118

Some PMU events count incorrectly

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p2. Fixed in r1p0..

Description

The Cortex-R82 processor implements a number of performance monitor events. Because of this erratum, some of the events will not count correctly.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when one of the *Performance Monitoring Unit* (PMU) event counters is configured to count one of the following events:

- 0x0019 BUS_ACCESS
- 0x0060 BUS_ACCESS_RD
- 0x0061 BUS_ACCESS_WR
- 0x021D SPP_CYCLES

Implications

If this erratum occurs:

- Any count of BUS_ACCESS, BUS_ACCESS_RD or BUS_ACCESS_WR would be 0. Software will not be able to use these events for performance analysis.
- Any count of SPP_CYCLES would be incorrect. Software will not be able to use these events for performance analysis.

Workaround

There is no workaround.

2445341

Cache initialization and reset of register fields with UNKNOWN values do not work as expected after Debug recovery

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2. Fixed in r1p0.

Description

Cortex-R82 contains hardware that initializes programmer-visible state when a reset is applied, unless the reset is because of Debug recovery. Specifically, caches are invalidated, and the register file and certain System registers are initialized to fixed values, despite the fact they are specified to reset to UNKNOWN values.

Because of this erratum, this feature may not work as expected.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs on any reset caused by Debug recovery.

Implications

With regard to register initialization:

- On Debug recovery with power-on reset, all registers inside the CPU power domain are initialized and therefore do not retain their values as expected.
- On Debug recovery with either power-on or warm reset, the following register families are initialized and therefore do not retain their values as expected:
 - TCR_EL1, TCR_EL2, VSCTLR_EL2, VSTCR_EL2, VTCR_EL2, MAIR_EL1, MAIR_EL2, CONTEXTIDR_EL1, CONTEXTIDR_EL2, PAR_EL1, PMCID1SR, PMCID1SRa, PMCID2SR, PMVIDSR, CPACR_EL1, CPTR_EL2, HCR_EL2, IMP_BPCTLR_EL1, SCTLR_EL1, SCTLR_EL2
 - Core and Cluster Performance Monitor (PMU) registers
 - *Reliability, Availability, and Serviceability* (RAS) registers (on power-on reset only)
 - Special purpose register SPSR_EL2
 - *Generic Interrupt Controller* (GIC) CPU interface system registers

With regard to cache invalidation:

- On Debug recovery with power-on reset, the L2 cache and L1 Duplicated tag RAMs is invalidated.

Workaround

There is no workaround for the affected registers for register initialization.

The L2 cache invalidation works as expected if Debug recovery is used with warm reset. Leave CLUSTERPPU_PTCR.DBG_RECOV_PORST_EN to 0, which is the default value. For correct operation, ensure the value of the core's PPU_PTCR.DBG_RECOV_PORST_EN matches the value set for the *Cluster Power Policy Unit* (PPU).

2604629

ETM data trace values for ST atomics are incorrect

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2. Fixed in r1p0

Description

The Cortex-R82 processor implements the *Embedded Trace Macrocell* (ETM). The ETM generates trace for instruction and data transfers.

Because of this erratum, the ETM the data trace generated for the ST versions of atomic instructions (for example STADD) is incorrect.

Configurations affected

The erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when all the following conditions are met:

- ETM trace is enabled, and data trace is active
- The core executes an atomic instruction with WZR or XZR as target

Implications

If this erratum occurs, the ETM will generate incorrect data trace P1/P2 pairs with index 0 and 1.

Index 0 data is not expected to be traced (the data read from memory is not available to trace) but will contain the operand data.

Index 1 data is expected to contain the operand data but will contain an UNKNOWN value.

No trace is generated for index 2, this is as expected.

The atomic instructions which load data from memory into a register (for example LDADD) are not affected by this erratum.

Workaround

There is no workaround.

2617173

An external atomic receiving a SLVERR or DECERR might not raise an asynchronous abort

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, and r0p2. Fixed in r1p0

Description

The Cortex-R82 processor supports sending Non-cacheable or Device atomics on the *Main Manager* (MM) AXI port. If one of these atomics gets an error response, the atomic might only abort synchronously when it cannot be guaranteed that memory has not been updated.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor where the system supports atomics on the MM AXI port (**BROADCASTATOMICM** == 1).

Conditions

This erratum occurs when the following sequence of conditions is met:

1. An atomic instruction that returns data is executed with Non-cacheable or Device attributes
2. The atomic is sent on the MM AXI port
3. An error occurs resulting in a RRESP for the atomic of SLVERR or DECERR
4. The BRESP for the atomic is OK
5. The memory targeted by the atomic is still modified despite the previous error occurring

Implications

If this erratum occurs a synchronous exception will be raised despite the associated memory location having been updated.

Workaround

No workaround is expected to be needed as it is expected that for most systems the response would be the same for both BRESP and RRESP.

2618272

When toggling SPIDEN or DBGEN pins close to a core reset, the system might deadlock

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2. Fixed in r1p0.

Description

The Cortex-R82 processor implements different core power modes which reset the CPU, with OFF power mode being a mode susceptible to be used for power savings.

Cortex-R82 further includes pins to enable invasive debug (DBGEN) and secure privilege invasive debug (SPIDEN).

Because of this erratum, toggling these pins in the proximity of a power transition may result in a deadlock.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when all the following conditions are met:

- DBGEN or SPIDEN pins toggle
- A core in Cortex-R82 executes a power transition to OFF, either dynamically or statically programmed
- Complex micro architectural timing events happen

Implications

If this erratum occurs, the system might become unresponsive.

Workaround

There is no workaround.

2652888

Receiving poison on invalid data lanes might result in a data abort when poison is not supported

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2 and r1p0. Fixed in r1p1

Description

The Cortex-R82 processor supports poison on the *Main Manager* (MM) AXI interface in order to defer errors. When poison is indicated on an invalid data lane for a read and the associated read data is consumed by an agent that does not support poison it might result in a spurious data abort. This can be for a request from a processor when *Error Correcting Code* (ECC) protection is not enabled, or a request on the *Main Accelerator Coherency Port* (MACP) which does not support poison.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when all the following conditions are met:

- A read request on the MM interface has **RPOISONM** asserted for an invalid data lane
 - Poison is at a granularity of 64-bits, so an invalid data lane is a 64-bit chunk where no bytes are accessed by the transaction
- At least one of the following conditions is met:
 - The processor is configured without RAM protection (**RAM_PROTECTION=0**)
 - RAM protection is disabled (**IMP_CLUSTERMEMPROTCTLR_EL1.MEMPROTEN=0**)
 - The data is for a MACP request

Implications

When this erratum occurs due to cache protection being disabled an exception will be raised when the associated data is consumed by a load. This is not expected to have significant implications as it is not an expected use case to have a system configured with poison support while the processor does not have any RAM protection configured or enabled.

When this erratum occurs for a MACP request, the transaction will return a SLVERR response. This is not expected to have significant implications as the MACP port is optimized for cacheline transactions and so it is not expected that transactions will have invalid data lanes.

Workaround

No workaround is required for this erratum.

2656238

New interrupts might not be taken after an atomic instruction is interrupted

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p2. Fixed in r1p0.

Description

The Cortex-R82 processor implements features to improve the interrupt latency. Atomic instructions once started can be interrupted if certain conditions are met.

Because of this erratum, after an atomic instruction is interrupted and a non-typical interrupt handler which contains no memory access operations is used, new interrupts might not be taken.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when the following sequence of conditions is met:

1. Core executes an atomic instruction
2. An interrupt is taken and the atomic instruction is interrupted
3. An interrupt handler which contains no load or store instruction is used

Implications

If this erratum occurs, any new interrupts will not be taken until a load or store instruction is executed.

Workaround

No workaround is expected to be required as the interrupt handler normally contains memory access operations which will unlock the core from taking new interrupts.

2659537

Spurious ECC error might be reported when changing operating mode from DL1ONLY to FULL RAM

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2. Fixed in r1p0

Description

The Cortex-R82 processor supports operating modes which allow powering down specific components. This includes the DL1ONLY operating mode where the L2 cache is powered down with supporting shared logic still active. Due to this erratum, under specific conditions it is possible for an *Error Correcting Code* (ECC) error to be spuriously reported in the RAS registers when the L2 cache is powered up by a transition to the FULL RAM operating mode.

Configurations affected

This erratum affects all configurations of the Cortex-R82 process with an L2 cache (`L2_CACHE_SIZE > 0`) and configured to include RAM protection (`RAM_PROTECTION == 1`).

Conditions

This erratum occurs when the following sequence of conditions is met:

1. The L2 cache is powered up (in the FULL RAM operating mode)
2. The L2 cache contains only 1 or 2 valid cachelines
 - One of these cachelines is at index 0 in the cache
3. The L2 cache is powered down (changed to the DL1ONLY operating mode)
4. The L2 cache is powered up again (changed to the FULL RAM operating mode)

Implications

If this erratum occurs, a single or double bit ECC error might be reported for index 0 of the L2 cache Tag RAM in the error record register 4, 5 or 6.

There is still substantial benefit being gained from the ECC logic. There might be a negligible increase in overall system failure rate due to this erratum.

Workaround

No workaround is required for this erratum as it is expected that when the L2 cache is enabled and in use it will contain more than 2 valid cachelines.

2661859

Incorrect value reported in RAS registers on LLRAM receiving poison when ECC is not supported

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2. Fixed in r1p0

Description

The Cortex-R82 processor supports receiving poisoned data on the *Low-latency RAM* (LLRAM) port and will report this to the *Reliability, Availability, and Serviceability* (RAS) registers when *Error Correcting Code* (ECC) is not supported by the core and so the error cannot be deferred. Because of this erratum, the value reported in `ERRORMISCO.MEM` will be incorrect when this error is reported.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when RAM protection is disabled (`IMP_CLUSTERMEMPROTCTLR_EL1.MEMPROTEN=0`) or not present (`RAM_PROTECTION` configuration parameter is set to 0) and the following condition occurs:

- Poisoned data is received on the LLRAM AXI port

Implications

If this erratum occurs, instead of being set to 0x48 as expected, the information in the `ERRORMISCO.MEM` fields will be a Reserved value rather than any of the valid values for this field. Bit[4] will always be 1 which does not occur for any valid value of `ERRORMISCO.MEM`, which are 0x40, 0x41, 0x43, 0x44 and 0x48.

There is still significant benefit gained from the ECC logic because this erratum does not impact the detection or correction of the ECC errors. It only affects the reporting of errors that cannot be deferred in the error record registers.

Workaround

No workaround is required for this erratum.

2693781

Quality of Service is applied to Main Manager accesses when disabled

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p1, r0p2. Fixed in r1p0.

Description

The Cortex-R82 processor contains a mechanism to provide increased Quality of Service (QoS) to a particular core in the processor. Due to this erratum, when the QoS feature is not enabled it will still be applied to the core configured by **IMP_CLUSTERQOSR_EL1.COREQOSID**.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when all the following conditions are met:

- The QoS feature is not enabled, that is **IMP_CLUSTERQOSR_EL1.COREQOSEN=0**
- The value in **IMP_CLUSTERQOSR_EL1.COREQOSID** corresponds to a valid core in the cluster

Implications

When this erratum occurs, QoS is applied despite not being enabled. If **IMP_CLUSTERQOSR_EL1** has not been written then QoS is applied to core 0.

Workaround

No workaround is required for this erratum.

2694966

Fault handling interrupt can cause power transition to deadlock

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, and r0p2. Fixed in r1p0

Description

The Cortex-R82 processor implements the *Reliability, Availability, and Serviceability* (RAS) extension, with RAS System Architecture 1.1. The processor can be configured to raise a Fault Handling Interrupt request through an external pin in the presence of certain types of RAS errors.

Because of this erratum, Fault Handling Interrupts might not work as expected. When the software is attempting to clear errors from a record simultaneously with a new error arriving, it might be possible that the `ERR<n>STATUS` is cleared but the Fault Handling Interrupt pin is set high for that node. The Fault Handling Interrupt pin might be unable to be cleared by software unless a new error occurs. Additionally, if errors occur while Fault Handling Interrupts are disabled, enabling them might not cause an interrupt to be triggered for records that are already recorded.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when all the following conditions are met:

- Fault Handling Interrupts are enabled for a RAS node, with `ERR<n>CTLR.FI` and/or `ERR<n>CTLR.CFI` set to 1, where `<n>` is 0, 1, or 4.
- The RAS node is fully populated by errors:
 - For RAS record 0 to be affected, the single record must be populated.
 - For RAS records 1-3 and 4-6 (available when `RAM_PROTECTION=1`) to be affected, all three records must be populated with errors, with at least two of the three records with errors which do not cause a Fault Handling Interrupt (for example, corrected errors but corrected counter not overflowed).
- The RAS software reads a RAS record and attempts to clear an error by writing the appropriate value into `ERR<n>STATUS`
- At the same time as the error is being cleared, a new error that can cause a Fault Handling interrupt occurs and is recorded into the RAS record being cleared.

Implications

When this erratum occurs, the Fault Handling interrupt pin for a core or for the cluster might be asserted, although the corresponding ERR<n>STATUS will be clear. The interrupt will be unable to be cleared by software unless a new error of the same type occurs.

A side effect is that while a Fault Handling Interrupt is active the affected core or cluster will deny requests to power down.

Workaround

The fault interrupt handler should be modified as follows:

- Disable Fault Handling interrupt for RAS errors by clearing the ERR<n>CTLR.FI and ERR<n>CTLR.CFI bits
- Execute an ISB instruction to ensure the write has completed
- Clear the ERR<n>STATUS normally
- Re-enable Fault Handling interrupts by restoring the ERR<n>CTLR.FI and ERR<n>CTLR.CFI bits to their original values
- Re-check ERR<n>STATUS for any new errors that occurred in this window, since new errors recorded while Fault Handling interrupts are disabled might not cause the Fault Handling Interrupt to be set when re-enabled.

2719885

Software step exception might set the ESR_ELx.ISV to a wrong value

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2, and r1p0. Fixed in r1p1

Description

Software Step is a debug resource that a debugger can use to make the core single-step instructions.

Because of this erratum, the Software Step exception might set the ESR_ELx.ISV to a wrong value after Software Step enters the active-pending state from the inactive state.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when the following sequence of conditions is met:

1. The debugger sets MDSCR_EL1.SS to 1 and executes an exception return instruction setting PSTATE.SS to 1. Software Step is now in Active-not-pending state.
2. The core takes an exception to an Exception level that debug exceptions are disabled from. Software Step is now in Inactive state.
3. The core executes instructions changing the debug target Exception level to be the same as the current Exception level and setting the PSTATE.D to 0. Software Step is now in Active-pending state.
4. Software takes the Software Step exception.

Implications

If this erratum occurs, the ESR_ELx.ISV will be set to 1 and ESR_ELx.EX will be set to 0 though architecture requires ESR_ELx.ISV to be set to 0 when Software Step enters the active-pending state directly from the inactive state.

Workaround

There is no workaround.

2729228

Debug accesses via APB are not supported in EMU power states

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2, r1p0. Fixed in r1p1

Description

Cortex-R82 includes *Advanced Peripheral Bus* (APB) interface for debug. Cortex-R82 also features an internal *Power Policy Unit* (PPU) which allows setting the system, and in particular the cluster, to *Off Emulated* (OFF_EMU) and *Emulated Memory Retention Mode* (MEM_RET_EMU) power modes. Under these emulated modes, it should still be possible to access debug components in the system.

Due to this erratum, in these emulated modes, debug accesses under APB are not possible.

Configurations affected

This erratum affects all configurations.

Conditions

This erratum occurs when the cluster is configured to a power policy of OFF_EMU or MEM_RET_EMU and an APB access is made to any cluster or core component, for example, cluster and core ROM tables, though this applies to any component.

Implications

When this erratum occurs a SLVERR is returned on the APB bus.

Workaround

There is no workaround for this erratum.

2729398

L2RDLAT and L2WRLAT fields in IMP_CLUSTERACTLR_EL1 are hardcoded

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2, r1p0. Fixed in r1p1.

Description

IMP_CLUSTERACTLR_EL1 is an **IMPLEMENTATION DEFINED** register which contains control bits that affect the cluster behavior. Two of the fields in this register L2RDLAT and L2WRLAT were provided so that software can control the L2 cache data RAM latencies. These fields are reset to the values set by the global configuration parameters L2_DATA_RD_LATENCY and L2_DATA_WR_LATENCY respectively. The software would be able to write to these fields and read the corresponding values before L2 cache begins operating. Additionally, the write values would change the L2 cache data RAM latencies. Because of this erratum, writes to these fields are ignored and that they have no effect.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor with an L2 cache (L2_CACHE_SIZE > 0).

Conditions

This erratum occurs when the following sequence of conditions occurs:

1. Cortex-R82 cluster is brought out of reset and L2 cache is not yet being used.
2. An MSR instruction to IMP_CLUSTERACTLR_EL1 register with intention to change the values of L2RDLAT and L2WRLAT.

Implications

- Use cases which rely on this feature will not work.
- An MRS instruction to IMP_CLUSTERACTLR_EL1 will return the values of global configuration parameters L2_DATA_RD_LATENCY and L2_DATA_WR_LATENCY for the fields L2RDLAT and L2WRLAT respectively
- Hardware would use the L2_DATA_RD_LATENCY and L2_DATA_WR_LATENCY values to control the L2 cache data RAM latencies.

Workaround

No workaround is needed for this erratum, as it is expected that the values of the L2_DATA_RD_LATENCY and L2_DATA_WR_LATENCY should be set to safe values that work for the implemented L2 cache data RAMs.

2747728

Some cluster PMU events are incorrect

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2, r1p0. Fixed in r1p1

Description

MM_PREFETCH_CPU_MATCH (0x472), MM_PREFETCH_CPU_KILL (0x473), MACP_STASH_ACP_MATCH (0x165), MACP_STASH_ACP_KILL (0x166), LLRAM_ACCESS_SHARED (0x762), LLRAM_ACCESS_NOT_SHARED (0x763) are **IMPLEMENTATION DEFINED** *Performance Monitoring Unit* (PMU) events which are used to monitor certain behavior of the stash requests. Due to the erratum, the *MATCH events will never be triggered, and the *KILL events will be triggered but not correspond to the stash actually being dropped which means that the event is incorrect. For the LLRAM_ACCESS events, all *ACE-Lite Subordinate* (ACELS) accesses are counted as shared so LLRAM_ACCESS_NOT_SHARED will not count, and LLRAM_ACCESS_SHARED will count non-shared ACELS accesses.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs if one or more of the following scenarios occur:

Scenario 1 - The following sequence of conditions is met:

1. PMU counters are selected to count MACP_STASH_ACP_MATCH/MM_PREFETCH_CPU_MATCH
2. A read request is issued by one of the CPUs to an address A
3. A stash request is sent from one of the CPUs or through ACP port to the same address A

Scenario 2 - The following sequence of conditions is met:

1. PMU counters are selected to count MACP_STASH_ACP_KILL/MM_PREFETCH_CPU_KILL
2. There is no L2 cache, L2 cache is powering down, or L2 cache is powered down
3. A stash request is sent from one of the CPUs or through ACP port

Scenario 3 - The following sequence of conditions is met:

1. PMU counters are selected to count LLRAM_ACCESS_SHARED/LLRAM_ACCESS_NOT_SHARED
2. An LLRAM Non-shareable access occurs via the ACELS port

Implications

If this erratum occurs:

- Use cases which rely on counting these PMU events will not be able to do so
- MM_PREFETCH_CPU_MATCH, MACP_STASH_ACP_MATCH will never count
- MM_PREFETCH_CPU_KILL, MACP_STASH_ACP_KILL will count incorrectly
- Any ACELS accesses will be counted in LLRAM_ACCESS_SHARED, regardless of Shareability

Workaround

No workaround is required.

2753234

An external atomic receiving poison might not raise an asynchronous abort

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2, r1p0. Fixed in r1p1

Description

The Cortex-R82 processor supports sending Non-cacheable or device atomics on the *Main Manager* (MM) AXI port. If one of these atomics gets poison on the load data, the atomic might only abort synchronously when it cannot be guaranteed that memory has not been updated.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor where the system supports atomics on the MM AXI port (**BROADCASTATOMICM** == 1).

Conditions

This erratum occurs when the following sequence of conditions is met:

1. An atomic instruction that returns data is executed with Non-cacheable or device attributes
2. The atomic is sent on the MM AXI port
3. An error is detected after memory is updated resulting in poison on the load data
4. The BRESP for the atomic is OK

Implications

If this erratum occurs a synchronous exception will be raised despite the associated memory location having been updated. Moreover atomics to Non-cacheable and device memory is not architecturally guaranteed, so only limited cases will make use of this.

Workaround

No workaround is expected to be needed.

2763783

Speculative accesses might still be made when LLRAM is disabled

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2, r1p0. Fixed in r1p1

Description

The *Low-Latency RAM* (LLRAM) port provides controls to allow enabling and disabling transactions to be made. Due to this erratum, it is possible for speculative accesses to be made to the LLRAM port when it is disabled.

Configurations Affected

This erratum affects all configurations of the Cortex-R82 which implement the LLRAM port.

Conditions

This erratum occurs if the following sequence of events occurs:

1. An MPU region or page is configured corresponding to the physical address of LLRAM
 - This must have read permissions granted
2. The LLRAM region is disabled, `IMP_LLRAMREGIONR_EL1.ENABLE = 0`
3. A load is executed speculatively to the same physical address as the page previously configured
4. Specific micro-architectural conditions occur

Implications

A speculative access will be performed to the LLRAM when this erratum occurs. It is expected that when the LLRAM port is present and translations are set up to give access to it, that a speculative access to the port will not cause any functional issues.

Workaround

No workaround is required for this erratum.

2773193

32-bit accesses to ERR<n>MISC0 (n= 1-6) will not work as expected

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2, r1p0. Fixed in r1p1

Description:

Cortex-R82 implements *Reliability, Availability, and Serviceability* (RAS) records. It also implements a 64-bit wide Utility bus that allows an external agent to access internal RAS registers.

Due to this erratum, 32-bit accesses to the 64-bit ERR<n>MISC0 (n= 1-6) via the Utility bus might not work as expected.

Configurations affected:

This erratum affects configurations of Cortex-R82 with RAM_PROTECTION = 1.

Conditions:

This erratum occurs when 32-bit accesses are made to the 64-bit register ERR<n>MISC0 (n= 1-6) via the Utility bus.

Implications:

- Reads to the lower half work correctly
- Reads to the upper half return 0
- Writes to the lower half work correctly for written data, but will also zero out the upper half
- Writes to the upper half have no effect

Workaround:

A workaround is not expected to be needed for most software applications. Impacted reads and writes to the upper half of these registers contain the correctable error count (CEC), error type, and overflow (OF), but the ERR<n>STATUS.CE bit will still show if at least one correctable error exists as well as overflow information.

If a workaround is needed, an external agent can access these registers by performing a 64-bit read.

Software running on the core is not affected by this erratum. That is, access to all ERR<n>MISCO registers through ERXMISCO_EL1 works as expected.

2780544

Reset of register fields with UNKNOWN values does not work as expected in the presence of debug recovery

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2, r1p0, r1p1. Open

Description

Cortex-R82 contains hardware that initializes programmer-visible state when a reset is applied, unless the reset is because of Debug recovery mode. Specifically, the register file and certain System registers are initialized to fixed values, despite the fact they are specified to reset to UNKNOWN values, except if the reset is due to Debug recovery mode in which case they retain the previous value.

Because of this erratum, this feature might not work as expected.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor in which the processor application relies on persistence of values of System registers with UNKNOWN reset values under debug recovery.

Conditions

This erratum occurs on any Debug recovery mode exit for the cores or cluster.

Implications

On any reset of the listed registers' fields (and, if applicable, their external views) which reset to UNKNOWN might not retain their values when exiting Debug recovery mode:

- PMEVCNTRn
- ICH_VMCR_EL2
- ICV_PMR_EL1
- PMOVSSET_ELO
- PMOVSLR_ELO
- CNTKCTL_EL1
- CNTP_CTL_ELO
- CNTV_CTL_ELO
- CNTHCTL_EL2
- CNTHPS_CTL_EL2
- CNTVOFF_EL2

- CNTP_CVAL_ELO
- CNTV_CVAL_ELO
- CNTHPS_CVAL_EL2
- IMP_CLUSTERPMSELR_EL1
- IMP_CLUSTERPMCCNTR_EL1
- IMP_CLUSTERPMCNTENCLR_EL1
- IMP_CLUSTERPMCNTENSET_EL1
- IMP_CLUSTERPMINTENCLR_EL1
- IMP_CLUSTERPMINTENSET_EL1
- IMP_CLUSTERPMOVSCLR_EL1
- IMP_CLUSTERPMOVSSET_EL1
- IMP_CLUSTERPMXEVTYPER_EL1
- IMP_CLUSTERPMXVCNTR_EL1
- ERR<n>CTLR

Workaround

There is no workaround.

2788717

An interrupted atomic operation with bus error to LLRAM may raise unexpected asynchronous abort

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r1p0. Fixed in r1p1.

Description:

A bus error on *Low-latency RAM* (LLRAM) port during an atomic operation is expected to generate an asynchronous abort. However, if the atomic operation is interrupted any following bus error for that atomic operation is not expected to generate asynchronous abort. Due to this erratum, an asynchronous abort is generated due to the bus error on LLRAM port for the atomic operation that is already interrupted.

Configurations Affected:

All configurations with *Low-latency RAM* (LLRAM) implemented.

Conditions:

This erratum occurs when the following sequence of conditions are met:

1. An atomic instruction is executed to LLRAM
2. Atomic operation is interrupted before it completes
3. BRESP, other than OK, is received for the atomic operation
4. Above conditions occur along with specific micro-architectural conditions with precise timing

Implications:

Due to this erratum, an asynchronous abort is raised. The interrupt and the bus error that generate the asynchronous abort are independent asynchronous events. Software cannot tell whether the bus error happened before or after the interrupt and hence whether the asynchronous abort was expected or not.

Workaround:

No workaround is expected to be required for this erratum.

2798198

Incorrect system reset behavior under MEM_RET and MEM_RET_EMU modes for IMP_CLUSTERACTLR_EL1.UBACCLVL

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r1p1. Open

Description

Cortex-R82 supports multiple power modes including the cluster Memory retention power mode (MEM_RET) and an emulated counterpart (MEM_RET_EMU). There exists a configuration field in a System register to configure Utility Bus privilege accesses (IMP_CLUSTERACTLR_EL1.UBACCLVL).

Due to this erratum, once MEM_RET or MEM_RET_EMU is entered, the behavior of the system might mismatch the configuration of this field.

Configurations affected

This erratum affects all configurations of Cortex-R82 processor.

Conditions

This erratum occurs when the following sequence of conditions is met:

1. IMP_CLUSTERACTLR_EL1.UBACCLVL has a value different than its reset value
2. The system enters a Memory Retention state (MEM_RET or MEM_RET_EMU)

Implications

The Utility Bus access privileges will not be reset and will retain their previously programmed more restrictive value. Software reading the IMP_CLUSTERACTLR_EL1.UBACCLVL field will see the reset value instead.

Workaround

To avoid this erratum:

Memory retention states will not reset the behavior of IMP_CLUSTERACTLR_EL1.UBACCLVL. The software should not rely on the first read of this register after reset and should instead only rely on its value after a write.

2842855

AFSR0_ELx might have stale value after taking an SError interrupt

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r0p1, r0p2, r1p0, r1p1. Open

Description

The Cortex-R82 processor implements AFSR0_ELx registers to record additional IMPLEMENTATION DEFINED fault status information when taking exceptions.

Because of this erratum, if a new SError interrupt was signaled at the same time as the previous SError interrupt was taken, then AFSR0_ELx might contain stale value when the new SError interrupt is taken.

Configurations affected

This erratum affects all configurations of the Cortex-R82 processor.

Conditions

This erratum occurs when the following sequence of conditions is met:

1. An SError interrupt is pended because of an error in LLRAM, SPP or MM
2. The SError interrupt is taken and marks ESR_ELx.AET as 'Uncontainable'; at the same time, a new SError interrupt is pended because of a different type of error in LLRAM, SPP or MM
3. The new SError interrupt is taken

Implications

If this erratum occurs, the AFSR0_ELx associated with the new SError interrupt will have the stale value of the previous SError interrupt.

Workaround

There is no workaround.

2847045

External read of TCM while CPUHALT<m> is HIGH might see unexpected ECC errors

Status

Affects: Cortex-R82

Fault Type: Programmer Category C

Fault Status: Present in r1p0, r1p1. Open

Description

The Cortex-R82 processor implements IMP_MEMPROTCTLR_EL1.MEMPROTEN to control RAM protection functionality. The reset value of this control takes the value of the top-level pin CFGRAMPROTEN.

Because of this erratum, if there is an external read of *Tightly Coupled Memory* (TCM) during TCM preload, the RAM protection control reset value is ignored and unexpected *Error Correcting Code* (ECC) errors might be received.

Configurations affected

This erratum affects any configuration of Cortex-R82 processor that includes RAM protection (RAM_PROTECTION configuration parameter is set to 1).

Conditions

This erratum occurs when the following sequence of conditions is met:

1. CFGRAMPROTEN is set to 0
2. Out of reset, CPUHALT<m> is held HIGH for TCM preloading
3. There is an explicit read through ACELS to TCM
4. ECC errors are detected

Implications

When this erratum occurs, and with RAM protection disabled:

- The external read will see the corrected value when there is a correctable ECC error
- The external read will see a SLVERR response when there is a non-correctable ECC error

Note as ERR<n>CTLR.ED is reset to 0, there will be no errors recorded to RAS registers.

Workaround

No workaround is expected. The typical case of using TCMs from reset is through write-only *Direct Memory Access* (DMA) to TCMs and ECC errors will be suppressed.