



Arm® Neoverse™ CMN-650 Coherent Mesh Network

Software Developer Errata Notice

Date of issue: 28-Sep-2022


Non-Confidential

Document version: v8.0

Copyright © 2019-2022 Arm® Limited (or its affiliates). All rights reserved.

Document ID: SDEN-1504336

This document contains all known errata since the r0p0 release of the product.



Non-confidential proprietary notice

This document is protected by copyright and other related rights and the practice or implementation of the information contained in this document may be protected by one or more patents or pending patent applications. No part of this document may be reproduced in any form by any means without the express prior written permission of Arm. No license, express or implied, by estoppel or otherwise to any intellectual property rights is granted by this document unless specifically stated.

Your access to the information in this document is conditional upon your acceptance that you will not use or permit others to use the information for the purposes of determining whether implementations infringe any third party patents.

THIS DOCUMENT IS PROVIDED "AS IS". ARM PROVIDES NO REPRESENTATIONS AND NO WARRANTIES, EXPRESS, IMPLIED OR STATUTORY, INCLUDING, WITHOUT LIMITATION, THE IMPLIED WARRANTIES OF MERCHANTABILITY, SATISFACTORY QUALITY, NON-INFRINGEMENT OR FITNESS FOR A PARTICULAR PURPOSE WITH RESPECT TO THE DOCUMENT. For the avoidance of doubt, Arm makes no representation with respect to, and has undertaken no analysis to identify or understand the scope and content of, third party patents, copyrights, trade secrets, or other rights.

This document may include technical inaccuracies or typographical errors.

TO THE EXTENT NOT PROHIBITED BY LAW, IN NO EVENT WILL ARM BE LIABLE FOR ANY DAMAGES, INCLUDING WITHOUT LIMITATION ANY DIRECT, INDIRECT, SPECIAL, INCIDENTAL, PUNITIVE, OR CONSEQUENTIAL DAMAGES, HOWEVER CAUSED AND REGARDLESS OF THE THEORY OF LIABILITY, ARISING OUT OF ANY USE OF THIS DOCUMENT, EVEN IF ARM HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

This document consists solely of commercial items. You shall be responsible for ensuring that any use, duplication or disclosure of this document complies fully with any relevant export laws and regulations to assure that this document or any portion thereof is not exported, directly or indirectly, in violation of such export laws. Use of the word "partner" in reference to Arm's customers is not intended to create or refer to any partnership relationship with any other company. Arm may make changes to this document at any time and without notice.

If any of the provisions contained in these terms conflict with any of the provisions of any click through or signed written agreement covering this document with Arm, then the click through or signed written agreement prevails over and supersedes the conflicting provisions of these terms. This document may be translated into other languages for convenience, and you agree that if there is any conflict between the English version of this document and any translation, the terms of the English version of the Agreement shall prevail.

The Arm corporate logo and words marked with ® or ™ are registered trademarks or trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere. All rights reserved. Other brands and names mentioned in this document may be the trademarks of their respective owners. Please follow Arm's trademark usage guidelines at <https://www.arm.com/company/policies/trademarks>.

Copyright © 2019-2022 Arm® Limited (or its affiliates). All rights reserved.

Arm Limited. Company 02557590 registered in England.

110 Fulbourn Road, Cambridge, England CB1 9NJ.

(LES-PRE-20349)

Confidentiality status

This document is Non-Confidential. The right to use, copy and disclose this document may be subject to license restrictions in accordance with the terms of the agreement entered into by Arm and the party that Arm delivered this document to.

Unrestricted Access is an Arm internal classification.

Feedback

Arm welcomes feedback on this product and its documentation. To provide feedback on Arm® Neoverse™ CMN-650 Coherent Mesh Network , create a ticket on <https://support.developer.arm.com>.

To provide feedback on the document, fill the following survey: <https://developer.arm.com/documentation-feedback-survey>.

Inclusive language commitment

Arm values inclusive communities. Arm recognizes that we and our industry have used language that can be offensive. Arm strives to lead the industry and create change.

If you find offensive language in this document, please email terms@arm.com.

Contents

Introduction	5
Scope	5
Categorization of errata	5
Change Control	6
Errata summary table	7
Errata descriptions	8
Category A	8
Category A (rare)	8
Category B	9
1873199 SECC error on ABF operation can cause coherency failures for other memory addresses	9
Category B (rare)	10
Category C	11
2741287 RAS HN-I and SBSX ERRGSR registers do not capture correct device instance information	11
1711597 CMN-Rhodes Cbusy thresholds greater than 256 not functional	12

Introduction

Scope

This document describes errata categorized by level of severity. Each description includes:

- The current status of the erratum.
- Where the implementation deviates from the specification and the conditions required for erroneous behavior to occur.
- The implications of the erratum with respect to typical applications.
- The application and limitations of a workaround where possible.

Categorization of errata

Errata are split into three levels of severity and further qualified as common or rare:

Category A	A critical error. No workaround is available or workarounds are impactful. The error is likely to be common for many systems and applications.
Category A (Rare)	A critical error. No workaround is available or workarounds are impactful. The error is likely to be rare for most systems and applications. Rare is determined by analysis, verification and usage.
Category B	A significant error or a critical error with an acceptable workaround. The error is likely to be common for many systems and applications.
Category B (Rare)	A significant error or a critical error with an acceptable workaround. The error is likely to be rare for most systems and applications. Rare is determined by analysis, verification and usage.
Category C	A minor error.

Change Control

Errata are listed in this section if they are new to the document, or marked as "updated" if there has been any change to the erratum text. Fixed errata are not shown as updated unless the erratum text has changed. The [errata summary table](#) identifies errata that have been fixed in each product revision.

28-Sep-2022: Changes in document version v8.0

ID	Status	Area	Category	Summary
2741287	New	Programmer	Category C	RAS HN-I and SBSX ERRGSR registers do not capture correct device instance information

17-Sep-2021: Changes in document version v7.0

No new or updated errata in this document version.

08-Dec-2020: Changes in document version v6.0

No new or updated errata in this document version.

28-Aug-2020: Changes in document version v5.0

ID	Status	Area	Category	Summary
1873199	New	Programmer	Category B	SECC error on ABF operation can cause coherency failures for other memory addresses

26-May-2020: Changes in document version v4.0

No new or updated errata in this document version.

16-Apr-2020: Changes in document version v3.0

ID	Status	Area	Category	Summary
1711597	New	Programmer	Category C	CMN-Rhodes Cbusy thresholds greater than 256 not functional

11-Nov-2019: Changes in document version v2.0

No new or updated errata in this document version.

04-Jun-2019: Changes in document version v1.0

No errata in this document version.

Errata summary table

The errata associated with this product affect the product versions described in the following table.

ID	Area	Category	Summary	Found in versions	Fixed in version
1873199	Programmer	Category B	SECC error on ABF operation can cause coherency failures for other memory addresses	r0p0, r1p0, r1p1, r1p2	r2p0
2741287	Programmer	Category C	RAS HN-I and SBSX ERRGSR registers do not capture correct device instance information	r0p0, r1p0, r1p1, r1p2, r2p0	Open
1711597	Programmer	Category C	CMN-Rhodes Cbusy thresholds greater than 256 not functional	r1p0	r1p1

Errata descriptions

Category A

There are no errata in this category.

Category A (rare)

There are no errata in this category.

Category B

1873199

SECC error on ABF operation can cause coherency failures for other memory addresses

Status

Affects: CMN-Rhodes

Fault Type: Programmer CAT-B

Fault Status: Present in r0p0, r1p0, r1p1, and r1p2. Fixed in r2p0.

Description

CMN-Rhodes supports Address Based Flush (ABF) where upper and lower system addresses can be programmed and then request hardware based engine to flush out that address range from all System Level Caches (SLC). This ABF state machine works in presence of other memory requests.

Single-bit ECC errors on the ABF accesses can corrupt the CMN Snoop Filter state, and result in coherency failures for other unrelated memory addresses.

Configurations Affected

Any configuration of CMN-Rhodes where ABF is used.

Conditions

This bug appears when following three conditions occur:

- SLC address from flush set/way is outside ABF programmed range AND
- SLC Tag read has single bit ECC error AND
- There is independent request in pipeline N cycles ahead of ABF request (where N is SLC_TAG_RAM_LATENCY)
In this case, ABF request corrupts SF vector for independent request that's ahead of ABF causing coherency failure.

Implications

The ABF flush sequence can cause coherency fails for unrelated memory addresses during the sequence.

Workaround

Use the CMN power management features to flush the SLC, flushes the full SLC contents vs. the upper/lower range.

Category B (rare)

There are no errata in this category.

Category C

2741287

RAS HN-I and SBSX ERRGSR registers do not capture correct device instance information

Status

Affects: CMN-650

Fault Type: Programmer Category C

Fault Status: r0p0, r1p0, r1p1, r1p2, r2p0. Open.

Description

The CMN Error Group Status Registers (ERRGSR) capture device instance error information for RAS events. The registers indicate the device instance within a device group. The registers are not updated correctly for the HN-I and SBSX device groups, so cannot be used to determine the device instances for RAS events.

Configurations Affected

All CMN-650 configurations that use RAS error logging.

Conditions

A RAS event triggered by an HN-I or SBSX device.

Implications

Software cannot use the HN-I or SBSX ERRGSR registers.

Workaround

The RAS handler must read the individual HN-I and SBSX instance RAS logging registers when RAS interrupts occur.

1711597

CMN-Rhodes Cbusy thresholds greater than 256 not functional

Status

Affects: CMN-Rhodes

Fault Type: Programmer CAT-C

Fault Status: Present in r1p0. Fixed in r1p1.

Description

HN-F has counters which track CBusy values from an SN over a number of transactions (programmable value). These counters are then used to estimate the SN's busyness level and throttle the outstanding transactions. These counters were sized incorrectly to 8-bits and hence overflow under certain conditions. Per the TRM, 128 or 256 are the allowed values for the transaction count.

This feature is not enabled by default in CMN-Rhodes. Its a user programmable feature to enable throttling of requests to SN.

Configurations Affected

All configurations of CMN-Rhodes R1P0 EAC

Conditions

For this bug to occur, below conditions must be met:

- *por_hnf_cfg_ctl* register's *hnf_adv_cbusy_mode_en* must be set to 1. This enables the advanced CBusy mode.
- *por_hnf_cbusy_sn_ctl* register's *hnf_cbusy_txn_cnt* field must be set to 256 AND
- All the responses from SN must have the same CBusy value of 11 or 10 or 01, over the 256 transaction responses

Implications

When the counter overflows, the absolute SN CBusy is calculated incorrectly. For example, if the SN responded with cBusy=11 (**very busy**) over the 256 transaction, the counter will instead roll over to 0 upon the 256th response. Hence the HNF will estimate the final CBusy value for this SN as CBusy=00 (**not busy**) and continue to send requests at full capacity. This may lead to lower performance as the SN will likely retry all requests. Instead, if the requests were throttled at the HN-F, the retry rate would be reduced and lead to overall higher performance.

Workaround

Instead of 256, if the user programs 255 in the transaction count, the feature is fully functional.