



## Arm Cortex-X2 (MP121)

### Software Developer Errata Notice

Date of issue: 01-Nov-2022


Non-Confidential

Document version: v15.0

Copyright © 2020-2022 Arm® Limited (or its affiliates). All rights reserved.

Document ID: SDEN-1775100

This document contains all known errata since the r0p0 release of the product.



## Non-confidential proprietary notice

This document is protected by copyright and other related rights and the practice or implementation of the information contained in this document may be protected by one or more patents or pending patent applications. No part of this document may be reproduced in any form by any means without the express prior written permission of Arm. No license, express or implied, by estoppel or otherwise to any intellectual property rights is granted by this document unless specifically stated.

Your access to the information in this document is conditional upon your acceptance that you will not use or permit others to use the information for the purposes of determining whether implementations infringe any third party patents.

THIS DOCUMENT IS PROVIDED "AS IS". ARM PROVIDES NO REPRESENTATIONS AND NO WARRANTIES, EXPRESS, IMPLIED OR STATUTORY, INCLUDING, WITHOUT LIMITATION, THE IMPLIED WARRANTIES OF MERCHANTABILITY, SATISFACTORY QUALITY, NON-INFRINGEMENT OR FITNESS FOR A PARTICULAR PURPOSE WITH RESPECT TO THE DOCUMENT. For the avoidance of doubt, Arm makes no representation with respect to, and has undertaken no analysis to identify or understand the scope and content of, third party patents, copyrights, trade secrets, or other rights.

This document may include technical inaccuracies or typographical errors.

TO THE EXTENT NOT PROHIBITED BY LAW, IN NO EVENT WILL ARM BE LIABLE FOR ANY DAMAGES, INCLUDING WITHOUT LIMITATION ANY DIRECT, INDIRECT, SPECIAL, INCIDENTAL, PUNITIVE, OR CONSEQUENTIAL DAMAGES, HOWEVER CAUSED AND REGARDLESS OF THE THEORY OF LIABILITY, ARISING OUT OF ANY USE OF THIS DOCUMENT, EVEN IF ARM HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

This document consists solely of commercial items. You shall be responsible for ensuring that any use, duplication or disclosure of this document complies fully with any relevant export laws and regulations to assure that this document or any portion thereof is not exported, directly or indirectly, in violation of such export laws. Use of the word "partner" in reference to Arm's customers is not intended to create or refer to any partnership relationship with any other company. Arm may make changes to this document at any time and without notice.

If any of the provisions contained in these terms conflict with any of the provisions of any click through or signed written agreement covering this document with Arm, then the click through or signed written agreement prevails over and supersedes the conflicting provisions of these terms. This document may be translated into other languages for convenience, and you agree that if there is any conflict between the English version of this document and any translation, the terms of the English version of the Agreement shall prevail.

The Arm corporate logo and words marked with ® or ™ are registered trademarks or trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere. All rights reserved. Other brands and names mentioned in this document may be the trademarks of their respective owners. Please follow Arm's trademark usage guidelines at <https://www.arm.com/company/policies/trademarks>.

Copyright © 2020-2022 Arm® Limited (or its affiliates). All rights reserved.

Arm Limited. Company 02557590 registered in England.

110 Fulbourn Road, Cambridge, England CB1 9NJ.

(LES-PRE-20349)

## Confidentiality status

This document is Non-Confidential. The right to use, copy and disclose this document may be subject to license restrictions in accordance with the terms of the agreement entered into by Arm and the party that Arm delivered this document to.

Unrestricted Access is an Arm internal classification.

## Product status

The information in this document is for a product in development and is not final.

## Feedback

Arm welcomes feedback on this product and its documentation. To provide feedback on Arm Cortex-X2 (MP121), create a ticket on <https://support.developer.arm.com>.

To provide feedback on the document, fill the following survey: <https://developer.arm.com/documentation-feedback-survey>.

## Inclusive language commitment

Arm values inclusive communities. Arm recognizes that we and our industry have used language that can be offensive. Arm strives to lead the industry and create change.

If you find offensive language in this document, please email [terms@arm.com](mailto:terms@arm.com).

# Contents

<b>r2p0 implementation fixes</b>	10
<b>Introduction</b>	11
Scope	11
Categorization of errata	11
<b>Change Control</b>	12
<b>Errata summary table</b>	24
<b>Errata descriptions</b>	34
Category A	34
1791789 Fault info captured in FAR and ESR registers for LDP 64-bit variant might be incorrect	34
Category A (rare)	35
Category B	36
1785648 Atomic store instructions to shareable write-back memory might cause memory consistency failures	36
1793423 An unexpected data abort might occur under specific micro-architectural conditions following an abort on an earlier instruction	37
1801992 Hardware Access/Dirty flag updates might indicate successful completion, but PTE is not updated	38
1813969 TLBI range instructions with NUM>31 may not invalidate all required entries+	39
1863568 Core might generate Breakpoint exception on incorrect IA	40
1887102 IPA based TLB Invalidate might fail to invalidate translation table entries caching translations for the Trace Buffer Extension	41
1887413 Executing a SVE load with no active predicates might result in a deadlock under certain micro-architectural conditions	42
1890822 Stage 2 abort during Secure EL1 translation might report incorrect NS value in HPFAR_EL2	43
1901946 Executing software prefetch instructions from a context with memory tagging enabled might lead to corruption of architecture state	44
1906301 Core might deadlock when memory-mapped read to Debug/Trace/PMU register is followed by WFI or WFE	45
1914047 External debugger access to Debug registers might not work during Warm reset	46
1916945 Store operation that encounters multiple hits in the TLB might access regions of memory with attributes that could not be accessed at that Exception level or Security state	47
1917258 Non-fault SVE load does not update FFR when it reads data with ECC error or external abort	48
1918765 CFP RCTX and CPP RCTX instructions might incorrectly execute as a NOP in ELO	49

1927200	Atomic instructions with acquire semantics might not be ordered with respect to older stores with release semantics	50
1934260	Tag checked streaming write might report false fail	52
1984319	Incorrect read value for Performance Monitors Common Event Identification register	53
2002765	Embedded Trace of WFI or WFE instructions might corrupt PE architectural state	55
2008768	RAS errors during core power down might cause a deadlock	57
2012097	TRBE writes to MTE tagged pages might not report external aborts	59
2017096	Streaming STG and STG2 performance lower than expected with TCF=NONE	60
2023111	Utility Bus register accesses to reserved addresses of PE might hang	61
2054223	The trace data is not flushed completely during a TSB instruction executed in prohibited region	62
2058056	Disabling of data prefetcher with outstanding prefetch TLB miss might cause a deadlock	63
2081180	Executing a WFI or WFE instruction after a STREX instruction might result in a deadlock under specific conditions	64
2083908	Execution of ST2G instructions in close proximity might cause loss of MTE allocation tag data	66
2119858	Trace data might get overwritten in TRBE FILL mode	67
2136059	The CPP instruction will apply to an incorrect EL context	68
2147715	A CFP instruction might not invalidate the correct resources	69
2216384	PDP deadlock due to CMP/CMN + B.AL/B.NV fusion	70
2219376	Enabling TRBE might cause a data write to a page with the wrong ASID when owning Exception level is EL1	71
2224489	TRBE might cause a data write to an out-of-range address which is not reserved for TRBE	73
2267065	A CFP instruction might execute with incorrect upper ASID or VMID bits	74
2282622	Continuous failing STREX because of another PE executing prefetch for store behind consistently mispredicted branch	75
2291219	Denied power down request might prevent completion of future power down request	76
2371105	Translation table walk folding into an L1 prefetch might cause data corruption	77
2381390	A continuous stream of incoming DVM syncs may cause TRBE to prevent the core from forward progressing	78
2701952	The core might fetch stale instruction from memory when both Stage 1 Translation and Instruction Cache are Disabled with Stage 2 forced Write-Back	79
2742423	Page crossing access that generates an MMU fault on the second page could result in a livelock	81
2768515	The core might deadlock during powerdown sequence	82

2778471	The PE might generate memory accesses using invalidated mappings after completion of a DVM SYNC operation.	83
Category B (rare)		83
Category C		84
1786338	Memory uploads and downloads via memory access mode within Debug state can fail to accurately read or write memory contents	84
1787272	TSB instruction completion can be delayed when executed in region where trace is allowed	86
1799975	Watchpoint Exception on DC ZVA does not report correct address in FAR or EDWAR	87
1804175	CTI event from the core to the external DebugBlock might be dropped	88
1804563	Trace Buffer Extension unit might write trace packets to memory using incorrect memory page attributes	89
1817593	Persistent faults on speculative elements of SVE First-fault gather-load instructions might result in deadlock	90
1827136	External debug accesses in memory access mode with SCTLR_ELx.IESB set might result in unpredictable behavior	91
1838906	Noncompliance with prioritization of Exception Catch debug events	92
1851171	Transient L2 tag double bit Errors might cause data corruption	94
1851323	Incorrect trace timestamp value when self-hosted trace is disabled	95
1851816	The MPAM value associated with MMU descriptor fetch requests might be incorrect	96
1855551	ERR0MISC0_EL1.SUBARRAY, ERR0STATUS.CE, and ERR0STATUS.DE values for ECC errors in the L1 data cache might be incorrect	96
1859562	Incorrect read value for the Trace ID Register 3 SYSSTALL field	98
1862651	Incorrect read value for External Debug Processor Feature Register	99
1865453	The values for fields ID_AA64ZFR0_EL1.{SM4,SHA3,AES} read incorrectly as non-zero	100
1868638	The core does not treat the BAS field of the Debug Breakpoint Control Register as RES1	101
1870363	L2 data RAM may fail to report corrected ECC errors	102
1875555	Compare and Swap (CAS) instructions with stack pointer as base register are incorrectly treated as checked accesses	103
1875745	A Checked load that fails a Tag Check could set the ESR to an incorrect value	104
1884880	The core might report incorrect fetch address to FAR_ELx when the core is fetching an instruction from a virtual address associated with a page table entry which has been modified	105
1893664	Accessing a memory location using mismatched shareability attributes when MTE tag checking is enabled might lose coherency or deadlock	106

1896171	Access to External Debug Auxiliary Processor Feature Register might incorrectly return an error response	107
1899211	Some corrected errors might incorrectly increment ERR0MISC0.CECR or ERR0MISC0.CECO	108
1899435	PFG duplicate reported faults through a Warm reset	109
1909702	IDATAn_EL3 might represent incorrect value after direct memory access to internal memory for Instruction TLB	110
1911676	TFSR contents might be incorrect after executing a page crossing SVE predicated load instruction	111
1919240	The PE might deadlock if Pseudofault Injection is enabled in Debug State	112
1920415	Trace Buffer might write trace packets to memory using incorrect cache attributes	113
1920634	A Checked store with poisoned tags might result in a Tag Check Fail instead of taking an SError interrupt exception	114
1920871	MPAM value associated with translation table walk request might be incorrect	115
1925506	Unsupported atomic fault due to memory type defined in first stage of translation might result in exception being taken to EL2	116
1926908	Access with additional latency from alignment (LDST_ALIGN_LAT) PMU event does not count	117
1927566	ERR0MISC0_EL1.SUBARRAY value for ECC errors in the L1 data cache might be incorrect	118
1929989	Event Stream from the Virtual Counter is not correctly disabled by VHE in Secure State	119
1938354	Incorrect fault status code might be reported in Trace Buffer Extension register TRBSR_EL1.FSC	120
1949697	A Checked store that crosses a page boundary might not perform a Tag Check	121
1971496	VMID value in trace packets might be incorrect	122
1975917	AMU Event 0x0011, Core frequency cycles might increment incorrectly when the core is in WFI or WFE state	123
1980906	Reset Catch debug event might not cause core to enter Debug state immediately after Cold reset	125
1986267	DRPS might not execute correctly in Debug state with SCTLr_ELx.IESB set in the current EL	126
1989365	Floating-point Operations speculatively executed PMU events are not counted	127
2000010	Execution of STG instructions in close proximity might incorrectly write MTE Allocation Tag to memory more than once	128
2002779	CPU might fetch incorrect instruction from a page programmed as non-cacheable in stage-1 translation and as device memory in stage-2 translation	129
2017087	DSB might not guarantee completion of direct reads of L2 cache memories	130
2018317	External APB write to a register located at offset 0x084 might incorrectly issue a write to External Debug Instruction Transfer Register	131

2025108	Corrupted register state results from executing specific form of SEL instruction followed by SVE AESMC or AESIMC instruction	133
2050953	External aborts for streaming writes to MTE tagged pages may report multiple errors	134
2052424	An execution of MSR instruction might not update the destination register correctly when an external debugger initiates an APB write operation to update debug registers	135
2054222	Trace data lost during collection stop in TRBE	137
2058367	L3D_CACHE_ALLOC PMU inaccurate when using WriteEvictOrEvict transactions	138
2058540	Incorrect Fault Status code reported for predicated SVE op	139
2061107	Tag check fail might not be reported for an unaligned predicated SVE store	140
2089668	OSECCR_EL1/EDECCR is incorrectly included in the Warm Reset domain	141
2093019	Extra A-sync packet might get written to Trace Buffer in Trace prohibited region	142
2109742	Speculative access to a recently unmapped physical address previously containing page tables might occur	143
2112535	L1D_CACHE_INVALID and L2D_CACHE_INVALID PMU events fail to increment for SnpPreferUnique and SnpPreferUniqueFwd	144
2113481	MPAM value associated with instruction fetch might be incorrect	145
2117983	Data abort on SVE first fault load might be routed to incorrect Exception level	146
2141645	A64 WFI or A64 WFE executed in Debug state suspends execution indefinitely	147
2143136	Some SVE PMU events count incorrectly	149
2146514	PMU Event MEM_ACCESS_CHECKED_WR, 0x4026 counts incorrectly and MEM_ACC_CHECKED 0x4024 might be incorrect	151
2154216	FAR_ELx contents for a Data Abort exception on SVE first fault contiguous load instruction due to Tag Check fail might be incorrect	152
2159150	Direct access of L2 data RAMs using RAMINDEX returns incomplete data	153
2174188	PMU_HOVFS event not always exported when self-hosted trace is disabled	154
2178034	An SError might not be reported for an atomic store that encounters data poison	155
2186347	64 bit source SVE PMULLB/T not considered Cryptography instruction	156
2227174	Streaming writes to memory mapped Non-shareable and write-back might cause data corruption because of reordering	157
2238108	Read or write from Secure EL1 for ICV_BPR1_EL1 register might not work	158
2238111	Reads of DISR_EL1 incorrectly return 0s while in Debug State	159
2239139	DRPS instruction is not treated as UNDEFINED at EL0 in Debug state	160
2243871	ELR_ELx[63:48] might hold incorrect value when PE disables address translation	161
2245716	TRBE might use incorrect Cacheability attributes for TRBE data when address translation is disabled	162
2245832	ESR_ELx contents for a Data Abort exception might be incorrect when an L1D tag double bit error is encountered	163



2247178	L1 MTE Tag poison is not cleared	164
2254450	L1 Data poison is not cleared by a store	165
2276444	PMU event for full/partial/empty/not full predicate incorrect for some SVE instructions	166
2278134	PMU L1D_CACHE_REFILL_OUTER is inaccurate	167
2283666	Lower priority exception might be reported when abort condition is detected at both stages of translation	168
2307829	ESR_ELx.ISV can be set incorrectly for an external abort on translation table walk	169
2317617	ESR_ELx contents for a Data Abort exception might be incorrect when a data double bit error or external abort is encountered	170
2334390	L2 tag RAM double-bit ECC error might lead to the PE not responding to a forwarding snoop	171
2344960	CSSELR_EL1.TnD is RAZ/WI when CSSELR_EL1.InD == 0x1	172
2382765	Incorrect read value for Performance Monitors Configuration Register	173
2391680	Software-step not done after exit from Debug state with an illegal value in DSPSR	174
2444421	PMU STALL_SLOT_BACKEND and STALL_SLOT_FRONTEND events count incorrectly	175
2643627	ERXPFPGCDN_EL1 register is incorrectly written on Warm reset	176
2647274	Incorrect read value for Performance Monitors Control Register	177
2652240	FAR_ELx contents for a Data Abort exception on SVE first fault contiguous load instruction due to Tag Check fail might be incorrect	178
2676362	Execution of STG instructions in close proximity might cause loss of MTE allocation tag data	179
2692441	L3D PMU events may be inaccurate	180
2694769	MTE checked load might read an old value of allocation tag by not complying with address dependency ordering	181
2712632	Incorrect read value for Performance Monitors Configuration Register EX field	182
2769023	STALL_BACKEND_MEM, Memory stall cycles AMU event count incorrectly	183

## r2p0 implementation fixes

Note the following errata might be fixed in some implementations of r2p0. This can be determined by reading the REVIDR\_EL1 register where a set bit indicates that the erratum is fixed in this part.

REVIDR_EL1[0]	1791789 Fault info captured in FAR and ESR registers for LDP 64-bit variant could be incorrect
REVIDR_EL1[1]	1975917 AMU Event 0x0011, Core frequency cycles might increment incorrectly when core is in WFI or WFE state
REVIDR_EL1[2]	1980906 Reset Catch debug event might not cause core to enter Debug state immediately after Cold reset
REVIDR_EL1[3]	2017096 Streaming STG and STG2 performance lower than expected with TCF=NONE

Note that there is no change to the MIDR\_EL1 which remains at r2p0. Software will identify this release through the combination of MIDR\_EL1 and REVIDR\_EL1.

# Introduction

## Scope

This document describes errata categorized by level of severity. Each description includes:

- The current status of the erratum.
- Where the implementation deviates from the specification and the conditions required for erroneous behavior to occur.
- The implications of the erratum with respect to typical applications.
- The application and limitations of a workaround where possible.

## Categorization of errata

Errata are split into three levels of severity and further qualified as common or rare:

<b>Category A</b>	A critical error. No workaround is available or workarounds are impactful. The error is likely to be common for many systems and applications.
<b>Category A (Rare)</b>	A critical error. No workaround is available or workarounds are impactful. The error is likely to be rare for most systems and applications. Rare is determined by analysis, verification and usage.
<b>Category B</b>	A significant error or a critical error with an acceptable workaround. The error is likely to be common for many systems and applications.
<b>Category B (Rare)</b>	A significant error or a critical error with an acceptable workaround. The error is likely to be rare for most systems and applications. Rare is determined by analysis, verification and usage.
<b>Category C</b>	A minor error.

# Change Control

Errata are listed in this section if they are new to the document, or marked as "updated" if there has been any change to the erratum text. Fixed errata are not shown as updated unless the erratum text has changed. The [errata summary table](#) identifies errata that have been fixed in each product revision.

## 01-Nov-2022: Changes in document version v15.0

ID	Status	Area	Category	Summary
<a href="#">2742423</a>	New	Programmer	Category B	Page crossing access that generates an MMU fault on the second page could result in a livelock
<a href="#">2768515</a>	New	Programmer	Category B	The core might deadlock during powerdown sequence
<a href="#">2778471</a>	New	Programmer	Category B	The PE might generate memory accesses using invalidated mappings after completion of a DVM SYNC operation
<a href="#">1975917</a>	Updated	Programmer	Category C	AMU Event 0x0011, Core frequency cycles might increment incorrectly when the core is in WFI or WFE state
<a href="#">2769023</a>	New	Programmer	Category C	STALL_BACKEND_MEM, Memory stall cycles AMU event count incorrectly

## 09-Sep-2022: Changes in document version v14.0

ID	Status	Area	Category	Summary
<a href="#">2282622</a>	Updated	Programmer	Category B	Continuous failing STREX because of another PE executing prefetch for store behind consistently mispredicted branch
<a href="#">2701952</a>	New	Programmer	Category B	Core might fetch stale instruction from memory when both Stage 1 Translation and Instruction Cache are Disabled with Stage 2 forced Write-Back
<a href="#">2652240</a>	New	Programmer	Category C	FAR_ELx contents for a Data Abort exception on SVE first fault contiguous load instruction due to Tag Check fail might be incorrect
<a href="#">2676362</a>	New	Programmer	Category C	Execution of STG instructions in close proximity might cause loss of MTE allocation tag data
<a href="#">2692441</a>	New	Programmer	Category C	L3D PMU events may be inaccurate
<a href="#">2694769</a>	New	Programmer	Category C	MTE checked load might read an old value of allocation tag by not complying with address dependency ordering
<a href="#">2712632</a>	New	Programmer	Category C	Incorrect read value for Performance Monitors Configuration Register EX field

**26-May-2022: Changes in document version v13.0**

ID	Status	Area	Category	Summary
<a href="#">2391680</a>	New	Programmer	Category C	Software-step not done after exit from Debug state with an illegal value in DSPSR
<a href="#">2444421</a>	New	Programmer	Category C	PMU STALL_SLOT_BACKEND and STALL_SLOT_FRONTEND events count incorrectly
<a href="#">2643627</a>	New	Programmer	Category C	ERXPFPCDN_EL1 register is incorrectly written on Warm reset
<a href="#">2647274</a>	New	Programmer	Category C	Incorrect read value for Performance Monitors Control Register

**16-Dec-2021: Changes in document version v12.0**

ID	Status	Area	Category	Summary
<a href="#">1791789</a>	Updated	Programmer	Category A	Fault info captured in FAR and ESR registers for LDP 64-bit variant could be incorrect
<a href="#">1984319</a>	Updated	Programmer	Category B	Incorrect read value for Performance Monitors Common Event Identification Register
<a href="#">2002765</a>	Updated	Programmer	Category B	Embedded Trace of WFI or WFE instructions might corrupt PE architectural state
<a href="#">2008768</a>	Updated	Programmer	Category B	RAS errors during core power down might cause a deadlock
<a href="#">2012097</a>	Updated	Programmer	Category B	TRBE writes to MTE tagged pages might not report external aborts
<a href="#">2017096</a>	Updated	Programmer	Category B	Streaming STG and STG2 performance lower than expected with TCF=NONE
<a href="#">2023111</a>	Updated	Programmer	Category B	Utility Bus register accesses to reserved addresses of PE might hang
<a href="#">2054223</a>	Updated	Programmer	Category B	The trace data is not flushed completely during a TSB instruction executed in prohibited region
<a href="#">2081180</a>	Updated	Programmer	Category B	Executing a WFI or WFE instruction after a STREX instruction might result in a deadlock under specific conditions
<a href="#">2083908</a>	Updated	Programmer	Category B	Execution of ST2G instructions in close proximity might cause loss of MTE allocation tag data
<a href="#">2119858</a>	Updated	Programmer	Category B	Trace data might get overwritten in TRBE FILL mode
<a href="#">2136059</a>	Updated	Programmer	Category B	The CPP instruction will apply to an incorrect EL context
<a href="#">2147715</a>	Updated	Programmer	Category B	A CFP instruction might not invalidate the correct resources
<a href="#">2216384</a>	Updated	Programmer	Category B	PDP deadlock due to CMP/CMN + B.AL/B.NV fusion
<a href="#">2219376</a>	Updated	Programmer	Category B	Enabling TRBE might cause a data write to a page with the wrong ASID when owning Exception level is EL1
<a href="#">2224489</a>	Updated	Programmer	Category B	TRBE might cause a data write to an out-of-range address which is not reserved for TRBE
<a href="#">2267065</a>	Updated	Programmer	Category B	A CFP instruction might execute with incorrect upper ASID or VMID bits
<a href="#">2282622</a>	New	Programmer	Category B	Continuous failing STREX because of another PE executing prefetch for store behind consistently mispredicted branch

ID	Status	Area	Category	Summary
<a href="#">2291219</a>	Updated	Programmer	Category B	Denied power down request might prevent completion of future power down request
<a href="#">2371105</a>	New	Programmer	Category B	Translation table walk folding into an L1 prefetch might cause data corruption
<a href="#">2381390</a>	New	Programmer	Category B	A continuous stream of incoming DVM syncs may cause TRBE to prevent the CPU from forward progressing
<a href="#">1899211</a>	Updated	Programmer	Category C	Some corrected errors might incorrectly increment ERR0MISC0.CECR or ERR0MISC0.CECO
<a href="#">1920871</a>	Updated	Programmer	Category C	MPAM value associated with translation table walk request might be incorrect
<a href="#">1938354</a>	Updated	Programmer	Category C	Incorrect fault status code might be reported in Trace Buffer Extension register TRBSR_EL1.FSC
<a href="#">1911676</a>	Updated	Programmer	Category C	TFSR contents might be incorrect after executing a page crossing SVE predicated load instruction
<a href="#">1949697</a>	Updated	Programmer	Category C	A Checked store that crosses a page boundary might not perform a Tag Check
<a href="#">1971496</a>	Updated	Programmer	Category C	VMID value in trace packets might be incorrect
<a href="#">1975917</a>	Updated	Programmer	Category C	AMU Event 0x0011, Core frequency cycles might increment incorrectly when the core is in WFI or WFE state
<a href="#">1980906</a>	Updated	Programmer	Category C	Reset Catch debug event might not cause core to enter Debug state immediately after Cold reset
<a href="#">1986267</a>	Updated	Programmer	Category C	DRPS might not execute correctly in Debug state with SCTLR_ELx.IESB set in the current EL
<a href="#">1989365</a>	Updated	Programmer	Category C	Floating-point Operations speculatively executed PMU events are not counted
<a href="#">2000010</a>	Updated	Programmer	Category C	Execution of STG instructions in close proximity might incorrectly write MTE Allocation Tag to memory more than once
<a href="#">2002779</a>	Updated	Programmer	Category C	CPU might fetch incorrect instruction from a page programmed as non-cacheable in stage-1 translation and as device memory in stage-2 translation
<a href="#">2017087</a>	Updated	Programmer	Category C	DSB might not guarantee completion of direct reads of L2 cache memories
<a href="#">2018317</a>	Updated	Programmer	Category C	External APB write to a register located at offset 0x084 might incorrectly issue a write to External Debug Instruction Transfer Register
<a href="#">2025108</a>	Updated	Programmer	Category C	Corrupted register state results from executing specific form of SEL instruction followed by SVE AESMC or AESIMC instruction
<a href="#">2050953</a>	Updated	Programmer	Category C	External aborts for streaming writes to MTE tagged pages may report multiple errors
<a href="#">2052424</a>	Updated	Programmer	Category C	An execution of MSR instruction might not update the destination register correctly when an external debugger initiates APB write operation to update debug registers
<a href="#">2054222</a>	Updated	Programmer	Category C	Trace data lost during collection stop in TRBE

ID	Status	Area	Category	Summary
<a href="#">2058367</a>	Updated	Programmer	Category C	L3D_CACHE_ALLOC PMU inaccurate when using WriteEvictOrEvict transactions
<a href="#">2058540</a>	Updated	Programmer	Category C	Incorrect Fault Status code reported for predicated SVE op
<a href="#">2061107</a>	Updated	Programmer	Category C	Tag check fail might not be reported for an unaligned predicated SVE store
<a href="#">2089668</a>	Updated	Programmer	Category C	OSECCR_EL1/EDECCR is incorrectly included in the Warm Reset domain
<a href="#">2093019</a>	Updated	Programmer	Category C	Extra A-sync packet might get written to Trace Buffer in Trace prohibited region
<a href="#">2109742</a>	Updated	Programmer	Category C	Speculative access to a recently unmapped physical address previously containing page tables might occur
<a href="#">2112535</a>	Updated	Programmer	Category C	L1D_CACHE_INVALID and L2D_CACHE_INVALID PMU events fail to increment for SnpPreferUnique and SnpPreferUniqueFwd
<a href="#">2117983</a>	Updated	Programmer	Category C	Data abort on SVE first fault load might be routed to incorrect Exception level
<a href="#">2141645</a>	Updated	Programmer	Category C	A64 WFI or A64 WFE executed in Debug state suspends execution indefinitely
<a href="#">2143136</a>	Updated	Programmer	Category C	Some SVE PMU events count incorrectly
<a href="#">2146514</a>	Updated	Programmer	Category C	PMU Event MEM_ACCESS_CHECKED_WR, 0x4026 counts incorrectly and MEM_ACC_CHECKED 0x4024 might be incorrect
<a href="#">2154216</a>	Updated	Programmer	Category C	FAR_ELx contents for a Data Abort exception on SVE first fault contiguous load instruction due to Tag Check fail might be incorrect
<a href="#">2159150</a>	Updated	Programmer	Category C	Direct access of L2 data RAMs using RAMINDEX returns incomplete data
<a href="#">2174188</a>	Updated	Programmer	Category C	PMU_HOVFS event not always exported when self-hosted trace is disabled
<a href="#">2178034</a>	Updated	Programmer	Category C	An SError might not be reported for an atomic store that encounters data poison
<a href="#">2186347</a>	Updated	Programmer	Category C	64 bit source SVE PMULLB/T not considered Cryptography instruction
<a href="#">2227174</a>	Updated	Programmer	Category C	Streaming writes to memory mapped Non-shareable and write-back might cause data corruption because of reordering
<a href="#">2238108</a>	Updated	Programmer	Category C	Read or write from Secure EL1 for ICV_BPR1_EL1 register might not work
<a href="#">2238111</a>	Updated	Programmer	Category C	Reads of DISR_EL1 incorrectly return 0s while in Debug State
<a href="#">2239139</a>	Updated	Programmer	Category C	DRPS instruction is not treated as UNDEFINED at EL0 in Debug state
<a href="#">2243871</a>	Updated	Programmer	Category C	ELR_ELx[63:48] might hold incorrect value when PE disables address translation
<a href="#">2245832</a>	Updated	Programmer	Category C	ESR_ELx contents for a Data Abort exception might be incorrect when an L1D tag double bit error is encountered
<a href="#">2245716</a>	Updated	Programmer	Category C	TRBE might use incorrect Cacheability attributes for TRBE data when address translation is disabled
<a href="#">2247178</a>	Updated	Programmer	Category C	L1 MTE Tag poison is not cleared
<a href="#">2254450</a>	New	Programmer	Category C	L1 Data poison is not cleared by a store

ID	Status	Area	Category	Summary
<a href="#">2276444</a>	New	Programmer	Category C	PMU event for full/partial/empty predicate incorrect for some SVE instructions
<a href="#">2278134</a>	New	Programmer	Category C	PMU L1D_CACHE_REFILL_OUTER is inaccurate
<a href="#">2283666</a>	New	Programmer	Category C	Lower priority exception might be reported when abort condition is detected at both stages of translation
<a href="#">2307829</a>	New	Programmer	Category C	ESR_ELx.ISV can be set incorrectly for an external abort on translation table walk
<a href="#">2317617</a>	New	Programmer	Category C	ESR_ELx contents for a Data Abort exception might be incorrect when a data double bit error or external abort is encountered
<a href="#">2334390</a>	New	Programmer	Category C	L2 tag RAM double-bit ECC error might lead to the PE not responding to a forwarding snoop
<a href="#">2344960</a>	New	Programmer	Category C	CSSELR_EL1.TnD is RAZ/WI when CSSELR_EL1.InD == 0x1
<a href="#">2382765</a>	New	Programmer	Category C	Incorrect read value for Performance Monitors Configuration Register

**08-Oct-2021: Changes in document version v11.0**

ID	Status	Area	Category	Summary
<a href="#">2008768</a>	Updated	Programmer	Category B	RAS errors during core power down might cause a deadlock
<a href="#">2147715</a>	Updated	Programmer	Category B	A CFP instruction might not invalidate the correct resources
<a href="#">2267065</a>	New	Programmer	Category B	A CFP instruction might execute with incorrect upper ASID or VMID bits
<a href="#">2291219</a>	New	Programmer	Category B	Denied power down request might prevent completion of future power down request
<a href="#">2141645</a>	Updated	Programmer	Category C	A64 WFI or A64 WFE executed in Debug state suspends execution indefinitely
<a href="#">2227174</a>	Updated	Programmer	Category C	Streaming writes to memory mapped Non-shareable and write-back might cause data corruption because of reordering
<a href="#">2238108</a>	New	Programmer	Category C	Read or write from Secure EL1 for ICV_BPR1_EL1 register might not work
<a href="#">2238111</a>	New	Programmer	Category C	Reads of DISR_EL1 incorrectly return 0s while in Debug State
<a href="#">2239139</a>	New	Programmer	Category C	DRPS instruction is not treated as UNDEFINED at EL0 in Debug state
<a href="#">2243871</a>	New	Programmer	Category C	ELR_ELx[63:48] might hold incorrect value when PE disables address translation
<a href="#">2245716</a>	New	Programmer	Category C	TRBE might use incorrect Cacheability attributes for TRBE data when address translation is disabled
<a href="#">2247178</a>	New	Programmer	Category C	L1 MTE Tag poison is not cleared



**16-Jul-2021: Changes in document version v10.0**

ID	Status	Area	Category	Summary
<a href="#">2147715</a>	New	Programmer	Category B	A CFP instruction might not invalidate the correct resources
<a href="#">2216384</a>	New	Programmer	Category B	PDP deadlock due to CMP/CMN + B.AL/B.NV fusion
<a href="#">2219376</a>	New	Programmer	Category B	Enabling TRBE might cause a data write to a page with the wrong ASID when owning Exception level is EL1
<a href="#">2224489</a>	New	Programmer	Category B	TRBE might cause a data write to an out-of-range address which is not reserved for TRBE
<a href="#">2178034</a>	New	Programmer	Category C	An SError might not be reported for an atomic store that encounters data poison
<a href="#">2186347</a>	New	Programmer	Category C	64 bit source SVE PMULLB/T not considered Cryptography instruction
<a href="#">2227174</a>	New	Programmer	Category C	Streaming writes to memory mapped Non-shareable and write-back might cause data corruption because of reordering
<a href="#">2245832</a>	New	Programmer	Category C	ESR_ELx contents for a Data Abort exception might be incorrect when an L1D tag double bit error is encountered

**08-Jun-2021: Changes in document version v9.0**

ID	Status	Area	Category	Summary
<a href="#">1934260</a>	Updated	Programmer	Category B	Tag checked streaming write might report false fail
<a href="#">2002765</a>	Updated	Programmer	Category B	Embedded Trace of WFI or WFE instructions might corrupt PE architectural state
<a href="#">2136059</a>	New	Programmer	Category B	The CPP instruction will apply to an incorrect EL context
<a href="#">2141645</a>	New	Programmer	Category C	A64 WFI or A64 WFE executed in Debug state suspends execution indefinitely
<a href="#">2143136</a>	New	Programmer	Category C	Some SVE PMU events count incorrectly
<a href="#">2146514</a>	New	Programmer	Category C	PMU Event MEM_ACCESS_CHECKED_WR, 0x4026 counts incorrectly and MEM_ACC_CHECKED 0x4024 might be incorrect
<a href="#">2154216</a>	New	Programmer	Category C	FAR_ELx contents for a Data Abort exception on SVE first fault contiguous load instruction due to Tag Check fail might be incorrect
<a href="#">2159150</a>	New	Programmer	Category C	Direct access of L2 data RAMs using RAMINDEX returns incomplete data
<a href="#">2174188</a>	New	Programmer	Category C	PMU_HOVFS event not always exported when self-hosted trace is disabled

**14-Apr-2021: Changes in document version v8.0**

ID	Status	Area	Category	Summary
<a href="#">1927200</a>	Updated	Programmer	Category B	Atomic instructions with acquire semantics might not be ordered with respect to older stores with release semantics
<a href="#">2058056</a>	New	Programmer	Category B	Disabling of data prefetcher with outstanding prefetch TLB miss might cause a deadlock
<a href="#">2081180</a>	New	Programmer	Category B	Executing a WFI or WFE instruction after a STREX instruction might result in a deadlock under specific conditions
<a href="#">2083908</a>	New	Programmer	Category B	Execution of ST2G instructions in close proximity might cause loss of MTE allocation tag data
<a href="#">2119858</a>	New	Programmer	Category B	Trace data might get overwritten in TRBE FILL mode
<a href="#">2018317</a>	New	Programmer	Category C	External APB write to a register located at offset 0x084 might incorrectly issue a write to External Debug Instruction Transfer Register
<a href="#">2058540</a>	New	Programmer	Category C	Incorrect Fault Status code reported for predicated SVE op
<a href="#">2061107</a>	New	Programmer	Category C	Tag check fail might not be reported for an unaligned predicated SVE store
<a href="#">2089668</a>	New	Programmer	Category C	OSECCR_EL1/EDECCR is incorrectly included in the Warm Reset domain
<a href="#">2093019</a>	New	Programmer	Category C	Extra A-sync packet might get written to Trace Buffer in Trace prohibited region
<a href="#">2109742</a>	New	Programmer	Category C	Speculative access to a recently unmapped physical address previously containing page tables might occur
<a href="#">2112535</a>	New	Programmer	Category C	L1D_CACHE_INVALID and L2D_CACHE_INVALID PMU events fail to increment for SnpPreferUnique and SnpPreferUniqueFwd
<a href="#">2113481</a>	New	Programmer	Category C	MPAM value associated with instruction fetch might be incorrect
<a href="#">2117983</a>	New	Programmer	Category C	Data abort on SVE first fault load might be routed to incorrect Exception level

**02-Feb-2021: Changes in document version v7.0**

ID	Status	Area	Category	Summary
<a href="#">2023111</a>	New	Programmer	Category B	Utility Bus register accesses to reserved addresses of PE might hang
<a href="#">2054223</a>	New	Programmer	Category B	The trace data is not flushed completely during a TSB instruction executed in prohibited region
<a href="#">2002779</a>	New	Programmer	Category C	CPU might fetch incorrect instruction from a page programmed as non-cacheable in stage-1 translation and as device memory in stage-2 translation
<a href="#">2050953</a>	New	Programmer	Category C	External aborts for streaming writes to MTE tagged pages may report multiple errors
<a href="#">2052424</a>	New	Programmer	Category C	An execution of MSR instruction might not update the destination register correctly when an external debugger initiates APB write operation to update debug registers
<a href="#">2054222</a>	New	Programmer	Category C	Trace data lost during collection stop in TRBE
<a href="#">2058367</a>	New	Programmer	Category C	L3D_CACHE_ALLOC PMU inaccurate when using WriteEvictOrEvict transactions

**08-Dec-2020: Changes in document version v6.0**

ID	Status	Area	Category	Summary
<a href="#">2008768</a>	New	Programmer	Category B	RAS errors during core power down might cause a deadlock
<a href="#">2012097</a>	New	Programmer	Category B	TRBE writes to MTE tagged pages might not report external aborts
<a href="#">2017096</a>	New	Programmer	Category B	Streaming STG and STG2 performance lower than expected with TCF=NONE
<a href="#">2017087</a>	New	Programmer	Category C	DSB might not guarantee completion of direct reads of L2 cache memories
<a href="#">2025108</a>	New	Programmer	Category C	Corrupted register state results from executing specific form of SEL instruction followed by SVE AESMC or AESIMC instruction

**06-Nov-2020: Changes in document version v5.0**

ID	Status	Area	Category	Summary
<a href="#">1791789</a>	Updated	Programmer	Category A	Fault info captured in FAR and ESR registers for LDP 64-bit variant could be incorrect
<a href="#">1793423</a>	Updated	Programmer	Category B	An unexpected data abort might occur under specific micro-architectural conditions following an abort on an earlier instruction
<a href="#">1887413</a>	Updated	Programmer	Category B	Executing a SVE load with no active predicates might result in a deadlock under certain micro-architectural conditions
<a href="#">1901946</a>	Updated	Programmer	Category B	Executing software prefetch instructions from a context with memory tagging enabled might lead to corruption of architecture state
<a href="#">1917258</a>	Updated	Programmer	Category B	Non-fault SVE load does not update FFR when it reads data with ECC error or external abort
<a href="#">1984319</a>	New	Programmer	Category B	Incorrect read value for Performance Monitors Common Event Identification Register
<a href="#">2002765</a>	New	Programmer	Category B	Embedded Trace of WFI or WFE instructions might corrupt PE architectural state
<a href="#">1971496</a>	New	Programmer	Category C	VMID value in trace packets might be incorrect
<a href="#">1975917</a>	New	Programmer	Category C	AMU Event 0x0011, Core frequency cycles might increment incorrectly when the core is in WFI or WFE state
<a href="#">1980906</a>	New	Programmer	Category C	Reset Catch debug event might not cause core to enter Debug state immediately after Cold reset
<a href="#">1986267</a>	New	Programmer	Category C	DRPS might not execute correctly in Debug state with SCTLR_ELx.IESB set in the current EL
<a href="#">1989365</a>	New	Programmer	Category C	Floating-point Operations speculatively executed PMU events are not counted
<a href="#">2000010</a>	New	Programmer	Category C	Execution of STG instructions in close proximity might incorrectly write MTE Allocation Tag to memory more than once

## 30-Sep-2020: Changes in document version v4.0

ID	Status	Area	Category	Summary
<a href="#">1927200</a>	New	Programmer	Category B	Atomic instructions with acquire semantics might not be ordered with respect to older stores with release semantics
<a href="#">1920871</a>	Updated	Programmer	Category C	MPAM value associated with translation table walk request might be incorrect
<a href="#">1938354</a>	Updated	Programmer	Category C	Incorrect fault status code might be reported in Trace Buffer Extension register TRBSR_EL1.FSC
<a href="#">1911676</a>	New	Programmer	Category C	TFSR contents might be incorrect after executing a page crossing SVE predicated load instruction
<a href="#">1949697</a>	New	Programmer	Category C	A Checked store that crosses a page boundary might not perform a Tag Check

## 26-Aug-2020: Changes in document version v3.0

ID	Status	Area	Category	Summary
<a href="#">1887102</a>	New	Programmer	Category B	IPA based TLB invalidate might fail to invalidate translation table entries caching translations for the Trace Buffer Extension
<a href="#">1890822</a>	New	Programmer	Category B	Stage 2 abort during Secure EL1 translation might report incorrect NS value in HPFAR_EL2
<a href="#">1901946</a>	New	Programmer	Category B	Executing software prefetch instructions from a context with memory tagging enabled might lead to corruption of architecture state
<a href="#">1906301</a>	New	Programmer	Category B	Core might deadlock when memory-mapped read to Debug/Trace/PMU register is followed by WFI or WFE
<a href="#">1914047</a>	New	Programmer	Category B	External debugger access to Debug registers might not work during Warm reset
<a href="#">1916945</a>	New	Programmer	Category B	Store operation that encounters multiple hits in the TLB might access regions of memory with attributes that could not be accessed at that Exception level or Security state
<a href="#">1917258</a>	New	Programmer	Category B	Non-fault SVE load does not update FFR when it reads data with ECC error or external abort
<a href="#">1918765</a>	New	Programmer	Category B	CFP RCTX and CPP RCTX instructions might incorrectly execute as a NOP in ELO
<a href="#">1934260</a>	New	Programmer	Category B	Tag checked streaming write might report false fail
<a href="#">1851816</a>	Updated	Programmer	Category C	The MPAM value associated with MMU descriptor fetch requests might be incorrect
<a href="#">1875555</a>	New	Programmer	Category C	Compare and Swap (CAS) instructions with stack pointer as base register are incorrectly treated as checked accesses
<a href="#">1884880</a>	New	Programmer	Category C	The core might report incorrect fetch address to FAR_ELx when the core is fetching an instruction from a virtual address associated with page table entry which has been modified
<a href="#">1893664</a>	New	Programmer	Category C	Accessing a memory location using mismatched shareability attributes when MTE tag checking is enabled might lose coherency or deadlock

ID	Status	Area	Category	Summary
<a href="#">1896171</a>	New	Programmer	Category C	Access to External Debug Auxiliary Processor Feature Register might incorrectly return an error response
<a href="#">1899211</a>	New	Programmer	Category C	Some corrected errors might incorrectly increment ERR0MISCO.CECC or ERR0MISCO.CECO
<a href="#">1899435</a>	New	Programmer	Category C	PFG duplicate reported faults through a Warm reset
<a href="#">1909702</a>	New	Programmer	Category C	IDATAn_EL3 might represent incorrect value after direct memory access to internal memory for Instruction TLB
<a href="#">1919240</a>	New	Programmer	Category C	The PE might deadlock if Pseudofault Injection is enabled in Debug State
<a href="#">1920415</a>	New	Programmer	Category C	Trace Buffer might write trace packets to memory using incorrect cache attributes
<a href="#">1920634</a>	New	Programmer	Category C	A Checked store with poisoned tags might result in a Tag Check Fail instead of taking an SError interrupt exception
<a href="#">1920871</a>	New	Programmer	Category C	MPAM value associated with translation table walk request might be incorrect
<a href="#">1925506</a>	New	Programmer	Category C	Unsupported atomic fault due to memory type defined in first stage of translation might result in exception being taken to EL2
<a href="#">1926908</a>	New	Programmer	Category C	Access with additional latency from alignment (LDST_ALIGN_LAT) PMU event does not count
<a href="#">1927566</a>	New	Programmer	Category C	ERR0MISCO_EL1.SUBARRAY value for ECC errors in the L1 data cache might be incorrect
<a href="#">1929989</a>	New	Programmer	Category C	Event Stream from the Virtual Counter is not correctly disabled by VHE in Secure State
<a href="#">1938354</a>	New	Programmer	Category C	Incorrect fault status code might be reported in Trace Buffer Extension register TRBSR_EL1.FSC

**25-Jun-2020: Changes in document version v2.0**

ID	Status	Area	Category	Summary
<a href="#">1791789</a>	Updated	Programmer	Category A	Fault info captured in FAR and ESR registers for LDP 64-bit variant could be incorrect
<a href="#">1785648</a>	Updated	Programmer	Category B	Atomic store instructions to shareable write-back memory might cause memory consistency failures
<a href="#">1793423</a>	Updated	Programmer	Category B	An unexpected data abort might occur under specific micro-architectural conditions following an abort on an earlier instruction
<a href="#">1801992</a>	Updated	Programmer	Category B	Hardware Access/Dirty flag updates might indicate successful completion, but PTE is not updated
<a href="#">1813969</a>	Updated	Programmer	Category B	TLBI range instructions with NUM>31 may not invalidate all required entries+
<a href="#">1863568</a>	New	Programmer	Category B	Core might generate Breakpoint exception on incorrect IA
<a href="#">1887413</a>	New	Programmer	Category B	Executing a SVE load with no active predicates might result in a deadlock under certain micro-architectural conditions

ID	Status	Area	Category	Summary
<a href="#">1786338</a>	Updated	Programmer	Category C	Memory uploads and downloads via memory access mode within Debug state can fail to accurately read or write memory contents
<a href="#">1787272</a>	Updated	Programmer	Category C	TSB instruction completion can be delayed when executed in region where trace is allowed
<a href="#">1799975</a>	Updated	Programmer	Category C	Watchpoint Exception on DC ZVA does not report correct address in FAR or EDWAR
<a href="#">1804175</a>	Updated	Programmer	Category C	CTI event from the core to the external DebugBlock might be dropped
<a href="#">1804563</a>	Updated	Programmer	Category C	Trace Buffer Extension unit might write trace packets to memory using incorrect memory page attributes
<a href="#">1817593</a>	Updated	Programmer	Category C	Persistent faults on speculative elements of SVE First-fault gather-load instructions might result in deadlock
<a href="#">1827136</a>	Updated	Programmer	Category C	External debug accesses in memory access mode with SCTLR_ELx.IESB set might result in unpredictable behavior
<a href="#">1838906</a>	New	Programmer	Category C	Noncompliance with prioritization of Exception Catch debug events
<a href="#">1851171</a>	New	Programmer	Category C	Transient L2 tag double bit Errors might cause data corruption
<a href="#">1851323</a>	New	Programmer	Category C	Incorrect trace timestamp value when self-hosted trace is disabled
<a href="#">1851816</a>	New	Programmer	Category C	The MPAM value associated with MMU descriptor fetch requests might be incorrect
<a href="#">1855551</a>	New	Programmer	Category C	ERRORMISCO_EL1.SUBARRAY, ERROSTATUS.CE and ERROSTATUS.DE values for ECC errors in the L1 data cache might be incorrect
<a href="#">1859562</a>	New	Programmer	Category C	Incorrect read value for the Trace ID Register 3 SYSSTALL field
<a href="#">1862651</a>	New	Programmer	Category C	Incorrect read value for External Debug Processor Feature Register
<a href="#">1865453</a>	New	Programmer	Category C	The values for fields ID_AA64ZFR0_EL1.{SM4,SHA3,AES} read incorrectly as non-zero
<a href="#">1868638</a>	New	Programmer	Category C	The core does not treat the BAS field of the Debug Breakpoint Control Register as RES1
<a href="#">1870363</a>	New	Programmer	Category C	L2 data RAM may fail to report corrected ECC errors
<a href="#">1875745</a>	New	Programmer	Category C	A Checked load that fails a Tag Check could set the ESR to an incorrect value

## 12-May-2020: Changes in document version v1.0

ID	Status	Area	Category	Summary
<a href="#">1791789</a>	New	Programmer	Category A	Fault info captured in FAR and ESR registers for LDP 64-bit variant could be incorrect
<a href="#">1785648</a>	New	Programmer	Category B	Atomic store instructions to shareable write-back memory might cause memory consistency failures
<a href="#">1793423</a>	New	Programmer	Category B	An unexpected data abort might occur under specific micro-architectural conditions following an abort on an earlier instruction
<a href="#">1801992</a>	New	Programmer	Category B	Hardware Access/Dirty flag updates might indicate successful completion, but PTE is not updated
<a href="#">1813969</a>	New	Programmer	Category B	TLBI range instructions with NUM>31 may not invalidate all required entries+
<a href="#">1786338</a>	New	Programmer	Category C	Memory uploads and downloads via memory access mode within Debug state can fail to accurately read or write memory contents
<a href="#">1787272</a>	New	Programmer	Category C	TSB instruction completion can be delayed when executed in region where trace is allowed
<a href="#">1799975</a>	New	Programmer	Category C	Watchpoint Exception on DC ZVA does not report correct address in FAR or EDWAR
<a href="#">1804175</a>	New	Programmer	Category C	CTI event from the core to the external DebugBlock might be dropped
<a href="#">1804563</a>	New	Programmer	Category C	Trace Buffer Extension unit might write trace packets to memory using incorrect memory page attributes
<a href="#">1817593</a>	New	Programmer	Category C	Persistent faults on speculative elements of SVE First-fault gather-load instructions might result in deadlock
<a href="#">1827136</a>	New	Programmer	Category C	External debug accesses in memory access mode with SCTLRL_ELx.IESB set might result in unpredictable behavior

# Errata summary table

The errata associated with this product affect the product versions described in the following table.

ID	Area	Category	Summary	Found in versions	Fixed in version
<a href="#">1791789</a>	Programmer	Category A	Fault info captured in FAR and ESR registers for LDP 64-bit variant could be incorrect	r0p0, r1p0, r2p0	r2p1
<a href="#">1785648</a>	Programmer	Category B	Atomic store instructions to shareable write-back memory might cause memory consistency failures	r0p0	r1p0
<a href="#">1793423</a>	Programmer	Category B	An unexpected data abort might occur under specific micro-architectural conditions following an abort on an earlier instruction	r0p0	r1p0
<a href="#">1801992</a>	Programmer	Category B	Hardware Access/Dirty flag updates might indicate successful completion, but PTE is not updated	r0p0	r1p0
<a href="#">1813969</a>	Programmer	Category B	TLBI range instructions with NUM>31 may not invalidate all required entries+	r0p0	r1p0
<a href="#">1863568</a>	Programmer	Category B	Core might generate Breakpoint exception on incorrect IA	r0p0	r1p0
<a href="#">1887102</a>	Programmer	Category B	IPA based TLB invalidate might fail to invalidate translation table entries caching translations for the Trace Buffer Extension	r0p0, r1p0	r2p0
<a href="#">1887413</a>	Programmer	Category B	Executing a SVE load with no active predicates might result in a deadlock under certain micro-architectural conditions	r0p0	r1p0
<a href="#">1890822</a>	Programmer	Category B	Stage 2 abort during Secure EL1 translation might report incorrect NS value in HPFAR_EL2	r0p0, r1p0	r2p0
<a href="#">1901946</a>	Programmer	Category B	Executing software prefetch instructions from a context with memory tagging enabled might lead to corruption of architecture state	r1p0	r2p0
<a href="#">1906301</a>	Programmer	Category B	Core might deadlock when memory-mapped read to Debug/Trace/PMU register is followed by WFI or WFE	r0p0, r1p0	r2p0
<a href="#">1914047</a>	Programmer	Category B	External debugger access to Debug registers might not work during Warm reset	r0p0, r1p0	r2p0



ID	Area	Category	Summary	Found in versions	Fixed in version
<a href="#">1916945</a>	Programmer	Category B	Store operation that encounters multiple hits in the TLB might access regions of memory with attributes that could not be accessed at that Exception level or Security state	r0p0, r1p0	r2p0
<a href="#">1917258</a>	Programmer	Category B	Non-fault SVE load does not update FFR when it reads data with ECC error or external abort	r0p0, r1p0	r2p0
<a href="#">1918765</a>	Programmer	Category B	CFP RCTX and CPP RCTX instructions might incorrectly execute as a NOP in ELO	r0p0, r1p0	r2p0
<a href="#">1927200</a>	Programmer	Category B	Atomic instructions with acquire semantics might not be ordered with respect to older stores with release semantics	r0p0, r1p0	r2p0
<a href="#">1934260</a>	Programmer	Category B	Tag checked streaming write might report false fail	r1p0	r2p0
<a href="#">1984319</a>	Programmer	Category B	Incorrect read value for Performance Monitors Common Event Identification Register	r0p0, r1p0, r2p0	r2p1
<a href="#">2002765</a>	Programmer	Category B	Embedded Trace of WFI or WFE instructions might corrupt PE architectural state	r0p0, r1p0, r2p0	r2p1
<a href="#">2008768</a>	Programmer	Category B	RAS errors during core power down might cause a deadlock	r0p0, r1p0, r2p0	r2p1
<a href="#">2012097</a>	Programmer	Category B	TRBE writes to MTE tagged pages might not report external aborts	r1p0, r2p0	r2p1
<a href="#">2017096</a>	Programmer	Category B	Streaming STG and STG2 performance lower than expected with TCF=NONE	r0p0, r1p0, r2p0	r2p1
<a href="#">2023111</a>	Programmer	Category B	Utility Bus register accesses to reserved addresses of PE might hang	r0p0, r1p0, r2p0	r2p1
<a href="#">2054223</a>	Programmer	Category B	The trace data is not flushed completely during a TSB instruction executed in prohibited region	r0p0, r1p0, r2p0	r2p1
<a href="#">2058056</a>	Programmer	Category B	Disabling of data prefetcher with outstanding prefetch TLB miss might cause a deadlock	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">2081180</a>	Programmer	Category B	Executing a WFI or WFE instruction after a STREX instruction might result in a deadlock under specific conditions	r0p0, r1p0, r2p0	r2p1
<a href="#">2083908</a>	Programmer	Category B	Execution of ST2G instructions in close proximity might cause loss of MTE allocation tag data	r2p0	r2p1

ID	Area	Category	Summary	Found in versions	Fixed in version
<a href="#">2119858</a>	Programmer	Category B	Trace data might get overwritten in TRBE FILL mode	r0p0, r1p0, r2p0	r2p1
<a href="#">2136059</a>	Programmer	Category B	The CPP instruction will apply to an incorrect EL context	r0p0, r1p0, r2p0	r2p1
<a href="#">2147715</a>	Programmer	Category B	A CFP instruction might not invalidate the correct resources	r2p0	r2p1
<a href="#">2216384</a>	Programmer	Category B	PDP deadlock due to CMP/CMN + B.AL/B.NV fusion	r0p0, r1p0, r2p0	r2p1
<a href="#">2219376</a>	Programmer	Category B	Enabling TRBE might cause a data write to a page with the wrong ASID when owning Exception level is EL1	r0p0, r1p0, r2p0	r2p1
<a href="#">2224489</a>	Programmer	Category B	TRBE might cause a data write to an out-of-range address which is not reserved for TRBE	r0p0, r1p0, r2p0	r2p1
<a href="#">2267065</a>	Programmer	Category B	A CFP instruction might execute with incorrect upper ASID or VMID bits	r0p0, r1p0, r2p0	r2p1
<a href="#">2282622</a>	Programmer	Category B	Continuous failing STREX because of another PE executing prefetch for store behind consistently mispredicted branch	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">2291219</a>	Programmer	Category B	Denied power down request might prevent completion of future power down request	r0p0, r1p0, r2p0	r2p1
<a href="#">2371105</a>	Programmer	Category B	Translation table walk folding into an L1 prefetch might cause data corruption	r0p0, r1p0, r2p0	r2p1
<a href="#">2381390</a>	Programmer	Category B	A continuous stream of incoming DVM syncs may cause TRBE to prevent the CPU from forward progressing	r0p0, r1p0, r2p0	r2p1
<a href="#">2701952</a>	Programmer	Category B	Core might fetch stale instruction from memory when both Stage 1 Translation and Instruction Cache are Disabled with Stage 2 forced Write-Back	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">2742423</a>	Programmer	Category B	Page crossing access that generates an MMU fault on the second page could result in a livelock	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">2768515</a>	Programmer	Category B	The core might deadlock during powerdown sequence	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">2778471</a>	Programmer	Category B	The PE might generate memory accesses using invalidated mappings after completion of a DVM SYNC operation	r0p0, r1p0, r2p0, r2p1	Open

ID	Area	Category	Summary	Found in versions	Fixed in version
<a href="#">1786338</a>	Programmer	Category C	Memory uploads and downloads via memory access mode within Debug state can fail to accurately read or write memory contents	r0p0	r1p0
<a href="#">1787272</a>	Programmer	Category C	TSB instruction completion can be delayed when executed in region where trace is allowed	r0p0	r1p0
<a href="#">1799975</a>	Programmer	Category C	Watchpoint Exception on DC ZVA does not report correct address in FAR or EDWAR	r0p0	r1p0
<a href="#">1804175</a>	Programmer	Category C	CTI event from the core to the external DebugBlock might be dropped	r0p0	r1p0
<a href="#">1804563</a>	Programmer	Category C	Trace Buffer Extension unit might write trace packets to memory using incorrect memory page attributes	r0p0	r1p0
<a href="#">1817593</a>	Programmer	Category C	Persistent faults on speculative elements of SVE First-fault gather-load instructions might result in deadlock	r0p0	r1p0
<a href="#">1827136</a>	Programmer	Category C	External debug accesses in memory access mode with SCTLR_ElX.IESB set might result in unpredictable behavior	r0p0	r1p0
<a href="#">1838906</a>	Programmer	Category C	Noncompliance with prioritization of Exception Catch debug events	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">1851171</a>	Programmer	Category C	Transient L2 tag double bit Errors might cause data corruption	r0p0	r1p0
<a href="#">1851323</a>	Programmer	Category C	Incorrect trace timestamp value when self-hosted trace is disabled	r0p0	r1p0
<a href="#">1851816</a>	Programmer	Category C	The MPAM value associated with MMU descriptor fetch requests might be incorrect	r0p0, r1p0	r2p0
<a href="#">1855551</a>	Programmer	Category C	ERR0MISCO_EL1.SUBARRAY, ERROSTATUS.CE and ERROSTATUS.DE values for ECC errors in the L1 data cache might be incorrect	r0p0	r1p0
<a href="#">1859562</a>	Programmer	Category C	Incorrect read value for the Trace ID Register 3 SYSSTALL field	r0p0	r1p0
<a href="#">1862651</a>	Programmer	Category C	Incorrect read value for External Debug Processor Feature Register	r0p0	r1p0
<a href="#">1865453</a>	Programmer	Category C	The values for fields ID_AA64ZFR0_EL1.{SM4,SHA3,AES} read incorrectly as non-zero	r0p0	r1p0

ID	Area	Category	Summary	Found in versions	Fixed in version
<a href="#">1868638</a>	Programmer	Category C	The core does not treat the BAS field of the Debug Breakpoint Control Register as RES1	r0p0	r1p0
<a href="#">1870363</a>	Programmer	Category C	L2 data RAM may fail to report corrected ECC errors	r0p0	r1p0
<a href="#">1875555</a>	Programmer	Category C	Compare and Swap (CAS) instructions with stack pointer as base register are incorrectly treated as checked accesses	r1p0	r2p0
<a href="#">1875745</a>	Programmer	Category C	A Checked load that fails a Tag Check could set the ESR to an incorrect value	r1p0	r2p0
<a href="#">1884880</a>	Programmer	Category C	The core might report incorrect fetch address to FAR_ELx when the core is fetching an instruction from a virtual address associated with page table entry which has been modified	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">1893664</a>	Programmer	Category C	Accessing a memory location using mismatched shareability attributes when MTE tag checking is enabled might lose coherency or deadlock	r1p0	r2p0
<a href="#">1896171</a>	Programmer	Category C	Access to External Debug Auxiliary Processor Feature Register might incorrectly return an error response	r0p0, r1p0	r2p0
<a href="#">1899211</a>	Programmer	Category C	Some corrected errors might incorrectly increment ERR0MISC0.CECR or ERR0MISC0.CECO	r0p0, r1p0, r2p0	r2p1
<a href="#">1899435</a>	Programmer	Category C	PFG duplicate reported faults through a Warm reset	r0p0, r1p0	r2p0
<a href="#">1909702</a>	Programmer	Category C	IDATAN_EL3 might represent incorrect value after direct memory access to internal memory for Instruction TLB	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">1911676</a>	Programmer	Category C	TFSR contents might be incorrect after executing a page crossing SVE predicated load instruction	r1p0, r2p0	r2p1
<a href="#">1919240</a>	Programmer	Category C	The PE might deadlock if Pseudofault Injection is enabled in Debug State	r0p0, r1p0	r2p0
<a href="#">1920415</a>	Programmer	Category C	Trace Buffer might write trace packets to memory using incorrect cache attributes	r0p0, r1p0	r2p0

ID	Area	Category	Summary	Found in versions	Fixed in version
<a href="#">1920634</a>	Programmer	Category C	A Checked store with poisoned tags might result in a Tag Check Fail instead of taking an SError interrupt exception	r1p0	r2p0
<a href="#">1920871</a>	Programmer	Category C	MPAM value associated with translation table walk request might be incorrect	r0p0, r1p0, r2p0	r2p1
<a href="#">1925506</a>	Programmer	Category C	Unsupported atomic fault due to memory type defined in first stage of translation might result in exception being taken to EL2	r0p0, r1p0	r2p0
<a href="#">1926908</a>	Programmer	Category C	Access with additional latency from alignment (LDST_ALIGN_LAT) PMU event does not count	r0p0, r1p0	r2p0
<a href="#">1927566</a>	Programmer	Category C	ERR0MISCO_EL1.SUBARRAY value for ECC errors in the L1 data cache might be incorrect	r0p0, r1p0	r2p0
<a href="#">1929989</a>	Programmer	Category C	Event Stream from the Virtual Counter is not correctly disabled by VHE in Secure State	r0p0, r1p0	r2p0
<a href="#">1938354</a>	Programmer	Category C	Incorrect fault status code might be reported in Trace Buffer Extension register TRBSR_EL1.FSC	r0p0, r1p0, r2p0	r2p1
<a href="#">1949697</a>	Programmer	Category C	A Checked store that crosses a page boundary might not perform a Tag Check	r1p0, r2p0	r2p1
<a href="#">1971496</a>	Programmer	Category C	VMID value in trace packets might be incorrect	r0p0, r1p0, r2p0	r2p1
<a href="#">1975917</a>	Programmer	Category C	AMU Event 0x0011, Core frequency cycles might increment incorrectly when the core is in WFI or WFE state	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">1980906</a>	Programmer	Category C	Reset Catch debug event might not cause core to enter Debug state immediately after Cold reset	r0p0, r1p0, r2p0	r2p1
<a href="#">1986267</a>	Programmer	Category C	DRPS might not execute correctly in Debug state with SCTLR_ElX.IESB set in the current EL	r0p0, r1p0, r2p0	r2p1
<a href="#">1989365</a>	Programmer	Category C	Floating-point Operations speculatively executed PMU events are not counted	r0p0, r1p0, r2p0	r2p1
<a href="#">2000010</a>	Programmer	Category C	Execution of STG instructions in close proximity might incorrectly write MTE Allocation Tag to memory more than once	r2p0	r2p1

ID	Area	Category	Summary	Found in versions	Fixed in version
<a href="#">2002779</a>	Programmer	Category C	CPU might fetch incorrect instruction from a page programmed as non-cacheable in stage-1 translation and as device memory in stage-2 translation	r0p0, r1p0, r2p0	r2p1
<a href="#">2017087</a>	Programmer	Category C	DSB might not guarantee completion of direct reads of L2 cache memories	r0p0, r1p0, r2p0	r2p1
<a href="#">2018317</a>	Programmer	Category C	External APB write to a register located at offset 0x084 might incorrectly issue a write to External Debug Instruction Transfer Register	r0p0, r1p0, r2p0	r2p1
<a href="#">2025108</a>	Programmer	Category C	Corrupted register state results from executing specific form of SEL instruction followed by SVE AESMC or AESIMC instruction	r0p0, r1p0, r2p0	r2p1
<a href="#">2050953</a>	Programmer	Category C	External aborts for streaming writes to MTE tagged pages may report multiple errors	r1p0, r2p0	r2p1
<a href="#">2052424</a>	Programmer	Category C	An execution of MSR instruction might not update the destination register correctly when an external debugger initiates APB write operation to update debug registers	r0p0, r1p0, r2p0	r2p1
<a href="#">2054222</a>	Programmer	Category C	Trace data lost during collection stop in TRBE	r0p0, r1p0, r2p0	r2p1
<a href="#">2058367</a>	Programmer	Category C	L3D_CACHE_ALLOC PMU inaccurate when using WriteEvictOrEvict transactions	r0p0, r1p0, r2p0	r2p1
<a href="#">2058540</a>	Programmer	Category C	Incorrect Fault Status code reported for predicated SVE op	r0p0, r1p0, r2p0	r2p1
<a href="#">2061107</a>	Programmer	Category C	Tag check fail might not be reported for an unaligned predicated SVE store	r0p0, r1p0, r2p0	r2p1
<a href="#">2089668</a>	Programmer	Category C	OSECCR_EL1/EDECCR is incorrectly included in the Warm Reset domain	r0p0, r1p0, r2p0	r2p1
<a href="#">2093019</a>	Programmer	Category C	Extra A-sync packet might get written to Trace Buffer in Trace prohibited region	r0p0, r1p0, r2p0	r2p1
<a href="#">2109742</a>	Programmer	Category C	Speculative access to a recently unmapped physical address previously containing page tables might occur	r0p0, r1p0, r2p0	r2p1

ID	Area	Category	Summary	Found in versions	Fixed in version
<a href="#">2112535</a>	Programmer	Category C	L1D_CACHE_INVALID and L2D_CACHE_INVALID PMU events fail to increment for SnpPreferUnique and SnpPreferUniqueFwd	r0p0, r1p0, r2p0	r2p1
<a href="#">2113481</a>	Programmer	Category C	MPAM value associated with instruction fetch might be incorrect	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">2117983</a>	Programmer	Category C	Data abort on SVE first fault load might be routed to incorrect Exception level	r1p0, r2p0	r2p1
<a href="#">2141645</a>	Programmer	Category C	A64 WFI or A64 WFE executed in Debug state suspends execution indefinitely	r0p0, r1p0, r2p0	r2p1
<a href="#">2143136</a>	Programmer	Category C	Some SVE PMU events count incorrectly	r0p0, r1p0, r2p0	r2p1
<a href="#">2146514</a>	Programmer	Category C	PMU Event MEM_ACCESS_CHECKED_WR, 0x4026 counts incorrectly and MEM_ACC_CHECKED 0x4024 might be incorrect	r1p0, r2p0	r2p1
<a href="#">2154216</a>	Programmer	Category C	FAR_ELx contents for a Data Abort exception on SVE first fault contiguous load instruction due to Tag Check fail might be incorrect	r0p0, r1p0, r2p0	r2p1
<a href="#">2159150</a>	Programmer	Category C	Direct access of L2 data RAMs using RAMINDEX returns incomplete data	r0p0, r1p0, r2p0	r2p1
<a href="#">2174188</a>	Programmer	Category C	PMU_HOVFS event not always exported when self-hosted trace is disabled	r0p0, r1p0, r2p0	r2p1
<a href="#">2178034</a>	Programmer	Category C	An SError might not be reported for an atomic store that encounters data poison	r0p0, r1p0, r2p0	r2p1
<a href="#">2186347</a>	Programmer	Category C	64 bit source SVE PMULLB/T not considered Cryptography instruction	r0p0, r1p0, r2p0	r2p1
<a href="#">2227174</a>	Programmer	Category C	Streaming writes to memory mapped Non-shareable and write-back might cause data corruption because of reordering	r0p0, r1p0, r2p0	r2p1
<a href="#">2238108</a>	Programmer	Category C	Read or write from Secure EL1 for ICV_BPR1_EL1 register might not work	r0p0, r1p0, r2p0	r2p1
<a href="#">2238111</a>	Programmer	Category C	Reads of DISR_EL1 incorrectly return 0s while in Debug State	r0p0, r1p0, r2p0	r2p1

ID	Area	Category	Summary	Found in versions	Fixed in version
<a href="#">2239139</a>	Programmer	Category C	DRPS instruction is not treated as UNDEFINED at EL0 in Debug state	r0p0, r1p0, r2p0	r2p1
<a href="#">2243871</a>	Programmer	Category C	ELR_ELx[63:48] might hold incorrect value when PE disables address translation	r0p0, r1p0, r2p0	r2p1
<a href="#">2245716</a>	Programmer	Category C	TRBE might use incorrect Cacheability attributes for TRBE data when address translation is disabled	r0p0, r1p0, r2p0	r2p1
<a href="#">2245832</a>	Programmer	Category C	ESR_ELx contents for a Data Abort exception might be incorrect when an L1D tag double bit error is encountered	r0p0, r1p0, r2p0	r2p1
<a href="#">2247178</a>	Programmer	Category C	L1 MTE Tag poison is not cleared	r1p0, r2p0	r2p1
<a href="#">2254450</a>	Programmer	Category C	L1 Data poison is not cleared by a store	r0p0, r1p0, r2p0	r2p1
<a href="#">2276444</a>	Programmer	Category C	PMU event for full/partial/empty predicate incorrect for some SVE instructions	r0p0, r1p0, r2p0	r2p1
<a href="#">2278134</a>	Programmer	Category C	PMU L1D_CACHE_REFILL_OUTER is inaccurate	r0p0, r1p0, r2p0	r2p1
<a href="#">2283666</a>	Programmer	Category C	Lower priority exception might be reported when abort condition is detected at both stages of translation	r0p0, r1p0, r2p0	r2p1
<a href="#">2307829</a>	Programmer	Category C	ESR_ELx.ISV can be set incorrectly for an external abort on translation table walk	r0p0, r1p0, r2p0	r2p1
<a href="#">2317617</a>	Programmer	Category C	ESR_ELx contents for a Data Abort exception might be incorrect when a data double bit error or external abort is encountered	r0p0, r1p0, r2p0	r2p1
<a href="#">2334390</a>	Programmer	Category C	L2 tag RAM double-bit ECC error might lead to the PE not responding to a forwarding snoop	r0p0, r1p0, r2p0	r2p1
<a href="#">2344960</a>	Programmer	Category C	CSSELR_EL1.TnD is RAZ/WI when CSSELR_EL1.InD == 0x1	r0p0, r1p0, r2p0	r2p1
<a href="#">2382765</a>	Programmer	Category C	Incorrect read value for Performance Monitors Configuration Register	r0p0, r1p0, r2p0	r2p1
<a href="#">2391680</a>	Programmer	Category C	Software-step not done after exit from Debug state with an illegal value in DSPSR	r0p0, r1p0, r2p0, r2p1	Open



ID	Area	Category	Summary	Found in versions	Fixed in version
<a href="#">2444421</a>	Programmer	Category C	PMU STALL_SLOT_BACKEND and STALL_SLOT_FRONTEND events count incorrectly	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">2643627</a>	Programmer	Category C	ERXPFGCDN_EL1 register is incorrectly written on Warm reset	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">2647274</a>	Programmer	Category C	Incorrect read value for Performance Monitors Control Register	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">2652240</a>	Programmer	Category C	FAR_ELx contents for a Data Abort exception on SVE first fault contiguous load instruction due to Tag Check fail might be incorrect	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">2676362</a>	Programmer	Category C	Execution of STG instructions in close proximity might cause loss of MTE allocation tag data	r1p0, r2p0, r2p1	Open
<a href="#">2692441</a>	Programmer	Category C	L3D PMU events may be inaccurate	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">2694769</a>	Programmer	Category C	MTE checked load might read an old value of allocation tag by not complying with address dependency ordering	r1p0, r2p0, r2p1	Open
<a href="#">2712632</a>	Programmer	Category C	Incorrect read value for Performance Monitors Configuration Register EX field	r0p0, r1p0, r2p0, r2p1	Open
<a href="#">2769023</a>	Programmer	Category C	STALL_BACKEND_MEM, Memory stall cycles AMU event count incorrectly	r0p0, r1p0, r2p0, r2p1	Open

# Errata descriptions

## Category A

**1791789**

**Fault info captured in FAR and ESR registers for LDP 64-bit variant might be incorrect**

### Status

Fault Type: Programmer Category A

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

### Description

Under certain conditions, the FAR (Fault Address Register) and ESR (Exception Syndrome Register) might have incorrect values when the LDP (Load Pair) 64-bit variant generates an abort.

### Configurations affected

All configurations are affected.

### Conditions

All of the following conditions must be met:

1. The LDP 64-bit variant crosses a page boundary.
2. Data read from lower bytes on the first page results in a synchronous abort due to an internal ECC error, external abort, or MTE tag check fail.
3. Data read from upper bytes on the second page results in alignment fault, MMU fault, or watchpoint exception.

### Implications

If the above conditions are met, the contents of the FAR and ESR registers might have incorrect values.

### Workaround

This erratum can be avoided by setting CPUACTLR5\_EL1[10] to 1. Setting CPUACTLR5\_EL1[10] to 1 would have a significant performance (approximately 20%) impact on streaming workloads that use the LDP 64-bit variant. Performance impact on non-streaming workloads would be much smaller (approximately 1%).

## Category A (rare)

There are no errata in this category.

## Category B

1785648

### Atomic store instructions to shareable write-back memory might cause memory consistency failures

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

Atomic store instructions to shareable write-back memory that are performed as far atomics might cause memory consistency failures if the initiating PE has a shared copy of the cache line containing the addressed memory.

#### Configurations affected

This erratum affects all configurations that include a DSU L3 cache or Snoop Filter, or have an interconnect capable of handling far atomic transactions indicated by the BROADCASTATOMIC pin being set to 1.

#### Conditions

1. PEO executes atomic store instruction that hits in the L1 data cache and L2 cache in the Shared state.
2. PEO changes the L2 state to Invalid, sends an invalidating snoop to the L1 data cache, and issues a AtomicStore transaction on the CHI interconnect.
3. PEO invalidating snoop to the L1 data cache is delayed due to internal queueing.

#### Implications

If the above conditions are met, PEO might not observe invalidating snoops caused by other PEs in the same coherency domain and thus might violate memory consistency for loads to the same cache line as the atomic store.

#### Workaround

Set CPUACTLR2\_EL1[2] to force atomic store operations to write-back memory to be performed in the L1 data cache.

## 1793423

### An unexpected data abort might occur under specific micro-architectural conditions following an abort on an earlier instruction

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

Under certain micro-architectural conditions, an abort on a LDP 64-bit variant could leave the processor in a state that allows a subsequent instruction to report an unexpected data abort.

#### Configurations affected

All configurations are affected.

#### Conditions

All of the following conditions must be met:

1. LDP 64-bit variant signals a data abort.
2. An Instruction accessing memory is issued after the core services the LDP 64-bit variant data abort.

#### Implications

If the above conditions are met under specific micro-architectural conditions, the core might report an unexpected data abort after it services the data abort for LDP 64-bit variant.

#### Workaround

This erratum can be avoided by setting CPUACTLR5\_EL1[10] to 1. Setting CPUACTLR5\_EL1[10] to 1 will have a performance impact on workloads that use LDP 64-bit variant.

## 1801992

### Hardware Access/Dirty flag updates might indicate successful completion, but PTE is not updated

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

A page table walk that causes a hardware update of the Access or Dirty flags of the PTE (Page Table Entry) and requires an external request on the CHI interface, might indicate success to the MMU when the PTE Access and Dirty flags are not updated.

#### Configurations affected

All configurations are affected.

#### Conditions

1. Error detection and correction within the PE caches is disabled by `ERROCTLR.ED=0`.
2. MMU page table walk causes a hardware update of Access or Dirty flags in the PTE.
3. A/D update operation hits in the L2 cache on a line in a shared state, and issues a `MakeReadUnique` transaction.
4. Critical data beat returns without error indication is forwarded to the MMU, which allows the A/D update to succeed.
5. One or more subsequent data beats for the same cache line receives an error response.

#### Implications

If the above conditions are met, data returned to the MMU by the A/D update might indicate success, while the PTE cached by the L2 cache is not updated because the errors in the non-critical data beats could not be deferred. This might lead to successful performance of a load or store that should have taken an abort.

#### Workaround

If error detection and correction within the PE caches is disabled by `ERROCTLR.ED=0`, then set `CPUACTLR2_EL1[43]` to disable forwarding of the critical data beat.

## 1813969

### TLBI range instructions with NUM>31 may not invalidate all required entries+

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

When executing a TLB Invalidate (TLBI) range operation, if the NUM field of the operand has a value of 32 or higher, then the PE TLBs may not invalidate all the required entries. In addition, a TLBI DVM message might not convey the correct NUM value.

#### Configurations affected

This erratum affects all configurations.

#### Conditions

1. PE executes a TLBI range operation with a NUM argument of 32 or larger.

#### Implications

If the above conditions are met, the PE TLB might not invalidate all the required entries and a TLBI DVMMsg broadcast might not convey the correct NUM value.

#### Workaround

Software should not use TLBI range operations and use non-range TLBI operations instead.

## 1863568

### Core might generate Breakpoint exception on incorrect IA

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

Under certain conditions, the core can generate a breakpoint exception on the instruction sequentially before the address specified in the Debug Breakpoint Value Register (DBGBVR).

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Hardware breakpoint is enabled.

#### Implications

If the above conditions are met, breakpoint exception will incorrectly occur on the instruction sequentially before the hardware breakpoint address specified.

#### Workaround

Set CPUACTLR\_EL1[21] to 1. Setting this bit does not affect performance unless breakpoints are in use.



## 1887102

### IPA based TLB Invalidate might fail to invalidate translation table entries caching translations for the Trace Buffer Extension

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

When the Trace Buffer Extension (TBRE) is enabled and TRBLIMITR\_EL1.nVM is set, addresses generated by the TBRE are considered Intermediate Physical Addresses (IPA). Under such a scenario, a TLB Invalidate by IPA operation (TLBIIPAS2IS) might fail to invalidate translation table entries accessible to the TBRE.

#### Configurations affected

This erratum affects all configurations.

#### Conditions

1. PEO TRBE is enabled.
2. PEO TRBLIMITR\_EL1.nVM bit is set.
3. PE1 executes an Inner Shareable TLBI by IPA and a DSB which are snooped by PEO.
4. PE1 does not execute an Inner Shareable TLBI by VA or TLBI by VMID before the DSB mentioned in condition 3.

#### Implications

If the above conditions occur, the TBRE might not invalidate its translation table entries and generate trace packets using an incorrect physical address.

#### Workaround

To avoid this erratum, software should:

- set CPUACTLR2[27] to 1 (to allow the injected DSB to invalidate translation table entries caching translations for TRBE), or
- execute Inner Shareable TLBI by VA or TLBI by VMID before the DSB.

## 1887413

### Executing a SVE load with no active predicates might result in a deadlock under certain micro-architectural conditions

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

Under certain micro-architectural conditions, executing a SVE load where all predicates are inactive might result in a deadlock

#### Configurations Affected

All configurations are affected.

#### Conditions

1. A predicated SVE load with no active lanes.

#### Implications

If the above conditions are met under specific micro-architectural conditions, the core might deadlock.

#### Workaround

This erratum can be avoided by setting CPUACTLR5\_EL1[10] to 1. Setting CPUACTLR5\_EL1[10] to 1 will impact performance on AArch64 code.

## 1890822

### Stage 2 abort during Secure EL1 translation might report incorrect NS value in HPFAR\_EL2

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

Under certain conditions, a stage 2 permission or unsupported atomic fault generated on the translation table walk of Secure EL1 stage 1 translation might result in an incorrect value captured in the Non-Secure (NS) bit of HPFAR\_EL2.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Stage 2 translation is enabled for Secure EL1.
2. Permission fault or unsupported atomic fault is generated in the second stage of translation performed during the translation table walk of Secure EL1 stage 1 translation.

#### Implications

If the above conditions are met, the NS bit value in the HPFAR\_EL2 register might be incorrect. In this situation, which can be identified by the ESR\_EL2 encoding, the Hypervisor running at Secure EL2 cannot rely on the NS field in the HPFAR\_EL2 register. If it needs this information (as might be the case for a copy-on-write management of the memory holding stage 1 translation tables), it must determine it by some other means.

#### Workaround

There is no workaround.

## 1901946

### Executing software prefetch instructions from a context with memory tagging enabled might lead to corruption of architecture state

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r1p0. Fixed in r2p0.

#### Description

Under certain conditions, executing software prefetch instructions from a context with memory tagging enabled that accesses bytes from both Normal and Device memory could lead to corruption of architecture state.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Contiguous or gather variants of PRFD, PRFH, PRFW instructions are executed from a context.
2. Memory tagging is enabled for that context.
3. The prefetch instruction accesses bytes from both Normal and Device memory.

#### Implications

If the above conditions are met, architecture state might be corrupted.

#### Workaround

This erratum can be avoided by setting CPUACTLR4\_EL1[15] to 1. Setting CPUACTLR4\_EL1[15] to 1 will have a small impact on performance.

## 1906301

### Core might deadlock when memory-mapped read to Debug/Trace/PMU register is followed by WFI or WFE

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

When a load to device memory targeting a memory mapped component, such as Debug, Trace, or PMU register implemented on the same core is executed and is followed by a WFI/WFE instruction before the load data is returned to core, then it might deadlock the core.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Load to device memory targeting same core's memory mapped debug interface is executed.
2. WFI or WFE is executed in quick succession before the load instruction completes.

#### Implications

If the above conditions are met, then under certain conditions core might deadlock.

#### Workaround

Software should insert a DSB instruction between the load instruction and WFI/WFE instruction. This will ensure the load instruction completes before WFI/WFE is executed.

## 1914047

### External debugger access to Debug registers might not work during Warm reset

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

During Warm reset, external debugger access for Debug registers might be ignored.

#### Configurations Affected

All configurations are affected.

#### Conditions

1. Warm reset is asserted.
2. External debugger access is initiated for one of following Debug registers:
  - DBGBCR<n>\_EL1 (n=0-5)
  - DBGBVR<n>\_EL1 (n=0-5)
  - EDECCR

#### Implications

If the above conditions are met, the core might ignore the access request. The read operation might return incorrect data. The write operation might not take effect and stale data might be retained.

Warm reset is asserted when the core is in the OFF\_EMU, WARM\_RST, or DBG\_RECOV power modes.

#### Workaround

There is no workaround.

## 1916945

### Store operation that encounters multiple hits in the TLB might access regions of memory with attributes that could not be accessed at that Exception level or Security state

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

Under certain circumstances, a store operation that encounters multiple hits in the TLB can generate a prefetch request to regions of memory with attributes that could not be accessed at that Exception level or Security state.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. A store operation encounters multiple hits in the TLB due to inappropriate invalidation or misprogramming of a contiguous bit.
2. A read request is generated with a physical address and attributes that are an amalgamation of the multiple TLB entries that hit.

#### Implications

If the above conditions are met, a read request might be generated to regions of memory with attributes that could not be accessed at that Exception level or Security state. The memory location will not be updated.

#### Workaround

This erratum can be avoided by setting CPUECTLR\_EL1[8] to 1. There is a small performance cost (<0.5%) for setting this bit.

## 1917258

### Non-fault SVE load does not update FFR when it reads data with ECC error or external abort

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

Under certain conditions, a Non-fault SVE load that reads data with double bit ECC error or external abort does not update FFR.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Non-fault SVE load makes data access.
2. Data access encounters double bit ECC error or external abort.

#### Implications

If the above conditions are met, FFR contents would be incorrect.

#### Workaround

This erratum can be avoided by setting CPUACTLR4\_EL1[43] to 1. There is no performance impact associated with setting this bit.



## 1918765

### CFP RCTX and CPP RCTX instructions might incorrectly execute as a NOP in EL0

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0. Fixed in r2p0..

#### Description

HCR\_EL2.<E2H,TGE> and SCTLR\_EL1.EnRCTX control the execution of CPP and CFP instructions in EL0. These instructions might incorrectly execute as a NOP instruction due to this erratum.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. SCTLR\_EL1.EnRCTX=1 and E2H,TGE=(1,1)
2. CFP RCTX or CPP RCTX is executed at EL0

#### Implications

CFP RCTX and CPP RCTX instructions will be incorrectly executed as a NOP instruction.

#### Workaround

CFP RCTX and CPP RCTX can be trapped at EL0 by setting SCTLR\_EL2.EnRCTX=0 when E2H,TGE=1,1.

## 1927200

### Atomic instructions with acquire semantics might not be ordered with respect to older stores with release semantics

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

Under certain conditions, atomic instructions with acquire semantics might not be ordered with respect to older instructions with release semantics. The older instruction could either be a store or store atomic.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Load atomic, CAS or SWP with acquire but no release semantics is executed.
2. There is an older instruction with release semantics and it could either be a store to non-WB memory or a store atomic instruction that is executed as a far atomic.

#### Implications

If the above condition are met, memory ordering violation might happen.

#### Workaround

This workaround assumes that MTE is not enabled in precise mode.

This erratum can be avoided by inserting a DMB ST before acquire atomic instructions without release semantics. This can be implemented through execution of the following code at EL3 as soon as possible after boot:

```
LDR x0,=0x0
MSR S3_6_c15_c8_0,x0
LDR x0,= 0x10E3900002
MSR S3_6_c15_c8_2,x0
LDR x0,= 0x10FFF00083
MSR S3_6_c15_c8_3,x0
LDR x0,= 0x2001003FF
MSR S3_6_c15_c8_1,x0
```

```
LDR x0,=0x1
MSR S3_6_c15_c8_0,x0
LDR x0,= 0x10E3800082
MSR S3_6_c15_c8_2,x0
LDR x0,= 0x10FFF00083
MSR S3_6_c15_c8_3,x0
LDR x0,= 0x2001003FF
MSR S3_6_c15_c8_1,x0
```

```
LDR x0,=0x2
MSR S3_6_c15_c8_0,x0
LDR x0,= 0x10E3800200
MSR S3_6_c15_c8_2,x0
LDR x0,= 0x10FFF003E0
MSR S3_6_c15_c8_3,x0
LDR x0,= 0x2001003FF
MSR S3_6_c15_c8_1,x0
```

```
ISB
```

## 1934260

### Tag checked streaming write might report false fail

#### Status

Fault Type: Programmer Category B  
Fault Status: Present in r1p0. Fixed in r2p0.

#### Description

A PE performing tag-checked sequential writes that stream beyond the L1 data cache and hit in the L2 cache, might use stale allocation tags in the tag check comparison.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions:

1. MTE is enabled in imprecise exception mode.
2. PE performs a write of allocation tags to cache line A.
3. PE performs writes to several contiguous cache lines such that write streaming mode is engaged.
4. Streaming write request to cache line A hits in L2 cache on a line present in the L1 data cache, and therefore must snoop the L1 data cache for possibly dirty allocation tags.
5. L1 data cache returns dirty allocation tags for cache line A.

#### Implications

If the above conditions are met, the L2 cache might use the stale tags from the L2 cache for the tag check comparison, which might lead to a false tag check fail, or a false tag check pass.

#### Workaround

When testing MTE software in imprecise mode, disable write streaming by setting CPUECTLR\_EL1[25:18] to 'hff'. This workaround will result in reduced performance for workloads that benefit from write streaming.

When testing performance in MTE imprecise mode, no workaround is necessary. However, false MTE tag check fails might be reported to TFSR\_ELx.

## 1984319

### Incorrect read value for Performance Monitors Common Event Identification register

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

The AArch64 System register Performance Monitors Common Event Identification register 0 (PMCEID0\_ELO) returns an incorrect read value for the following fields in the register:

- ID44
- ID48
- ID49
- ID50
- ID51
- ID56
- ID57
- ID58
- ID59

The external register Performance Monitors Common Event Identification register 2 (PMCEID2) returns an incorrect read value for the following fields in the register:

- ID12
- ID16
- ID17
- ID18
- ID19
- ID24
- ID25
- ID26
- ID27

#### Configurations Affected

All configurations are affected.

#### Conditions

- Software reads the AArch64 System register PMCEID0\_ELO.  
or

- Debugger reads the PMCEID2 register.

## Implications

The register fields incorrectly report the value 0b0 indicating that the corresponding PMU common events are not implemented, or not counted. The expected value should be 0b1, as the corresponding PMU common events are implemented.

## Workaround

Software can read the MIDR\_EL1 register to identify the implemented PMU events.

## 2002765

### Embedded Trace of WFI or WFE instructions might corrupt PE architectural state

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, and r2p0. Fixed in r2p1.

#### Description

Executing a **WFI** or **WFE** instruction with Embedded Trace enabled might corrupt AArch64 PSTATE.BTYPE or trace information intended for Embedded Trace, resulting in architecture violations.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

The erratum occurs under the following conditions:

1. Embedded Trace is enabled.
2. A **WFI** or **WFE** instruction is executed.

#### Implications

Under certain internal timing conditions exacerbated by a high frequency of branch instructions, the PE might corrupt PSTATE.BTYPE or trace information. Corruption of any of these values might lead to any of the following architecture violations:

- Applying erroneous BTYPE information to AArch64 instructions in guarded pages (wrong BTYPE value resulting in erroneous Branch Target Exceptions or failing to report a Branch Target Exception).
- Reporting erroneous trace information to Embedded Trace.

#### Workaround

This erratum can be worked around by using the instruction patching mechanism. This can be done through the following write sequence to several IMPLEMENTATION DEFINED registers. The code sequence should be applied early in the boot sequence prior to any of the possible errata conditions being met. There is no performance or power impact associated with this workaround.

```
LDR x0,=0x6
MSR S3_6_c15_c8_0,x0 ; MSR CPUPSELR_EL3, X0
LDR x0,=0xF3A08002
MSR S3_6_c15_c8_2,x0 ; MSR CPUPOR_EL3, X0
LDR x0,=0xFFF0F7FE
MSR S3_6_c15_c8_3,x0 ; MSR CPUPMR_EL3, X0
LDR x0,=0x40000001003ff
MSR S3_6_c15_c8_1,x0 ; MSR CPUPCR_EL3, X0
ISB
```



## 2008768

### RAS errors during core power down might cause a deadlock

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

If a Reliability, Availability, and Serviceability (RAS) error occurs when a core is being powered down, then the power down sequence is designed to be aborted so that the error can be handled by software. As explained in this erratum, the power down sequence might complete despite the error occurring, or it might cause a deadlock.

#### Configurations affected

All configurations are affected.

#### Conditions

1. The ERXCTLR\_EL1.ED bit is set for any of the core error records, and at least one of the CI, DUI, CFI, FI, or UI bits is set.
2. Software running on the core sets the CPUPWRCTLR.CORE\_PWRDN\_EN bit and executes a **WFI** instruction.
3. The core Power Policy Unit (PPU) requests that the core transitions from the ON power mode to either the OFF or OFF\_EMU power mode.
4. During the L1 or L2 cache clean and invalidate done by the power transition, a RAS error occurs that causes any of the **nCOREFAULTIRQ**, **nCOREERRIRQ**, **nCOMPLEXFAULTIRQ**, or **nCOMPLEXERRIRQ** pins to be asserted.

#### Implications

The PPU will see the power down request being denied because of the RAS error, however the core will not wake up from the **WFI** instruction and therefore software is not able to handle the error. If the PPU requests the core to power down again, either because it is set to dynamic mode, or because the component programming the PPU requests the power down again, then the second power down might either:

- Complete and power off the core, despite the fact that the error has not been handled.
- Deadlock, preventing the power down from completing.

There is still substantial benefit being gained from the ECC logic. There might be a negligible increase in overall system failure rate because of this erratum.

## Workaround

The ERXCTLR\_EL1.ED bit should be cleared for all the core error records before software sets the CPUPWRCTLR.CORE\_PWRDN\_EN bit to request a power down. This will cause any error detected during the power down to be ignored. In systems that are particularly concerned about errors during this time, software can clean and invalidate the L1 and L2 caches before clearing the ERXCTLR\_EL1.ED bit. This will minimise, but not eliminate, the probability of detecting an error during the powerdown, but at the expense of a longer time to execute the power down sequence.

## 2012097

### TRBE writes to MTE tagged pages might not report external aborts

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r1p0, r2p0. Fixed in r2p1.

#### Description

Memory writes due to the Trace Buffer Extension (TRBE) to memory pages that are Tagged via the Memory Tagging Extension and present in the PE caches might fail to report external aborts.

#### Configurations Affected

This erratum affects all configurations with the BROADCASTMTE pin asserted.

#### Conditions

1. PE enables the TRBE features.
2. TRBE issues a write to a memory page that is marked MTE Tagged.
3. Interconnect returns a completion response with an error indication - Poison, DErr, or NDErr.

#### Implications

If the above conditions are met, the PE might fail to record the external abort in TRBSR\_EL1.EA (TRBE).

#### Workaround

If the external abort conditions are non-transient, a read of the TBRE memory buffers will observe the same external abort condition as the write and take a data abort. If the external abort conditions are transient, memory pages used for TBRE can be marked as Untagged.

## 2017096

### Streaming STG and STG2 performance lower than expected with TCF=NONE

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

When writing MTE allocation tags, STG and STG2 instructions might encounter lower than expected performance when SCTLR\_ELx.TCF is set to NONE.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. PE executes a series of STG or STG2 instruction with SCTLR\_ELx.TCF set to NONE.

#### Implications

If the above conditions are met, the measured bandwidth might be one half of what is expected.

#### Workaround

Disable store issue prefetching by setting CPUECLTR\_EL1[8] to 1. Note that doing so might incur a performance penalty of 0 to 0.3%.

## 2023111

### Utility Bus register accesses to reserved addresses of PE might hang

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

Utility Bus register accesses to some reserved regions of the PE might be ignored and result in a hang.

#### Configurations Affected

All configurations are affected.

#### Conditions

This erratum occurs under the following condition:

- Utility Bus Read/Write to a reserved region in PE is executed.

#### Implications

The Utility Bus register access to DSU might not complete, resulting in a hang.

#### Workaround

Utility Bus reserved regions of page size in the PE should not be mapped by an MMU onto system memory. Also, these regions should not be made accessible by lower ELs than host.

When using an external debugger, accesses to Utility Bus reserved addresses should be avoided.

## 2054223

### The trace data is not flushed completely during a TSB instruction executed in prohibited region

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

When Embedded Trace Extension (ETE) is in trace prohibited region, and a TSB instruction is executed, any trace data associated with the instructions before the TSB must be observable in memory. Because of this erratum, four bytes of trace data are not pushed to the memory before completing the TSB instruction and those bytes might get lost or might get written to memory in next context.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. ETE is enabled.
2. ETE is in trace prohibited region.
3. TRBE is enabled.
4. TSB instruction is executed.

#### Implications

Four bytes of trace data before TSB instruction might get lost or might get written to memory in next context.

#### Workaround

To avoid this erratum, software can execute two sequential TSB instructions in any code where one TSB instruction is expected to be required.

## 2058056

### Disabling of data prefetcher with outstanding prefetch TLB miss might cause a deadlock

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0, r2p1. Open.

#### Description

If the data prefetcher is disabled (by an MSR to CPUECTLR register) while a prefetch TLB miss is outstanding, the processor might deadlock on the next context switch.

#### Configurations Affected

All configurations are affected.

#### Conditions

- MSR write to CPUECTLR register that disables the data prefetcher.
- A TLB miss from the prefetch TLB is outstanding.

#### Implications

If the above conditions are met, a deadlock might occur on the next context switch.

#### Workaround

- Workaround option 1:  
If the following code surrounds the MSR, it will prevent the erratum from happening:
  - `cpp`
  - `dsb`
  - `isb`
  - MSR CPUECTLR - disabling the prefetcher
  - `isb`
- Workaround option 2:  
Place the data prefetcher in the most conservative mode instead of disabling it. This will greatly reduce prefetches but not eliminate them. This is accomplished by writing the following bits to the value indicated:
  - `ectlr2[14:11], PF_MODE= 4'b1001`

## 2081180

### Executing a WFI or WFE instruction after a STREX instruction might result in a deadlock under specific conditions

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, and r2p0. Fixed in r2p1.

#### Description

Under certain micro-architectural conditions, executing a WFI or WFE instruction after a STREX that has encountered an external abort might result in a deadlock.

#### Configurations Affected

This erratum affects all configurations where the BROADCASTMTE pin is HIGH.

#### Conditions

1. Memory tagging is enabled.
2. A STREX instruction executed in MTE precise mode encounters an external abort or poisoned MTE tag.
3. A WFI or WFE instruction is executed.

#### Implications

If the above conditions are met, then, under specific micro-architectural conditions, the core might deadlock.

#### Workaround

This erratum can be avoided by inserting a sequence of 16 DMB ST instructions prior to WFI or WFE. Performance impact is expected to be negligible in real systems. This sequence can be implemented through execution of the following code at EL3 as soon as possible after boot:

```

LDR x0,=0x3
MSR S3_6_c15_c8_0,x0 ; MSR CPUPSELR_EL3, X0
LDR x0,=0xF3A08002
MSR S3_6_c15_c8_2,x0 ; MSR CPUPOR_EL3, X0
LDR x0,=0xFFF0F7FE
MSR S3_6_c15_c8_3,x0 ; MSR CPUPMR_EL3, X0
LDR x0,=0x10002001003FF
MSR S3_6_c15_c8_1,x0 ; MSR CPUPCR_EL3, X0

LDR x0,=0x4

```



```
MSR S3_6_c15_c8_0,x0 ; MSR CPUPSELR_EL3, X0
LDR x0,=0xBF200000
MSR S3_6_c15_c8_2,x0 ; MSR CPUPOR_EL3, X0
LDR x0,=0xFFEF0000
MSR S3_6_c15_c8_3,x0 ; MSR CPUPMR_EL3, X0
LDR x0,=0x10002001003F3
MSR S3_6_c15_c8_1,x0 ; MSR CPUPCR_EL3, X0
```

ISB

## 2083908

### Execution of ST2G instructions in close proximity might cause loss of MTE allocation tag data

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r2p0. Fixed in r2p1.

#### Description

Under certain micro-architectural conditions, an ST2G instruction that crosses a 32-byte boundary might not write part of the MTE allocation tag to memory.

#### Configurations Affected

This erratum affects all configurations where the BROADCASTMTE pin is HIGH.

#### Conditions

1. Memory tagging is enabled.
2. Two or more ST2G instructions are executed in close proximity to the same cache line such that they miss in the L1 cache.
3. One of the ST2G instructions crosses a 32-byte boundary.

#### Implications

If the above conditions are met, then under specific micro-architectural conditions, the ST2G that crosses the 32-byte boundary might not write part of the MTE allocation tag to memory.

#### Workaround

This erratum can be avoided by setting CPUACTLR5\_EL1[13] to 1. Setting CPUACTLR5\_EL1[13] to 1 is expected to result in a small performance degradation for workloads that use MTE (approximately 1.6% when using MTE imprecise mode, 0.9% for MTE precise mode).

## 2119858

### Trace data might get overwritten in TRBE FILL mode

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

Trace Buffer memory size is defined using base pointer and limit pointer in the Trace Buffer Extension (TRBE) programming model. In trace buffer fill mode, TRBE is expected to generate an interrupt and stop the collection of trace after reaching the limit pointer. Due to this erratum, under some microarchitecture conditions, TRBE might roll back to the base pointer after generating an interrupt and continue to write at the base pointer, and up to three cache lines after the base pointer before the collection stops.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. ETE and TRBE are enabled.
2. ETE is in a trace allowed region.
3. TRBLIMITR\_EL1[2:1] is programmed to 2'b00.

#### Implications

Due to this erratum, trace data present at the base pointer location and up to three cache lines after the base pointer might get overwritten. The current write pointer also increments by same number of cache line locations.

#### Workaround

Software can program 256 bytes of ignore packets starting from the base pointer and offset the write pointer TRBPTR\_EL1 by 256 bytes before enabling TBE. That ensures oldest trace is not corrupted.

## 2136059

### The CPP instruction will apply to an incorrect EL context

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, and r2p0. Fixed in r2p1.

#### Description

The **CPP** instruction will not operate on the desired EL as encoded in the instruction.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs under the following condition:

1. A **CPP** instruction is executed.

#### Implications

The **CPP** instruction will cause the hardware prefetcher to invalidate the hardware prefetcher state associated with an EL other than the EL that is encoded in the instruction.

#### Workaround

Set CPUACTLR5\_EL1[44] which will cause the **CPP** instruction to invalidate the hardware prefetcher state trained from any EL.

## 2147715

### A CFP instruction might not invalidate the correct resources

#### Status

Fault Type: Programmer Category B  
Fault Status: Present in r2p0. Fixed in r2p1.

#### Description

Executing a CFP instruction under certain conditions might not invalidate resources specified by the instruction.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. A CFP instruction is executed.
2. The Exception level specified in the instruction is EL0.
3.  $HCR\_EL2.TGE==1$  and  $HCR\_EL2.E2H==1$ .

#### Implications

If the previous conditions are met, then the CFP instruction might not invalidate branch predictor resources associated with EL0 context managed by EL2.

#### Workaround

This erratum can be avoided by setting  $CPUACTLR\_EL1[22]=1$ . Setting  $CPUACTLR\_EL1[22]$  will cause the CFP instruction to invalidate all branch predictor resources regardless of context.

Using this workaround might cause the PE to encounter another erratum. Please refer to erratum ID 2243871 "ELR\_ELx[63:48] might hold incorrect value when PE disables address translation" for more details.

## 2216384

### PDP deadlock due to CMP/CMN + B.AL/B.NV fusion

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

When Performance Defined Power (PDP) is enabled, a Compare (CMP) or Compare negative (CMN) instruction followed by a conditional branch of form B.AL or B.NV might cause a deadlock.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. PDP configuration is enabled.
2. Execution of CMP/CMN, followed by B.AL/B.NV.

#### Implications

If above conditions are met, then a deadlock might result, requiring a reset of the processor.

#### Workaround

This erratum can be avoided by setting CPUACTLR5\_EL1[17] to 1 and applying following patch. These instructions are not expected to be present in the code often, so any performance impact should be minimal. The code sequence should be applied early in the boot sequence prior to any of the possible errata conditions being met.

```
LDR x0,=0x5
MSR S3_6_c15_c8_0,x0 ; MSR CPUPSELR_EL3, X0
LDR x0,=0x10F600E000
MSR S3_6_c15_c8_2,x0 ; MSR CPUPOR_EL3, X0
LDR x0,=0x10FF80E000
MSR S3_6_c15_c8_3,x0 ; MSR CPUPMR_EL3, X0
LDR x0,=0x80000000003FF
MSR S3_6_c15_c8_1,x0 ; MSR CPUPCR_EL3, X0
ISB
```

## 2219376

### Enabling TRBE might cause a data write to a page with the wrong ASID when owning Exception level is EL1

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

The Trace Buffer Extension (TRBE) can be used by software to store trace packets from Embedded Trace Extension (ETE) unit to memory. The TRBE unit interfaces with the MMU for translating a virtual address to a physical address. Once a physical address is available, the TRBE unit sends trace packets to the L2 unit to be stored to the memory. The TRBE unit requests a new translation to the MMU when a virtual address crosses the 4K page boundary. Due to this erratum, if a pending translation request from Exception level EL0 or EL1 is serviced after the PE switches context to Exception level EL2, then translation with an incorrect ASID might be provided to the TRBE unit. This can lead to a write to a page with the incorrect ASID.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. The TRBE is enabled.
2. Owing Exception level is EL1.
3. TRBLIMITR\_EL1.nVM is set to 0, such that the trace buffer pointer addresses are virtual addresses in the EL1&0 translation regime using the current ASID from TTBRx\_EL1. This means that the page is marked nG (non-global page).
4. The TRBE unit requests a memory translation request.
5. Before the above memory translation request completes, a context switch occurs from EL0 or EL1, to EL2.

#### Implications

If the above conditions are met, under certain microarchitectural conditions, incorrect physical address and page attributes from a different ASID might be provided to the TRBE unit. The TRBE might then write to memory using incorrect page attributes from another ASID, leading to a write that is not expected.

#### Workaround

The software should use global pages ( $nG=0$ ) for the pages that are used by the TRBE to store data when owning Exception level is EL1.



## 2224489

### TRBE might cause a data write to an out-of-range address which is not reserved for TRBE

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

Trace buffer memory size is defined using base pointer and limit pointer in Trace Buffer Extension (TRBE) programming model. TRBE is expected to wrap to base pointer without crossing the limit pointer. Because of this erratum, under some conditions, TRBE might generate a write to the next virtually addressed page following the last page of TRBE address space.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Embedded Trace Extension (ETE) and TRBE are enabled.
2. ETE is in trace allowed region.
3. TRBE current pointer is at last page of Trace buffer.
4. TRBE requests translation for the last page.
5. LS indicates to TRBE that it is unable to service the translation request.

#### Implications

When previous conditions are met under rare microarchitectural conditions, TRBE might incorrectly generate a data write to the next virtually addressed page following the last page of Trace Buffer. This can lead to data corruption if that page is currently used by another application and result in loss of trace up to 64 bytes.

#### Workaround

The software can mark as not valid the next page following the last TRBE page, meaning the errant access will generate a Translation Fault buffer management event. This will prevent the data corruption but will not prevent the loss of trace data.

## 2267065

### A CFP instruction might execute with incorrect upper ASID or VMID bits

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

The upper 8 bits of ASID or VMID might be incorrect for a CFP instruction.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. A CFP is executed with ELO target execution context and {HCR\_EL2.TGE, HCR\_EL2.E2H} is {1,1} and TCR\_EL2.AS=0.
2. A CFP is executed at EL2 or EL3 and the target execution context is ELO or EL1 and VTCR\_EL2.VS=0.

#### Implications

If either of the previous conditions are met, then the CFP instruction might not invalidate branch predictor resources associated with ELO or EL1 contexts.

#### Workaround

This erratum can be avoided by setting CPUACTLR\_EL1[22]=1. Setting CPUACTLR\_EL1[22] will cause the CFP instruction to invalidate all branch predictor resources regardless of context.

## 2282622

### Continuous failing STREX because of another PE executing prefetch for store behind consistently mispredicted branch

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0, r2p1. Open.

#### Description

A *Processing Element* (PE) executing a PLDW or PRFM PST instruction that lies on a mispredicted branch path might cause a second PE executing a store exclusive to the same cache line address to fail continuously.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs under the following conditions:

1. One PE is executing store exclusive.
2. A second PE has branches that are consistently mispredicted.
3. The second PE instruction stream contains a PLDW or PRFM PST instruction on the mispredicted path that accesses the same cache line address as the store exclusive executed by the first PE.
4. PLDW/PRFM PST causes an invalidation of the first PE's caches and a loss of the exclusive monitor.

#### Implications

If the above conditions are met, the store exclusive instruction might continuously fail.

#### Workaround

Set CPUACTLR2\_EL1[0] to 1 to force PLDW/PFRM ST to behave like PLD/PFRM LD and not cause invalidations to other PE caches. There might be a small performance degradation to this workaround for certain workloads that share data.

## 2291219

### Denied power down request might prevent completion of future power down request

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, and r2p0. Fixed in r2p1.

#### Description

If a Processing Element (PE) initiates a power down request that is ultimately denied due to an external event, a future power down request might fail to complete.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. PE initiates a power down request (ON to OFF state transition) by setting CORE\_PWRDN\_EN and executing a WFI instruction.
2. PE completes the hardware flush of its caches.
3. An event, such as an external interrupt, causes an abort of the power down request.
4. PE returns to the ON state without performing a hardware reset.

#### Implications

If the above conditions are met, the PE might fail complete a subsequent power down request resulting in a deadlock.

#### Workaround

This erratum can be avoided by setting CPUACTLR2\_EL1[36] to 1 before the power-down sequence that includes setting the CORE\_PWRDN\_EN bit, and executing a WFI. This bit should be cleared on exiting WFI by any mechanism other than reset.

## 2371105

### Translation table walk folding into an L1 prefetch might cause data corruption

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, and r2p0. Fixed in r2p1.

#### Description

A translation table walk that matches an existing L1 prefetch with a read request outstanding on CHI might fold into the prefetch, which might lead to data corruption for a future instruction fetch.

#### Configurations Affected

This erratum affects all configurations

#### Conditions

1. In specific microarchitectural situations, the PE merges a translation table walk request with an older hardware or software prefetch L2 cache miss request.

#### Implications

If the previous conditions are met, an unrelated instruction fetch might observe incorrect data.

#### Workaround

Disable folding of demand requests into older prefetches with L2 miss requests outstanding by setting CPUACTLR2\_EL1[40] to 1.

## 2381390

### A continuous stream of incoming DVM syncs may cause TRBE to prevent the core from forward progressing

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

A continuous stream of incoming *Distributed Virtual Memory* (DVM) syncs might cause the *Trace Buffer Extension* (TRBE) to prevent the core from forward progressing, while executing a WFX.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

The erratum occurs if all the following conditions are met:

- The *Processing Element* (PE) executes a WFE or WFI instruction.
- TRBE is in use and needs to write trace data to its buffer.
- A continuous stream of DVM sync operations is received from other PEs.

#### Implications

When all of the above conditions are met, the PE might be prevented from entering WFE or WFI, and the pending WFE or WFI operation cannot be interrupted.

#### Workaround

There is no workaround.

## 2701952

### The core might fetch stale instruction from memory when both Stage 1 Translation and Instruction Cache are Disabled with Stage 2 forced Write-Back

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0, r2p1. Open.

#### Description

If a core is fetching instructions from memory while stage 1 translation is disabled and instruction cache is disabled, the core ignores Stage 2 forced Write-Back indication programmed by HCR\_EL2.FWB and make Non-cacheable, Normal memory request. This may cause the core to fetch stale data from memory subsystem.

#### Configurations Affected

This erratum might affect system configurations that do not use Arm interconnect IP.

#### Conditions

The erratum occurs if all the following conditions apply:

- The *Processing Element* (PE) is using EL1 translation regime.
- Stage 2 translation is enabled (HCR\_EL2.VM=1).
- Stage 1 translation is disabled (SCTLR\_EL1.M=0).
- Instruction cache is enabled from EL2 (HCR\_EL2.ID=0).
- Instruction cache is disabled from EL1 (SCTLR\_EL1.I=0).

#### Implications

If the conditions are satisfied, the core makes all instruction fetch request as Non-cacheable, Normal memory regardless of stage 2 translation output even if Stage 2 Forced Write-back is enabled. This might cause the core to fetch stale data from memory because Non-cacheable memory access does not probe any of cache hierarchy (e.g., Level-2 cache). If the bypassed cache hierarchy contains data modified by other initiators, stale data might be fetched from memory.

#### Workaround

For Hypervisor, initiating appropriate cache maintenance operations as if the core does not support stage 2 Forced Write-back feature. The cache maintenance operation should be initiated when new memory is allocated to a guest OS. This operation writeback the modified data in intermediate caches to point of coherency.



## 2742423

### Page crossing access that generates an MMU fault on the second page could result in a livelock

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0, and r2p1. Open.

#### Description

Under unusual micro-architectural conditions, a page crossing access that generates a *Memory Management Unit* (MMU) fault on the second page can result in a livelock.

#### Configurations Affected

All configurations are affected.

#### Conditions

This erratum occurs under all of the following conditions:

1. Page crossing load or store misses in the *Translation Lookaside Buffer* (TLB) and needs a translation table walk for both pages.
2. The table walk for the second page results in an MMU fault.

#### Implications

If the above conditions are met, under unusual micro-architectural conditions with just the right timing, the core could enter a livelock. This is expected to be very rare and even a slight perturbation due to external events like snoops could get the core out of livelock.

#### Workaround

This erratum can be avoided by setting CPUACTLR5\_EL1[56:55] to 2'b01.

## 2768515

### The core might deadlock during powerdown sequence

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0, and r2p1. Open.

#### Description

While powering down the *Processing Element* (PE), a correctable L2 tag ECC error might cause a deadlock in the powerdown sequence.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs under the following conditions:

1. Error detection and correction is enabled through ERXCTLR\_EL1.ED=1.
2. PE executes more than 24 writes to Device-nGnRnE or Device-nGnRE memory.
3. PE executes power-down sequence as described in TRM.

#### Implications

If the above conditions are met, the PE might deadlock during the hardware cache flush that automatically occurs as part of the powerdown sequence.

#### Workaround

Add a DSB instruction before the ISB of the powerdown code sequence specified in the TRM.

## 2778471

### The PE might generate memory accesses using invalidated mappings after completion of a DVM SYNC operation.

#### Status

Fault Type: Programmer Category B

Fault Status: Present in r0p0, r1p0, r2p0, r2p1. Open

#### Description

The Processing Element (PE) might generate memory accesses using invalidated mappings after completion of a Distributed Virtual Memory (DVM) SYNC operation.

#### Configurations Affected

All configurations are affected.

#### Conditions

This erratum can occur on a PE (PE0) only if the affected TLBI and subsequent DVM sync operations are broadcast from another PE (PE1). The TLBI and DVM sync operations executed locally by PE0 are not affected.

#### Implications

When this erratum occurs, after completion of a DVM SYNC operation, the PE can continue generating memory accesses through mappings that were invalidated by a previous TLBI operation.

#### Workaround

The erratum can be avoided by setting CPUACTLR3\_EL1[47]. Setting this chicken bit might have a small impact on power and negligible impact on performance.

### Category B (rare)

There are no errata in this category.

## Category C

1786338

### Memory uploads and downloads via memory access mode within Debug state can fail to accurately read or write memory contents

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

Memory uploads via memory access mode within Debug state might fail to set EDSCR.TXfull to 1, possibly resulting in an intended memory read being skipped and erroneous memory contents being displayed for that address.

Memory downloads via memory access mode within Debug state might prematurely clear EDSCR.RXfull, possibly resulting in an intended memory write being skipped and subsequent memory access mode downloads therefore writing data to incorrect addresses.

#### Configurations affected

This erratum affects all configurations.

#### Conditions

For memory upload:

1. The core is in Debug state having been properly set up via the external debug interface for memory upload (target to external host).
2. A series of external reads from DBGDTRTX\_ELO are used, where each read first clears EDSCR.TXfull to 0, then initiates memory uploads via PE-generated load & system register write instruction pairs, then sets EDSCR.(TXfull,ITE) to (1,1) on successful completion of each iteration.
3. Certain internal timing conditions relating to execution of a previous load instruction exist, resulting in the failure to set EDSCR.TXfull to 1 on some iteration.

For memory download:

1. The core is in Debug state having been properly set up via the external debug interface for memory download (external host to target).
2. A series of external writes to DBGDTRRX\_ELO are used, where each write first sets EDSCR.RXfull to 1, then initiates memory downloads via PE-generated system register read & store instruction pairs, then sets EDSCR.(RXfull,ITE) to (0,1) on successful completion of each iteration.

3. Certain internal timing conditions relating to execution of a previous load instruction exist, resulting in a premature clearing of EDSCR.RXfull to 0 on some iteration.

## Implications

If the above conditions are met, the failure mechanism could effectively skip an intended memory read in a memory upload loop, thus resulting in the erroneous display of data associated with the affected memory address. Or, the failure mechanism could effectively skip an intended memory write in a memory download loop, thus resulting in subsequent memory access mode downloads writing data to incorrect addresses.

## Workaround

A workaround is only needed if there is any possibility of connecting an external debugger to the core. If that possibility exists, then there are 2 separate workarounds:

1. Perform the memory upload or download operations with the debugger's FAST\_MEMORY\_ACCESS disabled. This can impact the performance of memory upload and download operations in Debug state, resulting in slight visible delays in the debugger user interface on memory upload and longer download times.  
or
2. Set CPUACTLR3\_EL1[47] in the boot sequence to prevent the faulty behavior. There is no performance impact associated with setting this bit, but there is a potential (workload dependent) power increase of approximately 1.5% total core power.

## 1787272

### TSB instruction completion can be delayed when executed in region where trace is allowed

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

If the Embedded Trace Macro Extension (ETE) unit is enabled and a TSB instruction is executed, then trace packets generated due to instructions executed before the TSB instruction must be output from the ETE unit. If the Trace Buffer Extension (TRBE) unit is also enabled, then these trace packets must be output from the TRBE unit before the TSB instruction can complete. Due to this erratum, under some conditions the TSB instruction completion might take an additional 8192 core clock cycles than normal.

#### Configurations affected

This erratum affects all configurations.

#### Conditions

1. The ETE unit is enabled.
2. Tracing is currently allowed in the ETE unit.
3. The TRBE unit is enabled.
4. A TSB instruction is executed.
5. The ETE unit has less than 4 bytes left to be output.
6. The ETE unit is not generating new trace packets.

#### Implications

If the above conditions are met, the TSB instruction might take an additional 8192 core clock cycles to complete.

#### Workaround

Software should execute the TSB instruction in a prohibited region. There is no workaround if the TSB instruction is executed in a trace allowed region.

## 1799975

### Watchpoint Exception on DC ZVA does not report correct address in FAR or EDWAR

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

If the watchpoint address targets a lower portion of a cache line, but not all of the cache line, and the address target of the Data Cache Zero by VA (DC ZVA) falls in the upper portion of the cache line that the watchpoint does not target, the Fault Address Register (FAR) (or External Debug Watchpoint Address Register (EDWAR) if setup for Debug Halt) will contain an incorrect address.

#### Configurations affected

This erratum affects all configurations.

#### Conditions

1. Watchpoint targets double word (or less or more) at address A.
2. DC ZVA targets address greater than A+7, but less than A+63. The cache line size is 64 bytes, which is a mis-aligned address.

#### Implications

FAR contains target address of DC ZVA.

EDWAR contains target address of DC ZVA if enabled for Debug Halt.

#### Workaround

There is no hardware workaround. The common case for DC ZVA targets is to be granule aligned, thus most software will not be affected by this case.

## 1804175

### CTI event from the core to the external DebugBlock might be dropped

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

The PE generates input trigger events which are routed to Cross-Trigger Interface (CTI) via the external DebugBlock. A CTI event from the core to the external DebugBlock might be dropped, in rare occurrences, if close in temporal proximity to a previous CTI event.

#### Configurations affected

This erratum affects all configurations.

#### Conditions

1. CTI event occurs.
2. Another CTI event occurs before the completion of the processing of the previous CTI event.

#### Implications

The earlier CTI event might be dropped.

#### Workaround

This erratum has no workaround.



## 1804563

### Trace Buffer Extension unit might write trace packets to memory using incorrect memory page attributes

#### Status

Fault Type: Programmer Category C

Fault status: Present in r0p0. Fixed in r1p0.

#### Description

Trace Buffer Extension (TRBE) can be used by software to store trace packets from Embedded Trace Extension (ETE) unit to memory. The TRBE unit interfaces with the MMU for translating a virtual address to a physical address. Once a physical address is available the TRBE unit sends trace packets to the L2 unit to be stored to memory. The TRBE unit requests a new translation to the MMU when a virtual address crosses the 4K page boundary. Due to this erratum, if this new translation request is completed while the TRBE unit is sending trace packets to L2 from a previous translation request, then the trace packets might incorrectly use cache and shareability attributes, Page Based Hardware Attributes (PBHA), and Non-Secure attributes (NS) from the new translation request.

#### Configurations affected

This erratum affects all configurations.

#### Conditions

1. The TRBE unit is enabled.
2. The TRBE unit is sending trace packets to the L2 unit using the last 64-byte address range of a 4K memory page.
3. The TRBE unit initiates a new memory translation request for the first 64-byte address range of the next 4K memory page.
4. The response for the new memory translation request completes before pending trace packets are accepted by the L2 unit.
5. Memory page attributes are different between these two 4K memory pages.

#### Implications

If the above conditions are met, the TRBE unit might write trace packets to memory with incorrect cache, shareability attributes, PBHA and NS from the new translation request related to next 4K page.

#### Workaround

Software should use consistent page attributes for all pages within the buffer.

## 1817593

### Persistent faults on speculative elements of SVE First-fault gather-load instructions might result in deadlock

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

Double-bit ECC errors or bus faults on a non-first active element of an SVE First-fault gather load might result in deadlock.

#### Configurations affected

This erratum affects all configurations.

#### Conditions

1. A double-bit ECC error or bus fault occurs on a non-first active element of an SVE First-fault gather-load instruction.
2. The double-bit ECC error or bus fault must be persistent, meaning on repeated attempted executions of the instruction, the fault consistently re-occurs.
3. Certain internal timing conditions concerning the execution order of the non-first active element relative to the first active element exist.

#### Implications

If the above conditions are met, the core can deadlock. An interrupt can be recognized, but the SVE First-faulting gather-load instruction makes no forward progress in the presence of persistent ECC double-bit errors or bus faults that occur on elements other than the first active element.

#### Workaround

No workaround is expected to be required. RAS error handling and recovery techniques cover this scenario.

## 1827136

### External debug accesses in memory access mode with SCTL<sub>R</sub>\_EL<sub>x</sub>.IESB set might result in unpredictable behavior

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

In Debug state with SCTL<sub>R</sub>\_EL<sub>x</sub>.IESB set to 1, memory uploads and downloads executed in memory access mode might lead to unpredictable behavior for the current exception level.

#### Configurations affected

This erratum affects all configurations.

#### Conditions

1. Core is In Debug state.
2. SCTL<sub>R</sub>\_EL<sub>x</sub>.IESB is set to 1 for the current exception level.
3. Memory access mode is enabled via EDSCR.MA set to 1.

#### Implications

If the above conditions are met, memory upload and download behavior is unpredictable for the current exception level and might lead to incorrect operation or results. The unpredictable behavior is limited to legal behavior at the current exception level.

#### Workaround

The erratum can be avoided by clearing SCTL<sub>R</sub>\_EL<sub>x</sub>.IESB before performing memory uploads or downloads in Debug state using memory access mode.

## 1838906

### Noncompliance with prioritization of Exception Catch debug events

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0, r2p1. Open.

#### Description

ARMv8.2 architecture requires that Debug state entry due to an Exception Catch debug event (generated on exception entry) occur before any asynchronous exception is taken at the first instruction in the exception handler. An asynchronous exception might be taken as a higher priority exception than Exception Catch and the Exception Catch might be missed altogether.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Debug Halting is allowed.
2. EDECCR bits are configured to catch exception entry to ELx.
3. A first exception is taken resulting in entry to ELx.
4. A second, asynchronous exception becomes visible at the same time as exception entry to ELx.
5. The second, asynchronous exception targets an Exception level ELy that is higher than ELx.

#### Implications

If the above conditions are met, the core might recognize the second exception and not enter Debug state as a result of Exception Catch on the first exception. When the handler for the second exception completes, software might return to execute the first exception handler, and assuming the core does not halt for any other reason, the first exception handler will be executed and entry to Debug state via Exception Catch will not occur.

#### Workaround

When setting Exception Catch on exceptions taken to an Exception level ELx, the debugger should do either or both of the following:

1. Ensure that Exception Catch is also set for exceptions taken to all higher Exception Levels, so that the second (asynchronous) exception generates an Exception Catch debug event.
2. Set Exception Catch for an Exception Return to ELx, so that when the second (asynchronous)

exception handler completes, the exception return to ELx generates an Exception Catch debug event.

Additionally, when a debugger detects that the core has halted on an Exception Catch to an Exception level ELy, where  $y > x$ , it should check the ELR\_ELy and SPSR\_ELy values to determine whether the exception was taken on an ELx exception vector address, meaning an Exception Catch on entry to ELx has been missed.

## 1851171

### Transient L2 tag double bit Errors might cause data corruption

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

Under certain uncommon conditions, transient double bit tag errors might cause valid cache data that is in an unrelated line in the same set to be overwritten.

#### Configurations affected

This erratum affects all configurations.

#### Conditions

The following conditions must be met during additional rare timing and state conditions:

1. A double bit error (DBE) in the tag occurs shortly after the read of a line.
2. The DBE occurs before a write to that same line in a different way.
3. The DBE corrects after the write to that line.
4. An additional read is made to that line before it is evicted from the cache.

#### Implications

If the above conditions are met, the data in an unrelated line in the same set might be overwritten and corrupted. The effect on the failure rate is negligible in such a case. There is still substantial benefit being gained from the ECC logic.

#### Workaround

There is no workaround.

## 1851323

### Incorrect trace timestamp value when self-hosted trace is disabled

#### Status

Fault Type: Programmer Category C  
Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

If the Embedded Trace Extension (ETE) unit is enabled and configured with global timestamp tracing enabled, the timestamp value might be incorrectly sourced.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

The trace timestamp might be incorrect when:

1. The ETE unit is enabled.
2. The ETE unit is configured with global timestamp tracing enabled.
3. Tracing is allowed.
4. Self-hosted trace is disabled.
5. Timestamp control is programmed to use a virtual counter value.

#### Implications

The trace timestamp might have an incorrect value from a virtual counter instead of being sourced from CoreSight time.

#### Workaround

The external debugger can program either:

- TRFCR\_EL2.TS == 0b11, or
- TRFCR\_EL2.TS == 0b00 and TRFCR\_EL1.TS == 0b11.

Software should preserve the values written by the debugger.

## 1851816

### The MPAM value associated with MMU descriptor fetch requests might be incorrect

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

The MPAM value associated with MMU descriptor fetch requests could be incorrect when performing address translation on behalf of *Address Translation* (AT) instructions or the table walk prefetcher.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. An MMU descriptor fetch request is made on behalf of AT instructions or the table walk prefetcher.

#### Implications

If the above condition is met, the core generates a memory-system request for the translation table walk using the MPAM ID for the:

1. Context associated with an AT instruction instead of the context that executed the instruction.
2. ELO context for translations generated by the table walk prefetcher trained in EL1 or EL2 context when  $\text{HCR\_EL2}\{E2H, TGE\} == \{1,1\}$ .

#### Workaround

There is no workaround.

## 1855551

### ERR0MISC0\_EL1.SUBARRAY, ERR0STATUS.CE, and ERR0STATUS.DE values for ECC errors in the L1 data cache might be incorrect

#### Status



Fault Type: Programmer Category C  
Fault Status: Present in r0p0. Fixed in r1p0.

## Description

Under certain conditions, the `ERRORMISCO_EL1.SUBARRAY`, `ERROSTATUS.CE`, and `ERROSTATUS.DE` values recorded for ECC errors in the L1 data cache might be incorrect.

## Configurations Affected

This erratum affects all configurations.

## Conditions

1. The L1 data cache contains both a single-bit and a double-bit ECC error on different words within the same 64-byte cacheline.
2. An access is made to the cacheline in the L1 data cache containing both the single-bit and double-bit ECC errors simultaneously.

## Implications

If the above conditions are met, then `ERRORMISCO_EL1.SUBARRAY`, `ERROSTATUS.CE`, and `ERROSTATUS.DE` might have an incorrect values.

## Workaround

There is no workaround for this erratum.

## 1859562

### Incorrect read value for the Trace ID Register 3 SYSSTALL field

#### Status

Fault Type: Programmer Category C  
Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

The Trace ID Register 3 (TRCIDR3) in the trace registers contains an incorrect value in the SYSSTALL field.

#### Configurations Affected

All configurations are affected.

#### Conditions

Software reads the TRCIDR3 register.

#### Implications

The TRCIDR3.SYSSTALL field contains the incorrect value of 0x1, indicating that PE stalling is permitted, instead of containing the expected value of 0x0 as stalling of the PE is not implemented. Any software using this field to check if stalling of the PE is permitted might not correctly identify it.

#### Workaround

Software should ignore the value of this field.

## 1862651

### Incorrect read value for External Debug Processor Feature Register

#### Status

Fault Type: Programmer Category C  
Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

Under certain conditions, External Debug Processor Feature Register (EDPFR) returns an incorrect read value for the GIC field.

#### Configurations Affected

All configurations are affected.

#### Conditions

1. GICCDISABLE input pin is set.
2. Debugger reads the EDPFR register.

#### Implications

The EDPFR.GIC field incorrectly reports the value 0x3 indicating that System register interface to version 4.1 of the GIC CPU interface is supported, instead of the expected value of 0x0, as GIC CPU interface system registers is not implemented when GIC CPU interface is disabled.

#### Workaround

There is no workaround.

## 1865453

### The values for fields ID\_AA64ZFR0\_EL1.{SM4,SHA3,AES} read incorrectly as non-zero

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

If configured without Cryptographic Extension support, the PE will incorrectly report non-zero values for certain SVE feature identification registers.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. The PE is configured with no Cryptographic Extension support.
2. A MRS from ID\_AA64ZFR0\_EL1 is executed.

OR

1. The PE is configured with Cryptographic Extension support and the CRYPTODISABLE pin is set.
2. A MRS from ID\_AA64ZFR0\_EL1 is executed.

#### Implications

If the above conditions are met, the values for fields ID\_AA64ZFR0\_EL1.{SM4,SHA3,AES} will incorrectly read as non-zero.

#### Workaround

There is no workaround.

## 1868638

### The core does not treat the BAS field of the Debug Breakpoint Control Register as RES1

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

The core is not treating the BAS field of the Debug Breakpoint Control Register (DBGBCR) as RES1, as specified in the Arm Architecture Reference Manual. When AArch32 is not supported at any Exception level, then the DBGBCR<n>.BAS field bits are RES1. This field should be written to 0b1111 by software and ignored by hardware.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Hardware breakpoint is enabled in address match mode.
2. The DBGBCRn\_EL1.BAS field is programmed to any value other than 0b1111.

#### Implications

If the above conditions are met, a breakpoint exception might not be taken as required by the Arm Architecture.

#### Workaround

This erratum can be avoided if software properly writes 0b1111 to the RES1 bits for the DBGBCR<n>.BAS field.

## 1870363

### L2 data RAM may fail to report corrected ECC errors

#### Status

Fault Type: Programmer Category C  
Fault Status: Present in r0p0. Fixed in r1p0.

#### Description

For specific operation types and cache states, a read of the L2 data RAM might fail to report a detected and corrected single-bit ECC error.

#### Configurations Affected

All configurations are affected.

#### Conditions

1. PE L1 data cache and L2 cache are in a SharedClean state and the exclusive monitor is armed for a given physical address.
2. PE executes a store exclusive instruction to this physical address.
3. L2 cache reads its data RAMs, and detects and corrects a single-bit ECC error.

#### Implications

If the above conditions are met, the PE will correct the error, but might fail to report it in the RAS error log registers. This can cause a small loss in diagnostic capability.

#### Workaround

There is no workaround.

## 1875555

### Compare and Swap (CAS) instructions with stack pointer as base register are incorrectly treated as checked accesses

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r1p0. Fixed in r2p0.

#### Description

Compare and Swap(CAS) instructions with stack pointer as base register and no offset are incorrectly treated as checked accesses when MTE tag checking is enabled.

#### Configurations affected

This erratum affects all configurations.

#### Conditions

1. MTE tag checking is enabled.
2. CAS (any flavor) with stack pointer as base register is executed.

#### Implications

The CAS instruction under consideration will be treated as a "checked" access, triggering unexpected tag check faults. Typical bring-up software is not expected to run into this scenario on test silicon.

#### Workaround

There is no workaround.

## 1875745

### A Checked load that fails a Tag Check could set the ESR to an incorrect value

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r1p0. Fixed in r2p0.

#### Description

Under certain conditions, memory access by a Checked load that generates a Tag Check fail on some bytes and an external data abort on other bytes could result in the setting of an incorrect value in the Exception Syndrome Register (ESR).

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Memory tagging is enabled and a Checked load that crosses a 16B aligned boundary performs memory access.
2. The first half of the access sees an ECC error or generates an external data abort.
3. The second half of the access generates a Tag Check fail.

#### Implications

If the above conditions are met, the ESR\_ELx.FnV and ESR\_ELx.EC values could be incorrect. ESR\_ELx.FnV could be set when the FAR contents are incorrect. ESR\_ELx.EC could be incorrectly set to 6'b010001. It is expected that software can handle this scenario on test silicon used for software bringup.

#### Workaround

There is no workaround.



## 1884880

### The core might report incorrect fetch address to FAR\_ELx when the core is fetching an instruction from a virtual address associated with a page table entry which has been modified

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0, r2p1. Open.

## Description

When a core fetches an instruction from a virtual address that is associated with a page table entry which has been modified and the fetched block is affected by parity error, the core might report an incorrect address within the same 32B block onto the Fault Address Register (FAR).

## Configurations Affected

All configurations are affected.

## Conditions

1. The core fetches instructions from an aligned 32B virtual address block.
2. A page table entry associated with the above 32B aligned block is updated. The new translation would cause an instruction abort.
3. TLB holds the old translation since the synchronization process, for example, TLB Invalidate (TLBI) followed by Data Synchronization Barrier (DSB), was not completed.
4. Some of the fetched instructions are affected by parity error in I-cache data RAM.
5. Context synchronization events were not processed between the last executed instruction and the above instruction.

## Implications

When the above conditions are satisfied, a core might report an incorrect fetch address to FAR\_ELx. The address reported in FAR\_ELx points at an earlier location in the same aligned 32B block. FAR\_ELx[63:5] still points correct virtual address.

## Workaround

There is no workaround.

## 1893664

### Accessing a memory location using mismatched shareability attributes when MTE tag checking is enabled might lose coherency or deadlock

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r1p0. Fixed in r2p0.

#### Description

A PE accessing a same physical memory location with mismatched shareability attributes and requiring a read of Memory Tagging Extension (MTE) tags might lose coherency or deadlock.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions:

1. PE accesses a physical memory location using cacheable and non-shareable attributes.
2. PE performs a clean and invalidate to satisfy requirements for shareability aliasing.
3. PE performs an untagged store to the same physical memory location using cacheable and shareable attributes.
4. PE performs a tagged memory access to the same physical address.

#### Implications

If the above conditions are met, the PE might lose the store data from condition 3 or fail to make forward progress on a load to the same physical address.

#### Workaround

Avoid using mismatched shareability attributes for aliases of the same memory location for tagged pages.

## 1896171

### Access to External Debug Auxiliary Processor Feature Register might incorrectly return an error response

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

An External Debug access to External Debug Auxiliary Processor Feature Register (EDAA32PFR) incorrectly gets an error response when OSLock is set.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. OSLSR\_EL1.OSLK bit is set.
2. A memory mapped access is made to the EDAA32PFR register.

#### Implications

The access would incorrectly get an error response when no error was expected due to OSLock.

#### Workaround

Debugger should clear OSLock before accessing the register.

## 1899211

### Some corrected errors might incorrectly increment ERR0MISC0.CECR or ERR0MISC0.CECO

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

If a Corrected Error is recorded because of a bus error which has no valid location (ERR0STATUS.MV=0x0), then a subsequent Corrected Error might incorrectly increment either of the ERR0MISC0.CECR or ERR0MISC0.CECO counters.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. A Corrected Error which has no valid location (ERR0STATUS.MV=0x0) is recorded.
2. A subsequent Corrected Error occurs.

#### Implications

The subsequent Corrected Error might improperly increment either of the ERR0MISC0.CECR or ERR0MISC0.CECO counters.

#### Workaround

No workaround is expected to be required.

**1899435****PFG duplicate reported faults through a Warm reset****Status**

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

**Description**

Under certain conditions, the Pseudo-fault Generation Error Record Registers might generate duplicate faults through a Warm reset.

**Configurations Affected**

This erratum affects all configurations.

**Conditions**

1. ERROPFGCDN is set with a non-zero countdown value.
2. ERROPFGCTL is set to generate a pseudo-fault with ERROPFGCTL.CDEN enabled.
3. The countdown value expires, generating a pseudo-fault.
4. Warm reset asserts.

**Implications**

After the Warm reset, a second generated pseudo-fault might occur.

**Workaround**

De-assert the ERROPFGCTL control bits before asserting a Warm reset.

## 1909702

### IDATAn\_EL3 might represent incorrect value after direct memory access to internal memory for Instruction TLB

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0, r2p1. Open.

#### Description

After implementation-defined RAMINDEX register is programmed to initiate direct memory access to internal memory for Instruction TLB, implementation-defined IDATAn\_EL3 value represents unpredictable value.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Implementation-defined RAMINDEX register is programmed to initiate direct memory access to internal memory for Instruction TLB.

#### Implications

If the above conditions are met, IDATAn\_EL3 register might represent incorrect value for Translation regime, VMID, ASID, and VA[48:21].

#### Workaround

There is no workaround.

## 1911676

### TFSR contents might be incorrect after executing a page crossing SVE predicated load instruction

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r1p0, r2p0. Fixed in r2p1.

#### Description

Under certain conditions, TFSR\_ELx bit[0] might be incorrect when an SVE predicated instruction accesses bytes that cross the 0xFFFF\_FFFF\_FFFF\_FFFF boundary.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. SVE predicate load is executed at EL1 or EL2 with HCR\_EL2.E2H=1 and accesses bytes crossing the 0xFFFF\_FFFF\_FFFF\_FFFF boundary.
2. Imprecise Checked access is generated for bytes in the first page and fails Tag Check.
3. Second page has no active elements.

#### Implications

If the above conditions are met, TFSR\_ELx bit[0] might be incorrectly updated instead of TFSR\_ELx bit[1].

#### Workaround

This erratum has no workaround.

## 1919240

### The PE might deadlock if Pseudofault Injection is enabled in Debug State

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

If Pseudofault Injection is enabled for the PE node (ERR1PFGCTL.CDNEN=0x1) and the PE subsequently enters Debug State, then the PE might deadlock. Alternatively, if the PE is executing in Debug State and the PE enables Pseudofault Injection for the PE node (ERR1PFGCTL.CDNEN=0x1), then the PE might deadlock.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. ERR1PFGCTL.CDNEN is set to 0x1 to enable Pseudofault Injection.
2. The PE enters Debug State.

OR

1. The PE is executing in Debug State.
2. ERR1PFGCTL.CDNEN is set to 0x1 to enable Pseudofault Injection.

#### Implications

If the above conditions are met, then the PE might deadlock.

#### Workaround

Ensure ERR1PFGCTL.CDNEN=0x0 before entering Debug State and while executing in Debug State.



## 1920415

### Trace Buffer might write trace packets to memory using incorrect cache attributes

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

Due to this erratum, a translation request from the Trace Buffer Extension (TRBE) unit might incorrectly use the write-back Cacheability attribute when both TRBLIMITR\_EL1.nVM and HCR\_EL2.CD are set.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. The TRBE is enabled.
2. TRBLIMITR\_EL1.nVM is set.
3. HCR\_EL2.CD is set.
4. Stage 2 translation is enabled.
5. The TBRE unit requests a translation.

#### Implications

If the above conditions are met, TRBE translations would be incorrectly marked as write-back cacheable instead of being assigned the correct non-cacheable attribute. As a result, TRBE could write trace packets to memory using the incorrect Cacheability attributes.

#### Workaround

There is no workaround.

## 1920634

### A Checked store with poisoned tags might result in a Tag Check Fail instead of taking an SError interrupt exception

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r1p0. Fixed in r2p0.

#### Description

Under certain conditions, poisoned data that is flagged when the Allocation Tag is accessed from memory by a Checked store that is executing in MTE imprecise mode, might result in a Tag Check Fail instead of reporting an SError interrupt exception.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Memory tagging is enabled.
2. A Checked store that is executing in imprecise mode performs a memory access.
3. The Allocation Tag is returned with the poison indication.

#### Implications

If the above conditions are met, then the Checked store might result in a Tag Check Fail being asynchronously accumulated instead of reporting an SError interrupt exception.

#### Workaround

There is no workaround.

## 1920871

### MPAM value associated with translation table walk request might be incorrect

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

Under some scenarios, MPAM value associated with translation table walk request might be incorrect when context changes along with security state.

#### Configurations Affected

All configurations are affected.

#### Conditions

1. Translation table walk request attempted before a context switch but is not completed until after a context change where the secure state changes.

#### Implications

MPAM value associated with the table walk request might be incorrect.

#### Workaround

There is no workaround.

## 1925506

### Unsupported atomic fault due to memory type defined in first stage of translation might result in exception being taken to EL2

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

Under certain conditions, when far atomics are not supported by the system, an unsupported atomic fault due to the memory type defined in the first stage of translation might result in an exception being taken to EL2.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Device memory type is defined in the first stage of translation for the atomic instruction.
2. HCR\_EL2.VM, HCR\_EL2.FWB, and HCR\_EL2.CD bits are set.
3. The system does not support far atomics.

#### Implications

If the above conditions are met, an exception is incorrectly taken to EL2.

#### Workaround

There is no workaround.

## 1926908

### Access with additional latency from alignment (LDST\_ALIGN\_LAT) PMU event does not count

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

The LDST\_ALIGN\_LAT, Access with additional latency from alignment, PMU event will not count correctly.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. One of the PMU event counters is configured to count the 0x4020, LDST\_ALIGN\_LAT PMU event.

#### Implications

The LDST\_ALIGN\_LAT PMU event will not be counted. The counter value for the event will not be correct and therefore cannot be used.

#### Workaround

There is no workaround.

## 1927566

### ERR0MISCO\_EL1.SUBARRAY value for ECC errors in the L1 data cache might be incorrect

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

Under certain conditions, the ERR0MISCO\_EL1.SUBARRAY value recorded for ECC errors in the L1 data cache might be incorrect.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. A load, store, or atomic instruction accesses multiple banks of the L1 data cache.
2. One of the banks accessed has an ECC error.

#### Implications

If the above conditions are met, then ERR0MISCO\_EL1.SUBARRAY might have an incorrect value. The remaining fields of the ERR0MISCO\_EL1 register remain correct.

#### Workaround

There is no workaround.

## 1929989

### Event Stream from the Virtual Counter is not correctly disabled by VHE in Secure State

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0. Fixed in r2p0.

#### Description

While the PE is executing in Secure State with Secure EL2 enabled (SCR\_EL3.EEL2=0x1), the Event Stream generated from the Virtual Counter is not correctly disabled when HCR\_EL2.(E2H, TGE)=(0x1, 0x1).

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. The PE is executing in Secure State and Secure EL2 is enabled (SCR\_EL3.EEL2=0x1).
2. CNTKCTL\_EL1 is configured to generate an Event Stream from the Virtual Counter.
3. HCR\_EL2.(E2H, TGE)=(0x1, 0x1) is configured to disable generation of an Event Stream from the Virtual Counter.

#### Implications

The Event Stream will be generated incorrectly.

#### Workaround

Secure EL2 can disable the generation of the Event Stream from the Virtual Counter by writing CNTKCTL\_EL1.

## 1938354

### Incorrect fault status code might be reported in Trace Buffer Extension register TRBSR\_EL1.FSC

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

The Trace Buffer Extension (TRBE) unit can be used by software to store trace packets from the Embedded Trace Extension (ETE) unit to memory. Due to this erratum, a translation request initiated by the TRBE which encounters multiple hits in the TLB might report an incorrect fault status code in TRBSR\_EL1.FSC.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. ETE is enabled.
2. ETE is in trace allowed region.
3. TRBE is enabled.
4. TRBE requests a memory translation.
5. This translation request encounters multiple hits in the TLB due to incorrect invalidation or misprogramming of translation table entries.

#### Implications

If the above conditions are met then one of the following behaviors might be observed.

1. The fault status code reported in TRBSR\_EL1.FSC might incorrectly indicate an illegal fault status code or
2. The fault status code reported in TRBSR\_EL1.FSC might incorrectly indicate another code instead of the correct TLB Conflict fault code or
3. A fault might be incorrectly reported when not expected with fault status code in TRBSR\_EL1.FSC indicating TLB conflict fault.

#### Workaround

There is no workaround.



**1949697**

## A Checked store that crosses a page boundary might not perform a Tag Check

### Status

Fault Type: Programmer Category C

Fault Status: Present in r1p0, r2p0. Fixed in r2p1.

### Description

Under certain micro-architectural conditions, a page-crossing Checked store executing in MTE imprecise mode might not perform a Tag Check if the second half of the memory access is Unchecked.

### Configurations Affected

This erratum affects all configurations.

### Conditions

1. Memory tagging is enabled.
2. A page-crossing Checked store performs memory access where the first half is an Imprecise Checked access and the second half is an Unchecked access.

### Implications

If the above conditions are met under specific micro-architectural conditions, Tag Check might not be performed for the first half of the memory access.

### Workaround

This erratum has no workaround.

## 1971496

### VMID value in trace packets might be incorrect

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

CX bit in Trace Filter Control Register EL2 (TRFCR\_EL2) enables VMID trace. This bit is ignored under some conditions and VMID field in trace elements might be zero.

#### Configurations affected

This erratum affects all configurations.

#### Conditions

The erratum occurs under the following conditions:

1. The Embedded Trace Extension unit is enabled.
2. Self hosted trace is enabled.
3. CID\_EL2 and VMID trace are allowed (TRCCONFIGR.VMID == 1 AND TRFCR\_EL2.CX == 1)
4. Core is executing in Secure EL0/EL1 with Secure EL2 disabled (SCR\_EL3.NS == 0 AND SCR\_EL3.EEL2 == 0)

#### Implications

If above conditions are met, then VMID field in trace elements might be zero, potentially leading to the generation of incorrect context elements by the trace unit.

#### Workaround

No workaround is required as the architecture is expecting that EL3 will clear TRFCR\_EL2 as part of a state switch in these conditions.

## 1975917

### AMU Event 0x0011, Core frequency cycles might increment incorrectly when the core is in WFI or WFE state

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0, r2p1. Open.

#### Description

The core frequency cycles Activity Monitor Unit (AMU) event may not count correctly when the core is in Wait For Interrupt (WFI) or Wait For Event (WFE) state and the clocks in the core are enabled.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. The architected activity monitor counter register 0 (AMEVCNTR00) is enabled.
2. The core executes WFE instructions in any version or the core executes WFI instructions in versions prior to r2p1.
3. The clocks in the core are never disabled, or
4. The clocks in the core are temporarily enabled without causing the core to exit WFE state in any version or WFI state in versions prior to r2p1 due to one of the following events:
  - A system snoop request that must be serviced by the core L1 data cache or the L2 cache.
  - A cache or Translation Lookaside Buffer (TLB) maintenance operation that must be serviced by the core L1 instruction cache, L1 data cache, L2 cache, or TLB.
  - An access on the Utility bus interface.
  - A Generic Interrupt Controller (GIC) CPU access or debug access through the Advanced Peripheral Bus (APB) interface.

#### Implications

The core frequency cycles AMU event will continue to increment when clocks are enabled even though the core is in WFE state for any version or WFI state for versions prior to r2p1. Arm expects this to be a minor issue as the resulting discrepancies will likely be negligible from the point of view of consuming these counts in the system firmware at the 1ms level.

The WFI condition was fixed in version r2p1, but the issue was not fully resolved for WFE. Therefore, the WFE condition exists on all versions, whereas the WFI condition is only present in r0p0, r1p0, and r2p0 versions.

## Workaround

There is no workaround.

## 1980906

### Reset Catch debug event might not cause core to enter Debug state immediately after Cold reset

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

The core might not enter Debug state immediately after Cold reset is deasserted when Reset Catch debug event is enabled and halting is allowed.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Reset Catch debug event is enabled.
2. Halting is allowed.
3. Cold reset is deasserted.

#### Implications

If the conditions are met, then the core might not enter Debug state after Cold reset is deasserted and before the first instruction is executed. The core will enter Debug state either before executing any instruction or after executing few instructions.

#### Workaround

There is no workaround.

## 1986267

### DRPS might not execute correctly in Debug state with SCTLR\_ELx.IESB set in the current EL

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

In Debug state with SCTLR\_ELx.IESB set to 1, the DRPS (debug only) instruction does not execute properly. Only partial functionality of the DRPS instruction is performed.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

The erratum occurs under the following conditions:

1. The core is in Debug state.
2. SCTLR\_ELx.IESB is set to 1 for the current exception level.
3. The DRPS instruction is executed.

#### Implications

If the above conditions are met, the DRPS instruction does not complete as intended, which might lead to incorrect operation or results. Register data or memory will not be corrupted. There are also no security or privilege violations.

#### Workaround

The erratum can be avoided by clearing SCTLR\_ELx.IESB followed by the insertion of an ISB and an ESB instruction in code before the DRPS instruction.

## 1989365

### Floating-point Operations speculatively executed PMU events are not counted

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

The following PMU events do not count correctly:

- 0x8014, FP\_HP\_SPEC, Half-precision floating-point Operations speculatively executed
- 0x8018, FP\_SP\_SPEC, Single-precision floating-point Operations speculatively executed
- 0x801C, FP\_DP\_SPEC, Double-precision floating-point Operations speculatively executed

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

One of the PMU event counters is configured to count any of the following events:

- 0x8014, FP\_HP\_SPEC
- 0x8018, FP\_SP\_SPEC
- 0x801C, FP\_DP\_SPEC

#### Implications

PMU event counters configured for these PMU events do not count.

#### Workaround

There is no workaround.

## 2000010

### Execution of STG instructions in close proximity might incorrectly write MTE Allocation Tag to memory more than once

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r2p0. Fixed in r2p1.

#### Description

Under certain micro-architectural conditions, an STG instruction might write MTE Allocation Tag to memory more than once.

#### Configurations Affected

This erratum affects all configurations where the **BROADCASTMTE** pin is HIGH.

#### Conditions

1. Memory tagging is enabled.
2. Two or more STG instructions that write both Allocation Tag and Data are executed in close proximity.
3. Above STG instructions access the same cache line address but different 32 bytes in memory.

#### Implications

If the above conditions are met, then under specific micro-architectural conditions Allocation Tag for the entire cache line may be written to memory twice. This is not expected to be an issue as Allocation Tags are written by only one software agent at a time. The value of Allocation Tag will not change between these two writes since there will not be another write to Allocation Tag from another PE.

#### Workaround

There is no workaround.



## 2002779

### CPU might fetch incorrect instruction from a page programmed as non-cacheable in stage-1 translation and as device memory in stage-2 translation

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

When an instruction fetch is initiated for a page programmed as non-cacheable normal memory in stage-1 translation and as device memory in stage-2 translation, the instruction memory might incorrectly return 0. This might cause an unexpected UNDEFINED exception.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs under the following conditions:

1. A CPU fetch instruction from a page satisfies the following:
  - Stage-1 translation of this page is programmed as non-cacheable normal memory.
  - Stage-2 translation of this page is programmed as device memory.

#### Implications

If the above conditions are met, the CPU might read 0 from the instruction memory. This instruction might cause an unexpected UNDEFINED exception. Instruction fetches to device memory are not architecturally predictable in any case, and device memory is expected to be marked as execute never, so this erratum is not expected to cause any problems to real-world software.

#### Workaround

This erratum has no workaround.

## 2017087

# DSB might not guarantee completion of direct reads of L2 cache memories

## Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

## Description

Direct reads of internal memories are implemented using a SYS #6, C15, C0, #0, <Xt> instruction executed in EL3. In response to this instruction, the PE reads an internal memory and places the contents in implementation defined DDATAx registers. A DSB is intended to guarantee completion of the memory access. If the targeted RAMs are the L2 tag, L2 victim, or L2 data RAM, a DSB might not provide this guarantee.

## Configurations Affected

This erratum affects all configurations.

## Conditions

1. PE executes a SYS #6, C15, C0, #0, <Xt> instruction, where Xt specifies the L2 tag, L2 data, or L2 victim RAMs.
2. PE executes a DSB.
3. PE reads the DDATAx registers.

## Implications

If the above conditions are met, along with specific microarchitectural conditions, the DDATAx registers may not be updated when the DSB completes.

## Workaround

When performing direct memory accesses to L2 cache memories do the following:

1. Set CPUACTLR2\_EL1[46].
2. Perform the direct memory accesses.
3. Clear CPUACTLR2\_EL1[46].

Note that setting CPUACTLR2\_EL1[46] incurs a 1-2% performance penalty. Thus, CPUACTLR2\_EL1[46] should not be set by default.

## 2018317

### External APB write to a register located at offset 0x084 might incorrectly issue a write to External Debug Instruction Transfer Register

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

The core might incorrectly issue a write to External Debug Instruction Transfer Register (EDITR) when an external APB write to another register that is located at offset 0x084 is performed in the Debug state. The following debug components share the offset alias with the EDITR register:

- ETE - TRCVIIECTLR - ViewInst Include/Exclude Control Register
- Reserved locations

The following debug component shares the offset alias with the EDITR register when the PE is configured with 20-PMUs:

- PMU - PMEVCNTR16[63:32] - Event Counter 16

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. The core is in debug state.
2. The External Debug Status and Control Register (EDSCR) cumulative error flag field is 0b0.
3. Memory access mode is disabled, in example, EDSCR.MA = 0b0.
4. The OS Lock is unlocked.
5. External APB write is performed to a memory mapped register at offset 0x084 other than the EDITR.

#### Implications

If the above conditions are met, then the core might issue a write to the EDITR and try to execute the instruction pointed to by the ITR. As a result of the execution, the following might happen:

- CPU state and/or memory might get corrupted.
- The CPU might generate an UNDEFINED exception.
- The EDSCR.ITE bit will be set to 0.

## Workaround

Before programming any register at this offset when the PE is in Debug state, the debugger should either:

- Set the EDSCR.ERR bit by executing some Undefined instruction (e.g. writing zero to EDITR); or
- Set the OS Lock and then unlock it afterwards.

## 2025108

### Corrupted register state results from executing specific form of SEL instruction followed by SVE AESMC or AESIMC instruction

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

Under certain conditions, execution of two SVE instructions, either SEL(vectors) followed by AESMC or SEL(vectors) followed by AESIMC, might result in corruption of a destination vector register.

#### Configurations affected

This erratum affects configurations with CRYPTO==TRUE.

#### Conditions

The following SVE instruction sequence is required

1. PE executes SEL <Zd>.B, <Pg>, <Zn>.B, <Zm>.B
2. PE executes either AESMC <Zd>.B, <Zd>.B or AESIMC <Zd>.B, <Zd>.B

#### Implications

The sequence of instructions described in the conditions above are not expected to occur in real code, because they do not perform useful computation. As such, no impact is expected to real systems.

#### Workaround

Because the code sequences for this erratum are not expected to occur in real code, no workaround is required.

## 2050953

### External aborts for streaming writes to MTE tagged pages may report multiple errors

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r1p0, r2p0. Fixed in r2p1.

#### Description

If a streaming write to a memory page with Memory Tagging Extension (MTE) tagging enabled receives an External abort, it may report multiple SError aborts.

#### Configurations Affected

This erratum affects all configurations with the BROADCASTMTE pin asserted.

#### Conditions

1. The Processing Element (PE) generates a write of a full cache line to a memory page that is marked MTE Tagged.
2. A transaction issued on the CHI interconnect on behalf of the streaming write receives an External abort from the interconnect

#### Implications

If the above conditions are met, the PE might report multiple SError aborts. External aborts received from the interconnect represent error conditions in the system, such as accesses to unmapped devices and uncorrectable ECC errors. These conditions are more severe than the possibility of the PE reporting multiple SError aborts.

#### Workaround

There is no workaround.

## 2052424

### An execution of MSR instruction might not update the destination register correctly when an external debugger initiates an APB write operation to update debug registers

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

When an **MSR** instruction and an APB write operation are processed on the same cycle, the **MSR** instruction might not update the destination register correctly.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs under the following conditions:

1. A CPU executes an **MSR** instruction to update any of following SPR registers:
  - a. DBGBCR<n>\_EL1
  - b. DBGBVR<n>\_EL1
  - c. DBGWCR<n>\_EL1
  - d. DBGWVR<n>\_EL1
  - e. OSECCR\_EL1
2. An external debugger initiates an APB write operation for any of following registers:
  - a. DBGBCR<n>
  - b. DBGBVR<n>
  - c. DBGBXVR<n>
  - d. DBGWCR<n>
  - e. DBGWVR<n>
  - f. DBGWXVR<n>
  - g. EDECCR
  - h. EDITR
3. The SPR registers (for example, OSLSR\_EL1.OSLK and EDSCR.TDA) and external pins are programmed to allow the following behavior:
  - a. The execution of an **MSR** instruction in condition 1 to update its destination register without neither a system trap nor a debug halt
  - b. The APB write operation in condition 2 to update its destination register without error
4. The **MSR** instruction execution in condition 1 and APB write operation in condition 2 happen in same

cycle.

5. The **MSR** write and the APB write are to two different registers. The architecture specifies that it is the software or debugger's responsibility to ensure writes to the same register are updated as expected.

## Implications

If the above conditions are met, an execution of the **MSR** instruction might not update the destination register correctly. The destination register might contain one of following values after execution:

1. The execution of the **MSR** instruction is ignored. The destination register of the **MSR** instruction holds an old value.
2. The execution of the **MSR** instruction writes an incorrect value to its destination register.

A external debugger and system software are expected to be coordinated to prevent conflict in these registers.

## Workaround

No workaround is required for this erratum.



## 2054222

### Trace data lost during collection stop in TRBE

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

When a collection stop event occurs in the Trace Buffer Extension (TRBE), trace collection from the Embedded Trace Extension (ETE) is stopped and the data in the TRBE buffers are flushed to memory. When this occurs under certain micro-architectural timing conditions, 64 bytes of trace data might get lost and replaced with Ignore bytes. This does not result in a current pointer mismatch.

#### Configurations affected

This erratum affects all configurations.

#### Conditions

This erratum occurs under the following conditions:

1. ETE and TRBE are enabled.
2. ETE is in a trace-allowed region.
3. A collection stop event occurs in TRBE.

#### Implications

When the above conditions are met, 64 bytes of trace data might get lost and replaced with Ignore bytes while getting written to memory.

#### Workaround

The erratum has no workaround.

**2058367****L3D\_CACHE\_ALLOC PMU inaccurate when using WriteEvictOrEvict transactions****Status**

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

**Description**

When the L2 cache issues a WriteEvictOrEvict transaction for a L2 copyback, the L3D\_CACHE\_ALLOC PMU event is not counted, even though it might cause an L3 cache allocation.

**Configurations Affected**

This erratum affects all configurations that enable WriteEvictOrEvict transactions through CPUECLTR\_EL1[45]=1.

**Conditions**

1. CPUECLTR\_EL1[45] is set to 1 (default value).
2. PE is configured to count PMU event 0x29 L3D\_CACHE\_ALLOCATE.
3. L2 victimizes a cache line in the UC or SC state and generates a WriteEvictOrEvict transaction.

**Implications**

If the above conditions are met, the PE fails to increment the PMU count.

**Workaround**

The DSU L3 cache PMU feature can be used to count L3 allocations across all PEs in the cluster.

## 2058540

### Incorrect Fault Status code reported for predicated SVE op

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

An SVE predicated store to a page with MTE tagging enabled that encounters a poisoned MTE Tag with no active elements and also has a tag check fail for a different MTE Tag might report a Synchronous External Abort instead of a Synchronous Tag Check Fault.

#### Configurations Affected

This erratum affects all configurations with the BROADCASTMTE pin asserted.

#### Conditions

This erratum occurs under the following conditions:

1. A PE executes an SVE predicated store to a page that is marked MTE Tagged.
2. The store accesses more than one Tag granule, such that there are no active elements corresponding to one of the granules accessed that also has a poisoned MTE tag.
3. The memory access results in a Tag check fail.

#### Implications

If the above conditions are met, the PE might report a Synchronous External Abort instead of Synchronous Tag Check Fault.

#### Workaround

This erratum has no workaround.

## 2061107

### Tag check fail might not be reported for an unaligned predicated SVE store

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

An SVE predicated store to a page with MTE tagging enabled might not report a fault when it encounters a tag check fail.

#### Configurations Affected

This erratum affects all configurations with the BROADCASTMTE pin asserted

#### Conditions

This erratum occurs under the following conditions:

1. A PE executes an SVE predicated store to a page that is marked MTE Tagged.
2. The store access crosses a cache line boundary.
3. Both cache line accesses encounter a tag check fault.
4. Before the fault is reported, the first cache line is snooped out and another PE modifies the tag.
5. The tag check passes for the first cache line access when the line is fetched again.

#### Implications

If the above conditions are met, the PE might not report a Synchronous Tag Check Fault. This erratum is reported as a Programmer Category C since most of the time, a tag check fault would be correctly detected.

#### Workaround

This erratum has no workaround.

**2089668****OSECCR\_EL1/EDECCR is incorrectly included in the Warm Reset domain****Status**

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

**Description**

OSECCR\_EL1/EDECCR is incorrectly included in the Warm Reset domain. If a Warm Reset occurs, then the value in this register will be lost.

**Configurations Affected**

This erratum affects all configurations.

**Conditions**

1. Warm Reset is asserted.

**Implications**

If the above conditions are met, then the value in OSECCR\_EL1/EDECCR will be lost.

**Workaround**

A debugger should enable a Reset Catch debug event by setting CTIDEVCTL.RCE to 1. This causes the PE to generate a Reset Catch debug event on a Warm reset, allowing the debugger to reprogram the EDECCR.

## 2093019

### Extra A-sync packet might get written to Trace Buffer in Trace prohibited region

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, and r2p0. Fixed in r2p1.

#### Description

An external trace analyzer can request that an A-sync packet is injected into the trace stream, which the Embedded Trace Extension (ETE) will insert when the next P0 Element is traced. Due to this erratum, this A-sync packet might incorrectly get generated and written to trace buffer memory via TRBE under the conditions mentioned below.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

The erratum occurs under the following conditions:

1. TRBE is enabled.
2. ETE is in trace prohibited region.
3. A **TSB** instruction is executed and completed.
4. TRBE is disabled.
5. A synchronization request is received on the ATB interface.
6. TRBE is enabled.

#### Implications

If the above conditions occur, an A-sync packet might go to TRBE and when a new **TSB** instruction is executed, this packet might get written to memory. Under normal usage Arm expects that this unexpected trace will have no impact.

#### Workaround

There is no workaround.

## 2109742

### Speculative access to a recently unmapped physical address previously containing page tables might occur

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

If the memory containing page tables is unmapped or cacheable attribute is changed while there are pending hardware prefetches to that table, the read requests might illegally occur after a DSB instruction.

#### Configurations Affected

All configurations are affected.

#### Conditions

- A table walk occurs.
- The hardware prefetcher generates a cacheable request to adjacent cache lines, allocating the L2 cache.
- The physical address containing the page tables is unmapped or cacheable attribute is changed.

#### Implications

If the above conditions are met, an illegal read might occur in a short window of time after the DSB instruction. Arm does not believe this will cause incorrect execution in any practical system.

#### Workaround

No workaround is required.

## 2112535

### L1D\_CACHE\_INVALID and L2D\_CACHE\_INVALID PMU events fail to increment for SnpPreferUnique and SnpPreferUniqueFwd

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

When the PE receives a SnpPreferUnique or SnpPreferUniqueFwd snoop from the interconnect, it might not correctly count the L1 data cache and L2 cache invalidations that result.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. PE receives SnpPreferUnique or SnpPreferUniqueFwd from the coherent interconnect.
2. PE invalidates the L1 data cache and L2 cache.

#### Implications

If the above conditions are met, the L1D\_CACHE\_INVALID event will fail to increment and the L2D\_CACHE\_INVALID event might fail to increment. The relative infrequency of the necessary conditions means that the L1D\_CACHE\_INVALID and L2D\_CACHE\_INVALID events are still meaningful.

#### Workaround

There is no workaround.



## 2113481

### MPAM value associated with instruction fetch might be incorrect

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0, r2p1. Open.

#### Description

Under some scenarios, the MPAM value associated with an instruction fetch request might be incorrect when context changes.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. An Instruction fetch request is attempted before a context switch but is not completed until after a context switch.

#### Implications

The MPAM value associated with the instruction fetch request might be incorrect.

#### Workaround

There is no workaround.

## 2117983

### Data abort on SVE first fault load might be routed to incorrect Exception level

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r1p0, r2p0. Fixed in r2p1.

#### Description

Under certain conditions, data abort on SVE first fault load might be routed to incorrect Exception level.

#### Configurations Affected

All configurations are affected.

#### Conditions

All of the following conditions must be met:

1. First active lane of SVE first fault load crosses a page boundary.
2. Translation table walk for the second page generates an external abort.
3. Memory tagging is enabled and access to bytes on the first page generates a tag check fail.
4. SCR\_EL3.EA or HCR\_EL2.TEA bits are set.

#### Implications

If the above conditions are met, data abort will not get routed to the correct Exception level. If this scenario occurred at EL0/EL1/EL2 and SCR\_EL3.EA bit is set, data abort will not get routed to EL3. Likewise if this scenario occurred at EL0/EL1 and HCR\_EL2.TEA bit is set and SCR\_EL3.EA bit is not set, data abort will not get routed to EL2. The potential impact of this erratum to a practical system is considered to be very minor, given the precondition of an unrecoverable error.

#### Workaround

There is no workaround for this erratum.

## 2141645

### A64 WFI or A64 WFE executed in Debug state suspends execution indefinitely

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

Executing an A64 WFI or WFE instruction while in Debug state results in suspension of execution, and execution cannot be resumed by the normal WFI or WFE wake-up events while in Debug state.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. The Processing Element (PE) is in Debug state and in AArch64 Execution state.
2. A WFI or WFE instruction is executed from EDITR.

#### Implications

If the above conditions are met, the PE will suspend execution.

This is not thought to be a serious erratum, because an attempt to execute a WFI or WFE instruction while in Debug state is not expected.

For WFI executed in Debug state, execution can only resume by any of the following:

- A Cold or Warm reset
- A Restart request trigger event from the Cross Trigger Interface (CTI) causing exit from Debug state, followed by a WFI wake-up event

For WFE executed in Debug state, execution can only resume by any of the following:

- A Cold or Warm reset
- A Restart request trigger event from the CTI causing exit from Debug state, followed by a WFE wake-up event
- An external event that sets the Event Register. Examples include executing an SEV instruction on another PE in the system or an event triggered by the Generic Timer.

#### Workaround

A workaround is unnecessary, because an attempt to execute a WFI or WFE instruction while in Debug state is not expected.

## 2143136

### Some SVE PMU events count incorrectly

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

The following Performance Monitoring Unit (PMU) events do not count correctly:

- 0x8074, SVE\_PRED\_SPEC, SVE predicated Operations speculatively executed
- 0x8075, SVE\_PRED\_EMPTY\_SPEC, SVE predicated operations with no active predicates, Operations speculatively executed
- 0x8076, SVE\_PRED\_FULL\_SPEC, SVE predicated operations with all active predicates, Operations speculatively executed
- 0x8077, SVE\_PRED\_PARTIAL\_SPEC, SVE predicated operations with partially active predicates, Operations speculatively executed

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

One of the PMU event counters is configured to count any of the following events:

- 0x8074
- 0x8075
- 0x8076
- 0x8077

#### Implications

Load and store operations due to SVE instructions are not counted by any of these events. The counter values for these events will only reflect predicated SVE data processing operations. For example, this means that the ratios of each of the 0x8075-0x8077 event values to the 0x8074 event value will not be as expected because load and store operations are not included. However, the types of predicate used by data processing operations will still be usefully indicated.

#### Workaround

There is no workaround.

## 2146514

### PMU Event MEM\_ACCESS\_CHECKED\_WR, 0x4026 counts incorrectly and MEM\_ACC\_CHECKED 0x4024 might be incorrect

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r1p0, r2p0. Fixed in r2p1.

#### Description

The PMU Event MEM\_ACCESS\_CHECKED\_WR, 0x4026 does not count correctly, and MEM\_ACC\_CHECKED 0x4024 might not count correctly.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. One of the PMU event counters is configured to count event 0x4026 or 0x4024.
2. MTE is enabled.
3. SCTLR\_ELx.ATA=1.
4. A store instruction is executed that generates a memory-write access that is Tag Checked.

#### Implications

The counter values for these events will not be correct and therefore cannot be used reliably.

#### Workaround

There is no workaround.

## 2154216

### FAR\_ELx contents for a Data Abort exception on SVE first fault contiguous load instruction due to Tag Check fail might be incorrect

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

A SVE first fault contiguous load instruction that encounters both a Tag Check fail when accessing the first active element and a watchpoint match on one of the non-first active elements can generate a Data abort exception with an incorrect value in FAR\_ELx.

#### Configurations Affected

All configurations are affected.

#### Conditions

This erratum occurs under all of the following conditions:

1. Memory tagging and watchpoints are enabled.
2. A SVE first fault contiguous load instruction accesses memory and generates a Data Abort exception due to a Tag Check fail on the first active element.
3. There is a watchpoint match on one of the non-first active elements.

#### Implications

If the above conditions are met, a Data Abort exception will be generated with an incorrect value in FAR\_ELx. ESR\_ELx will indicate Synchronous Tag Check Fault. The FAR\_ELx value could be anything between the start address of the access and up to twice the access size.

#### Workaround

This erratum has no workaround.



## 2159150

### Direct access of L2 data RAMs using RAMINDEX returns incomplete data

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

A direct access to the L2 data RAM using the RAMINDEX function returns incomplete data in the DDATA2 register.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs under the following condition:

1. Direct access to internal memory targeting L2 data RAM is executed.

#### Implications

A direct access to the L2 data RAM will result in zeros on DDATA2\_EL3[19:16]. These bits should contain ECC[15:12] corresponding to Data[127:64], but instead contains zeros.

#### Workaround

There is no workaround.

## 2174188

### PMU\_HOVFS event not always exported when self-hosted trace is disabled

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, and r2p0. Fixed in r2p1.

#### Description

PMU\_HOVFS is a PMU event that can be exported to the ETM.

This event should be exported if self-hosted trace is disabled, or, if self-hosted trace is enabled and TRFCR\_EL2.E2TRE == 0b1.

This event is not exported if self-hosted trace is enabled and TRFCR\_EL2.E2TRE == 0b0.

Due to this erratum, when self-hosted trace is disabled, the event is never exported if TRFCR\_EL2.E2TRE == 0b0.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. The ETM is configured to use PMU\_HOVFS as an external input event.
2. Self-hosted trace is disabled and TRFCR\_EL2.E2TRE == 0b0.

#### Implications

Overflows of PMU counters reserved by EL2 might not be visible.

#### Workaround

To use the PMU\_HOVFS as an external input event when self-hosted trace is disabled, ensure TRFCR\_EL2.E2TRE is set to 0b1.

## 2178034

### An SError might not be reported for an atomic store that encounters data poison

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

Under certain conditions, an atomic store that encounters data poison might not report an SError.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs under the following conditions:

1. An atomic store that is unaligned to its data size but within a 16-byte boundary accesses memory.
2. The atomic store accesses multiple L1 data banks such that not all banks have data poison.

#### Implications

If the above conditions are met, an SError might not be reported although poisoned data is consumed. Note that the data remains poisoned in the L1 and will be reported on the next access.

#### Workaround

This erratum has no workaround.

**2186347****64 bit source SVE PMULLB/T not considered Cryptography instruction****Status**

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

**Description**

64 bit source element variants of SVE PMULLB and PMULLT are incorrectly classified as non-cryptography instructions. When the **CRYPTODISABLE** pin is asserted, 64 bit source SVE PMULLB or SVE PMULLT instructions are executed rather than taking the expected undefined instruction exception. In addition to this, when the CRYPTODISABLE pin is deasserted, PMU counts for CRYPTO\_SPEC (PMU event 0x77) do not include 64 bit source SVE PMULLB and PMULLT in their counts.

**Configurations Affected**

This erratum affects all configurations.

**Conditions**

Cryptodisable

1. **CRYPTODISABLE** pin is high.
2. 64 bit source SVE PMULLB or SVE PMULLT is executed.

PMU Counts

1. **CRYPTODISABLE** pin is low.
2. PMU Enabled to count PMU EVENT 0x77 (CRYPTO\_SPEC).
3. 64 bit source SVE PMULLB or SVE PMULLT is executed.

**Implications**

If the above conditions are met, then the instructions will be executed instead of taking the undefined exception that is required by Arm architecture.

In addition, the PMU counter for the CRYPTO\_SPEC event (PMU EVENT 0x77) will not increment for 64 bit source SVE PMULLB PMULLT instructions.

**Workaround**

There is no workaround.

## 2227174

### Streaming writes to memory mapped Non-shareable and write-back might cause data corruption because of reordering

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

Writes to contiguous bytes might be combined into one streaming write of 64 bytes. If such writes are performed to memory mapped Non-shareable and write-back, then two streaming writes to the same physical address might be performed in the wrong order.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

Write stream operations to memory mapped Non-shareable and write-back can allocate the L2 cache without issuing a request on the CHI interface. This creates the possibility of two concurrent pending WriteNoSnpFull transactions of the same cache line on CHI, without the proper sequencing to guarantee the order they are performed.

#### Implications

If the above conditions are met, then the combined writes might be performed in the wrong order as determined by the sequential execution model.

#### Workaround

This erratum can be avoided by mapping all write-back memory as Inner or Outer Shareable.

## 2238108

### Read or write from Secure EL1 for ICV\_BPR1\_EL1 register might not work

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, and r2p0. Fixed in r2p1.

#### Description

Valid access to ICV\_BPR1\_EL1 from Secure EL1 when ICV\_CTLR\_EL1.CBPR is set to 1 should modify ICV\_BPRO\_EL1 on writes and return the value from ICV\_BPRO\_EL1 on reads. Instead, reads of ICV\_BPR1\_EL1 return ICV\_BPRO\_EL1 plus one, saturated to 0b111. Writes to ICV\_BPR1\_EL1 are ignored.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs under the following conditions:

1. The PE is in Secure state in the EL1 exception level.
2. ICV\_CTLR\_EL1.CBPR is set to 1.
3. A valid read or write access to ICV\_BPR1\_EL1 occurs.

#### Implications

If the above conditions are met, then an incorrect value might be returned on read or a valid write might be ignored potentially, affecting the priority of interrupts in the CPU.

#### Workaround

This erratum has no workaround.

## 2238111

### Reads of DISR\_EL1 incorrectly return 0s while in Debug State

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

When the Processing Element (PE) is in Debug State, reads of DISR\_EL1 from EL1 or EL2 with SCR\_EL3.EA=0x1 will incorrectly return 0s.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. The PE is executing in Debug State at EL1 or EL2, with SCR\_EL3.EA=0x1.
2. The PE executes an MRS to DISR\_EL1.

#### Implications

If the above conditions are met, then the read of DISR\_EL1 will incorrectly return 0s.

#### Workaround

No workaround is expected to be required.

## 2239139

### DRPS instruction is not treated as UNDEFINED at EL0 in Debug state

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

In Debug state, DRPS is not treated as an UNDEFINED instruction.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. The Processing Element (PE) is in Debug state.
2. PE is executing at EL0.
3. PE executes DRPS instruction.

#### Implications

If the above conditions are met, then the PE will incorrectly execute DRPS as NOP instead of treating it as an UNDEFINED instruction.

#### Workaround

There is no workaround.



## 2243871

### ELR\_ELx[63:48] might hold incorrect value when PE disables address translation

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

When the CPU executes an exception return in order to switch context and the new context satisfies certain rare conditions, the top 16 bits of ELR\_ELx might track an incorrect value.

#### Configurations Affected

The erratum affects all configurations.

#### Conditions

This erratum occurs under the following conditions:

1. CPUACTLR\_EL1[22] is set to 1.
2. The PE executes an ERET, ERETAA or ERETAB instruction to switch to a new context.
3. Either stage 1 or stage 2 translation was enabled when ERET is executed. After ERET, both stage 1 and stage 2 translations are turned off.
4. ELR\_ELx[63:48] specified by ERET is neither 0x0000 (all zero) nor 0xffff (all one).

#### Implications

When the above conditions are met, the PE takes instruction abort (address size fault) or asynchronous exception after ERET without executing the instruction in the context specified by ERET. After the exception is taken, ELR\_ELx specified by ERET should hold the same value because no instruction is executed. However, PE might modify ELR\_ELx[63:48] to zero.

ERET with non-zero ELR\_ELx[63:48] causes an address size fault during address translation disabled because the CPU supports less than 256TB physical address space. Arm also assumes the new context is controlled by privileged software (for example, Hypervisor) because translation is turned off. Therefore, software can hit this erratum only when the system software uses this malicious address in the ELR\_ELx register.

#### Workaround

This erratum has no workaround.

## 2245716

### TRBE might use incorrect Cacheability attributes for TRBE data when address translation is disabled

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

Under certain conditions, Trace Buffer Extension (TRBE) might use incorrect Cacheability attributes for TRBE data when address translation is disabled.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs under the following conditions:

1. TRBE is enabled with `TRBLIMITR_EL1.nVM == 1`.
2. `TRBMAR_EL1.Attr` is programmed to use Cacheable attributes.
3. `MDCR_EL2.E2TB = 2'b00` (EL2 owning)
4. `HCR_EL2.CD=1` and `HCR_EL2.VM=1`
5. PE is executing at EL=1 or EL=0.
6. TRBE writes data to memory.

#### Implications

When the above conditions are met, PE might incorrectly use Non-Cacheable attribute instead of Cacheable attribute from `TRBMAR_EL1.Attr[3:0]` for TRBE data. Trace data might be lost if the memory location used by TRBE is present in cache when this write happens.

#### Workaround

This erratum has no workaround.

## 2245832

### ESR\_ELx contents for a Data Abort exception might be incorrect when an L1D tag double bit error is encountered

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

When an L1D tag double bit error is encountered, a Data Abort exception might be reported with an incorrect fault type of Synchronous Tag Check Fault in the ESR\_ELx register under unusual micro architectural conditions.

#### Configurations Affected

This erratum affects all configurations with the BROADCASTMTE pin asserted.

#### Conditions

This erratum occurs under all of the following conditions:

1. Memory tagging is enabled.
2. A precise checked access due to a load instruction encounters L1D tag double bit error.

#### Implications

If the previous conditions are met, a Data Abort exception will be generated with an incorrect Data Fault Status Code (DFSC) of Synchronous Tag Check Fault in the ESR\_ELx register when it should have been Synchronous External Abort.

If this scenario occurred at EL0/EL1/EL2 and SCR\_EL3.EA bit is set, then Data Abort will not get routed to EL3.

Likewise if this scenario occurred at EL0/EL1 and HCR\_EL2.TEA bit is set, then Data Abort will not get routed to EL2. A fatal RAS error will still be reported.

#### Workaround

This erratum has no workaround.

## 2247178

### L1 MTE Tag poison is not cleared

#### Status

Fault Type: Programmer Category C  
Fault Status: Present in r1p0, r2p0. Fixed in r2p1.

#### Description

The MTE Tag poison is not cleared by an STG or DC G[Z]VA instruction.

#### Configurations Affected

This erratum affects all configurations with the BROADCASTMTE pin asserted.

#### Conditions

This erratum occurs under the following conditions:

1. A Processing Element (PE) accesses a line that encounters poison on the MTE Tag.
2. The PE executes an STG or DC G[Z]VA to the same 16-byte address.

#### Implications

If the above conditions are met, then the MTE Tag poison does not get cleared in the L1 Tag.

#### Workaround

There is no workaround.

## 2254450

### L1 Data poison is not cleared by a store

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

The L1 Data poison is not cleared by a store under certain conditions.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs under the following conditions:

1. A Processing Element (PE) executes a store that does not write a full word to a location that has data marked as poison.
2. The PE executes another store that writes to all bytes that contain data poison before the previous store is globally observable.

#### Implications

If the above conditions are met, then the poison bit in the L1 Data cache does not get cleared.

#### Workaround

This erratum can be avoided by inserting a DMB before and after a word-aligned store that is intended to clear the poison bit.

## 2276444

### PMU event for full/partial/empty/not full predicate incorrect for some SVE instructions

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

The PMU events for full/partial/empty/not full predicate capture the cases where an instruction reads a full, not full, partial, or empty value for governing predicate, according to the size of the instruction. Under certain circumstances, the event might be incorrectly captured.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

- PMU is configured to sample events for SVE\_PRED\_EMPTY\_SPEC (0x8075), SVE\_PRED\_FULL\_SPEC (0x8076), SVE\_PRED\_NOT\_FULL\_SPEC (0x8079), or SVE\_PRED\_PARTIAL\_SPEC (0x8077).
- One of these SVE conversion instructions is executed: SCVTF, UCVTF, FCTVZU, FCVTZS, FCVT, FCVTX, FCVTXNT, or FCVTNT.
- Governing predicate used by instruction has a different value than All-Active or All-Empty.

#### Implications

If the previous conditions are met, the following events might be incorrectly captured:

- PMU event SVE\_PRED\_EMPTY\_SPEC (0x8075)
- PMU event SVE\_PRED\_FULL\_SPEC (0x8076)
- PMU event SVE\_PRED\_NOT\_FULL\_SPEC (0x8079)
- PMU event SVE\_PRED\_PARTIAL\_SPEC (0x8077)

#### Workaround

This erratum has no workaround.

## 2278134

### PMU L1D\_CACHE\_REFILL\_OUTER is inaccurate

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

The L1D\_CACHE\_REFILL\_OUTER PMU event 0x45 is inaccurate due to ignoring refills generated from a system cache. The L1D\_CACHE\_REFILL PMU event 0x3 should be the sum of PMU events L1D\_CACHE\_REFILL\_INNER 0x44 and L1D\_CACHE\_REFILL\_OUTER 0x45, however, due to the inaccuracy of L1D\_CACHE\_REFILL\_OUTER 0x45 it is possible that this might not be the case.

Note: L1D\_CACHE\_REFILL PMU event 0x3 does accurately count all L1D cache refills, including refills from a system cache.

#### Configurations Affected

This erratum affects all configurations which implement a system cache.

#### Conditions

This erratum occurs under the following conditions:

1. The L2 inner cache is allocated with data transferred from a system cache.

#### Implications

When the previous condition is met the L1D\_CACHE\_REFILL\_OUTER PMU event 0x45 does not increment properly.

#### Workaround

The correct value of L1D\_CACHE\_REFILL\_OUTER PMU event 0x45 can be calculated by subtracting the value of L1D\_CACHE\_REFILL\_INNER PMU event 0x44 from L1D\_CACHE\_REFILL PMU event 0x3.

## 2283666

### Lower priority exception might be reported when abort condition is detected at both stages of translation

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, and r2p0. Fixed in r2p1.

#### Description

When a permission fault or unsupported atomic fault is detected in the second stage of translation during stage 1 translation table walk, and there is a higher priority alignment fault due to SCTLR\_EL1.C bit not being set, then Data Abort might be generated reflecting the lower priority fault.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs when all the following conditions apply:

1. The core executes an atomic, load/store exclusive, or load-acquire/store-release instruction.
2. SCTLR\_EL1.C bit is not set and access is not aligned to size of data element.
3. A permission fault or unsupported atomic fault is detected in the second stage of translation during stage 1 translation table walk.

#### Implications

If the previous conditions are met, a Data Abort exception will be generated and incorrectly routed to EL2 with Data Fault Status Code (DFSC) of permission fault or unsupported atomic fault, when it should have been routed to EL1 with DFSC of alignment fault.

#### Workaround

This erratum has no workaround.



## 2307829

### ESR\_ELx.ISV can be set incorrectly for an external abort on translation table walk

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

When a data double bit error or external abort is encountered during a translation table walk, synchronous exception is reported with ISV bit set in the ESR\_ELx register.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs under the following condition:

- Data double bit error or external abort is encountered during translation table walk and synchronous exception is reported.

#### Implications

If the previous conditions are met, ESR\_ELx.ISV bit will be set.

#### Workaround

This erratum has no workaround.

## 2317617

### ESR\_ELx contents for a Data Abort exception might be incorrect when a data double bit error or external abort is encountered

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, and r2p0. Fixed in r2p1.

#### Description

When a data double bit error or external abort is encountered on one half of an unaligned load, a Data Abort exception might be reported with an incorrect fault type of Synchronous Tag Check Fault in the ESR\_ELx register. This occurs under unusual micro-architectural conditions.

#### Configurations Affected

This erratum affects all configurations with the BROADCASTMTE pin asserted.

#### Conditions

This erratum occurs under all of the following conditions:

1. Memory tagging is enabled.
2. A precise checked access due to an unaligned load instruction encounters a data double bit error or external abort.

#### Implications

If the previous conditions are met, a Data Abort exception will be generated with an incorrect Data Fault Status Code (DFSC) of Synchronous Tag Check Fault in the ESR\_ELx register, when it should have been Synchronous External Abort.

If this scenario occurred at EL0/EL1/EL2, and the SCR\_EL3.EA bit is set, then the Data Abort will not get routed to EL3.

Likewise, if this scenario occurred at EL0/EL1, and the HCR\_EL2.TEA bit is set, then the Data Abort will not get routed to EL2. A RAS error will still be reported.

#### Workaround

This erratum has no workaround.

## 2334390

### L2 tag RAM double-bit ECC error might lead to the PE not responding to a forwarding snoop

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, and r2p0. Fixed in r2p1.

#### Description

A double-bit ECC error in a cache line containing Memory Tagging Extensions (MTE) tags might result in the L1 and L2 caches becoming out-of-sync with respect to MTE tag validity. This can lead to a situation in which the L1 evicts dirty MTE tags to the L2 as part of a fill/evict sequence or a snoop. If this eviction satisfies an external forwarding snoop, the RN-F might fail to provide legal responses which might lead to a deadlock.

#### Configurations Affected

This erratum affects all configurations using the Memory Tagging Extensions.

#### Conditions

When using MTE, under specific microarchitectural and timing conditions, an L2 double-bit ECC error in the L2 tag RAMs might allow the L1 data cache to later evict a cache line with dirty MTE tags.

The erratum occurs if the eviction satisfies an external snoop of one of these types:

- SnpUniqueFwd
- SnpCleanFwd
- SnpSharedFwd
- SnpNotSharedDirtyFwd
- SnpPreferUniqueFwd

#### Implications

If the previous conditions are met, the PE might provide an SnpRespDataFwded response to the HN-F, but fail to provide a CompData response to the original requester, leading to a system deadlock.

#### Workaround

This erratum has no workaround.

## 2344960

### CSSELR\_EL1.TnD is RAZ/WI when CSSELR\_EL1.InD == 0x1

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, and r2p0. Fixed in r2p1.

#### Description

In some contexts when CSSELR\_EL1.InD == 0x1, CSSELR\_EL1.TnD is defined to be RES0.

In other contexts when CSSELR\_EL1.InD == 0x0, CSSELR\_EL1.TnD is defined to be R/W.

When a bit is RES0 in some contexts and R/W in other contexts, then it cannot be implemented as RAZ/WI for RES0 contexts.

In affected products, CSSELR\_EL1.TnD is incorrectly treated as RAZ/WI instead of the correct R/W behavior when CSSELR\_EL1.InD == 0x1.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs under the following conditions:

1. The PE is executing with CSSELR\_EL1.InD == 0x1.
2. The PE attempts to read or write CSSELR\_EL1.TnD.

#### Implications

Reads of CSSELR\_EL1.TnD will return 0x0 and writes will be ignored.

#### Workaround

This erratum is not expected to require a workaround.

## 2382765

### Incorrect read value for Performance Monitors Configuration Register

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0. Fixed in r2p1.

#### Description

The external register Performance Monitors Configuration (PMCFGR) returns an incorrect read value for the following field in the register:

- CCD

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Debugger reads the PMCFGR register.

#### Implications

The register field PMCFGR.CCD incorrectly reads as 0b1, indicating that Cycle counter has prescale. The expected value is 0b0, since Aarch32 isn't supported.

#### Workaround

There is no workaround.

## 2391680

### Software-step not done after exit from Debug state with an illegal value in DSPSR

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0, and r2p1. Open

#### Description

On exit from Debug state, PSTATE.SS is set according to DSPSR.SS and DSPSR.M.

If DSPSR.M encodes an illegal value, then PSTATE.SS should be set according to the current Exception level. When the erratum occurs, the PE always writes PSTATE.SS to 0.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

- Software-step is enabled in current Exception level
- DSPSR.M encodes an illegal value, like:
  - M[4] set
  - M is a higher Exception level than current Exception level
  - M targets EL2 or EL1, when they are not available
- DSPSR.D is not set
- DSPSR.SS is set

#### Implications

If the previous conditions are met, then, on exit from Debug state the PE will directly take a Software-step Exception, without stepping an instruction as expected from DSPSR.SS=1.

#### Workaround

This erratum has no workaround.

**2444421**

## PMU STALL\_SLOT\_BACKEND and STALL\_SLOT\_FRONTEND events count incorrectly

### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0, and r2p1. Open.

### Description

The following Performance Monitoring Unit (PMU) events do not count correctly:

- 0x3D, STALL\_SLOT\_BACKEND, no operation sent for execution on a slot due to the backend
- 0x3E, STALL\_SLOT\_FRONTEND, no operation sent for execution on a slot due to the frontend

### Configurations Affected

This erratum affects all configurations.

### Conditions

One of the PMU event counters is configured to count any of the following events:

- 0x3D, STALL\_SLOT\_BACKEND
- 0x3E, STALL\_SLOT\_FRONTEND

### Implications

When operations are stalled in the processing element's dispatch pipeline slot, some of those slot stalls are counted as frontend stalls when they should have been counted as backend stalls, rendering PMU events 0x3D (STALL\_SLOT\_BACKEND) and 0x3E (STALL\_SLOT\_FRONTEND) inaccurate. The PMU event 0x3F (STALL\_SLOT) does still accurately reflect its intended count of "No operation sent for execution on a slot".

### Workaround

This erratum has no workaround.

## 2643627

### ERXPFGCDN\_EL1 register is incorrectly written on Warm reset

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0, and r2p1. Open.

#### Description

The ERXPFGCDN\_EL1 register is written a reset value of 0 at both cold and Warm reset, when it should only be reset at Cold reset.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs when a Warm reset occurs.

#### Implications

If the previous condition is met, the value of ERXPFGCDN\_EL1 will not be preserved across a Warm reset.

#### Workaround

This erratum has no workaround.



## 2647274

### Incorrect read value for Performance Monitors Control Register

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0 and r2p1. Open.

#### Description

The Performance Monitors Control Register (PMCR\_ELO) and the External Performance Monitor Control Register (PMCR) might return an incorrect read value for the X field.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

1. Software writes a nonzero value to the PMCR\_ELO.X, or debugger writes a nonzero value to the PMCR.X
2. Software reads the PMCR\_ELO register, or debugger reads the PMCR register

#### Implications

The PMCR\_EL1.X or PMCR.X field incorrectly reports the value 0x1, indicating exporting of events in an IMPLEMENTATION DEFINED PMU event export bus is enabled. The expected value is 0x0, as the implementation does not include a PMU event export bus.

#### Workaround

This erratum has no workaround.

## 2652240

### FAR\_ELx contents for a Data Abort exception on SVE first fault contiguous load instruction due to Tag Check fail might be incorrect

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0, r2p1. Open.

#### Description

A *Scalable Vector Extension* (SVE) first fault contiguous load instruction that encounters a Tag Check fail when accessing the first active element and a watchpoint match on one of the non-first active elements can generate a Data abort exception with incorrect value in FAR\_ELx.

#### Configurations Affected

All configurations are affected.

#### Conditions

This erratum occurs under all of the following conditions:

1. Memory tagging and watchpoints are enabled.
2. An SVE first fault contiguous load instruction accesses memory and generates a Data Abort exception due to Tag Check fail on the first active element.
3. There is a watchpoint match on one of the non-first active elements.

#### Implications

If the above conditions are met, a Data Abort exception will be generated with an incorrect value in FAR\_ELx. ESR\_ELx will indicate Synchronous Tag Check Fault.

#### Workaround

This erratum has no workaround.

## 2676362

### Execution of STG instructions in close proximity might cause loss of MTE allocation tag data

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r1p0, r2p0, r2p1. Open.

#### Description

Under certain rare micro-architectural conditions, two or more STG instructions that access the same cacheline but different 32-bytes might not write the *Memory Tagging Extension* (MTE) allocation tag to memory in the presence of an ECC error to the same cache index.

#### Configurations Affected

This erratum affects all configurations where the BROADCASTMTE pin is HIGH.

#### Conditions

This erratum occurs under the following conditions:

1. Memory tagging is enabled.
2. Two or more STG instructions are executed in close proximity to the same cache line.
3. The STG instructions access different 32-bytes locations.
4. An L2 fill for a different cacheline but to the same index has a single bit data error that could have otherwise caused a capacity evict of the cacheline accessed by the STG instructions.

#### Implications

If the above conditions are met, then under specific micro-architectural conditions, the MTE allocation tag might not be written to memory, resulting in a silent corruption of the MTE tag.

#### Workaround

If desired, this erratum can be avoided by setting CPUACTLR5\_EL1[13] to 1.

Note: setting CPUACTLR5\_EL1[13] to 1 is expected to result in a small performance degradation for workloads that use MTE (approximately 1.6% when using MTE imprecise mode, 0.9% for MTE precise mode).

## 2692441

### L3D PMU events may be inaccurate

#### Status

Fault Type: Programmer Category C

Fault Status: Found in r0p0, r1p0, r2p0, r2p1. Open.

#### Description

The following performance events might be unreliable due to this erratum:

- 0x0029 L3D\_CACHE\_ALLOCATE
- 0x002a L3D\_CACHE\_REFILL
- 0x002b L3D\_CACHE
- 0x00a0 L3D\_CACHE\_RD
- 0x400B L3D\_CACHE\_LMISS\_RD

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

No specific conditions are needed for this erratum to occur.

#### Implications

The following events might be over or under-counted:

- L3D\_CACHE\_ALLOCATE
- L3D\_CACHE\_REFILL
- L3D\_CACHE
- L3D\_CACHE\_RD
- L3D\_CACHE\_LMISS\_RD

#### Workaround

Use equivalent PMU counters in the L3 cache. Note that the L3 cache PMU counters will represent activity for all Processing Elements (PEs) in the DSU cluster.

## 2694769

### MTE checked load might read an old value of allocation tag by not complying with address dependency ordering

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r1p0, r2p0, r2p1. Open.

#### Description

Under some unusual micro-architectural conditions, checked load might read an old value of allocation tag by not complying with address dependency ordering.

#### Configurations Affected

All configurations are affected.

#### Conditions

The erratum occurs when all the following apply:

1. Initially, memory location M has allocation tag A.
2. Processing Element x (PE<sub>x</sub>) stores to M using allocation tag A.
3. PE<sub>y</sub> changes the allocation tag of M from A to B.
4. PE<sub>x</sub> makes a checked load from M using allocation tag A, with a dependency such that it should observe allocation tag B.

#### Implications

If the above conditions are met, PE<sub>x</sub> may not observe the new allocation tag for the memory location and may fail to report a tag check fail.

#### Workaround

This erratum has no workaround.

## 2712632

### Incorrect read value for Performance Monitors Configuration Register EX field

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0, r2p1. Open.

#### Description

The Performance Monitors Configuration Register (PMCFGR) might return an incorrect read value for the EX field.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

This erratum occurs when the software reads the PMCFGR register.

#### Implications

The PMCFGR.EX field incorrectly reports the value 0x1, indicating exporting of events in an IMPLEMENTATION DEFINED PMU event export bus is enabled. The expected value is 0x0, as the implementation does not include a PMU event export bus.

#### Workaround

This erratum has no workaround.

## 2769023

### STALL\_BACKEND\_MEM, Memory stall cycles AMU event count incorrectly

#### Status

Fault Type: Programmer Category C

Fault Status: Present in r0p0, r1p0, r2p0, and r2p1. Open.

#### Description

The following *Activity Monitor Unit* (AMU) event does not count correctly:

- 0x4005, STALL\_BACKEND\_MEM. The counter counts cycles in which the PE is unable to dispatch instructions from the frontend to the backend of the PE. It is due to a backend stall caused by a miss in the last level of cache within the PE clock domain. This event is counted by AMEVCNTR03.

#### Configurations Affected

This erratum affects all configurations.

#### Conditions

- AMU is enabled

#### Implications

The counter values for the event will not be correct and therefore cannot be used reliably.

#### Workaround

This erratum has no workaround.