



POWER ENGINEERING

#12 3-PHASE INDUCTION MOTORS (I)

2018



University
of Glasgow


3 Phase Induction Motors

Since its invention in the late 1800's the 3 phase Induction Motor has been the 'workhorse of industry' and even today accounts for approximately 45% of electricity consumption. Sizes range from hundreds of watts to several Megawatts with an equally diverse range of applications; driving industrial pumps and fans, railway traction and elevators drives to name but a few.

In today's lecture we will investigate:

- General introduction to Electric Motors
- Types of Motors
- The 3 Phase Induction Motor:
 - Basic Components
 - Stator Windings and rotating magnetic field

Electric Motor Drive:



Input Power (W)

Losses (W)

1] Device Losses

Losses (W)

1] Copper Loss



2] Iron Loss

3] Friction & Windage Loss

4] Others (Magnet, commutator)?

Output Power (W)

BASIC MAGNETIC FIELD



lifting lots of iron clips
via magnet force


Every magnet has two poles: a north and a south. **Two similar magnetic poles repel each other; while opposite magnetic poles attract each other.** Magnets have a continuous force around them that is known as a magnetic field. This field enables them to attract other metals.

Lines of force is often used to represent magnetic field, which travel from north pole to south pole. These **lines of force** are often called the **magnetic flux**. Here we will try to reveal how generators and motors **use these lines of force to generate electricity, as well as mechanical motion.**

Magnetic flux, Φ , in units of (Wb)

Magnetic flux density, \mathbf{B} , in units of (Wb/m² or T)

Magnetic field intensity, \mathbf{H} in units of (A/m)



**Magnetic flux lines
crossing a surface**

$$\Phi = B \cdot A$$

**Relative permeability for
common materials**

Material	μ_r
Air	1
Permalloy	100,000
Cast steel	1,000
Sheet steel	4,000
Iron	5,195

$$B = \mu H = \mu_r \mu_0 H$$

ELECTRICITY AND MAGNETISM

ELECTRIC CURRENT PRODUCES MAGNETIC FIELD




Figure 2






Figure 3



Ampere's Law


$$\oint H dl = \sum i \rightarrow B = \mu H = \mu_r \mu_0 H$$



Copyright © Addison Wesley Longman, Inc.

ELECTRICITY AND MAGNETISM:

CHANGING MAGNETIC FIELD PRODUCE ELECTRICITY





Faraday's Law

Electromotive force (emf):
a voltage

$$e = -N \frac{d\Phi}{dt}$$

ELECTRICITY & MAGNETISM

BI-DIRECTIONAL CONVERSION




Electro-magneto-Mechanical




ELECTRO-MECHANICAL

BI-DIRECTIONAL ENERGY CONVERSION




Motor action


Magnetic Field – medium for electromechanical conversion



Generator action



Fleming's Left Hand Rule
(Motors drive on the Left)



(The letter "g" is in "right" and "generator")

ELECTROMECHANICAL TORQUE GENERATION

In motor action, a **force F** will be produced whose direction is orthogonal to both the current and flux and whose magnitude is given by :



$$F = B l i$$

where **B** is magnetic flux density (Tesla or T, $1 \text{ T} = 1 \text{ Weber/m}^2$), **l** is the length of wire within the field, **i** is the current flowing in the wire

Current-carrying wire is shaped into a coil. The net effect of the two forces – one upward and one downward – is to exert a **turning moment** or **torque** of value

$$T = 2Fr$$


on the coil, where **r** is the distance between the centre line of the shaft and the conductor. Rotation direction can be reversed by changing the direction of the current.




GENERATE MECHANICAL MOTION

Interaction between two magnets


Note: The magnet can be a AC or DC current-flowing coil windings or a permanent magnet.




Rotating Induction



Linear (Induction) Moving



Synchronous Rotating
(stationary with respect to each other)




Linear (Synchronous) Moving


TYPES OF ELECTRIC MACHINE

Interaction between two magnets

- Opposite magnetic poles attract, and same magnetic poles repel each other.
- Magnets attract iron and seek to move to a position to minimize the reluctance to magnetic flux.
- Current-carrying conductors create an electromagnet and act like a current-controlled magnet.

ROTATING ELECTRIC MACHINES


Induction rotating  (AC) Induction motor/generator

Synchronous rotating  Synchronous motor/generator
DC motor/generator
Step motor/generator

LINEAR MOVING ELECTRIC MACHINES

Linear moving  Linear motor/generator

ROTATING ELECTRIC MACHINES



Rotor and **Stator** are **two magnets**, which generate magnetic flux using **coil windings** or **permanent magnet**. The rotor is mounted on a bearing-supported shaft, which can be connected to *mechanical loads (if machine is a motor)* or to a *prime mover (if machine is a generator)*.


To create a rotating electric motor, the key is **how to use electricity to produce a rotating magnetic field (i.e. a rotating stator magnet) to pull the rotor (magnet) to rotate about its center of mass.**

Torque:

$$T = K \bullet B_r \bullet B_s \bullet \sin \gamma$$

Motors: General #1


Torque (rotational force) and mechanical rotation is achieved by the interaction of a stator 'magnet' and a rotor 'magnet'.



The stator and rotor 'magnets' can be either permanent magnets or created by passing current through copper windings (electromagnets)

Typically the current in electromagnets must be switched on and off with respect to the rotor position. This is either achieved through a mechanical *Commutator* or a *Power Electronic Converter*

Motors: General #2




Stators and Rotors are constructed from stacks of insulated (oxidised layer) iron laminations which are typically $<0.5\text{mm}$ thick

Laminations are used to reduce the Eddy current iron loss (W) in the machine

The stator or rotor laminations may then have windings or permanent magnets added, dependant on the machine type....

Typical laminations:




Types of Electric Motors:

'Classical':

- Brushed DC Motor
- Universal Motor
- Induction Motor

Power Electronic Converter



Modern Brushless:



- Stepper Motor
- Switched Reluctance Motor
- Brushless DC Motor

Power Electronic Converter



Note: even although the 'Classical' motors do not require a Power Electronic Converter their performance can in fact be improved by the inclusion of a Converter

Brushed DC Motor




Applications:

- Automotive Ancillary's: windscreen wipers, window movers etc
- Wheelchair drives, golf buggies

Power Source	Stator	Rotor	Commutator	Rotor Position Sensor
DC	Magnets	Windings	Yes	No

Universal DC Motor:




Applications:


- Consumer electrics: washing machines, vacuum cleaners etc
- Power Tools: drills, screwdrivers, sanders etc
- Gardening tools: lawn movers, strimmers, hedge cutters etc

Power Source	Stator	Rotor	Commutator	Rotor Position Sensor
DC/AC	Windings	Windings	Yes	No


What is Commutation?



What is Commutation?




Coil Magnetic Flux
pattern if we pass current
through the winding



The coil magnetic poles are attracted to the opposite poles on the Stator and the result is that the Rotor rotates clockwise



What is Commutation?



BUT the rotor now locks in this position and therefore we get no further rotation


Solution

Have multiple coils on the rotor BUT only have current flowing in ONE coil at any particular time



The Mechanical Commutator (+ Brushes) selects which Coil to energise


So what's the big problem with having a Commutator?



The function of the Commutator is to connect a particular winding (one of many) on the rotor to an external power supply. Because the Commutator is rotating with the rotor we need carbon Brushes to electrically connect the stationary supply to the Commutator. These Brushes wear relatively quickly due to the rotation therefore reliability and maintenance are BIG issues with any machine which needs a Commutator.



Alternative: Electronic Commutation (Power Electronic Converter)

We essentially turn the Brushed DC motor 'inside out' and now have permanent magnets on the rotor and electro-magnets on the stator. The stator phase currents are now turned on and off with power electronic switches:




Note that we now need a Rotor Position Sensor to tell the controller which phase to energise at any particular time

Complete Power Electronic Converter: Brushless DC Drive



Stepper Motor:




Applications:

- Computer printers & scanners
- Positioning systems (CNC)
- Optics (mirror positioning)

Power Source	Stator	Rotor	Commutator	Rotor Position Sensor
Power Electronic Converter	Windings	Iron (Magnets)	No	No

Switched Reluctance Motor:




(Potential) Applications:

- Aircraft Surface Actuators
- Washing machines
- Automotive power steering

Power Source	Stator	Rotor	Commutator	Rotor Position Sensor
Power Electronic Converter	Windings	Iron	No	Yes

Brushless DC Motor:




Applications:

- Aircraft Surface Actuators
- Automotive power steering
- Hybrid Vehicle drive
- Compressors

Power Source	Stator	Rotor	Commutator	Rotor Position Sensor
Power Electronic Converter	Windings	Magnets	No	Yes

Induction Motor (No Commutator and No Electronic Converter Required!):



Applications:

- Industrial fans and pumps
- Railway traction
- Hoists and lifts

ie 24/7 applications!

Power Source	Stator	Rotor	Commutator	Rotor Position Sensor
AC	Windings	Aluminium Cage	No	No

Types of Induction Motors:

```
graph TD; A[Types of Induction Motors:] --> B[Single Phase]; A --> C[Three Phase]; B --> D[Single phase induction motors are common in small (100W+) domestic applications such as central heating pumps, fridge compressors]; C --> E[Squirrel Cage Rotor]; C --> F[Wound Rotor]; E --> G[This is the 'workhorse' of industry. Sizes range from 1's to 100's of kW.]; F --> H[These machines have copper windings on the rotor which are connected to external resistors or a Power Converter using brushes/sliprings. Typically BIG machines >200kW, also used in DFIG Generators];
```

Single Phase

Single phase induction motors are common in small (100W+) domestic applications such as central heating pumps, fridge compressors

Three Phase


Squirrel Cage Rotor

This is the 'workhorse' of industry. Sizes range from 1's to 100's of kW.

Wound Rotor

These machines have copper windings on the rotor which are connected to external resistors or a Power Converter using brushes/sliprings. Typically BIG machines >200kW, also used in DFIG Generators


ROTATING MAGNETIC FIELDS



The fundamental principle of operation of AC machines is the **generation of a rotating magnetic field**, which causes the rotor to turn at a speed that depends on the speed of rotation of the magnetic field.

A rotating magnetic field can be generated in the stator and air gap of an AC machine by means of AC currents as follows: coil windings **$a-a'$** , **$b-b'$** , and **$c-c'$** are geometrically spaced 120° apart, and a three-phase voltage is applied to the coils, three-phase currents also spaced by 120°. The **direction of rotation** can be reversed by interchanging any two phase connection.

2-POLES, 3-PHASE ROTATING FIELD



$$i_a(t) = I_m \cos(\omega t)$$

$$i_b(t) = I_m \cos(\omega t - 120^\circ)$$


$$i_c(t) = I_m \cos(\omega t - 240^\circ)$$

where $\omega = 2\pi f$

$$\Phi_n = \int v_n dt$$


$$n = a, b, c$$

0°




Rotating Airgap Flux


3 Phase Squirrel Cage Induction Motor




Stator




Rotor




Rotor




Rotor cage



Stator Windings: Mechanical Orientation of 3 Phase Windings




Centres of windings




Mechanical orientation of the
Three phase windings

Note: I will use Green instead of Yellow to denote Phase 2 as it is easier to see on the slides


Stator Windings: Star Connection to 3 Phase Power Supply




Stator Windings: 3 Phase Voltages & Voltage Space Vectors




Voltage Space Vectors:



vectors fixed in space but
magnitudes change wrt time
due to sine functions







0 Deg:

Ph1	$V_{pk} \sin 0$	0
Ph2	$V_{pk} \sin 240$	-0.86
Ph3	$V_{pk} \sin 120$	0.86


assume $V_{pk}=1$






30 Deg:


Ph1	$V_{pk} \sin 30$	0.5
Ph2	$V_{pk} \sin 270$	-1
Ph3	$V_{pk} \sin 150$	0.5






60 Deg:


Ph1	$V_{pk} \sin 60$	0.866
Ph2	$V_{pk} \sin 300$	-0.866
Ph3	$V_{pk} \sin 180$	0






90 Deg:

Ph1	$V_{pk} \sin 90$	1
Ph2	$V_{pk} \sin 330$	-0.5
Ph3	$V_{pk} \sin 210$	-0.5




**Note: 90° rotation In SPACE!
(same resultant magnitude)**

Resultant Voltage SPACE Vector



Resultant Airgap Flux




At a particular point in time



$$\Phi = \int v \cdot dt$$

Φ_{res}

Note: Sinusoidal Flux distribution
In the airgap



Resultant Magnetic Flux Rotation





--- flux path (simplified)

The Magnetic Flux rotates 1 mechanical revolution for 1 period of f_s – this is called the **SYNCHRONOUS SPEED**

Note: this is for a 2 pole machine – see next slide for higher pole number machines

Resultant Magnetic Flux Rotation



--- flux path (simplified)


The Magnetic Flux rotates 1 mechanical revolution for 1 period of f_s – this is called the **SYNCHRONOUS SPEED**

Note: this is for a 2 pole machine – see next slide for higher pole number machines

$$N_s = 60 f_s / (P / 2) \quad rpm$$

Relationship between Power Supply Frequency (f_s), Machine Pole Number (P) & Synchronous Speed (N_s)


2 Pole Machine (P = 2)



$$N_s \text{ (rpm)} = 60 \times f_s$$

$$N_s \text{ (rpm)} = \frac{120 \times f_s}{P}$$

4 Pole Machine (P = 4)




$$N_s \text{ (rpm)} = \frac{60}{2} \times f_s$$

$$N_s \text{ (rpm)} = \frac{120 \times f_s}{P}$$

Note: 6 pole machines are common as well

The story so far:



- The three phase voltages input to the three phase windings produces rotating stator flux in the motor airgap
- The stator flux rotates at **SYNCHRONOUS SPEED** (rpm) which is set by the supply frequency and the number of poles

In the next lecture we will investigate how currents induced in the rotor cage produce rotor flux which then interacts with the stator flux in the airgap. This results in **rotor torque and mechanical rotation**