

## Content:

### 11 Main Machine Error Codes



# Maintenance - Hydraulics & Electrics

## Main Machine Error Codes - Causes & Remedys

### DSP-Controls from DSP3

#### Alarm 2008

Check cooling circuit cooling unit

Cause: The temperature has risen above set value for a set time and is not dropping.

Reaction: Alarm on screen

Remedy: Check out the water too the glycol unit and general operation of this unit.

#### Alarm 2101

Suction filter clogged

Cause: The suction filter (oil cooling) is contaminated

Reaction: Stop of cycle after purging, alarm system On, motor Off

Remedy: Replace the filter in question. Can be cleaned but better replaced

#### Alarm 2102

Pressure filter contaminated

Cause: The pressure filter is contaminated

Reaction: Stop of cycle after purging, alarm system On, motor Off

Remedy: Replace the filter in question. Can not be cleaned

#### Alarm 2103

Hydraulic oil level low

Cause: The oil level below minimum level

Reaction: Stop of cycle after purging, alarm system On, motor Off

Remedy: Refill oil to required level. Always use a filter to filter the oil in

#### Alarm 2104

Disturbance in central lubrication

Cause: Can have additional number i.e 1 or 2

Reaction: Stop of cycle after purging, alarm system On, motor Off

Remedy: If number 1 central lubrication has not made pressure switch. Check for oil leaks or pipe split.

Check pressure switch.

If number 2 then pressure switch is made. Check pressure switch or blockage in pipes.

#### Alarm 2107

Pump motor of oil fine filter overloaded

Cause: Pump motor of fine filter unit mounted on injection unit is not working

Reaction: Stop of cycle after purging, alarm system On, motor Off

Remedy: Check that motor has not tripped out or contactor is made. Will only work when oil is up to temperature.

#### Alarm 2108

Connection interrupted between IMC and ????

Cause: The injection moulding computer has lost its connection with the other system

Reaction: Stop of cycle, alarm system On, motor Off

Remedy: The machine will have to be powered off and on again. Check voltages cables between the two systems and possibly the SPV print.

## Maintenance - Hydraulics & Electrics

### Alarm 2109

Empty the leak oil container

Cause: There is a level switch in the leg of the machine which has now made.

Reaction: just alarm on pre warning but has another switch that will stop machine

Remedy: Drain the leak oil from drain point under clamp.

### Alarm 2126

Handling device interlocks cycle

Cause: The robot is not correct for machine to operate

Reaction: unable to close mould

Remedy: Reference the takeout robot. Check cams on bed of machine

### Alarm 2144

Mould open position overran

Cause: The mould has opened more than 5mm of its open position S34

Reaction: Stop of cycle

Remedy: Check mould open /close for smooth operation. Set C239 = 2 and run in auto for approximate 10 cycles and see if mould open position gets better. Should be about 1mm overrun from S44 but to a maximum of 1.5mm overrun. Can be seen on S150

### Alarm 2154

Inadmissible status of input mould locked

Cause: The position of mould locked can not be correct

Reaction: unable to run machine in auto

Remedy: Check cams on bed of machine. Reset clamp force/ mould height S90. Take off clamp force by hand (wind back mould height). Lock over toggles in setup mode. Bring mould faces together by bringing forward mould height. Open mould, put into hand and set C238=1. Press to set clamp force automatically. C238 should automatically reset to zero if all ok.

### Alarm 2170

Dosing quantity too small

Cause : All configured screws are at the front stop (fixed mould platen) and the injection piston's metering end point has not been reached.

Reaction : Alarm system On

Remedy : Increase the metering stroke of the configured screws

### Alarm 2171

Slide not in position

Cause: The plug-in slide could not be moved to the desired position.

Reaction: Production stands still for as long as the slide is not in the desired position. During production the slide's reaching the end position is awaited, otherwise all movements and sequences are stopped.

Remedy: Check the activation of the plug-in slide (slides that direct the plastic from the screw to shooting pot)

### Alarm 2172

End of dosing not reached

Index: A Screw A B Screw B

Cause: The end of metering of the corresponding screw was not reached within 30s.

Reaction: Alarm system On

Remedy: Check material supply material temperature.

## Maintenance - Hydraulics & Electrics

### Alarm 2173

Overdosed, screw

Index A Screw A B Screw B

Cause: The maximum metering stroke (S832) of the corresponding screw was exceeded.

Reaction: Screw stop Alarm system On

Remedy: Check parameters S29 and S229

### Alarm 2174

Revolutions are limited for screw

Index: A Screw A B Screw B

Cause: If the screw speed on closed loop speed control is limited by N29, this alarm is output.

Reaction: Speed is limited as per N29.

Remedy: Reduce the metering reserve (T24) if possible

### Alarm 2175

Electric drive metering: not ready

Index: A Screw A B Screw B

Cause: The Inverter drive for the screw drive is not ready.

Reaction: The motor is stopped Starting of the drive is prevented Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: The drive should be checked. See what error codes are on drive

### Alarm 2176

Limit switch slide position purging defective

Cause: The plug-in slide is not in the purge position (manual purging).

Reaction: All movements are stopped

Remedy: Check the activation of the plug-in slide (slides that direct the plastic from the screw to shooting pot)

### Alarm 2177

Limit switch slide position injection defective

Cause: Limit switch position does not correspond to plug-in slide position.

Reaction: Blocked until position is correct Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: Check activation of plug-in slide and limit switch position (slides that direct the plastic from the screw to shooting pot)

### Alarm 2178

Limit switch slide position transfer defective

Cause: Limit switch position does not correspond to plug-in slide position.

Reaction: Blocked until position is correct Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: Check activation of plug-in slide and limit switch position (slides that direct the plastic from the screw to shooting pot)

### Alarm 2179

T-piece cannot be identified

Cause: The T-piece (type of plug-in slide) cannot be identified on the basis of the coding (Inadmissible bit combination).

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: Check the coding the barrel is coded so the machine knows what screw is fitted. This coding needs to be checked. Mounted in the heater plug going to barrel.

## Maintenance - Hydraulics & Electrics

### Alarm 2180

Pressure controller overdriven, screw

Index: A Screw A B Screw B

Cause: Controller overdrives on metering

Reaction: None

Remedy: Material temperature should be checked

### Alarm 2181

Speed controller overdriven, screw

Index: A Screw A B Screw B

Cause: Controller overdrives on transferring

Reaction: None

Remedy: Reduce transfer speed (V121 and V221, respectively) if appropriate Check transfer time T235 and compare with setting sheet. Can also be moog valve or velocity transducer?

### Alarm 2182

Barrel temperature not within band

Cause: Temperatures of plasticizing unit are not within band

Reaction: All movements are stopped Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

### Alarm 2183

Dosing electric drive: external aeration responded

Index: A Screw A B Screw B

Cause: External aeration of the screw motors failed

Reaction: None (prewarning)

Remedy: check cooling of drives Water cooling now.

### Alarm 2184

Electric drive metering: Warning

Index: A Screw A B Screw B

Cause: Temperature of screw motor too high

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system on

Remedy: Check drives alarms; reduce speed (revs.) if appropriate. Check material temperature

### Alarm 2185

Dosing electric drive: Current supervision rectifier responded (In other words: Current monitoring of the drive responded, screw)

Index: A Screw A B Screw B

Cause: See alarm text

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system on

Remedy: Make sure no mechanical problem prevails Reduce speed (revs.) if appropriate, check drive alarms

### Alarm 2186

T-piece code does not correspond to program (see C45)

Cause: Programming of the active screws does not correspond with the T-piece configuration Connector (type of plug-in slide).

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system on

Remedy: Correct the programming or the coding

## Maintenance - Hydraulics & Electrics

### Alarm 2187

Screw has been slid to mechanical stop

Index: A Screw A B Screw B

Cause: The screw in question was pushed to the front stop and the operating mode does not correspond to the setup mode.

Reaction: If all activated screws are at the front mechanical stop, the transfer is stopped.

Remedy: Check S29 and S229, respectively Check S24, transfer time, material

### Alarm 2189

None permitant closing movement of mould

Cause: The permanent position supervision checks the standstill and movement direction of the mould and prevents too far an over travelling of the mould open position. However, it is not effective in the Setup mode.

Reaction: machine stops.

Remedy: Check mould opening smoothness, set C239=2, slow mould opening up

### Alarm 2205

Excessive hydraulic pressure during injection

Cause: The pressure during the injection phase has exceeded the set value P101 / T201 P102/T202

Reaction: machine stops at end of cycle. Will also reduce hold pressure to zero during faulty cycle. If during purging, purging will stop

Remedy: Check that nozzle/mould is at temperature. There are no blockages in mould. Check filter in nozzle or material is degraded.

### Alarm 2218

Start interlock -----

Cause:

Reaction:

Remedy:

### Alarm 2233

Calibration of loop control processor for the screw is required

Cause: The calibration data for this machine filed in the PROM indicate that the stroke

Measuring systems for the screws and the injection piston are not calibrated.

Reaction: Screw movements are blocked

Remedy: Calibrate the screw stroke measuring systems

### Alarm 2235

Accumulator overload

Cause: The pressure has gone over the set value P242 (240 bar)

Reaction: Pump switched off but you are able to start again

Remedy: Check the system pressure. Gauge mounted back injection unit. Can be valve stuck on charging circuit, dirt in restrictors of charging circuit or faulty pressure transducer

## Maintenance - Hydraulics & Electrics

### Alarm 2236

Oil pressure measuring defective

Cause: Usually followed by an index, 0 = you already have had a oil pressure measuring fault

1 = internal hard ware error

2 = if the pressure does not change by P243 (0.5bar) and

T241 then we get this alarm.

3 = after first charge of the accumulator if the pressure then drops

below P246 then we get this alarm

4 = If the pressure goes above P823 during the time T815

Reaction: unable to switch on pump until fault cured. If you get index 0 then you need to power off/on of machine

Remedy: Check pressure transducer, pressure gauge to see if pressure is correct. Charging circuit and pump.

### Alarm 2239

DSC error mould .....

Cause: Usually has an index but this just indicates missing data from transducer for mould position

Reaction: Stop of cycle

Remedy: Check the magnet has not rubbed against the rod. This will take quite a bit of wear so if it has rubbed the rod adjust it so it now has a clearance around it and try again. Replace transducer. Replace ASC card or DSC card. Check dip switches and jumpers on card if fitting new one

### Alarm 2429

Mould waiting in vain for release condition

Cause: Mould would like to close but it has not been given the signal

Reaction: mould will not close

Remedy: Possibly robot or ejector stopping mould from closing

### Alarm 2465

Heating current monitoring of plastering unit ....

Cause: one of the heaters is not working

Reaction: stop machine at end of cycle heating switched off

Remedy: Check trips for heating, lower all set values and bring each one on in turn until you get alarm then you know which one is defective

### Alarm 2468

Limit switch for robot release not made B1014

Cause: The robot was triggered to go into mould and the switch on machine bed was not made

Reaction: Stop of cycle after purging, alarm system on,

Remedy: Check switch on bed of machine, mould open position, S103.

### Alarm 2490

Disturbance in mould control

Cause: Monitoring the mould open position usually has an index 1 = clamp moog valve limited has been exceeded.

passed S44

2 = the mould has opened further than 8mm

3 = The mould has creep forward (closing)

by more than 8mm

Reaction: alarm stop cycle

Remedy: Check mould movement by moving open/ close by 3% and mould should just close/open also at 100% and mould should not bang. Put C239 = 2. Check pressure transducers on clamp. Check mould movement Moog valve. Check clamp cylinder nuts.



## Maintenance - Hydraulics & Electrics

### Alarm 2493

Injection cancelled due to mould stop

Cause: The mould did not lock over and if pre-injection was selected C1=3 then if T12 times out we can get this alarm

Reaction: cycle stop

Remedy: Check locking, Check by switching off C1=0

### Alarm 2498

Monitoring of closing time during injection see T12

Cause: The machine is set up to inject before mould is locked by setting C1 = 3. The idea is to save reaction time and hence cycle time. The machine will start its injection phase at a position S1. When the mould gets to this position we monitor how long it takes before it is closed (locked) and display it with T22. We then set T12 just above it to monitor. If for some reason this time is exceeded we generate this alarm.

Reaction: cycle stops

Remedy: Check the times; check that mould movement is stable. Switch off C1 = 0

### Alarm 2605

Central mould height adjustment defective

Cause: The mould height is not working correctly

Reaction: stops machine

Remedy: check that die height will move back and forward manually. Also check this in slow speed. (by setting C32 =2) Check proximity switch on large gear wheel on die height. Check die height motor. Check its not tripped out.

### Alarm 2607

Clamp Force beyond limits

Cause: The clamp force F32 has to be between F34 and F35

Reaction: stops at end of cycle

Remedy: Check that C30 = 3 and clamp force is being read at F32. Check out clamp force system. Set C30 = 1 measuring only to keep machine running.

### Alarm 2608

Error in clamp force measuring

Cause: Usually has an index 0 = clamp force regulation error

1 = clamp force reads 0 or 10 volts

2 = offset error

3 = clamp force peak value

5 = time out in central mould height adjustment

Reaction: stop at end of cycle

Remedy: Check for damage on clamp force sensors. Calibration required. Set C30 = 0 and remove plug from clamp force measuring box (SKM)

### Alarm 4001

Connection interrupted between SYM and .....

Cause: The injection moulding computer has lost its connection with the other system

Reaction: Stop of cycle, alarm system On, motor Off

Remedy: The machine will have to be powered off and on again. Check voltages cables between the two systems and possibly the SPV print.

## Maintenance - Hydraulics & Electrics

### Alarm 4002

Interlock of safety cover is faulty:

Parameter: String of five characters, with 0 = pin is not in locking position

1 = pin is in locking position

*safety cover front, safety cover rear, safety cover robot left, safety cover robot right, safety cover nozzle*

Example: the string of characters „10111" means that the interlocking pin of the rear safety cover does not interlock.

Cause: The position of at least one interlocking pin does not correspond to its nominal position (interlocked: 1, unlocked 0)

Reaction: On interlocking:

Preparation of production is aborted

Mould movement is blocked

Mould movement is stopped

Remedy: Check the interlocks

### Alarm 4003

Supply voltage failed

Cause: Mains supply not correct

Reaction: Machine will stop and boot down

Remedy: Check mains supply coming into machine

### Alarm 4008

Disturbance in supply voltage ....

Cause: Usually has an index 1 = 24 volt fault

2 = monitoring of power supply

3 = safety relay K106

1xxx = e-stop or M24 fault before setting of hard-watchdog

2xxx = e-stop or M24 fault after setting of hard-watchdog

3xxx = e-stop or M24 fault after activation of e-stop

4xxx = e-stop or M24 fault after deactivation of e-stop

Reaction: Stop of cycle,

Remedy: The machine will have to be powered off and on again. Number 1 will probably be a short on a valve cable etc. Check voltages and possibly the SPV print for number 2. The others e-stop or other 24 volt problems. Need to check that e-stop breaks both channels.

### Alarm 4011

Safety switch in maintenance position

Cause: Its possible just to isolate the hydraulic pump or heaters if they are not on by switch the switch on the electrical panel Q1002. With this isolated then you get alarm on screen

Reaction: Turns off pump stops machine in cycle

Remedy: If nobody is working on machine you can switch it back on but always check that nothing has been removed as this is a maintenance isolation switch for maintenance work.

### Alarm 4035

Unlocking of safety cover is not possible reason .....

Cause: The safety cover before it will release the doors to open it has to have messages from the drive to say they are all off. If this is not the case you can get this alarm

Reaction: Stop of cycle

Remedy: release of drives is missing so check drives, standstill missing from drives(this is detecting no movement of motors)

## Maintenance - Hydraulics & Electrics

### Alarm 4036

Partial actuation of PNOZ switch

Cause: one or more switches on the safety covers did not make their switches correctly

Reaction: alarm

Remedy: Check by opening and closing the faulty cover. Check switches on faulty door

S1002-04 rear door

S1005-07 front door

### Alarm 4039

Accumulator charge is weak charging process is active

Cause: The machine has a battery back up so it switches down the control correctly under power failure.

This battery is checked from time to time and charged if too low.

Reaction: alarm

Remedy: should cure itself by charging the battery

### Alarm 4508

Watchdog failed

Cause: The machine has hard watchdog and soft watchdog. Hard watch dog monitors the voltages and if any fall out of tolerance the system will stop with an alarm. The same goes to the soft watchdog but this checks communication between computers

Reaction: machine will stop

Remedy: Check voltages

### Alarm 9000

Flow supervision of mould cooling responded

Cause: The control detected that the cooling water supply to the mould is not guaranteed.

Reaction: Heaters Off Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: Ensure that cooling water circulates. The flow sensor should have green LEDs all on.

### Alarm 9001

Monitoring of the mould open position has responded

Cause: Monitoring of the mould open position (which is additional to the basic SynErgy control) has responded. During production the corresponding limit switch must be activated for as long as the mould is open. If this is not the case, the above alarm is output on the screen.

Reaction: Product removal is not released Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: Adjust the limit switch, on the bed of machine, if necessary

### Alarm 9002

Dry air shroud existing

Cause: External disturbance message 3 is active

Reaction: 8-minute alarm, alarm system On

Remedy: check dry air

### Alarm 9003

Chillier; flow temperature is too high

Cause: External disturbance message 4 is active

Reaction: 8-minute alarm, alarm system On

Remedy: check chilled water

## Maintenance - Hydraulics & Electrics

### Alarm 9005

Disturbance in the robot control

Cause: Unexpected status of the robot depending on the machine's operating status:

During preparation for production the robot cannot be moved from the mould compartment or the robot cannot move to the reference position respectively. The robot is unable to move to the home position. Within 20s after a possible moving-in the removal gripper is still not ready or emptied, respectively. Signal "Ejector to advance" not received within 20s after "Robot to move in"

The robot has not been able to terminate production faultlessly within 100s.

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: Reference all robot positions.

### Alarm 9006

C.P.I.-disturbance

Cause: Disturbance message from the factory data capturing system

Reaction: Stop at the of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: -> Factory data capturing system

### Alarm 9008

Material slide is closed

Cause: The material slide is not open at "Start production"

Reaction: Production is not started, alarm system On

Remedy: Ensure that the material slide is open

### Alarm 9010 (reference)

Dry cycle is active

Cause: The machine is in the "Dry cycle" mode

Reaction: Monitoring. Machine <-> robot

### Alarm 9011

Change oil filter of electric circulation pump

Cause: The filter for extra oil filtration is blocked

Reaction: The filtration pump is switched off

Remedy: Exchange the corresponding filter

### Alarm 9012

Temperatures not within band

Cause: This alarm is output if, at the start of preparation for production, the temperatures of the plasticizing unit, the mould block or the mould nozzles are not within the band.

Reaction: Preparation for production is aborted, automatic operation is not possible.

Remedy: The alarm is cleared with the next preparation for production provided that the corresponding temperatures are in good order.

### Alarm 9013

Monitoring of the electric oil circulation pump has responded

Cause: Monitoring of the fine filtration pump has responded (bimetallic release or contactor, respectively).

Reaction: Pump is switched off, stop at end of cycle (when purged) 8-minute alarm, alarm system On

Remedy: Check pump has not tripped out and contactor is working.

### Alarm 9015

Robot in inadmissible position

Cause: Alarm if dry cycle without robot was selected without the robot being actively in the hand-over range (at top).

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: Check both limit switches which cover the hand-over range. (Servo drives must be switched on)

## Maintenance - Hydraulics & Electrics

### Alarm 9017

Exchange oil filter of circulation pump

Cause: The pressure filter of the circulation pump, running on the same shaft as the constant delivery pump, is blocked.

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: Replace the filter

### Alarm 9018

Collective alarm of heater auto. Fuses

Cause: Serial monitoring of all automatic fuses has responded.

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: check all fuses/ trips

### Alarm 9019

Error in injection unit movement

Cause : The injection unit has not reached the target position within 45s.

Reaction: None

Remedy: Check the activation of the injection unit

### Alarm 9020

Material booster disturbance

Cause: Booster is not ready at the start of preparation for production or booster reports disturbance during operation.

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: -> check material drier

### Alarm 9021

Material drier disturbance

Cause: Material drier reports disturbance

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system on

Remedy: -> Material drier

### Alarm 9022

Material booster temperature not in order

Cause: Booster temperature is not OK at the start of preparation for production or booster temperature is not OK during production.

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system on

Remedy: check temperature of booster

### Alarm 9023

Material drier temperature not in order

Cause: Temperature of the material drier is not in order.

Reaction: Alarm system on

Remedy: -> drier

### Alarm 9024

Temperature of plug-in slide not in order

Cause: Manual operation of the plug-in slide (slides that direct the plastic from the screw to shooting pot) is not permitted because the temperature required at the plug-in slide is not reached.

Reaction: The plug-in slide is not activated

Remedy Check temperature but also this is water cooled and this may need adjusting.

## Maintenance - Hydraulics & Electrics

### Alarm 9025

Emergency-off circuit defective

Cause: Message from "PNOZ" saying the emergency-off circuit is defective.

Reaction: Emergency-off (mushroom button) is deemed to be activated

Remedy: -> PNOZ, safety circuit

### Alarm 9026

Safety cover circuit mould side defective

Cause: Message from "PNOZ" saying the safety cover circuit is defective.

Reaction: Safety cover is deemed to be open

Remedy: -> PNOZ, safety circuit

### Alarm 9027

Safety cover circuit nozzle side defective

Cause: Message from "PNOZ" saying the nozzle cover circuit is defective.

Reaction: Nozzle cover is deemed to be open

Remedy: -> PNOZ, safety circuit checks nozzle cover.

### Alarm 9029

Monitoring of the cooling water pump has responded

Cause: See alarm text

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On Cooling water pump is switched off

Remedy: Individual; ensure proper water supply, check flow governor if necessary

### Alarm 9030

Check the oil filter of the circulating pump

Cause: Oil filter is heavily contaminated

Reaction: - alarm on screen

Remedy: Replace the filter of off line pump. (Not main pressure filter).

### Alarm 9031

Monitoring of the flow monitor of the cooling water pump has responded

Cause: No or insufficient water flow to cooling water pump

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On Cooling water pump is switched off

Remedy: Ensure proper water through flow Check sensor in main water line. Should have green Leeds lit

### Alarm 9033

Excessive transmission moment on the metering drive (status) (position)

Cause: Coupling balls for moment transmission on metering drive are disengaged B5065/B5066

Parameters: - Screw in question

- Operating condition

- Screw position at which the coupling balls disengaged

Reaction: Metering is stopped, purging sequence is stopped. Stop at end of cycle, cycle is blocked, 8-min. alarm, alarm system on

Elimination: The alarm can be acknowledged as soon as all coupling supervisions indicate that the coupling balls are engaged again. Check proximity switch and coupling. (Next to metering motor)

### Alarm 9059

Error in servo axis control ..... BTB

Cause: This can be for any axis where the current of the motor has got to maximum

Reaction: stops machine

Remedy: Check end stops of faulty axis, check if axis will home, check drive alarms. Will have to power machine off/on

## Maintenance - Hydraulics & Electrics

### Alarm 9111

Fault in system pneumatics

Cause: The air pressure for the pneumatic drives is inadequate

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system on

Remedy: Ensure adequate supply of compressed air Check the pressure switch

### Alarm 9112

Fault on external cooling air inlet (Better: Disturbance in external supply of cooling air)

Cause : The air pressure for air-blow cooling is inadequate

Reaction : Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: Ensure adequate supply of compressed air or switch off air-blow cooling by squeezing-off the air supply

### Alarm 9050

Removal basis is not in home position

Cause: In the home position movement (preparation for production) the robot basis (on which The robot is mounted) could not be moved to the home position. (Removal [unit] basis and robot basis is the same thing).

Reaction: The movement to the home position is aborted

Remedy: Move the removal basis to the production position

### Alarm 9051

Removal basis is not in production position

Cause: The robot basis is not in production position (The current operating mode corresponds to the manual mode)

Reaction: Vertical axis movement is blocked

Remedy: Move the removal basis to the production position

### Alarm 9052

Removal travel conditions are not met

Cause: Not all conditions for the robot movement are met. Conditions for robot travel (identical for moving in and out):

- The mould is open (incl. additional limit switch)
- Mould ejector is in rear position
- The robot basis is in production position
- The follow-up station does not block the removal axis, i.e. the transfer swivel unit is

either in hand-over position (horizontal) or it is in take-over position and the transfer return stroke is completed.

Reaction: The axis is blocked

Remedy: Check the above

### Alarm 9053

Error in removal reference travel

Cause: The removal axis could not terminate the reference movement correctly.

Reaction: The axis is blocked

Remedy: Check the reference limit switch, coupling and top mechanical stop

### Alarm 9054

Removal follow-up station cannot be moved to home position

Cause: The station (after cooling unit) following removal (vertical axis and gripper) could not be moved to the home position.

Reaction: Abortion of the movement to the home position

Remedy: See alarms on the screen displayed on the basis of an error in the follow-up station (if appropriate investigate the problem optically).

## Maintenance - Hydraulics & Electrics

### Alarm 9055

Removal unit gripper is not empty

Cause: There is at least one preform still left in the removal gripper, detected by one of the photoelectric cells which are also used to count the preforms.

Reaction: Removal axis moves from the take-over position to the hand-over position again (Without taking over the preforms), i.e. the preforms located on the cores can be ejected.

Remedy: Remove preforms from the removal gripper. Restart the cycle. Check and record which perform it is if repeated then check Calitec rubbers / alignment

### Alarm 9056

Time supervision of removal travel movement responded,

Cause: The movement of the removal gripper took too long.

Reaction: Automatic:

Removal gripper is stopped, the automatic cycle is interrupted

Home-position movement:

Home-position movement is regarded as unsuccessful

Remedy: Check the removal axis (servo drive, power supply, coupling, mech. blockage, etc.)

### Alarm 9057

Removal gripper is not in hand-over position

Cause: According to the resolver the robot is in the hand-over position, but the corresponding limit switch is not activated.

Reaction: Robot is deemed „not in hand-over position“

Remedy: For movement to mould change position, move the robot to the hand-over position, check limit switch or the programmed hand-over position (S9006). Check the limit switch setting which checks the hand-over position.

### Alarm 9058

Servo axis control of removal unit is not initialized

Cause: The servo drives (master and slave) are not yet initialized or could not be initialized.

Reaction: No travelling movements of the removal axis are possible

Remedy: Close the safety cover (incl. acknowledgment) Check the CAN connection between HCU and servo drives

### Alarm 9059

Error in servo axis control of removal unit

Cause: Servo drive (master or slave) reports error. This is displayed as extra information.

If no extra information is displayed with the alarm, the corresponding circuit breaker has fallen off. If the BTB contact has fallen off, the extra information „BTB“ on the alarm is output

Reaction: Depending on the error (from reference to interlocking of the removal axis)

Remedy: Individual according to error

### Alarm 9060

Removal gripper cannot be moved to the reference position

Cause: The reference movement of the removal axis could not be carried out successfully.

Reaction: No travelling movement is possible

Remedy: Check the wiring of the reference limit switch on the master servo drive of the removal axis. Check the top mechanical end stop of the removal axis

### Alarm 9061

Mould blocks removal unit gripper

Cause: Travel command to the removal unit gripper although the mould-open limit switch is not activated or the mould is not open according to the stroke measuring system.

Reaction: Travelling command is not executed

Remedy: Move the mould open Check the mould-open limit switch if appropriate



## Maintenance - Hydraulics & Electrics

### Alarm 9062

Ejector blocks removal unit gripper

Cause: The removal unit gripper is blocked because the ejector has not returned.

Reaction: Travelling command is not executed

Remedy: Return the ejector check switches on mould and check to see if ejector led is on the status page

### Alarm 9064

Supervision of removal vacuum pump has responded

Cause: See alarm text

Reaction: Pump is switched off

Remedy Check pump has not tripped out. Pump has to be switched on again to reset alarm

### Alarm 9065

Removal unit is not in home position

Cause: See alarm text

Reaction: The function is blocked

Remedy: Eliminate the malfunction which prevents the removal unit from being moved to the home position.

### Alarm 9066

Error on approaching removal unit home position

Cause: See alarm text

Reaction: Home position not OK

Remedy: Eliminate the malfunction which prevents the removal unit from being moved to the home position.

### Alarm 9067

Inadmissible mould movement

Cause: The mould has moved away from the limit switch "Mould open" although it was not released (but in fact blocked by the robot).

Reaction: Fatal error, robot blocked:

Remedy: While pressing the recovery key, press the Stop key. This means that the diagnosis data are compiled. After they are established (corresponding status message on the screen disappears) create the diagnosis floppies and send them to Netstal. Check switches on bed of machine and S103. Check mould open position is getting there correctly and smoothly

Switch the machine off and on again

### Alarm 9068

Inadmissible order to the removal unit control

Cause: See alarm text

Reaction: -

Remedy: -

### Alarm 9069

Inadmissible withdrawal of removal unit release

Cause: Release has been withdrawn from the removal unit (robot) in an inadmissible manner.

Reaction: The robot is blocked

Remedy: While pressing the recovery key, press the Stop key. This means that the diagnosis data are compiled. After they are established (corresponding status message on the screen disappears) create the diagnosis floppies and send them to Netstal

Switch the machine off and on again

### Alarm 9070

Follow-up station blocks removal gripper

Cause: The transfer swivel unit is in take-over position and the return transfer stroke has not been made.

Reaction: The removal gripper is blocked

Remedy: Carry out the return transfer stroke

## Maintenance - Hydraulics & Electrics

### Alarm 9071

Mould has not been emptied completely

Cause: While production was in progress, it was impossible to build up the vacuum at the removal gripper during the movement to the hand-over position. With activated preform counting: After moving out, there were not as many preforms in the removal gripper as specified in parameter C9001.

Index: Number of missing preforms. If the value 0 is shown here, it was impossible to build up a vacuum

Reaction: The mould does not close, production is stopped

Remedy: Possible causes

- At least one preform, perhaps more, could not be taken over
  - Untightness somewhere in the removal gripper's vacuum system
- Check air pressure, alignment, check with base setting sheet

### Alarm 9072

Error on handing over parts to follow-up station

Cause: The follow-up station did not take the preforms over from the removal gripper within 10s.

Reaction: Production is stopped

Remedy: Individual depending on the problem on hand

### Alarm 9080

Inadmissible order to the after-cooling station

Cause: See alarm text

Reaction: -

Remedy: -

### Alarm 9081

Lengthwise shifting of the cooling block is blocked

Cause: The following condition is not met: Transfer swivel unit is in hand-over position (horizontal position) and the return transfer stroke is completed

Reaction: The cooling block is blocked

Remedy: See cause

### Alarm 9082

Transfer stroke is blocked

Cause: The following conditions (on advancing) are not met:

- Transfer swivel unit is in take-over position (vertical position) and the removal axis is in hand-over position
- Transfer swivel unit is in hand-over position (horizontal position) and the cooling block is in take-over position
- transfer swivel unit is in hand-over position (horizontal position) and the cooling block is in hand-over position

Observed sources of errors:

- Limit switch B5053 (collision cooling block lengthwise) is actuated when it mustn't be

Reaction: Transfer stroke is blocked

Remedy: See cause

### Alarm 9083

Transfer swivel unit is blocked

Cause: The following condition is not met:

- Return transfer stroke is completed and cooling block is in hand-over position.

Reaction: The movement is blocked:

Remedy: See cause

## Maintenance - Hydraulics & Electrics

### Alarm 9084

Sidewise shifting of the cooling block is blocked

Cause: The following condition is not met:

- Return transfer stroke is not completed

Reaction: The movement is blocked

Remedy: See cause

### Alarm 9085

After-cooling station is not in home position

Cause: For the selected action the home position (preparation for production) must have been moved to at least once.

Remedy home

### Alarm 9086

Error on sidewise shifting of the cooling block

Cause: On sidewise shifting of the cooling block (position A, B, C or D) the end position was not reached.

Reaction: -

Remedy: Ensure that compressed air exists, Check the sensors which detect the end positions

Make sure there are no mechanical blockages Check the programmed travelling speed

### Alarm 9087

Time supervision of cooling block travel movement responded,

Cause: The cooling block's movement lasted too long.

Reaction: Automatic: - cooling block is stopped, automatic cycle is interrupted Home-position movement: - home-position movement is deemed to be unsuccessful

Remedy: Check the cooling block axis (servo drive, power supply, coupling, mech. blockage, etc.)

### Alarm 9088

Cooling block is not in handing-over position

Cause: According to the resolver the cooling block is in hand-over position, but the corresponding limit switch is not activated.

Reaction: The cooling block is deemed to be „not in hand-over position“

Remedy: Check the limit switch and the programmed hand-over position

### Alarm 9089

Servo axis control of cooling block is not initialized

Cause: The servo drive for the cooling block axis is not yet initialized or could not be initialized, respectively.

Reaction: A travelling movement of the cooling block axis is not possible

Remedy: Close the safety cover (incl. acknowledgment) Check the CAN connection between HCU and servo drives

### Alarm 9090

Error in servo axis control of the cooling block

Cause: Servo drive reports error, see extra information on alarm text (in the case of the extra information 8192 a following [drag] error is concerned [actual value is unable to follow the set value])

Reaction: Depending on the error (from reference to interlocking of the cooling block axis)

Remedy: Individual, depending on the error

### Alarm 9091

Cooling block cannot be moved to reference position

Cause: Reference movement of the cooling block axis could not be executed successfully.

Reaction: No travelling movements of the cooling block are possible

Remedy: Check the wiring of the reference limit switch onto the servo drive of the cooling block axis. Check the mech. end stop of the cooling block axis on the hand-over side

## Maintenance - Hydraulics & Electrics

### Alarm 9093

Cooling block is already charged, row

Cause: The stated row of the cooling block is already charged with preforms (vacuum existing).

On throwing-off of the preforms it was detected that at least one preform of the current row is still in the cooling block.

Reaction: The advance transfer stroke is blocked if it is in the hand-over position (horizontal position).

Remedy check sensor are positioned correctly, check vacuum, check that perform is not distorted and therefore sticking in cooling block. Can up pressures on Calitec

### Alarm 9094

Supervision of conveyor belt has responded

Cause: See alarm text

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: Check the activation of the conveyor belts (incl. monitoring of power uptake)

Make sure there is no mechanical blockage anywhere

### Alarm 9095

Supervision of vacuum/pressure pump of after-cooling station responded

Cause: See alarm text

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system On

Remedy: check the activation of the vacuum pump

### Alarm 9096

Supervision of vacuum pump of after-cooling station responded

Cause: See alarm text

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system on

Remedy: check the activation of the vacuum pump

### Alarm 9097

Transfer swivel unit is in undefined position

Cause: For the advance or return transfer stroke the transfer swivel unit must be in hand-over or take-over position. In the present case, however, it is in neither of these positions.

Reaction: The transfer stroke is blocked

Remedy: Move the transfer swivel unit to a defined position (hand-over or take-over position)

### Alarm 9098

Vacuum loss in vacuum supply of cooling block

Cause: See alarm text

Reaction: Stop at end of cycle, cycle is blocked, 8-minute alarm, alarm system on

Remedy: Ensure that no untightnesses exist anywhere

### Alarm 9099

Supervision of motor for lengthwise movement of cooling block responded

Cause: See alarm text

Reaction: The drive for the lengthwise movement is stopped

Remedy: Check the lengthwise movement for mechanical blockages

Check monitoring of power uptake

### Alarm 9109

Cooling block offset is faulty

Cause: Program of cooling block not correct

Reaction: can't go to auto

Remedy: Check settings, check cooling block positions and C9005 and C9007

## Maintenance - Hydraulics & Electrics

### Alarm 9113

Axis control for transfer stroke is not initialized

Cause: The servo drive for the transfer stroke is not yet initialized or could not be initialized, respectively.

Reaction: No travelling movements of the transfer stroke are possible.

Remedy: Check the CAN connection between HCU and servo drives

### Alarm 9114

Error in axis control for transfer stroke

Cause: Servo drive reports error; see extra information on alarm text

(in the case of the extra information 8192 a following [drag] error is concerned [actual value is unable to follow the set value])

Reaction: Depending on the error (from reference to interlocking of the transfer stroke)

Remedy: Individual depending on the error Check the power supply

### Alarm 9115

Transfer stroke cannot be referenced

Cause: The reference movement of the transfer stroke axis could not be executed successfully.

Reaction: No travelling movements of the transfer stroke are possible.

Remedy: Check the wiring of the reference limit switch to the servo drive of the transfer stroke.

Check the mechanical end stop

### Alarm 9116

Axis control for transfer pivoting is not initialized

Cause: The servo drive for transfer swivelling is not yet initialized or could not be initialized, respectively.

Reaction: No travelling movements of the transfer swivelling unit are possible

Remedy: Check the CAN connection between HCU and servo drives

### Alarm 9117

Error in axis control for transfer pivoting

Cause: Servo drive reports error, see extra information on alarm text (in the case of the extra information 8192 a following [drag] error is concerned [actual value is unable to follow the set value])

Reaction: Depending on the error (from reference to interlocking of the transfer swivel unit)

Remedy: Individual depending on the error Check the power supply reference, check end stops

### Alarm 9118

Transfer pivoting cannot be referenced

Cause: The reference movement of the transfer swivel axis could not be executed successfully.

Reaction: No travelling movements of the transfer swivelling unit are possible

Remedy: Check the wiring of the reference limit switch to the servo drive of the transfer swivel unit. Check the mechanical end stop

### Alarm 9119

Axis control for cooling block side movement is not initialized

Cause: The servo drive for the cooling block side movement axis is not yet initialized or could not be initialized, respectively.

Reaction: No travelling movement of the cooling block side movement is possible

Remedy: Check the CAN connection between HCU and servo drives

### Alarm 9120

Error in axis control for cooling block side movement

Cause: Servo drive reports error, see extra information on alarm text (in the case of the extra information 8192 a following [drag] error is concerned [actual value is unable to follow the set value])

Reaction: Depending on the error (from reference to interlocking of the side movement)

Remedy: Individual depending on the error Check the power supply reference, check end stops

## Maintenance - Hydraulics & Electrics

### Alarm 9121

Cooling block side movement cannot be referenced

Cause: The reference movement of the cooling block side movement axis could not be executed successfully.

Reaction: No travelling movements of the cooling block side movement are possible

Remedy: Check the wiring of the reference limit switch to the servo drive of the cooling block side movement.  
Check the mechanical end stop

### Alarm 9122

Cooling block could not be emptied

Cause: The cooling block could not completely throw off the preforms of the selected row.

In the fully automatic cycle the production is stopped after three unsuccessful attempts at throwing off.

Reactions: Production is stopped

Remedy: Individual Increase the blow-off air Check the installation of the photoelectric cells monitoring the throw-off

### Alarm 9124

Error in axis control for longitudinal movement

Cause: Servo drive reports error, see extra information on alarm text (in the case of the extra information 8192 a following [drag] error is concerned [actual value is unable to follow the set value])

Reaction: Depending on the error (from reference to interlocking of the side movement)

Remedy: Individual depending on the error Check the power supply reference, check end stops

### Alarm 9129

Error in axis control for stroke movement of cooling block

Cause: Servo drive reports error, see extra information on alarm text (in the case of the extra information 8192 a following [drag] error is concerned [actual value is unable to follow the set value])

Reaction: Depending on the error (from reference to interlocking of the side movement)

Remedy: Individual depending on the error Check the power supply, reference, check end stops

### Alarm 0003 BB1

Control panel communication problems error Kbox

Cause: Lost CAN communication so Kbox (main panel where you press keys) has lost even if it is for a short time CAN communication

Reaction: machine stops

Remedy: Possibly EMC errors, check earthing cable glands to motors

### Alarm 0011 BB1

Disturbance in card slot 17 error AD 528

Cause: An error occurred in card slot 17 in electrical panel (this case AIO) with an analogy to digital conversion. 528 is a decimal number and must be converted to Hexadecimal to trace error. Not important to trace actual input by this number due to it being quite complicated to find.

Reaction: Stops machine

Remedy: Check all analogy signals going into this card. This case it's a vacuum switch

## **Maintenance - Hydraulics & Electrics**

NOTES

