

# Poly Press Programming & Operations Manual

Version 1.2 | June 20, 2025

## Table of Contents

---

1. [System Architecture](#)
2. [Axis Configuration](#)
3. [I/O Mapping & Wiring](#)
4. [Core Programs](#)
5. [HMI Interface Design](#)
6. [Alarm Handling](#)
7. [Safety Validation](#)
8. [Maintenance Procedures](#)
9. [Motion Tuning](#)
10. [Simulation & Debugging](#)
11. [Appendix](#)

## 1. System Architecture

---

**Controller:** Trio Motion Controller (e.g., MC405)

**Programming Language:** Structured Text (ST) + Trio BASIC (legacy)

**HMI:** UNIPLAY 10" Touchscreen (Ethernet/IP)

**Safety System:** Schmersal SRB 206SQ Safety Relay

**I/O Modules:**

- IN16P (16 Digital Inputs)
- OUT16P (16 Digital Outputs)

- THC4 (4 Thermocouple Inputs)

### Network Topology:

- EtherCAT for real-time motion control
- Ethernet/IP for HMI communication
- Modbus TCP for external SCADA integration

## 2. Axis Configuration

---

### Z-Axis (Press Head)

```
AXIS(0);

CONFIG(0, 1, 1000, 5, 0); // Servo, 1000 pulses/mm, 5:1 gear ratio

Z_MAX_SPEED := 200.0;      // mm/s

Z_MAX_ACCEL := 500.0;      // mm/s2
```

### X-Axis (Feeder)

```
AXIS(1);

CONFIG(1, 1, 500, 2, 0); // Servo, 500 pulses/mm, 2:1 gear ratio

X_MAX_SPEED := 300.0;

X_MAX_ACCEL := 600.0;
```

### Axis Safety Limits:

```
SOFT_LIMIT(Axis_Z, 0.0, 150.0); // Prevent overtravel

SOFT_LIMIT(Axis_X, -10.0, 200.0);
```

```
HARD_LIMIT_ENABLE(ALL, TRUE);    // Enable hardware limit switches
```

### 3. I/O Mapping & Wiring

Signal	Type	Address	Device	Wiring
----- ----- ----- ----- -----				
Emergency Stop	DI	%I0.0	Schmersal E-stop	NC contact → IN0, COM → 0V
Door Interlock	DI	%I0.1	Schneider XCK-J115	NO contact → IN1, COM → 0V
Safety Curtain 1	DI	%I0.2	Leuze MLC OSSD1	PNP Out → IN2
Z Home Sensor	DI	%I0.6	Inductive Prox	Brown → 24V, Black → IN6, Blue → 0V
Heater Zone 1	DO	%Q0.0	Eaton DILMP20 Contactor	OUT0 → A1, A2 → 0V
Press Down Solenoid	DO	%Q0.4	MAC Valve	OUT4 → Solenoid (+)
Temp Zone 1	AI	%AI0.0	Type K Thermocouple	Yellow → THC0, Red → COM

Wiring Standards:

- 24VDC Power: Red (+), Black (-)
- Shielded cables for analog signals (thermocouples)
- Safety circuits wired with dual-channel redundancy

### 4. Core Programs

#### 4.1 Homing Routine ( homing.st )

```
PROGRAM Homing

VAR

homeZIn AT %I0.6 : BOOL;    // Z Home sensor
```

```
homeXIn AT %I0.7 : BOOL;    // X Home sensor

Z_HomeDir : INT := -1;      // Negative direction

Z_HomeSpeed : REAL := 10.0;

BEGIN

IF NOT SAFETY_OK THEN

PRINT("SAFETY FAULT: Homing aborted!");

RETURN;

END_IF;

// Home Z-axis

HOME(Axis_Z, Z_HomeDir, Z_HomeSpeed, 100.0); // 100 mm/s2 accel

REPEAT

WAIT(0.01);

UNTIL homeZIn;

MOVE(Axis_Z, 5.0, 20.0, 100.0); // Retreat 5mm at 20mm/s

SETPOS(Axis_Z, 0.0);

// Repeat for X-axis...

END_PROGRAM
```

## 4.2 Safety Monitoring ( safety.st )

```
PROGRAM Safety

VAR_GLOBAL

SAFETY_OK: BOOL;

END_VAR
```

VAR

E\_Stop\_In AT %I0.0: BOOL;

Door\_Sw\_In AT %I0.1: BOOL;

Curtain1\_OSSD AT %I0.2: BOOL;

SafetyRelay\_OK AT %I0.4: BOOL;

BEGIN

WHILE TRUE DO

SAFETY\_OK := E\_Stop\_In AND Door\_Sw\_In AND Curtain1\_OSSD AND SafetyRelay\_OK;

IF NOT SAFETY\_OK THEN

DISABLE; // Halt all motion

OUT[0..15] := FALSE; // Kill all outputs

END\_IF;

WAIT(0.1); // 100ms cycle

END\_WHILE;

END\_PROGRAM

## 4.3 Press Cycle ( press\_cycle.st )

PROGRAM Press\_Cycle

VAR

feederExtendPos: REAL := 150.0; // mm

pressDownPos: REAL := 40.0;

dwelTime: TIME := T#5S;

BEGIN

IF NOT SAFETY\_OK THEN RETURN; END\_IF;

```
// Feed material

MOVE(Axis_X, feederExtendPos, 100.0, 200.0); // 100mm/s, 200mm/s²

WAIT UNTIL INPOS(Axis_X);

// Press down

MOVE(Axis_Z, pressDownPos, 50.0, 100.0);

WAIT UNTIL INPOS(Axis_Z);

// Dwell

WAIT(dwellTime);

// Retract

MOVE(Axis_Z, 0.0, 100.0, 200.0);

END_PROGRAM
```

## 5. HMI Interface Design

---

### Dashboard Layout:



HMI Dashboard

### Key Elements:

#### 1. Safety Status LED:

- Green: SAFETY\_OK = TRUE
- Red: Any fault

#### 2. Temperature Control Panel:

- Setpoint entry fields for 4 zones
- Real-time trend graphs

#### 3. Cycle Counter:

- Total cycles / Today's count
- Reset with password

Recipe Management:

```
{  
  
  "recipe_name": "3mm Polycarbonate",  
  
  "parameters": {  
  
    "heater_setpoints": [160, 160, 155, 155], // °C  
  
    "feed_position": 150.0, // mm  
  
    "press_dwell_time": 5.0 // seconds  
  
  }  
  
}
```

# 6. Alarm Handling

Code	Description	Severity	Response
-----	-----	-----	-----
AL101	E-Stop Activated	Critical	Full shutdown
AL202	Heater Over-Temp	High	De-energize zone
AL303	Homing Timeout	Medium	Check sensors
AL404	Safety Relay Fault	Critical	Inspect SRB wiring

Alarm Reset Protocol:

1. Clear physical fault condition
2. Press HMI "Reset" button
3. Confirm SAFETY\_OK = TRUE

## 7. Safety Validation

---

### Test Cases:

#### 1. E-Stop During Press:

- Trigger E-stop at 50% stroke
- Verify press stops within 100ms
- Confirm OUT4 (solenoid) = FALSE

#### 2. Door Open at 150°C:

- Open door during heating
- Check heaters de-energize within 500ms

#### 3. Thermocouple Failure:

- Disconnect THC0
- Verify AL202 logged and zone disabled

## 8. Maintenance Procedures

---

### Monthly Tasks:

#### 1. Thermocouple Calibration:

- Apply known temperatures (0°C, 100°C, 200°C)
- Adjust scaling in THC4 config if error >  $\pm 2^\circ\text{C}$

#### 2. Contactor Inspection:

- Measure coil resistance (Eaton DILMP20:  $180\Omega \pm 10\%$ )
- Check for contact pitting

### Annual Tasks:

- Full axis re-calibration



- Safety relay functional test

## 9. Motion Tuning

---

### Z-Axis PID Settings:

```
GAIN(100, // KP  
20, // KI  
0, // KD  
0.1); // Feedforward  
JERK_LIMIT(5000.0); // mm/s3
```

### Vibration Reduction:

- Increase trajectory filter from 5ms → 10ms
- Reduce KI by 30% if overshoot occurs

## 10. Simulation & Debugging

---

### Motion Perfect Tools:

#### 1. Axis Simulator:

- Test homing without hardware

#### 2. Watch Window:

- Monitor SAFETY\_OK, POS\_Z in real-time

#### 3. Breakpoints:

- Pause program at specific lines

### Diagnostic Codes:

- Controller LED:
- Green: Normal
- Red blink (2/sec): I/O fault
- Red blink (4/sec): Motion error


# 11. Appendix

---

## A. Wiring Diagrams

 Power Distribution

*Main power and branch circuits*

 Control Circuits

*Safety relay and PLC I/O*

## B. Revision History

Version	Date	Changes
-----	-----	-----
1.0	2024-12-01	Initial release
1.1	2025-03-15	Updated safety logic
1.2	2025-06-20	Added thermocouple cal steps

## C. Contact Information

### Technical Support:

- Email: [support@triomotion.com](mailto:support@triomotion.com)
- Phone: +1 (800) 555-CODE (2633)

### Document Control:

- This manual must be reviewed annually.

### How to Convert to PDF:

1. **\*\*Install Pandoc\*\***:

- Download from [[pandoc.org](https://pandoc.org/installing.html)](https://pandoc.org/installing.html)

2. **\*\*Save the markdown\*\*** above as `poly\_press\_manual.md`

3. **\*\*Run conversion command\*\***:

```
```bash
```

```
pandoc poly_press_manual.md -o PolyPress_Manual.pdf --pdf-engine=xelatex -V geometry:margin=1in
```