




distance from NA



$$\epsilon_1 = \ln \frac{D_1}{D_0} = +ve$$

$$\epsilon_2 = \ln \frac{D_2}{D_0} = +ve$$



$$\epsilon_1 = \ln \frac{D_1}{D_0} = +ve$$

$$\epsilon_2 = \ln \frac{D_2}{D_0} = -ve$$

Von-Mises stress:

$$(\sigma_{11} - \sigma_{22})^2 + (\sigma_{22} - \sigma_{33})^2 + (\sigma_{33} - \sigma_{11})^2 + 6\sigma_{12}^2 + 6\sigma_{23}^2 + 6\sigma_{31}^2 = 2\gamma^2$$


For principal planes:

$$(\sigma_1 - \sigma_2)^2 + (\sigma_2 - \sigma_3)^2 + (\sigma_3 - \sigma_1)^2 = 2\gamma^2$$

Hill

$$F(\sigma_{22} - \sigma_{33})^2 + G(\sigma_{33} - \sigma_{11})^2 + H(\sigma_{11} - \sigma_{22})^2 + 2L\sigma_{23}^2 + 2M\sigma_{31}^2 + 2N\sigma_{12}^2 = 1$$

Forming limit diagram represents the limiting strength (in the form of major & minor ~~str~~ surface strength) which a sheet metal can be deformed under diff. plane stress conditions.



$$\epsilon_1 + \epsilon_2 + \epsilon_3 = 0$$


$$\epsilon_2 + \epsilon_3 = -\epsilon_1 \Rightarrow 2\epsilon_2 = -\epsilon_1$$

$$\Rightarrow \epsilon_1 + 2\epsilon_2 = 0$$

Mid-sem: Material Properties, Pattern & Core Design, Solidification, Riser design

- * Strainer gate must be used only for small castings and never for larger castings because impurities would start obstructing the flow of liquid.
- * If sprue is not designed very well, then air gets sucked into the mould cavity which is called Aspiration Effect.

If sprue is of vertical cylindrical design



$$\therefore h_1 + \cancel{\frac{v_1^2}{2g}} + \cancel{\frac{P_1}{\rho g}} = \cancel{h_3} + \frac{v_3^2}{2g} + \cancel{\frac{P_3}{\rho g}}$$

Let's assume 1 & 3 are kept at atm. pressure.

$$\Rightarrow v_3 = \sqrt{2gh_1} = \sqrt{2gh_t}$$

[$A_2 = A_3$ for vertical sprue

$$\Rightarrow v_2 = v_3]$$

$$\therefore h_2 + \cancel{\frac{v_2^2}{2g}} + \frac{P_2}{\rho g} = \cancel{h_3} + \cancel{\frac{v_3^2}{2g}} + \frac{P_3}{\rho g}$$

$$\Rightarrow P_3 - P_2 = \rho g h_2 = \rho g (h_t - h_c)$$

To keep 2 & 3 at atm. conditions, $v_2 = \sqrt{2gh_c}$
 $v_3 = \sqrt{2gh_t}$

$$R = \frac{A_3}{A_2} = \sqrt{\frac{h_c}{h_t}}$$

: equation of parabola

↓
difficult to
produce


(hence, the actual
& ideal shown in fig.)

$$\frac{1}{\sqrt{2g}} \int_0^{h_m} \frac{dh}{\sqrt{h_t - h}} = \frac{A_g}{A_m} \int_0^{t_f} dt$$

$$\Rightarrow \frac{1}{\sqrt{2g}} \left[-2\sqrt{h_t - h} \right]_0^{h_m} = \frac{A_g}{A_m} [t]_0^{t_f}$$

$$\Rightarrow \frac{-2}{\sqrt{2g}} \left[\sqrt{h_t - h_m} - \sqrt{h_t} \right] = \frac{A_g}{A_m} t_f$$

$$\Rightarrow t_f = \frac{A_m}{A_g} \cdot \frac{1}{\sqrt{2g}} \cdot 2 (\sqrt{h_t} - \sqrt{h_t - h_m})$$



A composition profile is developed ahead of solid-liquid interface

$$c_L(x) = c_s^* \left[1 + \frac{1-k_0}{k_0} e^{-\frac{Rx}{D}} \right]$$

Due to these composition change depending upon the phase diagram^{fig.(b)}, the freezing temp. profile is shown in fig.(c)

Reasons for formation of Dendrites :

1. Constitution under cooling, ahead of solid-liquid interface which will create instability of the solid-liquid interface and any perturbation can be stable.
2. There is a preferential direction of growth (it will be in the dirⁿ of higher temp. gradient). There exists also a preferred dirⁿ of growth in crystal structure as well. $[100]$ for BCC.
3. Also the latent heat of solidification is liberated at solid-liquid interface. Hence, the growth is not planar and hence, a tree-like structure or arms stretch.

$$G < \left. \frac{\partial T_L(x)}{\partial x} \right|_{x=0}$$

$$T_L(C) = T_m - mC$$

→ Melting temp. of pure metal

$$T_i = T_m - m \frac{C_s}{k_0}$$

$$T_m = T_i + m \frac{C_s}{k_0}$$

$$T_L = T_i + m \frac{C_s}{k_0} - m C_s \left[1 + \frac{1-k_0}{k_0} e^{-\frac{Rx}{D}} \right]$$

$$T_L(x) = T_i + m C_s^* \left(\frac{1-k_0}{k_0} \right) \left[1 - e^{-\frac{Rx}{D}} \right]$$

$$G < \left. \frac{\partial T_L(x)}{\partial x} \right|_{x=0} = \frac{R m C_s^*}{D} \left(\frac{1-k_0}{k_0} \right) e^{-\frac{Rx}{D}} \bigg|_{x=0} = \frac{m C_s^* R}{D} \left(\frac{1-k_0}{k_0} \right)$$

$$\therefore \boxed{\frac{G}{R} < \frac{m C_s^*}{D} \left(\frac{1-k_0}{k_0} \right)} \quad \text{Condition for Constitutional under cooling}$$

To avoid constitutional undercooling

$$\frac{G}{R} < \frac{m C_s^*}{D} \left(\frac{1 - k_0}{k_0} \right)$$




- Higher Temp. Gradient (G)
- Low Growth Rate
- Lower slope of the liquidus line
- Low alloying content

- Higher Diffusability
- Higher partitioning coeff. (k_0) i.e. close to 1 or
- Lower freezing range

Reasons for Hot Tears:

1. Development of stresses due to constraints encountered in cooling.
2. Higher freezing range

Deep Drawing Analysis



- To evaluate the force required for deep drawing
- Assumptions:
 - increase in flow strength (yield strength at each pt.) during deformation is negligible. (rigid + perfectly plastic)
 - material is homogeneous and isotropic.
 - change in thickness is neglected (plane strain only)
 - von-Mises criteria: $(\sigma_1 - \sigma_2)^2 + (\sigma_2 - \sigma_3)^2 + (\sigma_3 - \sigma_1)^2 = 2\gamma^2$ — (1)
 - Levy-Mises criteria: $\frac{d\epsilon_{ij}^p}{\sigma_{ij}'} = d\lambda$ $\frac{d\epsilon_1}{\sigma_1'} = \frac{d\epsilon_2}{\sigma_2'} = \frac{d\epsilon_3}{\sigma_3'} = d\lambda \Rightarrow d\lambda \cdot \sigma_3' = 0$ [for plane strain]

$$d\lambda \left(\sigma_3 - \frac{\sigma_1 + \sigma_2 + \sigma_3}{3} \right) = 0$$

$$\Rightarrow \frac{2}{3} d\lambda \left(\sigma_3 - \frac{\sigma_1 + \sigma_2}{2} \right) = 0 \Rightarrow \sigma_3 = \frac{\sigma_1 + \sigma_2}{2} \quad \text{--- (2)}$$

$$\text{Put (2) in (1), } \frac{3}{2} (\sigma_1 - \sigma_2)^2 = 2\gamma^2 \Rightarrow \boxed{\sigma_1 - \sigma_2 = \frac{2}{\sqrt{3}} \gamma}$$

- Blank holder force is only acting at the rim.
- Friction b/w the die wall and cup is not considered.

Slab Analysis

$$(\sigma_r + d\sigma_r)(r + dr) \frac{d\phi}{2} t - \sigma_r \cdot r \frac{d\phi}{2} t - \cancel{2\sigma_\theta \cdot dr \cdot t \cdot \sin \frac{d\phi}{2}} = 0$$

$$\Rightarrow (\sigma_r + d\sigma_r)(r + dr) - \sigma_r \cdot r - \sigma_\theta dr = 0 \Leftrightarrow \cancel{\sigma_r \cdot r} + \sigma_r dr + d\sigma_r \cdot r + d\sigma_r \cdot dr - \cancel{\sigma_r \cdot r} - \sigma_\theta \cdot dr = 0$$

$$\Rightarrow d\sigma_r \cdot r + (\sigma_r - \sigma_\theta) dr = 0 \quad (\text{Von-Mises } \sigma_r - \sigma_\theta = \sigma_\theta')$$

at $r = r_0$,

$$\sigma_r = \frac{2\mu F_h}{2\pi r_0 t} = \frac{\mu F_h}{\pi r_0 t}$$

$$\Rightarrow d\sigma_r \cdot r + \sigma_\theta' dr = 0$$

$$\Rightarrow \frac{d\sigma_r}{\sigma_\theta'} = -\frac{dr}{r} \Rightarrow \boxed{\frac{\sigma_r}{\sigma_\theta'} = -\ln r + C}$$

$$\frac{\mu F_h}{\sigma_\theta' \times \pi r_0 t} = -\ln r_0 + C \Rightarrow C = \frac{1}{\sigma_\theta'} \cdot \frac{\mu F_h}{\pi r_0 t} + \ln r_0$$

$$\boxed{\sigma_r = \sigma_\theta' \ln \frac{r_0}{r} + \frac{\mu F_h}{\pi r_0 t}}$$

- The stress required to draw the material at die wall

$$\boxed{\sigma_w = \sigma_r e^{\mu\pi/2}}$$

The force required to draw the material:

$$\boxed{F = \sigma_w \times 2\pi r_p t}$$