



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/05/2025

Shift: B

Incharge(s): Arnab Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on CO 5A	LT problem reported. Also Luffing Rec height indication lamp problem	LT okay . Indiacion lamp problem	19:45:00	20:00:00	
2	OHP	WOBR on CO 26	No drive running	Breaker in OFF condition , Made ON	20:10:00	20:20:00	
3	OHP	CO 14	BRS to be bypassed due to belt hole	Bypassed at CJB	19:00:00	19:10:00	
4	OHP	TBS on CO 22	Right BC overload acted	Reset done	21:30:00	21:45:00	
5	OHP	BRC on CO 28	CT speed to be increased by 20% as per operation requirement	CT speed increased from 15 Hz to 18 Hz	21:00:00	21:15:00	
6	CHP	CC 32 , SCR 5	LT problem	PCRD in zig zag condition. Checked, guide problem , informed to Mechanical. Again slewing problem, limit acted due to jamming . Informed to operation	17:30:00 20:30:00	17:40:00 20:40:00	
7	CHP	CC 32 , SCR 5	BC not running	Overload tripped	19:30:00	19:40:00	
8	CHP	CC 35 , SCR 2	LT not working	PCRD overtension released	18:40:00	18:50:00	
9	CHP	CC 58 TT	CJD acted without jamming	Control cable damaged , rejoined	20:45:00	21:15:00	
10	CHP	CC 58	Motor tripped on CURT SP alarm	reset done	21:15:00	21:25:00	
11	CHP	CC 54	Motor tripped on overload	reset done (3 times)	19:30:00	20:00:00	
12	CHP	CC 131	Motor tripped on Overload	Reset done	19:30:00 21:55:00	19:35:00 22:00:00	



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/05/2025

Incharge(s): Arnab Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
13	WT	CP 4	Communication problem	Reset done	20:15:00 20:30:00	20:20:00 20:35:00	