



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 02/05/2025

Shift: A

Incharge(s): V Balaji Naik,G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	tbs on co 20	It &right; luffing not taking place/	reclaiming height limit tied and luffing brake stuck ,released by hammer ing done	07:10:00	07:30:00	
2	OHP	brc on co31	bw 2 not running/olr acted	reset done	07:15:00	07:25:00	
3	OHP	BRC ON CO 33M	BW S ARE NOT running found stone struck	Slenoid valve pressed and revered the BW stone removed then ok	11:35:00	11:50:00	
4	OHP	BRC on CO31	BW 2 not working found olr acted	reset done	12:15:00	12:30:00	
5	OHP	BRC on CO31	BC not running olr acted	Reset done	12:15:00	12:30:00	
6	CHP	CC44	olr tripped 3 times checked belt is in over load	informed to operation	07:30:00 08:00:00 08:10:00	07:40:00 08:10:00 08:20:00	
7	CHP	cc107	over load acted due to material on belt	Reset done informed to operation remove load	12:35:00	12:40:00	
8	CHP	SCR4 on cc35	Boom position is showing in GVM but phisically in OHP side but in system showing GVM side	In TB of PLC panel bit removed informed to B shift	12:30:00	12:55:00	
9	CHP	SCR7 on CC39	boom conveyor not running	Found boom conveyor panel is in off condition made on	13:05:00	13:20:00	
10	CHP	CC54	over load tripped 4 times due to over load	informed to operation for load removal	09:00:00	09:50:00	