



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL GENERAL SHIFT REPORT

Date: 03/02/2026

Area: OHP

| Equipment | Job |
|--|---|
| co-41a,50,53,56 h/e hoists | motor and panel side ppm is done. |
| VF-16a chute vibrator | bed bolts got loose, fixed them properly. |
| OCR telecom room | Exchange room sump pump is not working, spare pump is put and de watering was started. |
| rsco-6a, co-10a,rsco-1a,rsco-2a,13a ; bf-1a,2a,3a,4a,7a,8a | bss circuit is checked and found ok. |
| co-8a,30,31,32,37a,65,69,70 | chute vibrators inspection is done, found working in auto mode as well. |
| DE-23 | OM-16 panel side blowing done and megger values of fan motor are recorded , trail run needs to be taken . |
| co-34 | motor side half coupling was found damaged, changed coupling and fixed back in position. |
| wobr-3 on co-26 | crmp side slew limit striker was missing, welded new one in its place. |
| co-8a, db-1, CO-17,18 ; co-31,32 ; co-36b,rcs-2a | motor and panel side ppm is done |
| de-101 | ral-1, chp side ral motor faulty, disconnected. |
| brc-4 on co-28 | Slip Ring B phase lug got cut , cleaning done at slipring box, re lug done and charged brc. |
| co-10a | jod kept in circuit after switch replacement. |