



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 02/05/2025

Incharge(s): Arnab Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	CHP	CC 31 , S-3	BC not running	Overload tripped , reset done	22:20:00	22:30:00	
2	CHP	CC 107	Tripped in overload	reset done	22:40:00	22:50:00	
3	CHP	CC 35 , SCR 2	LT not working due to PCRD overtension	Overtension released , then ok	23:10:00	23:30:00	
4	CHP	CC 34 , S- 1	LT not working	Drive reset	01:37:00	01:50:00	
5	CHP	CC 33 , SCR 4	LT not working	Track jamming , informed to operation	03:15:00	03:25:00	
6	CHP	CC 33 , SCR 4	Slewing not working	Due to material jamming slew limit acted . Informed opeartion for cleaning	03:39:00	03:50:00	
7	CHP	CC 132	Tripped in overload	reset done	03:00:00 04:20:00	03:10:00 04:35:00	
8	CHP	CC 51A	Tripped in overload	reset done	05:20:00	05:25:00	
9	CHP	CC 131	Tripped in overload	reset done	03:00:00 04:20:00	03:05:00 04:25:00	
10	WT	OP 6	Pusher not moving due to anti collision sensor acting frequently	Bypassed sensor , and given clearance	01:10:00	01:25:00	
11	WT	CT -1 ,CT -2	Lighting problem in hopper area	One phase damaged , spare core used . Also MCB problem , 16A single pole MCB replaced	22:30:00	22:40:00	