



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 07/09/2025

Incharge(s): V Balaji Naik

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO10A	Electronic olr acted	Reset done	07:40:00	07:50:00	
2	OHP	CO26	Electronic olr acted	Reset done	08:20:00	08:30:00	
3	OHP	CO16	DMPR acted	Reset done	12:45:00	12:55:00	
4	OHP	CO12 CD	MPCB trip	Made on	07:35:00	07:40:00	
5	OHP	WOBR on CO25	Operator cabin hydraulic motor not working found oil level low	Spare motor connected as per mechanical department	11:30:00	12:00:00	
6	CHP	SCR3 on CC40	LT PCRD pendulam limit not proper	pendulam limit released freely and cable tightness done then ok	11:25:00	11:50:00	Pendulam box cleaning and adjustment to be done
7	CHP	SCR8 on CC112	Slew not working found	Operator not done fault reset	11:00:00	11:00:00	Not an electrical problem
8	CHP	CC28	olr acted	reset done	11:50:00	11:55:00	
9	CHP	CC131	olr trip	Reset done	11:30:00	11:40:00	
10	CHP	CC51	MPD tripped on over load 3 times	Reset done	09:30:00	12:40:00	



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 07/09/2025

Incharge(s): V Balaji Naik

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
11	CHP	CC132	In C shift running inspection found motor side cable termination joints R and B phases temp are above 90 Deg	Termination opened and properly termination done	07:00:00	08:30:00	STILL THERE IS 90 Deg at B phase is to be rectified ASAP informed to B shift
12	CHP	COB5	No communication from RMHP CCR to cocke oven found FOC cable cut at COCP area	Spare Cores identified and checked continuity with torch	09:50:00	11:30:00	NO problem found in RMHP area FOC cable cut at COCP area same is informed to concern available at COCP
13	CHP	SCR3 on CC40	BC olr acted	Reset done	13:42:00	13:52:00	
14	CHP	CC108	Running feed back not coming from CC219 to CC108 ( No communication from allen bradly PLC i.e Cc219 to CC108 to siemens PLC found communication data transfer modem DC power came out or loose )	DC power given properly	12:00:00	12:30:00	
15	WT	CC3	belt drive MPCB tripped	Made on	07:10:00	07:15:00	



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 07/09/2025

Shift: A

Incharge(s): V Balaji Naik

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
16	WT	OP3	Parking zone 3 pole mcb problem and parking zone contactor not picking up	Proper earthing given, Section rods removed MCB made on	06:00:00	06:00:00	MCB may change further