



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 14/06/2025

Incharge(s): Saurabh Kumar Yadav

Shift: B

| Sl No | Area | Equipment     | Problem   | Action  | From     | To       | Remarks |
|-------|------|---------------|---|---|----------|----------|---------|
| 1     | OHP  | CO 25         | olr acted   | reset   | 19:00:00 | 19:10:00 |         |
| 2     | CHP  | CC 131        | olr acted   | reset   | 21:00:00 | 21:05:00 |         |
| 3     | CHP  | CC 131        | zss acted,cage stucked due to stone                                       | stone removed                                 | 18:00:00 | 18:10:00 |         |
| 4     | CHP  | cc 39 SCR7    | TUL C/ SENSOR acted,cable got cut   | cable jointed                                 | 20:10:00 | 20:17:00 |         |
| 5     | CHP  | CC 32 scr5    | Lt not working,mpcb 3 tripped   | made it on                                    | 19:20:00 | 19:35:00 |         |
| 6     | CHP  | CC 105 scr 10 | lighting not working,lighting mcb tripped                                 | mcb made on                                   | 19:00:00 | 19:10:00 |         |
| 7     | CHP  | CC 111 S3     | luffing not working,plc power is in off,slew not working                  | plc power made on,slew potentiometer adjusted | 17:18:00 | 17:30:00 |         |
| 8     | CHP  | CC 105 scr 10 | luffing not working,in plc glass relay RB1,2 and 3 not connected properly | rb1 ,2 and 3 pressed manually                 | 15:50:00 | 16:05:00 |         |
| 9     | CHP  | CC 39 SCR 7   | LT not taking place,control high loop loose connection                    | loop tightened                                | 15:22:00 | 15:50:00 |         |