



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 16/08/2025

Shift: B

Incharge(s): Amit Roy,K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-29	REPORTED RED CHECKED AND FOUND OLR ACTED	OLR RESET DONE	14:50:00	15:00:00	
2	OHP	CO-25	REPORTED STOPPING IN HEALTHY	ROUTE SELECTION PROBLEM INFORMED TO OPERATION	18:00:00	18:15:00	
3	OHP	STACKER ON CO-20	REPORTED CHUTE SENSOR ACTED NOT GETTING RESET	CHUTE SENSOR ALREADY IN BYPASS.WIRELESS MODEM POWER RECYCLED AND TESTED OKAY	17:20:00	18:00:00	
4	OHP	STACKER ON CO-20	REPORTED CJD ACTED.	CHECKED AND FOUND BOOM AND CJD SIGNAL MISSING IN FATAK PLC.SECOND FATAK PLC PANEL MADE ON AND TESTED OKAY	19:20:00	20:00:00	
5	OHP	CO-58(B/D)	REPORTED NOT HEALTHY	MPCB TRIPPED DUE TO JAMMING.MADE ON	21:10:00	21:30:00	AFTER CLEARING JAMMING RESET DONE AND TESTED OKAY
6	CHP	CC-51	OLR ACTED (2TIMES)	RESET DONE	19:03:00	20:20:00	
7	CHP	CC-31	REPORTED NOT HEALTHY	OLR ACTED.RESET DONE	18:00:00	18:10:00	
8	WT	SCO-1A	STOPPING ON ZSS CHECKED AND FOUND PROBE FIXING PLATE LOOSE	PROBE FIXING PLATE PROPERLY FIXED THAN OK	19:55:00	20:10:00	
9	WT	OP 10	NOT MOVING IN FORWARD NEITHER IN REVERSE	I/C-2 BREAKER TRIPPED IN LC-10B.MADE ON AND TESTED OKAY	21:25:00	21:35:00	