



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 03/08/2025

Incharge(s): V Balaji Naik, Saurabh Kumar Yadav

Shift: C

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------------|--|--|----------------------|----------------------|--|
| 1 | OHP | BRC on CO30 | @LT not working found PCRD over tension acted and MCB trip in PCRD panel. @LT brakes are not working found M4 brake cable cut. @LT Brakes not working found in brake panel Ac not coming from LT panel and one fuse also blow out. @LT speed is more | * tension limit released and MCB made on. * Brake cable reconnected *AC incoming to brake panel loose tightened and fuse blown , rewired and given clearance. *Speed reduced from 35 to 15 percent in drive panel. | 01:45:00 | 04:00:00 | Problem solved while running machine and taken 30 min for brake panel problem rectification. |
| 2 | OHP | CO15 | Olr acted 2 times due to material jamming | Reset done | 23:00:00 23:30:00 | 23:15:00 23:40:00 | |
| 3 | OHP | CO26 | olr acted | Reset done | 02:00:00 | 02:10:00 | |
| 4 | OHP | CO67 | over load acted | Reset done | 23:15:00 | 23:20:00 | |
| 5 | OHP | CO 3(b) | OLr acted | reset | 05:45:00 | 05:50:00 | due to jamming |
| 6 | CHP | CC 28 flap gate | no movement due to jamming,mpcb tripped | mpcb made on | 00:30:00 | 00:40:00 | |
| 7 | CHP | CC 40 scr 3 | all drive not working,mains not on by operator | mains on in operator cabin | 00:50:00 | 01:05:00 | |
| 8 | CHP | CC 33 SCR4 | LT not taking place, OT acted in PCRD | OT released | 02:25:00 | 02:35:00 | |
| 9 | CHP | CC 125 | OLR acted | reset | 03:35:00 | 03:40:00 | |
| 10 | CHP | CC52 | MPD tripped on over load | Reset done | 02:10:00 | 02:15:00 | |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 03/08/2025

Shift: C

Incharge(s): V Balaji Naik, Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------|---|---|----------|----------|---------------------|
| 11 | CHP | CC54 | Complaint red found Pull card acted tail end road side area one pull card operated by operation people for cleaning deck sheets | Get released after cleaning the deck sheets | 23:04:00 | 23:14:00 | No electrical delay |
| 12 | CHP | CC54 | Over load acted 2 times | Reset done | 00:00:00 | 00:10:00 | 01.40am to 01.45am |
| 13 | WT | CC 2 (B) | mpcb NO contact problem | No contact bypassed | 23:15:00 | 23:20:00 | |