



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 01/05/2025

Shift: A

Incharge(s): G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	tbs on co 22	no drives running/operator didnt on main control at control desk	control on then tested ok	06:10:00	06:20:00	
2	OHP	co 1a	zss acted due to probe cable rubbing with belt and damage the probe cable	cable re-jointed then ok	12:15:00	12:35:00	
3	OHP	tbs on co 5a	It not taking place/pcrd cable tension acted no cable on the drum because of tbs extream end	pcrd cable tension released by bypass the tension relay	10:10:00	10:25:00	
4	OHP	brc on co31	bc not running/olr acted	reset done	11:50:00	12:00:00	
5	CHP	cc 7	reported red/mccb off	mccb made on	11:50:00	12:00:00	
6	CHP	scr 9 on cc 104	luffing not taking place/hydraulic pressure problem	pressure increased(at that time boom down)and normalised after luffing	06:20:00	06:45:00	
7	CHP	scr 4 on cc33	b/w not running/didnt operate proper	start pb pressed then ok	07:30:00	07:40:00	
8	CHP	scr 6 on cc 40	luffing up not working/	inform to mech.	07:55:00	08:10:00	
9	CHP	scr 6on cc40	slewing not taking place/fuse blown at i/o rack	fuse replaced	10:45:00	10:50:00	
10	CHP	scr 9on cc104	boom signal bypasse removed for ope.requirement	done	10:15:00	10:25:00	
11	CHP	cc 104	chute sensor	kept in ckt	09:20:00	09:25:00	
12	CHP	scr 2 on cc 34	luffing lower limit bypass removed	.	12:00:00	12:10:00	
13	CHP	scr 6 on cc40	b/w stopping frequently/hydraulic oil cooling fan bit missing	cooling fan terminals tightend at panel then ok	12:50:00	13:15:00	



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 01/05/2025

Incharge(s): G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	WT	op 6	forward/reverse not taking place/D3 olr acted while coupling	reset done	11:10:00	11:20:00	