



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 26/11/2025

Incharge(s): Amit Roy

Shift: B

| Sl No | Area | Equipment     | Problem                           | Action   | From     | To       | Remarks               |
|-------|------|---------------|-----------------------------------|--|----------|----------|-----------------------|
| 1     | OHP  | WOBR on CO-26 | Reported LT not taking place      | Checked and found drive emergency push button contact broken.Bypassed and Lt tested okay.PCRD overtension released | 20:30:00 | 20:50:00 |                       |
| 2     | OHP  | BF-1A         | Reported ZSS acting               | Wrong complaint  | 19:20:00 | 19:30:00 |                       |
| 3     | OHP  | Co-34         | Reported tripped                  | OLR acted.Reset done   | 20:50:00 | 21:00:00 |                       |
| 4     | OHP  | TBS on CO-22  | Reported B/C CJD signal missing   | Checked and wires tightened and tested okay  | 14:00:00 | 14:30:00 |                       |
| 5     | CHP  | CC-105 SCr 10 | Reported LT not taking place      | PCRd overtension acted.Released and tested okay  | 17:10:00 | 17:40:00 |                       |
| 6     | CHP  | CC-112 S-3    | Reported slewing not taking place | Drive tripped.Reset done   | 19:29:00 | 19:42:00 |                       |
| 7     | CHP  | Cc-58         | Reported tripped                  | OLR acted.Reset done(3 times) due to H/E pulley jamming  | 17:15:00 | 17:35:00 |                       |
| 8     | CHP  | CC-58         | Reported not healthy              | Checked and found chute sensor acted due to jamming  | 14:47:00 | 15:06:00 | Informed to operation |
| 9     | CHP  | Cc-29         | Reported ZSS acting               | OLD joint insulation damaged.Fresh joint made  | 15:30:00 | 16:00:00 |                       |