



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 01/01/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-16	Reported tripped	OLR acted due to heavy material on belt.Reset done(2 times)	07:15:00	08:00:00	
2	OHP	CO-2	Chute sensor not working	Wrong complaint	09:30:00	09:35:00	
3	OHP	CO-34	Reported tripped	OLR acted.Reset done(2times)	09:25:00	09:30:00	
4	OHP	BRC on CO-34	Ct not taking place	Local Stop PB acted,Released and tested okay	11:50:00	12:05:00	
5	OHP	TBS on CO-22	Reported LT not taking place	PCRD tension acted.Released and tested okay	09:00:00	09:10:00	
6	CHP	Cc-31	Reported tripped	OLR acted.Reset done	07:58:00	08:05:00	
7	CHP	CC-28 TT	Chute sensor problem	Control wire problem.Rectified	06:45:00	07:30:00	
8	CHP	CC-51	MPD acted	Feeding conveyor stopped.Reset done(2 times)	07:59:00	08:15:00	
9	CHP	CC-54	Reported tripped	OLR acted.Reset done(4times)	08:09:00	12:00:00	
10	CHP	Cc-117	Reported tripped	OLR acted.Reset done(4 times)	07:56:00	09:05:00	
11	CHP	VF-3	Reported tripped	OLR acted.Reset done	08:30:00	08:35:00	
12	CHP	CC-131	Reported tripped	OLR acted.Reset done	13:33:00	13:38:00	
13	CHP	SCR-6 on CC-39	Profibus cable got crushed due to slew over travel	Cable traced out and joint was done and operations tested okay	06:00:00	08:45:00	
14	WT	OT-2	Reported drive tripping on encoder fault	No electrical problem.Mechanical problem	06:00:00	09:30:00	Informed to mechanical