



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/12/2025

Incharge(s): K SANKARA RAO

Shift: A

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|---|---|----------|----------|---------|
| 1 | OHP | TBS ON CO-21 | REPORTED LT NOT TAKING PLACE FOUND LT BRAKE PROBLEM | BRAKE ADJUSTED WITH MECHANICAL HELP THAN OK | 07:40:00 | 08:00:00 | |
| 2 | OHP | CO-45 | OLR ACTED | RESET DONE | 07:10:00 | 07:20:00 | |
| 3 | OHP | TBS ON CO-5A | LT NOT TAKING PLACE M-2 OLR ACTED | RESET DONE | 13:00:00 | 13:10:00 | |
| 4 | OHP | WOBR ON CO-26 | LT NOT TAKING PLACE PCRD O/T ACTED | RELEASED THAN OK | 13:20:00 | 13:35:00 | |
| 5 | CHP | CC-14 | OLR ACTED | RESET DONE | 09:45:00 | 09:50:00 | |
| 6 | CHP | CC-51 | MPD TRIP (FEEDING CONVEYOR STOP) (7 TIMES) | RESET DONE | 08:20:00 | 10:25:00 | |
| 7 | CHP | CC-113 S-3 | REPORTED SIGNAL MISSING | S-3 PLACED MIDDLE AREA THAN OK | 06:45:00 | 07:30:00 | |
| 8 | CHP | CC-105 SCR-10 | REPORTED SLEW NOT WORKING FOUND 30 DEGREE LIMIT ACTED | RELEASED THAN OK | 07:45:00 | 08:00:00 | |
| 9 | CHP | CC-38 SCR-6 | LT NOT WORKING FOUND PCRD CABLE INSULATION STUCK IN GUIDE | REMOVED THAN OK | 09:10:00 | 09:35:00 | |
| 10 | CHP | CC-45 | REPORTED STOPPING ON ZSS FOUND ZS PROBE DAMAGED | ZSS PROBE REPLACED WITH NEW ONE THAN OK | 10:20:00 | 10:45:00 | |