



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 11/08/2025

Shift: A

Incharge(s): V Balaji Naik

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TT4	MPCB tripped. again tripped spark observed near CO20 location found insulation damaged for one core	Insulation provided and Reset done	13:15:00 13:30:00	13:35:00 13:40:00	informed to B shift for providing sheath and to give strength to cable
2	OHP	CO87	Reported red found olr acted two times	Reset done	07:30:00	07:35:00	
3	OHP	CO35	olr acted	reset done	12:30:00	12:35:00	
4	OHP	TT1	LT not working found MPCB tripped	Made on	13:00:00	13:10:00	
5	OHP	BRC on CO31	No power found	Wrong complaint	13:20:00	13:30:00	
6	CHP	CC26 TT	LT Not moving found MPCB tripped due to jamming	Informed to operation after clearance MPCB made on	06:40:00	06:55:00	
7	CHP	Cc15 BRS	BRS bypassed due to belt offcentering after mech dept adjustment	Again put in ckt	09:10:00	09:12:00	
8	CHP	CC15 belt	Drive olr tripped	Reset done	10:53:00	11:00:00	
9	CHP	SCR9 on CC104	Slew not working found spider alaram charge pressure P3	Informed to mechanical and reset done	06:40:00	06:50:00	
10	CHP	S1 on Cc39	>CJS not healthy found module problem >CJS frequently acting found probe cable insulation got cut and touching the body	> Module replaced. > Probe properly insulated and given clearance.	08:00:00 10:20:00	08:15:00 10:30:00	
11	CHP	CC223	Motor not healthy found C2 contactor not picking up	Power recycling done then ok	11:00:00	11:10:00	



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 11/08/2025

Incharge(s): V Balaji Naik

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	CHP	CC51	feeding conveyor stop olr acted	Reset done	11:50:00	12:00:00	
13	CHP	CC54	olr tripped 3 times	Reset done	12:50:00	13:05:00	advised to reduce feeding