



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 26/11/2025

Incharge(s): Amit Roy

Shift: B

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|-----------------------------------|--|----------|----------|-----------------------|
| 1 | OHP | WOBR on CO-26 | Reported LT not taking place | Checked and found drive emergency push button contact broken. Bypassed and Lt tested okay. PCRD overtension released | 20:30:00 | 20:50:00 | |
| 2 | OHP | BF-1A | Reported ZSS acting | Wrong complaint | 19:20:00 | 19:30:00 | |
| 3 | OHP | Co-34 | Reported tripped | OLR acted. Reset done | 20:50:00 | 21:00:00 | |
| 4 | OHP | TBS on CO-22 | Reported B/C CJD signal missing | Checked and wires tightened and tested okay | 14:00:00 | 14:30:00 | |
| 5 | CHP | CC-105 SCr 10 | Reported LT not taking place | PCRD overtension acted. Released and tested okay | 17:10:00 | 17:40:00 | |
| 6 | CHP | CC-112 S-3 | Reported slewing not taking place | Drive tripped. Reset done | 19:29:00 | 19:42:00 | |
| 7 | CHP | Cc-58 | Reported tripped | OLR acted. Reset done(3 times) due to H/E pulley jamming | 17:15:00 | 17:35:00 | |
| 8 | CHP | CC-58 | Reported not healthy | Checked and found chute sensor acted due to jamming | 14:47:00 | 15:06:00 | Informed to operation |
| 9 | CHP | Cc-29 | Reported ZSS acting | OLD joint insulation damaged. Fresh joint made | 15:30:00 | 16:00:00 | |