



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 01/06/2025

Shift: C

Incharge(s): V Balaji Naik,G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO87	Over load acted	Reset done	00:00:00	00:10:00	
2	OHP	CO62 belt drive	MPCB trip due to material jamimg	after jam clearance	04:00:00 05:10:00	04:10:00 05:15:00	
3	OHP	CO29	OLR acted 3 times due to over load and lack of return idlers	Reset done	02:30:00 05:30:00 05:50:00	02:45:00 05:40:00 05:55:00	
4	OHP	CO51 carriage	Over load trip due to jam	Reset done	00:00:00	00:10:00	
5	OHP	BRC on CO31	BW1 not running found DMPR acted	Reset done	00:34:00	00:42:00	
6	OHP	CO35	Over load acted	Reset done	01:37:00	01:39:00	
7	OHP	BRC on CO34	Bucket wheel not working found stone struck b/w chute and BW	Stone removed by reversing and clearance given	03:45:00	04:10:00	
8	CHP	SCR1 on CC36	Boom position physically in OHP side but showing in GVM side found bit bypassed in IO rake	By pass removed in IO rake then ok	01:25:00	01:35:00	
9	CHP	CC203	Over load cacted	Reset done	01:45:00	01:55:00	
10	CHP	R1 on CC31	Boom conveyor frequently stopping found no return idlers near ZSSs cage	Informed to mechanical and ZSS bypassed	03:10:00	03:45:00	
11	CHP	SCR5 on CC32	LT not working found drive tripped in over load	Reset done	04:30:00	04:45:00	



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 01/06/2025

Shift: C

Incharge(s): V Balaji Naik, G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	CHP	CCR punching machine	Power tripped	Reset done	03:05:00	03:15:00	
13	CHP	CC117	Over load trip	Reset done	05:25:00	05:45:00	
14	CHP	CC28	ZSS acting found oil leakage in fluid coupling	Informed to mechanical after oil top up then ok	00:05:00	00:25:00	
15	CHP	CC22	Belt drive MPCB trip due to over load	Made on then ok	02:05:00 04:05:00	02:15:00 04:25:00	jamming is to be cleared further
16	CHP	CC24	ZSS acting found probe not working	Probe changed then ok	04:05:00	04:15:00	
17	CHP	CP3	Over load acted for D3 during coupling time	Reset done	02:40:00	03:00:00	D4 tyre missing infomed to mehanical and informed to operation not to push wagons as pusher is running with 4 drives
18	WT	CP3	Not moving found Drive2 bed base bolt loose, Drive 3 cable lug loose	D2 bed bolts Tightened and D3 lug replaced then ok	04:15:00	05:15:00	



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 01/06/2025

Incharge(s): V Balaji Naik, G Eswara Rao

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
19	IOSA	WOBR on OC17a	Slewing not working due to bucket wheel over load due to over load	Informed to operation after jam clearance then ok	23:40:00	23:50:00	