



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 19/05/2025

Shift: A

Incharge(s): V Balaji Naik

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|--|---|----------|----------|---------|
| 1 | OHP | BRC on CO33M | Lt not working found drive trip | Reset done | 12:40:00 | 12:55:00 | |
| 2 | OHP | CO27a | BRS bypassed as per operation request | By passed | 12:30:00 | 12:40:00 | |
| 3 | CHP | CC109 | Pull card acted | Reset done | 11:00:00 | 11:10:00 | |
| 4 | CHP | Cc131 | over load trip | Reset done | 11:00:00 | 11:05:00 | |
| 5 | CHP | CC54 | Over load trip(3 times) due to over load | Informed to mechanical after load clearance Reset done | 12:05:00 | 12:15:00 | |
| 6 | CHP | SCR5 on CC32 | Luffing working slowly found BC and BW area coal jamming | Informed to operation | 07:25:00 | 07:35:00 | |
| 7 | CHP | SCR7 on CC39 | Slew not working found anti clock wise limit acted | Informed to operation | 08:35:00 | 08:50:00 | |
| 8 | CHP | CC108 | Healthy stop found ZSS return core loose tightened | Then ok | 11:15:00 | 11:35:00 | |
| 9 | CHP | CC222 | Healthy not showing red and not starting found Drive tripped | Reset done found load on belt informed to operation | 12:35:00 | 12:45:00 | |
| 10 | CHP | SCR1 on CC36 | BC not running found BSS acting | Informed to mechanical | 13:30:00 | 13:45:00 | |
| 11 | CHP | CC112 | BRS not resetting both sensors cleaned | found ok | 10:25:00 | 10:35:00 | |
| 12 | IOSA | All conveyors | Reported RED found communication problem in PLC | Power recycling done then ok | 12:40:00 | 13:30:00 | |