



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 06/06/2025

Shift: B

Incharge(s): V Balaji Naik

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO26	BC not running found ZSS cage struck by stone	Stone removed clearance given	20:30:00	20:45:00	
2	CHP	CC131	Pull card is not showing healthy found tail end side acted condition	Reset done	14:15:00	14:25:00	
3	CHP	CC131	Over load acted	Reset done	16:40:00	16:50:00	
4	CHP	CC117	Over load acted	Reset done	19:00:00	19:15:00	
5	CHP	CC132	ZSS acted due to over load 2 times	Informed to operation taken in to local at 8.20pm	20:00:00	20:10:00	while clearing the jam belt snapped at 21.30pm
6	CHP	RSCO10A	Belt not showing ZSS	Potentiometer speed decreeseed by 1% found ok	18:40:00	18:55:00	
7	CHP	CC28	TT Flap gate OLR acted	Reset done	14:55:00	15:00:00	
8	CHP	CC13	OLR acted	Reset done	15:35:00	15:40:00	
9	CHP	OT2	D1 and D2 tripped on encoder fault found encoder wire loose in CJB	Tightened then ok	14:00:00	14:10:00	
10	CHP	SCR10 on CC105	HT incoming panel alarm ringing found earth fault relay tripped	alaram acknowledged, reset and panel charged found ok	15:00:00	15:10:00	
11	CHP	CC31	ZSS not working found neutral cable got cut b/w module and JB	Rejointed then ok	14:30:00	15:00:00	
12	CHP	CC38	DE chute jam acted	No jam probe cleaned then ok	17:10:00	17:20:00	
13	CHP	CC33	sparks observed in in Drive end side Junction box found water drops in JB	Cleaned arrested then ok	18:30:00	18:40:00	



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 06/06/2025

Incharge(s): V Balaji Naik

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	CHP	SCR6 on CC20	BC not running found no CPP signal	ok	20:30:00	20:50:00	
15	CHP	SCR8 on CC112	BC stopping frequently found due to belt offcentering BSS acting again normal	informed to operation and mechanical	17:00:00	17:10:00	
16	CHP	SCR8 on CC112	Derailed towards Tail end side	Work under progress same informed	21:00:00	21:05:00	
17	CHP	CC 111 s3	no power,breaker trip in LC 2 in over current fault	reset and given clearance	22:00:00	22:25:00	
18	WT	OP8	D4 tripped	Reset done	16:30:00	16:40:00	
19	WT	CO4 Carriage	Drive tripped	Reset done	17:45:00	17:50:00	
20	WT	CC2 belt	Drive tripped	Reset done	18:20:00	18:25:00	
21	WT	OT5	No lighting in tippler house found MCB incomer cable damage	Rejointed then ok	20:20:00	20:30:00	