



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/11/2025

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------------------|---|---|----------|----------|------------------------------|
| 1 | OHP | wobr on CO 6A | pending complaint, both 12 slot extendable rack having problem, lower and upper house | rack replaced | 22:00:00 | 03:10:00 | |
| 2 | OHP | co 29 | OLR acted | reset | 23:00:00 | 23:08:00 | 2 times |
| 3 | OHP | brc on co 30 | bc not running, olr acted | reset | 22:35:00 | 22:50:00 | |
| 4 | OHP | tbs on co 21 | LT not working, Brake problem | informed operation | 22:30:00 | 22:45:00 | |
| 5 | CHP | cc 35 scr3 | LT not working, drive tripped | reset | 22:40:00 | 22:55:00 | |
| 6 | CHP | cc 125 | olr acted | reset | 00:15:00 | 00:25:00 | |
| 7 | CHP | CC 34 scr 2 | b/c not running, zss sensor not working | bypassed in i/o rack | 01:00:00 | 01:15:00 | informed A shift to replaced |
| 8 | CHP | CC 26 A | mpcb tripped of flap gate | made it on | 22:30:00 | 22:40:00 | |
| 9 | CHP | CC 26 signal to cc 38 | signal missed, loose connection in tbs | tightened | 23:00:00 | 23:10:00 | |
| 10 | WT | OC 1A(B) | OLR acted | reset | 02:00:00 | 02:10:00 | |
| 11 | WT | OT1 | wagon over traveled O/L side and tippler rotated 20 degree, sensor acted and RLS not high | sensor and RLS bypass and kept in ckt after wagon proper placement in tippler | 01:00:00 | 01:10:00 | |