



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 04/12/2025

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-68	Reported ZSS acted	Checked and found okay	15:30:00	16:05:00	No problem found
2	OHP	CO-11A	Reported ZSS acting	ZSS cable cut.Rejointed and tested okay	15:30:00	15:45:00	
3	OHP	CR-2A	Reported ZSS acted	Probe gap adjusted and tested okay	17:35:00	17:55:00	
4	OHP	CO-25	Reported tripped	OLR acted.Reset done(2 times)	19:25:00 21:45:00	19:35:00 21:55:00	
5	OHP	BF-3A	ZSS acting	Checked and found ZSS targets damaged.Bypassed and target welding done and bypass removed and tested okay	20:23:00	21:50:00	
6	OHP	WOBR on CO-6A	Reported slewing not taking place	B/C full jamming.Asked to clear material	21:50:00	22:00:00	
7	CHP	CC109	Reported BRS acting	Sensors adjusted and tested okay	18:50:00	19:10:00	
8	CHP	CC 29	Reported tripped	OLR acted.Reset done(3 times)	15:00:00 15:15:00 16:10:00	15:10:00 15:25:00 16:15:00	
9	CHP	CC 28	Reported tripped	OLR acted.Reset done	20:05:00	20:10:00	
10	CHP	CC-35 SCR-3	Reported LT not working.	Drive tripped.Reset done	20:55:00	21:10:00	
11	CHP	Cc 35 SCR-5	Reported LT not working	Wrong complaint	21:55:00	22:05:00	
12	WT	OT-5	Reported side clamping and declamping not working	Checked and found vertical clamp pressure not reaching set point.Set point adjusted and tested okay.Mechanical problem	20:00:00	21:00:00	Not an electrical problem



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 04/12/2025

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
13	WT	Pusher-9	Reported FWD and Rev not taking place	Reset done in system and tested okay	17:30:00 20:30:00	17:40:00 20:40:00	