



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 04/10/2025

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TIS 4 on CO 44	pending from b shift, control ckt problem, aux relay not getting 110 v, selector switch ok	control cable trace found loose connection in TBs tightened than ok, bypass removed from program	22:30:00	23:20:00	no delay, co44 in running only (kindly provide drawing of TIS, for fast troubleshooting of problem)
2	OHP	VS 2	olr acted	reset	23:30:00	23:35:00	
3	OHP	CO 67	olr acted	RESET	00:10:00	00:15:00	
4	OHP	OC 36A	zss acted, stone stucked in cage	removed	23:30:00	23:45:00	
5	OHP	TBS on CO 7A	It not working, vfd trips	reset	05:15:00	05:30:00	
6	OHP	CO 29	OLR acted	reset	05:30:00	05:40:00	
7	OHP	WOBR on CO 25	b/c not running, zss cage stuck with pellets	pellets removed	01:00:00	01:15:00	
8	CHP	CC 32 R1	luffing down not working, down limit bypass, limit switch stucked	limit switch made free, bypass removed after, up than ok	22:50:00	23:02:00	
9	CHP	CC 23	zss acted, material stucked in cage	cage cleaned	22:45:00	22:50:00	
10	CHP	CC 51	mpd trips 9 times	reset	01:00:00	05:00:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 04/10/2025

Incharge(s): Saurabh Kumar Yadav

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
11	CHP	CC 31 SCR 4	B/W not running, mech problem	electrical side all ok, even b/w not running when pressed manually in anticlock wise dir	02:00:00	02:15:00	even after telling many times operation not ready to accept mechanical problem
12	CHP	CC 112 SCR8	b/c not running in reclaiming mode, material selection not done	informed operation incharge depak kindly do material selection	03:45:00	03:50:00	
13	WT	CO 3(B)	olr acted	reset	22:20:00	22:25:00	
14	WT	OT1	D1 trips in pgf1 fault	reset	00:55:00	01:00:00	
15	WT	OP 9	NO fwd movement, control fuse of limit switchblown in PLC panel	fuse replaced	04:15:00	04:25:00	
16	IOSA	OC 36 A	zss acted, probe problem	probe replaced	22:00:00	22:25:00	