



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/10/2025

Shift: A

Incharge(s): Amit Roy

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------|-------------------------|--|----------------------------------|----------------------------------|---------------------------|
| 1 | OHP | DB-1 | Reported tripped | OLR acted.Reset done | 12:45:00 | 13:00:00 | |
| 2 | OHP | CO-26 | Reported tripped | OLR acted.Reset done | 11:05:00 | 11:15:00 | |
| 3 | OHP | TBS on CO-7A | Right luff tripping | brakes made loose and chute material jamming cleared after boom run and motor hot blowing done and up/down tested okay | 08:20:00 | 09:30:00 | |
| 4 | CHP | CC-33 | Reported tripped | OLR acted(3 times) due to belt overload at T/E.Reset done | 09:20:00 | 09:35:00 | Tripped at 9.20,9.35,9.50 |
| 5 | CHP | Cc-35 SCR-5 | LT not working | Drive tripped.Reset done(2 times) | 09:20:00 09:50:00 | 09:35:00 10:00:00 | |
| 6 | CHP | CC-104 SCR-9 | Slew and B/W not moving | Oil cooler motor trip and oil temperature high.Oil cooler made on and oil temperature found normal and tested okay | 11:05:00 | 11:30:00 | |
| 7 | WT | OC-1A | Reported Tripped | OLR acted(3 times).Reset done | 12:00:00 12:40:00 13:10:00 | 12:05:00 12:50:00 13:20:00 | |
| 8 | IOSA | OC-7B | Reported fail to start | Breaker racked out and inserted properly and tested okay | 07:50:00 | 08:10:00 | |
| 9 | IOSA | WOBR | LT not taking place | PCRD chain problem.Loop given for reclaiming | 09:00:00 | 09:20:00 | Informed to mechanical |