



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/07/2025

Incharge(s): Lal Singh, Arnab Roy

Shift: B

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|---|--------------------------------------|----------------------|----------------------|---|
| 1 | OHP | CO 9 | Thermal OLR acted (3 times) | reset done | 14:30:00 20:00:00 | 14:46:00 22:00:00 | motor temp 85 degree .. power and control made off and asked operation to change the stream ... physical checked return side cutting stringer post and idlers not rotating near 150 |
| 2 | OHP | CO 87 | OLR acted | reset done | 15:10:00 15:30:00 | 15:15:00 15:45:00 | |
| 3 | OHP | WOBR on CO 6A | BC not running due to BSS acted , belt off centering | BSS reset | 15:50:00 | 16:05:00 | |
| 4 | OHP | CO 65 | CJD not working due to feedback wire opened at module | feedback wire connected properly | 14:15:00 | 14:30:00 | |
| 5 | OHP | WOBR on CO 25 | LT not working due to M-1 tripped in Drive mode | kept in DOL mode and given clearance | 17:30:00 | 17:45:00 | |
| 6 | OHP | CO 26 | OLR acted | reset done | 21:20:00 | 21:30:00 | |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/07/2025

Incharge(s): Lal Singh, Arnab Roy

Shift: B

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------------|----------------------------|--|----------|----------|--|
| 7 | CHP | CC 29 | Chute sensor acted | Cleaned and given clearance | 14:30:00 | 14:40:00 | |
| 8 | CHP | CC 32 , SCR 5 | BC zero speed cage problem | Cage lifted and zero speed bypassed | 17:00:00 | 17:20:00 | cage changing going on after machine stopped, also informed to C shift |
| 9 | CHP | CC 105 , SCR 10 | BC stopping | ZSS cage stucked , adjusted | 15:30:00 | 16:00:00 | |
| 10 | CHP | CC 125 | OLR acted (2 times) | reset done | 17:30:00 | 18:20:00 | |
| 11 | CHP | CC 31 , R-1 | Slew not working | Drive tripped, reset done | 18:20:00 | 18:35:00 | |
| 12 | CHP | CC 32 , SCR 5 | BC stopping frequently | Checked, no electrical problem found | 14:47:00 | 15:10:00 | |
| 13 | CHP | CC 113A | Tripped on overload | reset done | 15:00:00 | 15:10:00 | |
| 14 | CHP | CC 131 | Tripped on overload | reset done | 20:40:00 | 20:45:00 | |
| 15 | WT | CO 2 | MPCB tripped (2 times) | reset | 15:45:00 | 16:25:00 | |
| 16 | WT | CO 3 | Not moving | Chceked , in B phase lug got cut in motor terminal box . Connected and clearance given | 17:30:00 | 17:55:00 | |
| 17 | WT | SCO 1A | OLR acted | reset done | 16:50:00 | 16:55:00 | |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/07/2025

Shift: B

Incharge(s): Lal Singh, Arnab Roy

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------|---|-----------------------------------|----------|----------|---------|
| 18 | WT | OT1 | Not moving due to outhaul side reverse limit not closing properly | Limit adjusted properly , then ok | 17:35:00 | 17:50:00 | |