



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 23/05/2025

Shift: A

Incharge(s): V Balaji Naik, G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 33M	tripped on olr	reset done	07:20:00	07:30:00	
2	OHP	brc on co 33m	bc not running/olr acted due to jamming	reset done	11:00:00	11:30:00	
3	OHP	Left boom conveyor on co 23	lbc zss acting/module defective	zss module replaced then ok	11:00:00	11:30:00	
4	OHP	co 30	brs acting /belt pieces hanging	inform to operation	12:10:00	12:25:00	
5	OHP	co 29	tripped on olr	reset done	13:25:00	13:30:00	
6	OHP	TT1 flap gate	OLR acted due to stone struck	Reset done	14:00:00	14:00:00	10.10am to 10.20am
7	CHP	SCR7 on CC39	Slew not working found in stacking mode 30 degrees acted	Bypassed and removed after completion of work	14:00:00	14:00:00	07.08am to 07.30am
8	CHP	CC36	BRS acted	Sensors cleaned then ok	14:00:00	14:00:00	07.35am to 08.00am
9	CHP	SCR1 on CC36	Luffing not working found, BW and BC deck sheets full jammimg	Informed to operation after cleaning luffing ok	14:00:00	14:00:00	09.20am to 10.05am
10	CHP	SCR5 on Cc32	Reclaiming mode BC not working found chute sensor acted	Bypassed in IO rake	14:00:00	14:00:00	07.32am to 07.50am
11	CHP	SCR5 on CC32	LT not working found drive fault	Reset done	14:00:00	14:00:00	12.16pm to 12.36pm
12	CHP	SCR3 on CC38	Slew not working found jamming in slew area	Informed to operation	14:00:00	14:00:00	08.30am to 08.50am



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 23/05/2025

Shift: A

Incharge(s): V Balaji Naik,G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
13	CHP	CC201	DE side chute sensor acted found snub pulley and return idlers side Jamming	Informed to operation for clearing jam	14:00:00	14:00:00	10.45am to 11.00am
14	CHP	CC222	not working found VFD drive side C-1 contactor fault	contactor replaced then ok	14:00:00	14:00:00	11.15am to 11.45am
15	CHP	Cc35	ZSS acting found ZSS cage rod missing	New rod fixed then ok	14:00:00	14:00:00	1.25pm to 1.35p
16	CHP	SCR1 on CC36	BSS bypassed as per operational request due to belt off centering and rain signal also missing	BSS bypassed and ethernet cable reconnected	14:00:00	14:00:00	07.05am to 07.30am
17	CHP	CC35	BRS not getting reset	Sensors cleaned then ok	14:00:00	14:00:00	08.25am to 08.35am
18	CHP	SCR2 on CC35	LT not working found pcrd over tension limit acted	Reset done	14:00:00	14:00:00	10.38am to 10.50am
19	CHP	CC32	Conveyor tripped due to over load acting	Reset done	14:00:00	14:00:00	11.36am to 11.41am
20	CHP	CC131	OLR acted	Reset done	14:00:00	14:00:00	05.05pm to 05.10pm
21	CHP	SCR5 on Cc32	BC not running found chute sensor rope damage and fuse also blown	Replaced	14:00:00	14:00:00	04.40pm to 05.00pm
22	WT	CT1 inhaul	MPCB trip	Reset done	14:00:00	14:00:00	10.30am to 10.40am
23	WT	CP1	D6 tripped 2 times found B phase got cut	D6 bypassed in programme	14:00:00	14:00:00	10.30am to 10.40am



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 23/05/2025

Incharge(s): V Balaji Naik, G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
24	WT	OP9	Not moving found Rev limit acted	Reset done	14:00:00	14:00:00	03.40pm to 04.00pm
25	WT	OP6	Not moving found D2 tripped on Over load relay during coupling time	Reset done	14:00:00	14:00:00	12.50pm to 01.00pm