



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 24/05/2025

Shift: C

Incharge(s): Lal Singh, Arnab Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on CO 20	Right boom not running	OLR acted due to material jamming , reset done	22:50:00	23:10:00	
2	OHP	TBS on CO 20	LT not working	Reclaimer height limit tied	23:45:00	00:00:00	
3	OHP	COP 35	OLR acted	reset done	00:30:00	00:35:00	
4	OHP	TBS on CO 20	Right luff not working due to OLR acted	reset done	02:15:00	02:30:00	
5	OHP	Crusher 2A	Lubrication mechanical problem	Crusher 3A lubrication motor interchanged with Crusher 2A on mechanical request	22:00:00	22:45:00	
6	CHP	CC 36 , SCR 1	Luff not working	Up limit bypassed in IO rack	23:40:00	00:30:00	
7	CHP	CC 41	Chute sensor acting frequently	Bypassed	00:40:00	01:15:00	In system
8	CHP	CC 35 , SCR 2	LT not working due to overtension acted	Overtension released	02:30:00	02:40:00	
9	CHP	CC 125	OLR acted	reset done	00:30:00 04:15:00	00:40:00 04:20:00	
10	CHP	CC 36	Zero speed module problem	Bypassed in IO rack	03:40:00	04:00:00	Informed to A shift .
11	CHP	CC 54	Motor tripped in overload	reset done	00:45:00	00:50:00	
12	CHP	CC 130 TIS	Tripped due to big iron piece	reset done	05:00:00	05:15:00	
13	CHP	CC 114	BRS to be bypassed as per operation request	BRS bypassed	23:50:00	00:00:00	In IO rack



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 24/05/2025

Shift: C

Incharge(s): Lal Singh, Arnab Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	WT	Air compressor	Not working due to high temp	After normal temp reached started and found ok	03:00:00	03:30:00	
15	WT	OT 4	Clamping and declamping not working	Changed to Hydraulic pump 2 , then ok	04:45:00	04:50:00	