



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 17/09/2025

Shift: C

Incharge(s): V Balaji Naik

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBr on CO29	BW not running found MPCB trip due to BW stone struck	Stone removed by LT movenet	23:00:00	23:20:00	
2	OHP	WOBR on CO25	yard conveyor inter lock indication not coming	ZSS acge stone struck removed then ok	23:20:00	23:40:00	
3	OHP	CO35	BRS acted not getting reset due to belt offcentering and material	BRS bypassed in module	01:35:00	01:50:00	
4	OHP	CO19	olr acted	Reset done	04:00:00	04:10:00	
5	OHP	BRC on CO28	Bridge conveyor not running due to CRMP side full material jamming	Informed to operation	05:35:00	05:45:00	
6	CHP	S1 on CC40	Luffing not working found power contactor R phase problem	Power contactor replaced	22:30:00	22:40:00	
7	CHP	SCR3 on CC39	*LT not working found PCRD cable over tension limit acted *BC frequently stopping found signal problem	*OT limit reset done. * ZSS cage placed properly	00:00:00	00:00:00	
8	CHP	CC44	Motor over load MPD trip	Rest done	01:50:00	02:00:00	
9	CHP	CC219	Motor healthy stop found CJS acted	Informed to operation	02:00:00	02:10:00	
10	CHP	SCR7 on CC37	LLT not working found operator cabin side fault reset not done	fault reset get done by operator	04:20:00	04:30:00	not electrical delay
11	CHP	VF3	motor tripped on olr	Reset done	23:30:00	23:35:00	
12	CHP	CC131	Motor tripped on olr	Reset done	03:30:00	03:35:00	
13	CHP	CC54	Motor tripped on over load	Reset done	05:15:00	05:20:00	



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 17/09/2025

Incharge(s): V Balaji Naik

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	CHP	Cc51	MPD tripped on over load 2 ties stopped feeding conveyor	Reset done	22:30:00	22:35:00	05.45am to 05.50am
15	CHP	Cc113	stopped on chute sensor fault found chute jamming	Informed to operation	05:55:00	05:55:00	
16	CHP	Cc115	BRS not getting reset after throe hole patch work found MCB off condition	MCB made on then reset ok	01:20:00	01:30:00	
17	WT	OT2	M1 tripped due to PGF 4 fault	Informed to mechanical dept for brake adjustment	01:20:00	01:40:00	