



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 24/09/2025

Incharge(s): Nagendra Midde

Shift: C

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------------|----------------------------|-----------------------------------|----------------------|----------------------|--|
| 1 | OHP | CO 77 | MCCB R PHASE GOT FAILURE | CO 83 MCCB REMOVED AND REPLACED | 00:00:00 | 00:30:00 | NEW MCCB LM 200 HAS TO BE PROVIDED FOR CO 83 |
| 2 | OHP | BRC ON CO 32 | B/C OLR ACTED | RESET | 04:00:00 05:20:00 | 04:15:00 05:40:00 | |
| 3 | OHP | CO 29 | SLEW DRIVE TRIPPED | RESET | 04:30:00 | 04:50:00 | |
| 4 | OHP | CO 49 | BRS NOT RESETTING | BYPASSED | 05:50:00 | 06:00:00 | |
| 5 | OHP | VS2 | OLR ACTED | RESET | 02:00:00 | 02:10:00 | |
| 6 | CHP | SCR 7 ON CC 37 SLEW | CHARGE PRESSURE ACTED | RESET | 23:20:00 | 23:45:00 | |
| 7 | CHP | SCR 1 ON CC 36 | LT DRIVE TRIPPED | RESET | 00:50:00 | 01:10:00 | |
| 8 | CHP | SCR 3 ON CC 40 | B/C SIGNAL MISSING | LT DONE TOWARDS DRIVE END THEN OK | 03:20:00 | 03:40:00 | |
| 9 | CHP | CC 27A | TRIPPER POSITION SENSOR | BYPASSED ON CO 39 | 23:10:00 | 23:20:00 | SENSOR ALIGNMENT TO BE DONE PROPERLY |
| 10 | CHP | CC 54 | OLR ACTED | RESET | 04:50:00 | 05:30:00 | |
| 11 | CHP | CC 51 | OLR FEEDING CONVEYOR ACTED | RESET | 00:00:00 | 05:30:00 | 9 TIMES |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 24/09/2025

Incharge(s): Nagendra Midde

Shift: C

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|---|------------------|----------|----------|---------|
| 12 | WT | OT5 | VERTICAL CLAMPING FUSE BLOWN DUE TO WATER IN LS 3 | FUSE REPLACED | 01:55:00 | 02:00:00 | |
| 13 | IOSA | TBS ON OC 13A | RBC STOPPING FREQUENTLY DUE TO BS AND OFF CENTERING | INFORMED TO MECH | 00:30:00 | 00:50:00 | |