



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/08/2025

Shift: A

Incharge(s): V Balaji Naik, Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------------|--|---|----------------------|----------------------|-------------------|
| 1 | OHP | CO9 | Reported not healthy found pull card acted due to belt piece | Informed operation to cut belt pieces | 07:00:00 | 07:20:00 | |
| 2 | OHP | CO28 on BRC | BCnot running found over load acted due to over material | Reset done | 07:20:00 | 07:30:00 | |
| 3 | OHP | WOBR on CO25 | LT not moving found Motor1 gear box touching track due to bearing problem | Informed to mechanical and operation | 08:45:00 | 09:00:00 | |
| 4 | OHP | CO85 | Reported olr acted | Reset done | 10:00:00 | 10:10:00 | |
| 5 | OHP | Co87 | Red found OLR acted | Reset done | 10:45:00 | 10:50:00 | |
| 6 | OHP | RSCO 10 A carriage | Drive tripped due to track jamming | informed to operation and MPCB made on | 11:30:00 | 11:40:00 | |
| 7 | OHP | TT4 | Indication not coming | Toggle switch reset done | 12:45:00 | 12:50:00 | |
| 8 | OHP | TBS on CO22 | LT drive tripped due to track jamming | Power recycling done then ok | 11:50:00 | 12:00:00 | |
| 9 | OHP | OM12 | All conveyors red found breaker tripped in LC3 | made on again tripped on earth fault in LC 3 MLdb made on and breaker made on then ok | 12:10:00 12:15:00 | 12:45:00 12:30:00 | May check further |
| 10 | OHP | OM12 | All conveyors tripped with earth fault | Reset done and breaker made on in LC3 | 12:15:00 | 12:25:00 | |
| 11 | OHP | TT2 | position bit not coming found control fuse blown in CJB | Fuse replaced | 13:30:00 | 13:40:00 | |
| 12 | OHP | CO34a | BRS bypassed in module as per operational request due to belt joint opened | Bypassed | 12:50:00 | 12:50:00 | |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 13/08/2025

Incharge(s): V Balaji Naik, Saurabh Kumar Yadav

Shift: A

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|---|---|----------|----------|---|
| 13 | CHP | SCR4 on CC33 | LT not working found OT limit acted | tension limit Released | 07:00:00 | 07:25:00 | Due to timer it is acting early informed to G shift |
| 14 | CHP | SCR2 on CC34 | Over tension limit acted | Released | 07:29:00 | 07:35:00 | 08.29am to 08.33am |
| 15 | CHP | SCR1 on CC35 | LT not working due to jamming on track | Informed to operation after cleaning ok | 08:40:00 | 09:30:00 | |
| 16 | CHP | SCR8 on CC111 | Slew not working 2 times | Wrong complaint | 11:20:00 | 11:30:00 | 12.00pm tom 12.30pm |
| 17 | CHP | CC26a | Burn motor removed and new motor installed and termination done | Trail taken given clearance | 06:00:00 | 11:00:00 | |
| 18 | CHP | CC29 | Flap gate tripped | Reset done | 10:30:00 | 10:40:00 | |
| 19 | CHP | CC 51 | olr acted due to feeding conveyor stopped | reset | 10:30:00 | 10:35:00 | 4 times |
| 20 | CHP | CC21 belt | Drive tripped on olr | reset done | 11:45:00 | 11:59:00 | |
| 21 | CHP | CC 54 | olr acted due to feeding increased | reset | 11:40:00 | 11:45:00 | 3 times |
| 22 | CHP | CC 58 | olr acted | reset | 10:50:00 | 10:59:00 | |
| 23 | CHP | RG 3 | tripped in high temp fault NDE crusher side | temp came down | 11:45:00 | 12:10:00 | |
| 24 | CHP | VS3 | not running in plc, control cable loose connection in i/o rack to o/p relay | control cable tightened | 08:30:00 | 09:20:00 | |