



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 31/05/2025

Shift: A

Incharge(s): K SANKARA RAO

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|----------------|--|--|----------|----------|----------------|
| 1 | OHP | CO 29 | OLR ACTED | RESET | 08:45:00 | 09:00:00 | |
| 2 | CHP | CC13 | STOPPING ON ZS | ZS PROBE GAP ADJUSTED | 08:40:00 | 08:50:00 | |
| 3 | CHP | cc-34 scr-2 | LT NOT WORKING | OVER TENSION ACTED ... RELEASED | 13:10:00 | 13:20:00 | |
| 4 | CHP | CC-40 SCR-9 | LT NOT WORKING | DRIVE TRIPPED RESET | 13:35:00 | 13:45:00 | |
| 5 | CHP | CC-35 S-1 | LT NOT WORKING | DRIVE TRIPPED ... RESET DONE | 09:35:00 | 09:45:00 | |
| 6 | CHP | CC-31 R-1 | BC NOT RUNNING | C/S AND ZSS FUSE BLOWEN ... CONTROL MCB IN OFF CONDITION. FUSE CHANGED ... MCB MADE ON | 06:45:00 | 07:15:00 | |
| 7 | CHP | CC-111 S-3 | BC NOT RUNNING , SLEW ALSO NOT RUNNING | MCCB TRIPPED ...MADE ON ... SLEW OLR ACTED .. RESET DONE | 06:20:00 | 07:00:00 | |
| 8 | WT | CP2 | ROTAREY CONTACTOR TIMER NOT PICK UP | TIMER CNTACT BYPASSED | 08:45:00 | 09:15:00 | |
| 9 | WT | OC1A | TRIPPED ON OVER CURRENT | RESET DONE | 11:00:00 | 11:15:00 | DUE TO JAMMING |
| 10 | WT | OP5 OP6 | NO POWER I/C TRIPPED IN LC 2B | MADE ON THAN OK | 11:15:00 | 11:30:00 | |