



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/05/2025

Shift: A

Incharge(s): V Balaji Naik, G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 29	tripped on thermal olr	reset done	08:45:00 10:40:00	09:00:00 10:50:00	
2	OHP	co 34	tripped on olr	reset done	09:15:00	09:30:00	
3	OHP	co 4a	brs by- pass request from ope.	bypassed at module	11:00:00	11:10:00	
4	OHP	co 35	tripped on olr	reset done	12:15:00	12:25:00	
5	CHP	SCR2 on CC34	Left slew not working found high is not coming from cabin, No continuity from cabin to PLC panel, control cable got rubbed and cut below the cabin	one core coming from PLC(TB1-37%I1.8.2 -XA06-5 slew left) rejoined and given clearance	11:30:00	11:50:00	Remaining 5 core no's found no continuity from PLC to cabin, further inspection of control cable may done 9No delay required position is arranged by PLC local contactor pressing)
6	CHP	SCR1 on CC36	Slewing not working found full material jam	Informed to operation	12:20:00	12:30:00	



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/05/2025

Incharge(s): V Balaji Naik, G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
7	CHP	SCR4 on CC33	BC not working found TUL chute sensor acted	On operational request TUL bypassed again not working found Stacking/Reclaimer bypass switch problem rectified then ok	11:00:00	11:20:00	
8	CHP	scr 8 on cc40	tul c/s kept in ckt	.	06:00:00	06:10:00	
9	CHP	cc 41	c/s not working/c/s core problem	c/s and epb kept in series	06:00:00	06:15:00	emergency stop pb replaced
10	CHP	cc 33	tripped on olr	reset done	12:15:00	12:20:00	
11	CHP	cc 125	tripped on olr	reset done	12:20:00	12:30:00	
12	CHP	scr 10 on cc105	bc not running/jamming	only motor is running /inform to ope.	13:20:00	13:30:00	
13	WT	CC2	ZSS acted found/tyre coupling problem	inform to mech. and ope.	13:00:00	13:20:00	tyre came out