



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

#### ELECTRICAL SHIFT REPORT

Date: 09/10/2025

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on CO-29	B/C zss acted	ZSS probe cable cut. cable joined and tested okay	07:30:00	07:40:00	
2	OHP	TT-1A	Reported Lt not taking place	OLR acted.Reset done	07:50:00	08:10:00	
3	OHP	WOBR on CO-29	Reported B/W not rotating	OLR acted.Reset done	08:30:00	08:35:00	
4	OHP	CO-29	Reported tripped	OLR acted. Reset done	10:20:00 13:45:00	10:30:00 13:50:00	
5	CHP	VF-101	Reported tripped	OLR acted due to heavy jamming.Reset done	08:50:00	09:30:00	
6	CHP	CO-51	Feeding conveyor stopping	MPd acted due to heavy material on belt(28 times MPD acted).Reset done	06:40:00	13:40:00	
7	CHP	CC-54	Reported tripped	OLR acted(7 times). Reset done	06:40:00	14:00:00	
8	CHP	CC-32 R-1	Reported luff down not taking place.Pending from C-shift	Checked and found relay contact not making.Relay changed and tested okay	06:00:00	08:00:00	
9	CHP	CC-33 SCR-5	Reported Lt not taking place	Wires tightening done and tested okay	10:10:00	10:15:00	
10	CHP	CC-107	Reported tripped	OLR acted.Reset done	10:10:00	10:15:00	
11	CHP	CC-47	Emergency pb problem	PB changed and tested okay	12:15:00	12:30:00	
12	CHP	CC-203	Reported Tripped	OLR acted.Reset done	13:15:00	13:25:00	
13	CHP	Cc-45	Reported Tripped	OLR acted.Reset done	13:20:00	13:30:00	
14	WT	OP-9	Reported not moving	Checked and found breaker tripped at LC-10B. C-Clamp and U-clamp got bent at column no.35.Changing is going on	13:40:00	14:30:00	NO delay as no rake