



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 31/08/2025

Shift: C

Incharge(s): Amit Roy,K SANKARA RAO

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------|-----------------------------------|---|--|--|------------------------|
| 1 | OHP | CO-58 | Reported tripped | MPCB tripped due to overload on belt.(2 times).Reset done | 02:00:00 23:00:00 | 02:12:00 23:05:00 | |
| 2 | OHP | BRC on CO-28 | B/C not running | OLR acted.Reset done(2times) | 00:40:00 | 01:00:00 | |
| 3 | OHP | CO-29 | Reported tripped | OLR acted.Reset done(4times) | 00:00:00 01:00:00 04:10:00 05:40:00 | 00:10:00 01:00:00 04:20:00 05:45:00 | |
| 4 | CHP | CC-54 | Reported tripped | OLR acted.Reset done | 00:45:00 | 00:55:00 | |
| 5 | CHP | CC-51 | Reported tripped | Feeding conveyor stopped(7 times). | 22:55:00 | 01:45:00 | |
| 6 | CHP | CC-114 | Reported tripped | OLR acted.Reset done | 01:30:00 | 01:40:00 | |
| 7 | CHP | CC-36 SCR-1 | Reported slew not taking place | SLew motor side jamming. | 23:20:00 | 23:40:00 | Informed to operation. |
| 8 | CHP | CC-39 SCR-7 | Reported LT not working | Checked and found to be working fine | 23:30:00 | 23:35:00 | Wrong Complaint |
| 9 | CHP | CC-34 SCR-2 | Reported Luffing not taking place | Operator problem.Not able to identify buttons.Not an electrical problem | 00:40:00 | 01:00:00 | Informed to operation |
| 10 | CHP | CC-38 SCR-6 | LT not taking place | Drive tripped.Reset done | 01:20:00 | 01:35:00 | |
| 11 | CHP | CC-39 SCR-7 | LT not working | Checked and found track jamming | 02:40:00 | 02:45:00 | Informed to operation |
| 12 | CHP | CC-104 SCR-9 | Reported luffing not taking place | checked and found MPCB tripped.made on | 03:50:00 | 04:10:00 | |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 31/08/2025

Shift: C

Incharge(s): Amit Roy, K SANKARA RAO

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|----------------|------------------------------------|--|----------------------|----------------------|---|
| 13 | CHP | CC-39 SCR-7 | Slew and LT not taking place | Slew right LS bypassed due to jamming. LT OT acted and M-2,6 tripped. OT released and MPCB made on | 01:05:00 | 01:30:00 | PCRD drum arrested. Inform to mechanical. |
| 14 | WT | AF-3 | Reported not running in local mode | Checked and found wire cam out of selector switch. Wire reconnected and tested okay | 03:00:00 22:30:00 | 03:15:00 22:40:00 | |