



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 19/07/2025

Shift: A

Incharge(s): Lal Singh, Arnab Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on CO 6A	BC not running bcz of belt sway acting due to belt off centering	Belt sway bypassed and informed operation	06:45:00	07:00:00	
2	OHP	CO 51	OLR acted	reset done	08:05:00	08:10:00	
3	OHP	CO 76R	Chute sensor malfunctioning	Bypassed	07:45:00	08:05:00	kept in circuit after rectification
4	OHP	CO 36A	Chute sensor malfunctioning	Bypassed at module	10:00:00	10:15:00	
5	OHP	All conveyors	LC 7 and LC 8 Incomer 1 no power	LC 7 bus coupler made on . LC 8 Incomer 2 made on	12:10:00	12:30:00	
6	CHP	CC 54	Tripped on overload	reset done	08:45:00	08:50:00	
7	CHP	CC 8	Chute sensor acting frequently due to loose connection in module	Connections tightened , then ok	08:55:00	09:10:00	
8	CHP	CC 39 , S-1	BC signal missing	LT done , PLC recycled . Still problem continues , informed to general shift	08:20:00	09:00:00	
9	CHP	CC 201 , CC 202	Frequently stopping and showing in local	Found that chute jamming in CC 202 . Also BRS,BSS acted. After cleaning reset done and healthy	10:00:00	10:30:00	
10	CHP	CC 44	Tripped on overload	reset done	09:00:00	09:10:00	
11	WT	CC 2	Carriage drive, belt drive tripped on overload	reset done	07:30:00	07:40:00	
12	IOSA	L and T WOBR	BW not rotating	BW stucked in material , LT reverse done and then BW made free and running	11:30:00	11:50:00	