



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 11/11/2025

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on CO-29	Reported LT not working	M4 acted.Reset done	14:20:00	14:50:00	
2	OHP	WOBR on CO-26	Slewing not moving	Drive olr acted.Reset done	15:00:00	15:40:00	
3	OHP	CO-29	Reported tripped	OLR acted.Reset done	18:00:00	18:05:00	
4	OHP	TBS on CO-22	LT not taking place	Drive tripped.Reset done	19:30:00	19:40:00	
5	OHP	CO-22	Reported BRS not getting Reset	Checked and found I/O rack side return wire cut.Wire was put properly and tested okay	18:10:00	18:25:00	
6	OHP	CO-21	Reported ZSS acting	ZSS probe problem.Replaced and tested okay	20:15:00	20:40:00	
7	OHP	CO-67	Reported tripped	OLR acted.Reset done	18:45:00	19:00:00	
8	OHP	CO-23 TBS	Reported no power	3 ht fuses blown.Coupler flashover found.Cable meggered and found okay.Coupler cleaned and tested okay	14:00:00	15:30:00	
9	CHP	Cc-19	Reported tripped	OLR acted.Reset done	16:40:00	16:45:00	
10	CHP	CC-44	Reported tripped	OLR acted.Reset done	16:00:00	16:05:00	
11	CHP	Cc38 SCR -6	B/C not running	OLR acted due to jamming.Reset done	19:20:00	19:30:00	informed to operation
12	CHP	Cc125	Reported tripped	OLR acted.Reset done	20:35:00	20:40:00	
13	CHP	CC51	Reported tripped	MPD acted.Reset done(8times)	16:45:00	20:20:00	
14	WT	AF-2	Drive tripping	due to jamming	21:15:00	21:30:00	
15	WT	OT-4	Initial not coming	Probe adjusted and tested okay	18:40:00	18:45:00	