



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 09/10/2025

Shift: A

Incharge(s): Amit Roy

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|--|--|----------------------|----------------------|---------------------|
| 1 | OHP | WOBR on CO-29 | B/C zss acted | ZSS probe cable cut. cable joined and tested okay | 07:30:00 | 07:40:00 | |
| 2 | OHP | TT-1A | Reported Lt not taking place | OLR acted.Reset done | 07:50:00 | 08:10:00 | |
| 3 | OHP | WOBR on CO-29 | Reported B/W not rotating | OLR acted.Reset done | 08:30:00 | 08:35:00 | |
| 4 | OHP | CO-29 | Reported tripped | OLR acted. Reset done | 10:20:00 13:45:00 | 10:30:00 13:50:00 | |
| 5 | CHP | VF-101 | Reported tripped | OLR acted due to heavy jamming.Reset done | 08:50:00 | 09:30:00 | |
| 6 | CHP | CO-51 | Feeding conveyor stopping | MPd acted due to heavy material on belt(28 times MPD acted).Reset done | 06:40:00 | 13:40:00 | |
| 7 | CHP | CC-54 | Reported tripped | OLR acted(7 times). Reset done | 06:40:00 | 14:00:00 | |
| 8 | CHP | CC-32 R-1 | Reported luff down not taking place.Pending from C-shift | Checked and found relay contact not making.Relay changed and tested okay | 06:00:00 | 08:00:00 | |
| 9 | CHP | CC-33 SCR-5 | Reported Lt not taking place | Wires tightening done and tested okay | 10:10:00 | 10:15:00 | |
| 10 | CHP | CC-107 | Reported tripped | OLR acted.Reset done | 10:10:00 | 10:15:00 | |
| 11 | CHP | CC-47 | Emergency pb problem | PB changed and tested okay | 12:15:00 | 12:30:00 | |
| 12 | CHP | CC-203 | Reported Tripped | OLR acted.Reset done | 13:15:00 | 13:25:00 | |
| 13 | CHP | Cc-45 | Reported Tripped | OLR acted.Reset done | 13:20:00 | 13:30:00 | |
| 14 | WT | OP-9 | Reported not moving | Checked and found breaker tripped at LC-10B. C-Clamp and U-clamp got bent at column no.35.Changing is going on | 13:40:00 | 14:30:00 | NO delay as no rake |